

Insurance Tailor

REF: M81G

# ASSIGNMENT

From: Date: 23/5/2018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLM 5913 Y  
at Workshop m/s: performance motor  
of 303 Alexandra Rd

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Han

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLM 5913 Y Yr Regn: 2017 / March  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 530i cc 1998

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 24534 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAJA52080 495321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I: 23/5/18

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23/5/2018

Date/Time File Pass to?

29/6/18

1) 29/6/18

Date/Time File Return to?

2)

☒ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

1 S + RS \$

2 Photos

3 Clean

TOTAL

Report Format: Preli Report

Lump Sum / I.B.F: (\$)

150

10

160