

ASS. REC. BY:

REF:

CS/MSG 18008432/TLSB/

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Inne Tan Gek Ing

MSIA

Date/Time:

09/08/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 5913Y

Insured:

SLF 8332R

at Workshop m/s

Performance Motors

Tel:

of

303 Alexandra Road, Sime Darby Performance Centre

Policy No:

Claim No:

TP/557721

Sum Insured:

Excess:

\$ 600.00

Make of Veh:

(Client's Record)

D.O.A.

05/05/18

CA / REV / REP. / REV 24 HRS WPI

23052018

Ah Han 9116 5700

H.O.D. Endorsement:

Date/Time:

9/5.

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Han
24/05/18	@ 14:29 p.m. revised IA to Inne Tan Gek Ing via merimer.	
28/08/18	Ah Han (repairer) mentioned owner not agreed the bumper parts due to his colleague discuss with the owner misunderstanding.	
	Submit Prel; Report	

REF: M81G

ASSIGNMENT

From: Date: 23/5/2018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 5913 Y
at Workshop m/s Performance motor
of 303 Alexandra Rd

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make-of Veh: Han

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLM 5913 Y Yr Regn: 2017 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 530i c.c. 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 24534 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAJA52080 GFS 5341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 23/5/18

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 28 AUG 2018

Date/Time. File Pass to?

29/6/18

1) Typist

Date/Time. File Return to?

2)

☒ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) Photos

) Others

TOTAL

Report Format: Preli Report

Lump Sum / I.B.I: (\$)

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		09 May 2018 09:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		FAIZAL BIN BOHARI, ID: S7626225Z							
Main Claimant:		SOH BENG HWEE, ID: S1163245I							
Vehicle Reg. No.:		SLM5913Y	Date of Loss:	05/05/2018 08:00 - :59 [13 Months and 5 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 557721	Policy/Cover Note No.:	8054719QMX (Comprehensive) Coverage: 09/03/2018 - 08/03/2019					
Vehicle Reg. No. (Insured):		SLF8332R	Policy No. (Claimant):						
		Excess:	S\$600.00						
Repairer:		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/05/2018]							
Adj Asg. Remarks:		PML SELECT LKK AS SJE							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Caroline Veh Out

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Tel. 63190528 (AfterSales)
63190539 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

08 MAY 2018

Estimate No. : b1 46867
Date Estimated : 08/05/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Soh Beng Hwee
105 Petir Road
#17-11

Singapore 678274

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SIM5913Y	G455341	31/03/2017	530iA	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident

VALUE
850 1,275.00

To respray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: **2,570.00**DESCRIPTION

REAR BUMPER CARRIER
EXHAUST SUPPORT
REAR BUMPER COVER (M)
REAR BUMPER PANEL PRIMED (M)

QTY	PRICE	VALUE
1	793.55	? 793.55
1	47.45	? 47.45
1	176.45	de 176.45
1	1,587.75	de 1,587.75

Total Parts : **2,605.20**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/5/18 Excess S\$ _____

Surveyor's Name Tanjun Sign _____

Surveyor's Tel 92498249 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjun @ lkkauto.com

No. of Working Days Recommend 03 days

Labour 1 : 2,570.00
Parts : 2,605.20
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 362.26
Grand Total : **5,537.46**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/05/2018 17:31
Date Of Accident	05/05/2018 08:40
Exact Location Of Accident	EXIT OF BLK 962A JURONG WEST MSCP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM5913Y
Insured/Policyholder	
Name Of Registered Owner	SOH BENG HWEE
NRIC No	S1163245I
Email Address	NELSONSOHBH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98266223
Alternative Phone No	OFFICE-98266223
Vehicle Particulars	
Manufacturer	BMW
Model	530I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	NOTAVAIL
Cover Note Number	
Driver	
Name of Driver	SOH BENG HWEE
NRIC No	S1163245I
Date Of Birth	17/11/1956
Occupation	INDOOR
Date Of Driving Pass	25/09/1975
Driving Experience	42 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98266223
Fax Number	
Contact Number	OFFICE-98266223
EMail Address	NELSONSOHBH@GMAIL.COM

Address	105 PETIR RD #17-11
Postcode	678274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUNG LAI FONG
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF8332R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FAIZAL BIN BOHARI
NRIC/Passport Number	S7626225Z
Contact Number	98537359
Address	BLK 837 JURONG WEST ST 81#07-73
Postcode	640837
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 5/5/18 at around 8:38 am while my car stopped behind another car at the exit of MSCP B1C 962a HDB Jurong West MSCP, suddenly a car SLF8332R driven by one Faizal Bin Bohari crashed into my rear. We were shocked. When we sighted Faizal apologised and we exchanged particulars.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 7/5/18
4:45 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018		09 May 2018 09:39 Edit Adj Rpt	S\$3,698.20 Edit Estimates	S\$3,698.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: FAIZAL BIN BOHARI , ID: S7626225Z									
Main Claimant: SOH BENG HWEE , ID: S1163245I									
Vehicle Reg. No.: SLM5913Y		Date of Loss: 05/05/2018 08:00 - :59 [13 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 557721		Policy/Cover Note No.: 8054719QMX (Comprehensive) Coverage: 09/03/2018 - 08/03/2019							
Vehicle Reg. No. (Insured): SLF8332R		Policy No. (Claimant):							
		Excess: S\$600.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/06/2018]									
Adj Asg. Remarks: PML SELECT LKK AS SJE									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM5913Y (557721)
[SLF8332R]
TP
SOH BENG HWEE
May 5 2018 8:00AM
[FAIZAL BIN BOHARI]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 16:29	Non Reporting Letter to OI	Load HTM	
Assessment Reports			1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 14:29	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page 3 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
2	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
3	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
4	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
5	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
6	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
7	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
8	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
9	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
10	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
11	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
12	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
13	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
14	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
15	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
16	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
17	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
18	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
19	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
20	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
21	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
22	29/08/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/05/18 16:25	TPD SLM5913Y GIA REPORT.PDF	Load PDF	
2	08/05/18 16:25	SLM5913Y -EST & PARTICULARS IC &	Load PDF	
3	08/05/18 18:15	EMAIL TO APPOINT LKK.pdf	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008482/T1SBE2

Date: 30/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 8054719QMX

Claimant Vehicle No : SLM5913Y

Insured Vehicle No : SLF8332R

Date of Loss: 05/05/2018

Nature of Claim: TP

Claim No: 557721

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM5913Y

Make & Model: BMW 530i, 2.0 LED NAV (A)

Engine No: 11699867B48B20B

Reg. Date: 31/03/2017 (Man. Year: 2017)

Chassis No: WBAJA52080G455341

Colour: Grey

Odometer: 24554 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35R19

Rear Tyre Size: 275/35R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,685.20	1,764.20	921.00	34.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,175.20	3,698.20	1,477.00	28.54
+ GST 7.00/7.00% (S\$)	362.26	258.87	103.39	28.54
Nett Amount (S\$)	5,537.46	3,957.07	1,580.39	28.54

INSPECTION

Date of Assignment: 09/05/2018

Date Inspected: 23/05/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$921.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)
Parts:	143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM5913Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CARRIER	*Check	793.55 FS	*- FS
2	1		*EXHAUST SUPPORT	*Check	47.45 FS	*- FS
3	1		*REAR BUMPER COVER (M)	Deformed	176.45 FS	*176.45 FS
4	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,587.75 FS	*1,587.75 FS
5	1		*SUNDRIES	*Check	80.00 FS	*- FS
					Total Parts (S\$)	2,685.20 1,764.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >