

INS. CASE OWNER:

Frankman

CCY / AXA1800

8441, T2 job

LKK:
IDAC:

Surveyor:

Tantek

DOI:

ASSIGNMENT

10/5/18

Date / Time:

9/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

4m307R

Name of Insured:

HUB DISTRIBUTIONS SERVICES

Insured Tel No.:

HP:

D.O.A.:

Nature of Accident:

Excess Sec II : \$

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

PERN JIMM 41

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8MOU6F8 / 44136

Policy No.:

P1130444

Make / Model:

MITSUBISHI

Place of Accident:

6 FISHERY PORT RD


OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability:

%

Final ? Yes / No

YP 333J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin Gheo



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/5/18
WY

YP 333J - Y 4m307R - Y

A smart claim

16-07-18

IN VIEW OF DAMAGE PROFILE, WE BELIEVE DIB'S VERSION IS CREDIBLE. TO REJECT TP CLAIM.

Reject Case

By (staff):

Approved by:

Date:

16-07-18

RECEIVED 17 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

16/5/18

Sent By:

DM

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

COPY SENT 17/7/18

Case No.

Tan Jhi

REF:

AXA

ASSIGNMENT

From:

Date: 10/5/2018

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: YP333J

at Workshop m/s Sin Sheng
of 3 Pech Park Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

490K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

YP333J

Yr Regn

2015 Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Fuso FM65

CC 7545

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

164679

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FM65 FMA 2014

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/80R22.5

R:

225 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Master

Front

R/Bal:

8

mm

Rear

R/Bal:

8/8

mm

L/Bal:

8

mm

L/Bal:

8/8

mm

D.O.A.

D.O.I.

10/5/18

Survey held at

Sin Sheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

w/s will mail 9/11/18

Trust-Link. Express LLP. T 0585A
1583N

L/S \$ 4,500

R (\$ 1,652.93 / 27 %)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) \$ + RS \$

2) Photos

3) Others

4)

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008491/T1jb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 09-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 3872R	Veh. Inspected	YP 333J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/05/2018	Inspection Date	10/05/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002471

Date : 08/05/2018

Vehicle Num. : YP333J

Make/Model : MITSUBISHI FM 65-2015

Chassis/Eng# : FM65FMA20114/6M60208409

Accident Date : 07/05/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	HINGE, FR DOOR	bt 419.71	
2.	1	HINGE, FR DOOR, UPR	bt 419.71	
3.	1	FRONT CORNER PANEL	cur 1,097.11	
4.	1	DOOR ASSY	buy 3,913.86	
5.	1	WEATHERSTRIP, FR DOOR OPENING, INR, RHS	wt 246.85	
List Total S\$:				6,097.24
25.00% Discount S\$:				1,524.31
				✓ 4,572.93
LABOUR :				
TO PANEL BEAT/REPAIR RH BODY			450	650.00
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS				
SPRAY PAINTING			450	650.00
TO APPLY NEW LOGO			120	180.00
TOWING CHARGES			✓	100.00
LOSS OF USE: 4 DAYS @ \$ 200/DAY				
Labour Total S\$:			1120	1,580.00

Total S\$: 6,152.93

=====

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia 97498749 5692.93
WP
w/ 5/18 @ 1615 450 4500
resurvey after repair 4 days
4 days
sur @ LKK Auto Consultants

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002471

Date : 08/05/2018

Vehicle Num. : YP333J

Make/Model : MITSUBISHI FM 65-2015

Chassis/Eng# : FM65FMA20114/6M60208409

Accident Date : 07/05/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	HINGE, FR DOOR	bt 419.71	
3.	1	HINGE, FR DOOR, UPR	bt 419.71	
4.	1	FRONT CORNER PANEL	car 1,097.11	
5.	1	DOOR ASSY	but 3,913.86	
5.	1	WEATHERSTRIP, FR DOOR OPENING, INR, RHS	wt 246.85	

List Total S\$:

6,097.24

25.00% Discount S\$:

1,524.31

4,572.93

LABOUR :

TO PANEL BEAT/REPAIR RH BODY

450

650.00

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

450

650.00

SPRAY PAINTING

120

180.00

TO APPLY NEW LOGO

✓

100.00

TOWING CHARGES

LOSS OF USE: 4 DAYS @ \$ 200/DAY

Labour Total S\$:

1,580.00

Total S\$:

6,152.93

=====

SIN SHENG ENGINEERING SERVICES

Tanpin 97495249

w/s 1/80/1615

ready after repair

4 days

sur @ 1/16/1615

Lump Sum \$4500/2



Service Request Details

Claim

S8M00GFZ

Reference

None 

Loss Date

May 7, 2018

Request Date

May 8, 2018

Due Date

May 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

YP333J

Make

TPVD

Sin Sheng
Subm @ 240pm
Veh. In

LKK AUTO CONSULTANTS PTE LTD (TP) *

Service Address

Primary Contact/Insured

HUB DISTRIBUTORS SERVICES PTE LTD
2 CLEMENTI LOOP, #01-04, 129809, Singapore
65674755

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

5/8/18 5:06 PM

FROM

CHAN Kian Chuan

SUBJECT

OI NON REPORTING

BODY

FOR YOUR FOLLOW UP ACTION PLEASE





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Survey Details:

Date of loss	7-May-18
Date of appointment	9-May-18
Date of survey	10-May-18
Location of survey	SIN SHENG ENGINEERING SERVICES

Vehicle Details:

Claim Type:	Third party
Vehicle number	YP 333J
Make and Model	MITSUBISHI FUSO FM65FM2RDEB
Date of registration	01.12.2015
Excess	
Market Value	\$90,000
Part Rebate	\$32,929
Nett Loss	\$57,071

Repair details:

Initial Estimate	\$ 6,152.93
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,572.93
Check items (estimate)	\$ -
Labour	\$ 1,120.00
Total	\$ 5,692.93
Lump Sum(if applicable)	\$ -

Number of days for repair	4
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		%
Proposed repair cost	\$	
Loss of use	\$	
Loss of rental	\$	
Loss of income	\$	
LTA search fees	\$	
Others	\$	
Proposed Total		



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

1-Jun-18

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2018/0166

Your ref: S8M00ALO MC/C

Attn: Officer In Charge

Dear Sir,

VEHICLE: YP333J (DoA: 07/05/2018)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	4,815.00
Loss of Use: 6 days @ S\$ 200/day (including 2 day for PRI)	:	1200.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	7.49
Total	:	<u><u>6,022.49</u></u>

Thank You

Yours faithfully

Susan Tan
OPERATIONS EXECUTIVE

Encl

AUTHORIZATION TO ACT

I, GOLDBELL LEASING PTE LTD ("The Third Party Claimant") of
NO 59, SENOKO ROAD, SINGAPORE 758123 (address),
being the owner of YP333J (vehicle no.) hereby authorize
SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me
with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my
vehicle bearing registration no. YP333J that was damaged pursuant to the accident
which occurred on 07/05/2018 along Loading Bay @ 6 Fishery Port Road
involving vehicle's YP333J / YM3872R ("the
accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem
fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability in so far as the driver/owner/insurers of
the other vehicle is concerned.

Dated this 01 day of JUN (month) 2018 (year)




Signed by "the Third Party claimant"



Signed by "the workshop"



新盛機械工程服務

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT, TUAS TECH PARK, SINGAPORE 638129

TEL: 6863 9595 FAX: 6863 6477

REGISTRATION NO.: 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Tax Invoice : TI002471

Date : 01/06/2018

Vehicle Num. : YP333J

Make/Model : MITSUBISHI FM 65-2015

Chassis/Eng# : FM65FMA20114/6M60208409

Accident Date : 07/05/2018

Claim No. : S8M00GFZ MC/CKC

Reference :

Policy No. : 29004183

LUMP SUM REPAIR

Amount S\$

4,500.00



SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Total S\$:	4 500.00
GST @ 7% S\$:	215.00
Amount Due S\$:	4 615.00

N.B: • All cheque should be crossed and made payable to "SIN SHENG ENGINEERING SERVICES".
• Interest at the rate 1.5% per month will be levied on overdue accounts.
• Please verify the above and notify us of any discrepancies within 7 days.

CUSTOMER COPY



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 08 May 2018 / 15:27:49

Receipt Date/Time : 08 May 2018 / 15:27:49

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180508-001564

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YM3872R As at 07 May 2018/21:20:00 Insurance Co: AXA INSURANCE PTE LTD YP333J (07/05/2018) Owner : GBL				
1	Insurance Enquiry - YM3872R Enquiry Fee 20180508152657707225	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SLP1357M As at 05 May 2018/10:35:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD. GBC3642M (DoA:05/05/2018) Owner : GBL				
2	Insurance Enquiry - SLP1357M Enquiry Fee 20180508152657735034	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		14.00	0.98	14.98
Rounding Difference				0.03
Total Amount Payable				14.95
Paid By				
	20180508152724526	Direct Debit: eNETS Debit (Internet Banking)		14.95
Total				14.95
Cash Change				0.00
Tendered Amount				14.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

Your Insured's vehicle : YM3872R

Our customer's vehicle : YP333J

Date : 08/05/2018

AXA INSURANCE SINGAPORE PTE LTD

Dear Sirs,

DATE OF ACCIDENT : 07 MAY 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. YP333J
Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services
Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129
Contact : Ms Susan / Ms Cheryl Yuan
Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below, Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.

Your sincerely,

Susan

Acknowledgement

This is to confirm that I *Tan Jiah* \[Full Name of Surveyor]
of *Lku* \[Surveyor's Company]
have completed the pre-repair inspection on *10/5/18* \[Date if Inspection]
at *1615* \[Time of Inspection]

.....
Signature of Appointed Surveyor
Company Stamp

Susan
.....
Witnessed By:
Date

Waiver

We waive our rights to an inspection/survey of the above vehicle.

.....
Signature
Name :
Date :



Re:IA uploaded

Type

🔗 Question

Message

PLS REJECT CLAIM, TP OPEN DOOR AND COLLIDED ONTO OIV

Reply

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 16 July 2018 2:41 PM
To: 'sinsheng engineeringservices'
Cc: Admin A; CS A Team
Subject: ACCIDENT INVOLVING YP 333J ON 07/05/2018 / AXA YM 3872R

WITHOUT PREJUDICE

Dear Susan,

We refer to the subject.

Our insured reiterated that the accident was due to the entire negligence of your client by opening door.

In view of the above, we regret to inform you that we are unable to look into your claim.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

<< Service Request Details

Claim	S8M00GFZ	Vehicle Information	
Reference	CC4/ASM18008491/jt3oss Date	Incident Vehicle	YP333J
		Registration #	TPVD
		Make	TBC
		Model	TPVD
		Service Address	
May 7, 2018	Request Date	Primary Contact/Insured	
May 8, 2018	Due Date	HUB DISTRIBUTORS SERVICES	
May 9, 2018	Vendor Name	PTE LTD	
	Type of	2 CLEMENTI LOOP, #01-04,	
		129809, Singapore	
		65674755	
		LTD (TP)	
		Third Party Vehicle Services	
		Damage	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
IA FOR QUANTUM MANDATE REQUEST-SIN SHENG.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 13, 2018
IA FOR QUANTUM MANDATE REQUEST-SIN SHENG.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 13, 2018
IA FOR QUANTUM MANDATE REQUEST-SIN SHENG.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 13, 2018
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 13, 2018
RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 13, 2018
ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 12, 2018
Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
EMAIL RECIEVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	May 8, 2018

<< **Service Request Details**

Claim	S8M00GFZ	Vehicle Information	
Reference CC4/ASM18008491/jt3oss Date 		Incident Vehicle	YP333J
		Registration #	Make Address
		Model	TPVD
		TBC	
May 7, 2018	Request Date		
May 8, 2018	Due Date		
May 9, 2019	Vendor Name		
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss		
Third Party Vehicle Damage	Services		
		Primary Contact/Insured	
		HUB DISTRIBUTORS SERVICES PTE LTD 2 CLEMENTI LOOP, #01-04, 129809, Singapore 65674755	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
YP333J

Purchase Date
mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

12/01/2015



Mileage

164679

Age of Vehicle
2

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT...

CATEGORY Driver Name

ASSESSMENT INFO...

2015

FNOL INFORMATI... TBC

CATEGORY

Make

POST SURVEY INF...

FNOL INFORMATION...	0
POST SURVEY INFORMATION...	
CATEGORY	Driver License #
FNOL INFORMATION...	
POST SURVEY INFORMATION...	
CATEGORY	License Type
FNOL INFORMATION...	
POST SURVEY INFORMATION...	
CATEGORY	License Issue Date
FNOL INFORMATION...	
POST SURVEY INFORMATION...	mm/dd/yyyy 
CATEGORY	License Expiration Date



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

AUSTONE8mm

Rear left side

AUSTONE8/8mm

Front right side

AUSTONE8mm

Rear right side

AUSTONE8/8mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts			
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	1	1			HINGE, FR DOOR			Bent	419.71		25		314.78
	2	1			HINGE, FR DOOR, UPR			Bent	419.71		25		314.78
	3	1			FRONT CORNER PANEL			Cracked	1097.11		25		822.83
	4	1			DOOR ASSY			Buckled	3913.86		25		2935.4
	5	1			WEATHERSTRIP, FR DOOR OPENING, INR, RHS			Cut	246.85		25		185.14
Labour													
EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT		
	1				TO PANEL BEAT / REPAIR RH BODY, TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS.	450	0	0	Reviewing				
	2				SPRAY PAINTING.	450	0	0	Reviewing				
	3				TO APPLY NEW LOGO.	120	0	0	Reviewing				
	4				TOWING CHARGES.	100	0	0	Reviewing				

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	DAYS OF REPAIR	Reviewing	4		

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$5,692.93	Claim Amount	\$5,692.93	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$1,120.00	\$1,120.00
--------	------------	------------

Spare Parts	\$4,572.93	\$4,572.93
-------------	------------	------------

Submit for Review

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

		1	Reviewing	4500		
FINAL LUMP SUM						