

REF:

REF: CS/SMD/8008508/Gcd/307

Special instruction:

## SUMMARY

GQ

### ASSIGNMENT (Office)

From (Person): Grace Teo of SMD Date/Time: 9/5/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 1117P Insured: SKD 8882E

at Workshop m/s Nq Motor Tel: 64531432

of Bk 8 8/m #01-70

Policy No: \_\_\_\_\_ Claim No: CMTD18D1977 GPL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 7/5/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS

10/5/2018 Morning

H.O.D. Endorsement:

Date/Time: 9/5 Person Contacted: \_\_\_\_\_ Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate.
	SKD1117P-X
	SLD8882E-X.

REF: SMO

## ASSIGNMENT

From: Date: 10052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 1117P

at Workshop m/s

of Blk 8 Sin Ming Ind Est #01-70

Insured:

Policy No. 62266922 Yanyechin

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

ID&amp;C Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKD 1117P

Yr Regn:

09 Feb 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes E250

C.C.

1796

Colour:

Brown

A/C.

Insured / Std / NI / NA

Sp. Reading:

128547

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2073472F030251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/P or

Tyre Size:

F:

255/35ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10-05-18

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/9

Submit final fig &amp; foot and 3 days without finalise. (Red Foot, 50%) No Lump Sum

16/9/2019

Date/Time. File Pass to?



Prel. Report

1)



Final Report

Date/Time. File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

250

Transportation:

1. S + P: \$

2. Photos

3. Others

TOTAL

250

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / (B) (\$

Foot

## Catherine Chong (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 9 May, 2018 4:19 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** MAXIMUS LAW LLC\_YC; Gnoh, Pau Loong; Ye, Yong Kang Melvin  
**Subject:** CMTD1801977/GPL - SUV(LKK)/ Accident Involving SLD8882E & SKD1117P on 7.5.2018 at Seletar Mall Basement Carpark.  
**Attachments:** PRI letter to Sompo Ins, 20180509.pdf

Our Reference: CMTD1801977/GPL

Dear LKK AUTO/KENNETH,

Please make arrangement to conduct the survey for SKD1117P.

Please be informed that Gnoh Pau Loong the handler of this case

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

*Veh In  
10/5/18 Morning*

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** MAXIMUS LAW LLC\_YC [mailto:yamcheng@maximuslaw.com.sg]

**Sent:** Wednesday, May 09, 2018 4:13 PM

**To:** Teo, Grace

**Subject:** Re: CMTD1801977/GPL - PRI/ Accident Involving SLD8882E & SKD1117P on 7.5.2018 at Seletar Mall Basement Carpark.

Hi Grace,

Our client instructs that he will choose your surveyor LKK Auto Consultants (Kenneth Kong).

For your necessary action. Thank you.

To: **SOMPO INSURANCE SINGAPORE PTE LTD**  
(Motor Claims Department)  
Your insured vehicle: **SLD8882E**

By Fax: 62213302

Our customer's vehicle: SKD1117P

Date: 9.5.2018

Dear Sirs,

**RE: Notice to Insurer to Conduct Pre-repair Inspection on SKD1117P;  
Accident Involving SKD1117P and SLD8882E on 7.5.2018 at Seletar Mall Basement Carpark.**

We have been appointed to repair motor vehicle no. SKD1117P.

Please be informed that the said vehicle can be inspected on/at:-

Please be informed that the said vehicle can be inspected at:-

Address : Ng Motor Vehicle Spray Painting  
Blk 8 Sin Ming Industrial Estate Sector C, #01-70/72  
Singapore 575643  
Contact : Mr Ng Boon Chye  
Tel : 6453-1432  
Fax : 6458 4553

Pursuant to ePractice Direction No. 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next two (2) working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below. Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

We attach herewith our list of surveyors for your perusal.

Yours sincerely,

Acknowledgement

This is to confirm that \_\_\_\_\_ (Full name of surveyor)  
of \_\_\_\_\_ (Surveyor's Company)  
has completed the pre-repair inspection on \_\_\_\_\_ (Date of Inspection)  
at \_\_\_\_\_ (Time of Inspection)

Signature of Appointed Surveyor/Witnessed by: \_\_\_\_\_  
Company Stamp/Date: \_\_\_\_\_

Waiver

We waive our rights to inspection of the above vehicle

Signature: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4785B
Vehicle Details	
Vehicle No.:	SKD1117P
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI COUPE
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	27186030022610
Chassis No.:	WDD2073472F030251
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$60,783.00
Original Registration Date:	09 Feb 2010
First Registration Date:	09 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$60,783.00
Intended PARF Rebate Detail	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2020
PARF Rebate Amount:	\$30,391.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
COE Paid:	\$23,180.00
COE Rebate Amount:	\$1,931.00
<b>Total Rebate Amount:</b>	<b>\$32,322.00</b>

The information contained herein is correct as at 08 Apr 2019

OK

5/8/2018

E-FILE

(Draft)

MLHM180E0068 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming  
 ENTRY DATE & TIME: 08/05/2018 16:31  
 SUBMITTED BY: [To Be Confirmed]

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date Of Report 08/05/2018 16:31  
 Date Of Accident 07/05/2018 17:30  
 Exact Location Of Accident BASEMENT CARPARK OF SELETAR MALL  
 Country/State of Loss SINGAPORE

Vehicle Registration Number SKD1117P  
**Insured/Policyholder**  
 Name Of Registered Owner LEE KAH LOONG  
 NRIC No S6844785B  
 Email Address LEELOY821@HOTMAIL.COM  
 Mobile Phone No (LOCAL) +65-96855734  
 Alternative Phone No Others-96855734

**Vehicle Particulars**  
 Manufacturer MERCEDES-BENZ  
 Model E250  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

**Insurance Company**  
 Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 2100366243-04  
 Cover Note Number

**Driver**  
 Name of Driver LEE KAH LOONG  
 NRIC No S6844785B  
 Date Of Birth 17/11/1968  
 Occupation OUTDOOR  
 Date Of Driving Pass 27/04/1993  
 Driving Experience 25 YEARS AND 0 MONTHS  
 Gender MALE

5/8/2018

E-FILE

Mobile Number (LOCAL) +65-96855734

Fax Number

Contact Number OTHERS-96855734

Email Address LEELOY821@HOTMAIL.COM

Address 21 FERNVALE CLOSE  
#18-08

Postcode 797460

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Vehicle Registration Number SLD8882E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 16/11/2016

Driver's Signature

(If driver is not the policyholder)

Date & Time:

  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Poh Kwee Choo  
S6840583A

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7<sup>th</sup> May, about 17:30 pm at Selatun Mall Basement Car Park Vehicle SLD 8882E while opening the back door hit my car on the left side (Passenger side) and cause a dent on my car. It is a lady who open the door and hit my car.

Both the cars are stationary. I was loading my grocery at the back while the incident happen. I heard the 'knock' sound, immediately I informed the driver of SLD 8882E.

However he deny the dent is caused by his door, even though when he open the door and the position of the knock is the point of the door open widely that hit my car in that spot. I have taken photo of the point of contact while the door is opened. Refer to the picture.

The driver refuse to hand over his particular and deny any wrong doing.

Their cars has 4 passengers. 2 women, 2 kids and one driver. I am the only driver person in my car.

## DECLARATION

I, We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

16:31 hrs

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Poh Kwee Choo  
S6540583A

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MLHM18060068 Vehicle Registration No : SLD1117P  
Name (as shown in NRIC) : LEE KAH LOONG NRIC/FIN/Passport No : S6644785B  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : 21 River trees Close, #18-06 Singapore (797410)  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 96855734  
Email Address : leeby921@hotmail.com  
Date of Accident : 7th May 2018 Time of Accident : 17:30 p.m  
Place of Accident : Solestar Mall Basement Car Park  
Insurance Company : AIG

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The attached is the police report.

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Policyholder / Driver's Signature  
Date:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:



## POLICE REPORT (NP299)

Report No. E/20180508/2085

Police Station Of Origin  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

Date/Time Report Made 08/05/2018 17:43	Vide Report No.	Station Diary No. 60	
Name Of Informant LEE KAH LOONG	Address 21 FERNVALE CLOSE #18-06 SINGAPORE 797460		
ID Type / ID No. NRIC NO / S6844785B	Contact No. Home/Office	Mobile 96855734	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Business Development	Sex Male	Age 49	Date of Birth 17/11/1968
Institution/School Name	Race Chinese		
Date/Time Of Incident 07/05/2018 17:30	Language English		
	Location Of Incident 33 SENGKANG WEST AVENUE THE SELETAR MALL SINGAPORE 797653		

### Brief details

On 7th May at about 1730hrs, I was loading my groceries into my car at B3 of Seletar Mall after my grocery shopping.

Later, I heard a loud knock sound which a passenger of the vehicle parked on the left side of my car (SLD8882E) opened the rear right passenger door and hit onto the left portion of my vehicle. The passenger then stared at me which I then went to confront them regarding the damages. The driver then denied that it was not his passenger who damaged the left portion of my vehicle after I tried to explain to

Signature Of Officer Recording The Report: E / Sgt 2 PANG XIU KANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 08/05/2018 17:43
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Insp LEE WAN TING, MAGDALENE Contact No.:	Classification Of Case:

Authentication Stamp



SINGAPORE  
POLICE FORCE



E/20180501 2065

2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20180501 2065

him about the situation. He also refused to hand over his particulars and was very defensive when I confronted him. I wish to inform that the car (SLD8882E) was parked on parking lot 29 at B3 Seletar and he was together with his family. Due to the knock, my car sustained scratches and dents on the left portion and I am unsure how much is the cost of the damages.

I am lodging this report for my own follow up actions and advised by my lawyer.

Signature Of Officer Recording The Report:

E/ Sgt 2 PANG XIU KANG

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
E/ Tanglin Police Divisional Investigation Branch /  
Inspector LEE WAN TING, MAGDALENE  
Contact No.:

Authentication Stamp

Signature Of Informant

Date/Time:  
08/05/2018 17:43

Classification Of Case:

# 黄摩哆汽车喷漆 NG MOTOR VEHICLE SPRAY PAINTING

BLK 8, SIN MING IND. EST #01-70 / 72 S(575643)  
Tel: 6453 1432 Fax: 6458 4553 Reg No.: 42432000B

Date : 09/05//2018

Mr Lee Kah Loong  
21 Fernvale Close  
#18-08  
Singapore 797460

Estimate Of Repair Cost - Vehicle No. SKD 1117 P Mercedes Benz E250

	Amount (\$)	
1 Spray Painting For LH Rear Mudguard (Big) Colour Code : Pearl	1,000.00	400
2 Panel Beating, Remove Inner & Refit For Above Mudguard Labour Charge	400.00	300
Total Estimate Cost :	\$1,400.00	700.

Singapore Dollars : One Thousand Four Hundred Only.

3 Days.  
\$700.

After repair photos.

Guo Qiang - 8288 0282

Guo Qiang @kkauto.com

10/5/18.



Let Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18008508/Gcd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 17-09-2019	
		Code : SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLD 8882E	Veh. Inspected	SKD 1117P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801977/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	09/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ E 250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WDD2073472F030251	Colour	BROWN
Odometer	128547	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	255/35Z R18	PIRELLI	6 mm
L/H Front Tyre	255/35Z R18	PIRELLI	6 mm
R/H Rear Tyre	255/35Z R18	PIRELLI	6 mm
L/H Rear Tyre	255/35Z R18	PIRELLI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/05/2018	Inspection Date	10/05/2018
Survey held at	NG MOTOR VEHICLE SPRAY PAINTING BLK 8 SIN MING IND.ESTATE SECTOR C #01-70/72 SINGAPORE 575643		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 1117P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	SPRAY PAINTING FOR LH REAR MUDGUARD (BIG) COLOUR CODE : PEARL.		1,000.00	400.00
	PANEL BEATING, REMOVE INNER & REFIT FOR ABOVE MUDGUARD LABOUR CHARGE.		400.00	300.00
			1,400.00	700.00
	<b>GRAND TOTAL</b>		<b>1,400.00</b>	<b>700.00</b>
	<b>RECOMMENDED COST OF REPAIRS (UN-CONFIRM)</b>			<b>700.00</b>

Report Ref No. CS/SMO18008508/Gcd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.