

ASS. REC. BY:

REF

CS3/MSG18002542/SZ4b42

Special Instructions:

Surveyor
Muslimen

Sebastian.

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSIG

Date/Time: 9/5/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: 85V1212 P

Insured: SKA 6247E

at Workshop m/s Toh Paintino

Tel: 67607541

of Blk 3 Woodlands Rd 391c

Policy No: 270839528MP

Claim No: 557218

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/4/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (\times) Estimate
	SJYDZP-7.
	SKA LATE - CUS' HICRUC TCH job3 due: SJH 0610 .

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJV 1212 P Yr Regn: 2017 / Jul 20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes BenzC.C. 159BColour: Red

A/C. Insured / Std / NI / NA

Sp. Reading: 9430

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1760932 JS-90856Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: NR / S/Rim / STD A/Rim orTyre Size: F: 225/45 R17R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mm

D.O.A. _____

D.O.I. 10/5/18

Survey held at

Tek Pany

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S, N/S FA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 14000 - 15000

* 3 days

17/5/18 Submit PRS report

RECEIVED 10 MAY 2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + PS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		09 May 2018 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN SEH TOON WILLIAM, ID: S1248048B								
Main Claimant:	YAP POH KIAN, ID: S1223025G								
Vehicle Reg. No.:	SJV1212P	Date of Loss:	27/04/2018 00:00 - :59 [9 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557218	Policy/Cover Note No.:	27083952SMP Coverage: 18/03/2018 - 17/03/2019						
Vehicle Reg. No. (Insured):	SKA6247E	Policy No. (Claimant):							
	Excess:								
Repairer:	Toh Painting & Services Pte Ltd (HQ) BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW TEE INDUSTRIAL ESTATE, 677966 Woodlands - Tel: 67607541								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/05/2018]								
Adj Asg. Remarks:	TP disagree with SJE - Proceed to appoint LKK. Liability not clear								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veh lu.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2018 15:47
Date Of Accident	27/04/2018 21:20
Exact Location Of Accident	NEWTON CIRCUS ROUNDABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV1212P
Insured/Policyholder	
Name Of Registered Owner	YAP POH KIAN
NRIC No	S1223025G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96884995
Alternative Phone No	OFFICE-96884995

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700027246
Cover Note Number	

Driver

Name of Driver	CHIA AN NI
NRIC No	S8070358I
Date Of Birth	13/04/1980
Occupation	INDOOR
Date Of Driving Pass	09/02/2007
Driving Experience	11 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96884995
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	100 FLORA ROAD #02-66
Postcode	509743
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I HAVE CHECK CLEAR BEFORE ENTERING TO MAIN ROAD, ROUNDABOUT. CAR B (SKA6247E) IS ON MY LEFT, WHEN WE ENTER TO MAIN ROAD I AM KEEPING MY LANE TO 2ND LANE. ALL OF SUDDEN, CAR B FROM 1ST LANE CUT INTO 2ND LANE AND COLLIDED MY CAR. I HAVE IN-CAR CAMERA FOOTAGE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER CSE ALAN QUEK
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA6247E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SEH TOON
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHIA AN NI
Approximate Age	
Injuries Sustain	LEG AND NECK
Injured person in which vehicle?	SJV1212P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form; and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"); and disclose and transfer such Personal Information to all insurers, who have insured vehicles, involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling, and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers (who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder,
Date & Time

Reporting Centre Personnel's
Name Alex Quek
NRIC/FIN No.

28/04/18

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① I have check clear before entering to main road, round about.
- ② (B) vehicle is on my left, when we enter to main road, I'm keeping my lane to 2nd lane.
- ③ All of sudden (B) vehicle from 1st lane cut into 2nd lane and collided my car.
- ④ I have in car camera footage

DECLARATION

We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details.)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name
NRIC/FIN No.

28/04/18
Name Alex Guek
NRIC/FIN No.



































...CLAIM SUBFOLDER...(Pending for Survey Report)




CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		09 May 2018 16:38 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN SEH TOON WILLIAM , ID: S1248048B								
Main Claimant:	YAP POH KIAN , ID: S1223025G								
Vehicle Reg. No.:	SJV1212P	Date of Loss:	27/04/2018 00:00 - :59 [9 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557218	Policy/Cover Note No.:	27083952SMP Coverage: 18/03/2018 - 17/03/2019						
Vehicle Reg. No. (Insured):	SKA6247E	Policy No. (Claimant):							
		Excess:							
Repairer:	Toh Painting & Services Pte Ltd (HQ) BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW TEE INDUSTRIAL ESTATE, 677966 Woodlands - Tel: 67607541								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 10/05/2018]								
Adj Asg. Remarks:	TP disagree with SJE - Proceed to appoint LKK. Liability not clear								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV1212P (557218)**
[SKA6247E]
TP
YAP POH KIAN
Apr 27 2018 12:00AM
[TAN SEH TOON WILLIAM]
Toh Painting & Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/05/18 12:04	Accident Statement From: SC - Reg. No: SKA6247E, Claimant: TAN SEH TOON	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 10:49	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)				
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	02/05/18 18:09	SJV1212P GJA Rpt	 Load PDF	
2	08/05/18 15:10	PRI	 Load PDF	
3	09/05/18 14:33	TP provide us with name of workshop and contact person	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008542/SZ4BE2

Date: 21/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27083952SMP

Claimant Vehicle No : SJV1212P

Insured Vehicle No : SKA6247E

Date of Loss: 27/04/2018

Nature of Claim: TP

Claim No: 557218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV1212P**Make & Model: MERCEDES-BENZ A200, 1.6 FL STYLE (R17 HLG)
(A)

Engine No: 27091031256598

Reg. Date: 20/07/2017 (Man. Year: 2017)

Chassis No: WDD1760432J590856

Colour: Red

Odometer: 9430 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/05/2018

Date Inspected: 10/05/2018 Inspected At:

Toh Painting & Services Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD, UNIT
391C&G YEW TEE INDUSTRIAL ESTATE
Singapore 677966

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000.00 - \$15,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 May 2018)
Parts: 144 **MERCEDES-BENZ A200 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJV1212P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >