

Shurini

CC 4/1111800 8557, U pa3

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler: Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

( days)

Loss of Use (LOU):

S\$

3w.w (\$100 x 3)

( days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

SME Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 300.00

COPY SENT 14/9/18

RECEIVED 14 SEP 2018



**SME MOTOR PTE LTD**

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. &amp; GST Reg. No: 201119451E

not allowed  
 after  
 more  
 14/6/18  
 try 2/5  
 to be kept before  
 3 days

TP INSURER: India International Insurance Pte Ltd (HQ)

TEE KOK LUAN

212 LOYANG AVE #01-02

Singapore 509064

Claimant Insurer: AXA Insurance Pte Ltd

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	18/III/TP-093 (05)
Policy No:		Date of Loss:	04/05/2018
Vehicle Reg. No.:	SCK882C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TEE KOK LUAN	Driver (Insured):	TEE KOK LUAN
Make/Model:	LEXUS GS350, 3.5 LUXURY (L10) (A)	Vehicle Reg. Date:	30/04/2012
Vehicle Colour:	BLACK	Chassis No:	JTHBE1BL005007412
Engine No:	2GR8751908		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	MY VEHICLE WAS STATIONARY AT TRAFFIC LIGHT. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

SMR Field - Insurers hence notify the Insurer of the following:

- To be done before after spray painting
- To discuss damaged part(s) during resurvey
- Paint prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplier's items must be resurveyed and is subject to final approval from Insurance Company

**COST OF CLAIMS**

	Amount
Parts	2,385.00
Miscellaneous Items	360.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,665.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>256.55</b>
<b>Nett Amount (S\$)</b>	<b>3,921.55</b>

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 May 2018)

Parts: 143 LEXUS GS350 3.5 LUXURY (L10) (A) (Catalogue Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SCK882C/07/05/2018 12:36

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LOGO 11	10.00	0.00	*70.00 FL
2	1		*REAR BOOT EMBLEM GS 350 11	10.00	0.00	*95.00 FL
3	1		*REAR BOOT EMBLEM LEXUS 11	10.00	0.00	*95.00 FL
4	1		*REAR BUMPER 10/02	10.00	0.00	*930.00 FL
5	2		*REAR BUMPER SIDE RETAINER 301	10.00	0.00	*270.00 FL
6	10		*REAR BUMPER CLIP 100	10.00	0.00	*50.00 FL
7	1		*REAR BUMPER REINFORCEMENT 12	10.00	0.00	*465.00 FL
8	1		*REAR BUMPER INNER SPONGE 11	10.00	0.00	*165.00 FL
9	1		*REAR BUMPER REFLECTOR LH 11	10.00	0.00	*75.00 FL
10	1		*REAR BUMPER LOWER SPOILER 12/101	10.00	0.00	*435.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)

2,650.00

- List Item Discount on L Items (\$\$)

265.00

Total Parts (\$\$)

2,385.00

SME Motor Pte Ltd/SCK882C/07/05/2018 12:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

1685  
1516.50

2576.50

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR REVERSE SENSOR (4PCS)	350.00
2	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			360.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	20.00
2	LABOUR CHARGE	New	500.00
3	SPRAY PAINTING	New	400.00
Gross Labour Cost (S\$)			920.00

SME Motor Pte Ltd/SCK882C/07/05/2018 12:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;



## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 6 September 2018 12:08 PM  
**To:** 'ying@smemotor.com.sg'  
**Cc:** Admin A  
**Subject:** RE: Your Ref: SCK 882C \*Our Ref: CC4/III18008557/Upa3 [ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018]

### Without Prejudice

Hi Ying,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 2,756.86
2. Loss of Use (3days x \$100.00)	\$ 300.00
3. LTA/ GIA Search Fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$ 3,064.31</u></b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 7 July 2018 12:09 PM  
**To:** 'ying@smemotor.com.sg' <ying@smemotor.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** Your Ref: SCK 882C \*Our Ref: CC4/III18008557/Upa3 [ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018]

Your Ref: **SCK 882C**  
Our Ref: CC4/III18008557/Upa3

**Without Prejudice**

Dear Sirs.

## Hsiao Tong (LKKAUTO)

---

**From:** ying@smemotor.com.sg  
**Sent:** Thursday, 6 September 2018 12:31 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Admin A  
**Subject:** Re: Your Ref: SCK 882C \*Our Ref: CC4/III18008557/Upa3 [ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018]

hi Hsiao Tong,

Accepted your offer of \$3,064.31.

Kindly send your DV for completion.

thanks & regards  
YING

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Thursday, September 6, 2018 12:07 PM  
**To:** ying@smemotor.com.sg  
**Cc:** Admin A  
**Subject:** RE: Your Ref: SCK 882C \*Our Ref: CC4/III18008557/Upa3 [ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018]

**Without Prejudice**

Hi Ying,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 2,756.86
2. Loss of Use (3days x \$100.00)	\$ 300.00
3. LTA/ GIA Search Fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$ 3,064.31</u></b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."



Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hsiao Tong (LKKAuto)

**Sent:** Saturday, 7 July 2018 12:09 PM

**To:** 'ying@smemotor.com.sg' <[ying@smemotor.com.sg](mailto:ying@smemotor.com.sg)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Your Ref: SCK 882C \*Our Ref: CC4/III18008557/Upa3 [ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018]

Your Ref: **SCK 882C**

**Without Prejudice**

Our Ref: CC4/III18008557/Upa3

Dear Sirs,

**ACCIDENT INVOLVING SH 8532L(III) AND SCK 882C ON 04/05/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

INDIA International Insurance Pte Ltd  
64 Cecil Street # 04-05  
IOB Building  
Singapore 049711

Your Insured Veh No. : **SH8532L**  
Your Ref :  
Our Ref : **SCK882C**  
Date : **24/07/2018**

**WITHOUT PREJUDICE**

**By Hand**

Dear Sir/Madam

**Accident involving SH8532L and SCK882C  
on 04/05/2018 at OLD TAMPINES ROAD.**

**Please refer only to the boxes marked ( x ).**

- ☒ We refer to ☒ the above accident  
☐ our/your letter dated
- ☒ We have been authorised by the owner of vehicle number **SCK882C** which was damaged by your insured's motor vehicle number **SH8532L** in the aforesaid accident.
- ☒ We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

Cost of Repair / Insurance Excess	<b>2,756.86</b>
Survey report fees	-
Loss of Use( 3days @ \$120.00 per day)	<b>360.00</b>
Car Rental Fees	-
GIA/LTA search fees	<b>7.45</b>
<b>Total S\$</b>	<b>3,124.31</b>

- ☒ We forward herewith the following relevant supporting documents:-

☐ Survey Reports & photographs (To be returned within 7 days on demand)

☒ Final repair bill(Tax Invoice)

☐ Bill/Receipt for the excess

☐ Rental Agreement

☒ Copy of the Insurance Certificate

☒ Copy of NRIC/Driving licence

☒ Copy of LTA/GIA vehicle search

☒ Non-injury motor report form

☒ Letter of Authority

- ☒ Cheque to be make payable to **Messrs SME MOTOR PTE LTD.**

☐ Any request for a re-survey of our client's vehicle must be arrange within the 14 days upon receipt of this letter. The re-survey must be conducted at our premises, in the presence of our client.

- ☒ Please note that you should send to us an acknowledgment of receipt of this letter within 07 days of your receipt of this letter.

Yours faithfully,

**WE HEREBY ACKNOWLEDGE RECEIPT**

**SME MOTOR PTE LTD**

encl:

Date: \_\_\_\_\_  
**PLEASE CHOP AND SIGN**

## LETTER OF AUTHORITY

To: M/s India International Insurance pte ltd  
Singapore


Accident involving my/our vehicle no. SCK882C and SH 8532L on 04/05/2018  
along Old Tampines Rd.

I/We, TEE KOK Luan NRIC No. S2507366B  
of 213 Loyang Ave #01-02 Singapore 509064

the registered owner of vehicle no. SCK 882 C at the material time of accident, do  
hereby authorise Messrs SME MOTOR PTE LTD as my/our agent and representative  
to correspond in, negotiate and settle, on my/our behalf, my/our claim against you as  
owner/operator/insurer of vehicle no. SH 8532L.

I/We also authorise them to accept settlement cheque on my/our behalf. Kindly issue  
your cheque in favour of "M/s. SME MOTOR PTE LTD".

Dated this 04 day of 05 20 18

  
Signature of Owner or his/her/their  
Duly Authorised Representative

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18050057  
 Claimant Ref: SCK882C

We/I, SME Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2,756.86 (repair cost), S\$ 300.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SCK 882C that was damaged pursuant to the accident which occurred on 04/05/2018 (date) at Old Tampines Road (location) involving vehicle no. SH 8532L (insured vehicle). This is pursuant to the inspection conducted on 12/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEE KOK LUAN ("the third party claimant") of vehicle no. SCK 882C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SCK 882C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,064.31 to SME Motor Pte Ltd

Dated this 08 day of 09 2018

#### CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

SME MOTOR P/L

NRIC:

201119457 E

Address:

1 KAH BUKIT AVE 6 #02-15  
AUTOBAY @ KAH BUKIT (S) 417883

Nationality:

-

Occupation:

-

#### WITNESS:

Signature:



LKS

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

51 Ubi Avenue 1,  
#01-25 Paya Ubi Ind. Park S(408933)

Nationality:

-

Occupation:

-

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
 GST:201119451E RCB NO:201119451E

**M/S :** INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 Cecil Street #04/05,  
 IOB Building  
 Singapore 049711  
**TEL:** 63476100 **FAX:** 62244174  
**ATTN:** Motor Claim Department  
**Your Ref No:** 18/III/TP-093(05)  
**Claim Type:** Third Party  
**Accident Date:** 09/04/2018  
**TP Veh Reg No:** SHD4448A

**Claim No:** EST0004299  
**Final No:** INV0003534  
**Date:** 24 Jul 2018  
**Policy No:** GA216971  
**Veh Reg No:** SCK882C  
**Make/Model:** LEXUS GS350  
**Chasis No:** 0  
**Engine No:**  
**Reg. Date:**

## Tax Invoice to Vehicle No :SCK882C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>Others</b>			
1 COST OF REPAIR	1 PC	2,576.50	
		2,576.50	2,576.50
		Total	S\$ 2,576.50
		Add GST @ 7%	180.36
		Total Amount Payable	S\$ 2,756.86

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SEVEN HUNDRED FIFTY SIX AND CENTS EIGHTY SIX ONLY

For SME Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 07 May 2018 / 12:21:19

Receipt Date/Time : 07 May 2018 / 12:21:19

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180507-000972

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SH8532L				
As at 04 May 2018/08:40:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SH8532L Enquiry Fee 20180507121918872535	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx6735	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2018 Sendback Est	07 May 2018 12:36 \$3,665.00	09 May 2018 15:51 Edit Adj Rpt	\$2,576.50 Edit Estimates	\$2,576.50 View Rpt		Pending for Survey Report Cancel Case











Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R, Tel: +6596302081								
Main Claimant:	<b>TEE KOK LUAN</b> , ID: S2501366B								
Vehicle Reg. No.:	<b>SCK882C</b>	Date of Loss:	04/05/2018 08:00 - :59 [72 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18050057</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SH8532L</b>	Policy No. (Claimant):	GA178221						
		Excess:							
Repairer:	<b>SME Motor Pte Ltd (Kaki Bukit)</b> 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sherini Pillai</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 18/05/2018]								
Driver/Custodian (Insured):	TEE KOK LUAN (64), NRJC: S2501366B, Tel: +6596302081								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>III_SG (03/09/2018): Alert - Adj Mandate Approved (\$3064.31) - SCK882C - Claim Handler: Sherini Pillai...</li> <li>III_SG (26/06/2018): Alert - Adj Mandate Approved (\$0.00) - SCK882C - Claim Handler: Sherini Pillai</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















## Claim Documents

**SCK882C (MCT18050057)**  
**[SH8532L]**  
**TP**  
**TEE KOK LUAN**  
**May 4 2018 8:00AM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**SME Motor Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/05/18 12:36	Repairer Estimates	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/09/18 09:51	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	01/09/18 09:51	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
4	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
5	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
6	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
7	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
8	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
9	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
10	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
11	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
12	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
13	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
14	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
15	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
16	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
17	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
18	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
19	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
20	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
21	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
22	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
23	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
24	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
25	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
26	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
27	01/09/18 09:51	General View	Load JPG	<input checked="" type="checkbox"/>
28	01/09/18 09:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	01/09/18 09:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	01/09/18 09:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	01/09/18 09:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	01/09/18 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	01/09/18 09:52	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	01/09/18 09:52	Reinspection Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
35	01/09/18 09:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/05/18 12:38	E-filed GIA report	 Load PDF	
2	07/05/18 12:38	LTA SEARCH	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/05/18 08:48	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/06/18 15:26	TP ESTIMATE - MARKED	 Load PDF	
2	08/08/18 17:20	LTA SEARCH	 Load PDF	
3	19/09/18 09:37	WORKSHOP INVOICE	 Load PDF	
4	19/09/18 09:37	AUTHORISATION TO ACT FORM	 Load PDF	
5	19/09/18 09:37	DISCHARGE VOUCHER	 Load PDF	
6	19/09/18 09:37	LOD	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/05/18 17:23	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/05/18 17:12	Driving License	 Load JPG	<input checked="" type="checkbox"/>
2	04/05/18 17:12	INSURANCE	 Load JPG	<input checked="" type="checkbox"/>
3	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	04/05/18 17:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/05/18 17:12	Sketch Plan	 Load TIF	
2	04/05/18 17:12	Sketch Plan #2	 Load TIF	
3	04/05/18 17:12	Sketch Plan #3	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				



# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18008557/UPA3Q2

Date: 19/09/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SCK882C

Insured Vehicle No: SH8532L

Date of Loss: 04/05/2018

Nature of Claim:

TP

Claim No: MCT18050057

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCK882C

Make &amp; Model: LEXUS GS350, 3.5 LUXURY (L10) (A)

Engine No: 2GR8751908

Reg. Date: 30/04/2012 (Man. Year: 2012)

Chassis No: JTHBE1BL005007412

Colour: Black

Odometer: 121648 km

Engine Capacity: 3456 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/45 R18

Rear Tyre Size:

235/45 R18

Front Left Side: Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,385.00	1,516.50	868.50	36.42
Miscellaneous Items	360.00	260.00	100.00	27.78
Labour	920.00	800.00	120.00	13.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,665.00</b>	<b>2,576.50</b>	<b>1,088.50</b>	<b>29.70</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>256.55</b>	<b>180.36</b>	<b>76.19</b>	<b>29.70</b>
<b>Nett Amount (S\$)</b>	<b>3,921.55</b>	<b>2,756.86</b>	<b>1,164.69</b>	<b>29.70</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		<b>300.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>3,064.31</b>		

### INSPECTION

Date of Assignment: 09/05/2018 Present Location:

Date Inspected: 12/06/2018 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2018)
<b>Parts:</b>	143	LEXUS GS350 3.5 LUXURY (L10) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCK882C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LOGO	Not Necessary	70.00 FL	*- FL
2	1		*REAR BOOT EMBLEM GS 350	Not Necessary	95.00 FL	*- FL
3	1		*REAR BOOT EMBLEM LEXUS	Not Necessary	95.00 FL	*- FL
4	1		*REAR BUMPER	Dented / Deformed	930.00 FL	*930.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Bent	270.00 FL	*270.00 FL
6	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	465.00 FL	*- FL
8	1		*REAR BUMPER INNER SPONGE	Not Necessary	165.00 FL	*- FL
9	1		*REAR BUMPER REFLECTOR LH	Not Necessary	75.00 FL	*- FL
10	1		*REAR BUMPER LOWER SPOILER	Deformed /Twisted	435.00 FL	*435.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,650.00</b>	<b>1,685.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	265.00	168.50

<b>Total Parts (S\$)</b>	<b>2,385.00</b>	<b>1,516.50</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	REAR REVERSE SENSOR (4PCS) (SHORTED)	350.00	250.00
2	1	OD/TP Case (Insurer) (NECESSARY)	10.00	10.00
Sub Total (S\$)			360.00	260.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRE CHECKING	New	20.00	20.00
2	LABOUR CHARGE	New	500.00	400.00
3	SPRAY PAINTING	New	400.00	380.00
Gross Labour Cost (S\$)			920.00	800.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;