

ASS. REC. BY:

REF:

G3 / III 18008583 / Uz41622

Special Instruction:

Surveyor

Matus.

ASSIGNMENT (Office)

McGowan

From (Person): Andrew Lim

of

III

Date/Time:

03/05/2018 4:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 3361X

Insured:

SHD 7161G

at Workshop n/s

Blumel Automotive

Tel:

6745 2088

of

Blk 1 Kaki Bukit Ave 6 #01-28

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Sally

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKZ 3361X - X

SHD 7161G - 004 / 170114510 / Mileage 352

9A: 250717

Dismantle part 11/05/2018

111 /
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK23361Xat Workshop m/s Bul

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK23361X Yr Regn: 11 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or LA1Make: Mazda 5 C.C. 1998Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 34411 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW107140123137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 30/4/18 D.O.I. 10/5/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

o/s Ref.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

474 56394 No further.11/5/18 Submit PRS Report

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 80Transportation: 80

\$ > RS. \$ _____

Photos

Others 10

TOTAL

170

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Catherine Chong (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 10 May, 2018 10:29 AM
To: assignments
Subject: FW: PRE-REPAIR SURVEY - SKZ 3361X
Attachments: 03052018101731.pdf

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Thursday, 3 May 2018 4:57 PM
To: Serene Tan <serene.tan@mneduco.com.sg>
Cc: Zuhaidah Samsuri <aida@iii.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: PRE-REPAIR SURVEY - SKZ 3361X

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKZ3361X
III INSURED VEHICLE NO. : SHD7161G
DATE OF LOSS : 30/04/2018

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Aida.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

From: Serene Tan [mailto:serene.tan@mneduco.com.sg]
Sent: Thursday, 3 May, 2018 3:28 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR SURVEY - SKZ 3361X

Our Ref : MN.IG.B1.1812352

WITHOUT PREJUDICE
SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS
PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Hi Sir/Mdm,

1. We refer to your email below.
2. We are instructed by LEE YUET LI, the claimant and/or BLUWEL AUTOMOTIVE SERVICE PTE LTD, the motor workshop for SKZ 3361X that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	NICKY SEAH (Absolute Appraisal Services)	6.	ANDREW HOW (Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7.	NG KONG BENG PATRICK (Carlink Consultancy)
3.	DIXON YEO (Treasure Appraisal Services)	8.	ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4.	LOI BOON JUAN (Par Automotive Consultancy)	9.	DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)
5.	AMAS ONG (AEON Auto Consultants LLP)	10.	ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know within two (2) working days whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO

Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Thursday, May 3, 2018 2:24 PM

To: Serene Tan <serene.tan@mneduco.com.sg>

Subject: RE: PRE-REPAIR SURVEY - SKZ 3361X

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

Sent: Thursday, 3 May, 2018 10:22 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: PRE-REPAIR SURVEY - SKZ 3361X

URGENT

WITHOUT PREJUDICE

Our Ref: MN.IG.B1.1812388.st

Dear Sirs,

Notice of Accident dated **3/5/2018** attached herein.

Kindly arrange for the pre-repair survey of our client's vehicle SKZ 3361X.

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim,

which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/04/2018 15:21
Date Of Accident 30/04/2018 12:55
Exact Location Of Accident PARAGON ENTRANCE TO DRIVE WAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ3361X
Insured/Policyholder
Name Of Registered Owner LEE YUET LI
NRIC No S7835299Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96905533
Alternative Phone No OFFICE-96905533
Vehicle Particulars
Manufacturer MAZDA
Model 5
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5077126763-02
Cover Note Number
Driver
Name of Driver MERVYN HENG CHIN-YEONG
NRIC No S7702375E
Date Of Birth 26/01/1977
Occupation INDOOR
Date Of Driving Pass 15/07/2003
Driving Experience 14 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97420374
Fax Number
Contact Number
Email Address NOEMAIL

Address 12C HOUGANG STREET 11
#06-66
Postcode 534072
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HUSBAND
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD7161G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver LAI LEOK SHEN
NRIC/Passport Number
Contact Number 96197050
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulator's, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time:

30/4/2018

Driver's Signature

(If driver is NOT the policyholder)

Date & Time: 30/4/2018


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting to turn into Paragon. I was stationary, taxi turn into my lane from 2 lane and bang my right front portion and rim.
My car has in-car camera.

Menzies

DECLARATION

(We declare the foregoing particulars are true in every respect)

Lee
Policyholder's Signature
Date & Time: 30/4/2018

Menzies
Driver's Signature
(if driver is not the policyholder)
Date & Time: 30/4/2018

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GARMG Singaporean V2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5299Z
Vehicle Details	
Vehicle No.:	SKZ3361X
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	PE10294819
Chassis No.:	JM6CW1071G0123137
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,833.00
Original Registration Date:	19 Jan 2016
First Registration Date:	19 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$18,833.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2026
PARF Rebate Amount:	\$14,124.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$42,270.00
Total Rebate Amount:	\$56,394.00

The information contained herein is correct as at 11 May 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	14 May 2018 Edit Reg		03 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LEE YUET LI , ID: S7835299Z								
Vehicle Reg. No.:	SKZ3361X	Date of Loss:	30/04/2018 12:00 - :59 [27 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHD7161G	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/05/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ3361X
[SHD7161G]
TP
LEE YUET LI
Apr 30 2018 12:00PM
[-]
Bluwel Automotive Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
						1 per page	<input checked="" type="checkbox"/>
Documentation							
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail Print
1	11/05/18 12:21	LKKPhotosIn6-1.pdf				1	Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail Print
1	14/05/18 08:46	Singapore Accident Statement				1	Load PDF

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18008583/UZ4BE2
Date: 15/05/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Claimant Vehicle No: SKZ3361X

Date of Loss: 30/04/2018

Policy No:

Insured Vehicle No: SHD7161G

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ3361X**
Make & Model: MAZDA 5, 2.0 (A)
Reg. Date: 19/01/2016 (Man. Year: 2015)
Colour: Blue
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: PE10294819
Chassis No: JM6CW1071G0123137
Odometer: 34411 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm
Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/05/2018
Date Inspected: 10/05/2018 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 15/5/2018

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2018)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ3361X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >