

AXA-45

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305157309

REGN NO : SHA8024D

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 24.09.2014

DATE/TIME IN : 06.05.2018 08:50

ACCIDENT DATE : 06.05.2018

1240

48hrs Ended

JOB / PARTS DESCRIPTION

Lxx-Kalvin

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	X Repair
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	X sub
0003 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	49.00	20.00	39.20	X sub
0004 04-01-0103-0851-G	REAR BUMPER REFLECTOR LH	1	32.00	20.00	25.60	X sub
0005 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	2.00-	50.00	X m
0006 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	0.20	135.70	X sub

SUB-TOTAL : 913.38

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 L	R/I REVERSE SENSOR

~~280.00~~ 100
~~250.00~~ 200
~~120.00~~ 50 m

SUB-TOTAL : 650.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.05.2018

Time: 12:29:43

Page: 2/2

AXA

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305157309
REGN NO : SHA8024D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.09.2014
DATE/TIME IN : 06.05.2018 08:50
ACCIDENT DATE : 06.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,563.38

Lmf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kahar (LKK)
9/5/18 1420h
2 Rep.
4/5
After Repair p Lh

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: