




PAR Automotive Consultancy

Regn. No: 32986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0154-18-N51

28 March 2018

ACCIDENT VEHICLE SURVEY REPORT

Karthigaisamy Srithar Selvan
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SKM4055S	Odometer:	197627km
Make & Model:	Honda Civic 1.8L 5AT	Colour:	Silver
Chassis number:	JHMFD16309S200567	Date of accident:	03/09/2017
Year of Regn.:	17/11/2008	Date inspected:	06/09/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	11/09/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

