

REC. BY:

REF:

CS/MS1718008650/Tlgber

Special Instruction:

Surveyor:

Taufik.

ASSIGNMENT (Office)

From (Person):

Angie Tiong

of

MS26

Date/Time:

11052018 1057am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No:

XD 6502Z

Insured:

Public Liability

at Workshop m/s

Lee Kuan, Hwa.

Tel:

6269 9192.

of

24 Sungai Kudat St 4

Policy No:

Claim No:

552556 PLY 558318 PLY

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13032018 22/4/18

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

11052018 1.09pm

Person Contacted:

Shue Ting

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XD 6502Z - NGA / LIP 14011760 / SU

DCA: 220614

Public Liability - x

15/5/18 @ 4:41pm verified to Angie Tiong by email.

18/5/18 @ 3:33pm confirmed with Adeline LS \$12000, 5 days.  
(red \$19774.96, 62%)

Signature

Tanpin

REF:

MS (G)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: XD 650 2 Z Yr Regn: 2012, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Tipper truck.

Make: MAN

C.C. 10518

Colour: Orange

A/C Insured / Std / NI / NA

Sp. Reading: 475213

T/Radio: Insured / Std / NI / NA

Eng/No:

WMA 2 63227 CM 598009

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_

295/80R22.5  
u - (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 8/8 mm

L/Bal. 8 mm

L/Bal. 8/8 mm

D.O.A.

D.O.I. 4/5/18

Survey held at Lee Kuan Yew

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 SEP 2018

18/9/2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1) 19/9/2018

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

250

2)

Add Fee: ☐ : Site Insp (\$)

Transportation

\$ + PS \$

Report Format :

nicr-TP

Lump Sum / I.B.F. (\$) 2000

☐ : Interview (\$)

Photos

☐ : Tech Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

250

## Catherine Chong (LKK Auto)

---

**From:** Angie Tiong <angie\_tiong@sg.msig-asia.com>  
**Sent:** Friday, 11 May, 2018 10:57 AM  
**To:** assignments@lkkauto.com  
**Subject:** New assignment - Survey of third party vehicle XD6502Z - Public liability claim  
Date of accident: 13/3/18  
**Attachments:** Scan Data from FX-D59479 (1.55 MB)

Our ref: 552556 PLY

Dear Veron

We refer to our telephone conversation this morning.

Please arrange survey of TP vehicle XD6502Z on Without Prejudice basis. We attach the repair quotation, incident report and copy of photographs showing the damage for your attention.

Please advise surveyor to check on the consistency of damage.

Thanks & Regards

Angie Tiong  
Executive, Claims Services  
D: +65 6594 2526 | F: +65 66431 349 | [angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Shiau Chan (LKKAUTO)

---

**From:** kuanhwa@singnet.com.sg  
**Sent:** Tuesday, 18 September 2018 3:35 PM  
**To:** Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)  
**Subject:** Re: Urgent. Re: XD 6502 Z (Finalise)

Dear Shiau Chan,

Confirm \$12,000.00. 5 days.

Kindly submit the report to MSIG.

Thank you.

Adeline Lee  
Lee Kuan Hwa Motor Service  
Tel: 6269 9192 Fax: 6269 2239  
H/P: 9028 8798

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, September 18, 2018 3:22 PM  
**To:** kuanhwa@singnet.com.sg ; Taufikh (LKKAUTO)  
**Subject:** RE: Urgent. Re: XD 6502 Z (Finalise)

Dear Adeline,

WITHOUT PREJUDICE

Offer Lump Sum \$12,000.00 and 5 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** kuanhwa@singnet.com.sg <kuanhwa@singnet.com.sg>  
**Sent:** Tuesday, 18 September 2018 11:52 AM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Subject:** Fw: Urgent. Re: XD 6502 Z (Finalise)

Please revert asap. Thanks.

Regards,  
Adeline Lee  
Lee Kuan Hwa Motor Service  
Tel: 6269 9192 Fax: 6269 2239  
H/P: 9028 8798

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 15 May 2018 4:41 PM  
**To:** 'Angie Tiong'; assignments  
**Cc:** SUR  
**Subject:** RE: New assignment - Survey of third party vehicle XD6502Z - Public liability claim  
Date of accident: 22/4/18  
**Attachments:** CSMMSG18008650T1qb.pdf

Dear Angie,

Enclosed herewith preliminary advice of XD 6502Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 15 May 2018 4:31 PM  
**To:** 'Angie Tiong' <[angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: New assignment - Survey of third party vehicle XD6502Z - Public liability claim Date of accident: 22/4/18

Dear Angie,

Noted with thanks.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Angie Tiong [[mailto:angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)]  
**Sent:** Tuesday, 15 May, 2018 4:06 PM  
**To:** Catherine Chong (LKK Auto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** [sur@lkkauto.com](mailto:sur@lkkauto.com)  
**Subject:** RE: New assignment - Survey of third party vehicle XD6502Z - Public liability claim Date of accident: 22/4/18

Our ref: 558318 PLY

Dear Catherine

Please note our claim reference No for this case should be 558318 PLY and date of accident should be 22/4/18.

Thanks & Regards

Angie Tiong  
Executive, Claims Services



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 558318PLY

Date: 15<sup>th</sup> May 2018

Our Ref: CS/MSG18008650/T1qb

The Motor Claims Department  
MSIG Insurance

Attn: Angie

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. XD 6502Z.**

We thank you for the instruction on 11/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/05/2018 at the premises of M/s LEE KUAN HWA and have the following to report:-

Workshop Estimate Amount	: S\$ <u>31,774.96</u> .
Revised Estimate Amount	: S\$ <u>16,850.27</u> .
"Check" Items Amount	: S\$ <u>2,242.79</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:  
The vehicle sustained damages at the front o/s.



Comments/ Present Status:  
Damages consistent.  
We have not authorized repair.

Yours faithfully

Taufikh  
Automotive Assessor

10 Sin Ming Drive Singapore 575701  
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

14 Nov 2012

Our ref 1411120101N004532489

HUATONG CONTRACTOR PTE LTD  
9 BENOI CRESCENT  
SINGAPORE 629972

000047/1



RECEIVED  
21 NOV 2012

BY: \_\_\_\_\_  
via email) ML, MW, Tpt. WGP  
21/11/2012

Dear Sir/Madam

**NOTIFICATION ON REGISTRATION OF VEHICLE AND ROAD TAX  
(PLEASE DISPLAY THE ENCLOSED ROAD TAX DISC ON YOUR VEHICLE  
WINDSCREEN)**

We wish to inform you that you have successfully registered vehicle XD6502Z on 14 Nov 2012. Enclosed is a validated road tax disc for the vehicle. Please display the said disc on your vehicle windscreen.

2. The details of the registration are as follows:

**A) Owner Particulars**

1. Name	: HUATONG CONTRACTOR PTE LTD
2. Identification No. Type	: Company
3. Identification No.	: 198304322E
4. Place Of Passport Issue	: -
5. Registered Address	: 9 BENOI CRESCENT SINGAPORE 629972
6. Mailing Address	: -

**B) Vehicle Particulars**

1. Vehicle No.	: XD6502Z
2. Previous Vehicle No.	: -
3. Effective Date of Ownership	: 14 Nov 2012
4. Original Registration Date	: 14 Nov 2012
5. First Registration Date	: 14 Nov 2012
6. Vehicle Type	: B33 - Goods (Open) Tipper/Dumper Truck
7. Vehicle Scheme	: Normal
8. Attachment 1	: No Attachment
9. Attachment 2	: -
10. Attachment 3	: -
11. Vehicle Make	: MAN
12. Vehicle Model	: TGS 26.360 6X4 BB
13. Year of Manufacture	: 2012
14. Primary Colour	: Orange
15. Secondary Colour	: Beige
16. Passenger Capacity	: 1

17.	Chassis/Trailer Chassis No.	: WMA26SZZ7CM598009 / -
18.	Propellant	: Diesel
19.	Engine No./Motor No.	: 50531722363173 / -
20.	Engine Capacity(cc)/Power Rating(kw)	: 10518 / -
21.	Unladen Weight(kg)	: 13780
22.	Maximum Laden Weight(kg)	: 28000
23.	Open Market Value	: \$118,341.00
24.	PARF Eligibility	: No
25.	PARF Eligibility Expiry Date	: -
26.	Minimum PARF Benefit	: \$0.00
27.	No. of Transfers	: 0
28.	IU Label No.	: -
29.	COE No.	: 2012110105000187N
30.	COE Expiry Date	: 13 Nov 2022
31.	COE Category	: C - Goods Vehicle & Bus
32.	Quota Premium/Prevailing Quota Premium	: \$57,889.00
33.	Actual Quota Premium/PQP Paid	: \$57,889.00
34.	Actual ARF Paid	: \$5,918.00
35.	Vehicle Lifespan Expiry Date	: 13 Nov 2032
36.	Road Tax Amount	: \$765.00
37.	Road Tax Start Date	: 14 Nov 2012
38.	Road Tax End Date	: 13 May 2013
39.	Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category C.

3. You may use your NRIC number and SingPass or User ID and Password (for non-Singaporeans/PRs) to login to <http://www.onemotoring.com.sg> and see the details of the above transaction. For ACRA-registered businesses and companies with EASY accounts, your authorised staff may also access the wide range of vehicle-related services via <http://www.onemotoring.com.sg> using EASY. If you do not have an EASY account, you can apply for it at <http://www.iras.gov.sg>. For non-Singaporeans/PRs who do not have a User Password, please contact us at 1800-CALL LTA (1800-2255 582) to request for a new password. Please note that a separate Transaction PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Before you perform these transactions, please request for your Transaction PIN. You may find out more information on how to obtain your Transaction PIN and the documents needed (such as Board Resolution for companies and businesses, etc) via <http://www.onemotoring.com.sg> > **LTA Information & Guidelines > Transaction PIN & User Account.**

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

4. All new In-vehicle Units (IUs) are covered by a 5-year warranty against manufacturer's defect.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/04/2018 12:15
Date Of Accident	22/04/2018 12:00
Exact Location Of Accident	FORT RD ISLAND PLANT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD6502Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HUATONG CONTRACTOR PTE LTD
Co Reg No	198304322E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-83057454

### Vehicle Particulars

Manufacturer	MAN
Model	PRIME MOVER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	PALANIAPPAN BALAMURUGAN
NRIC No	G7907620T
Date Of Birth	05/12/1985
Occupation	OUTDOOR
Date Of Driving Pass	12/06/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLANS

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC7271H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

A = XD6502Z

B = WC7217H

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22.04.18 around 12pm I was  
(Maha Island plant)  
driving my company truck XD6502Z at Fort Road Island plant.  
At that time, I want to unloading but there is a wheel loader  
WC 7217H inside there, so I stop and wait. Unfortunately,  
when the wheel loader reverse he didn't saw me and hit my truck.  
Our truck front right bumper, front right foot step damage.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Workshop: 24, Sungei Kadut Street 4 Singapore 729050

Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712

Business Reg No: 36463500B

M/s: **MSIG Insurance (Singapore) Pte Ltd**

No. 16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Motor Claim Dept

Vehicle number : **XD 6502 Z**

Make/Model : **MAN TGS 26.360**

Date of accident : **22.04.2018**

Claim Type : **TP Claim**

Business Reg No: 36463500B  
 To resurvey before/after spray painting  
 To display damaged part(s) during resurvey  
 Parts prices are subject to confirmation  
 Third party survey is on a "Without Prejudice" basis  
 No illegal modification(s) is allowed  
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 09.05.2018

Taufik 97495749

Resurvey after repair.

5 days

sure (Mantab. com)  
 11/5/18 @ 1530.

**Accident involving XD 6502 Z & Wheel Loaded WC 7271 H (policy no: B29071170PLY) at Ford Road Island Plant on 22.04.2018.**

1.	1 pc	Front bumper RH	17.00 \$	1,939.32 <i>bt</i>
2.	1 pc	Front headlamp RH	\$	1,042.58 <i>coa</i>
3.	1 pc	Front small lamp RH	\$ <i>coa</i>	337.08 <i>? photo</i>
4.	1 pc	Front signal lamp RH	\$ <i>coa</i>	217.11 <i>?</i>
5.	1 pc	Front step mudguard RH	1500 \$	1,827.88 <i>coa</i>
6.	2 pcs	Front step plate RH	\$	564.12 <i>Rp</i>
7.	1 pc	Front step mudguard lamp RH	\$	160.66 <i>x m</i>
8.	1 pc	Front mudguard inner seal RH	\$	320.93 <i>fm</i>
9.	1 pc	Front panel <i>shield</i>	4200 \$	5,600.84 <i>coa</i>
10.	1 pc	Front step extension RH	\$	1,410.28 <i>dis</i>
11.	1 pc	Front bumper side RH	\$	65.48 <i>dis photo</i>
12.	1 pc	Front bumper center	1800 \$	2,192.20 <i>bt</i>
13.	1 set	Front corner panel RH	\$	620.76 <i>coa</i>
14.	1 pc	Front bumper bracket	\$	738.76 <i>? photo</i>
15.	1 pc	Front shock absorber RH	\$	949.84 <i>? photo</i>
16.	1 pc	Front steering pump	\$	11,085.92 <i>x m</i>
17.	1 pc	Front mudflat	\$	101.20 <i>x m</i>

13214.22 \$ 29,174.96

To Wiring Service

\$ 100.00

To Replace & Repair Labour Charge

\$ 1,500.00

To Putty & Spray Painting

\$ 1,000.00

Total

\$ 31,774.96

30.

900 / 100

700

1830

15044.22.

430 12,000, 5 days.

李光華 摩哆 燒焊

Yours Faithfully,

LEE KUAN HWA MOTOR SERVICE  
 39, Westwood Avenue, Singapore 648719  
 TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18008650/T1qbe2	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 20-09-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PUBLIC LIABILITY		Veh. Inspected	XD 6502Z
Policy No.			Coverage (\$)	0.00
Claim No.	558318 PLY		Excess (\$)	0.00
Assign From	ANGIE TIONG		Assign Date	11/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAN TGS		c.c	10518
Engine No.	HIDDEN		Year of Reg.	2012
Chassis No.	WMA26SZZ7CM598009		Colour	ORANGE
Odometer	475213		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	YOKOHAMA	8 mm	
L/H Front Tyre	295/80 R22.5	YOKOHAMA	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/04/2018		Inspection Date	11/05/2018
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 6502Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER RH	BENT	1,939.32	1,700.00
1	FRONT HEADLAMP RH	CRACKED	1,042.58	1,042.58
1	FRONT SMALL LAMP RH	CRACKED	337.08	337.08
1	FRONT SIGNAL LAMP RH	CRACKED	217.11	217.11
1	FRONT STEP MUDGUARD RH	CRACKED	1,827.88	1,500.00
2	FRONT STEP PLATE RH	TO REPAIR SEE LABOUR	564.12	-
1	FRONT STEP MUDGUARD LAMP RH	NOT NECESSARY	160.66	-
1	FRONT MUDGUARD INNER SHIELD RH	TORN	320.93	320.93
1	FRONT PANEL	CRACKED	5,600.84	4,200.00
1	FRONT STEP EXTENSION RH	DISTORTED	1,410.28	1,410.28
1	FRONT BUMPER SIDE RH	DISTORTED	65.48	65.48
1	FRONT BUMPER CENTER	BENT	2,192.20	1,800.00
1	SET FRONT CORNER PANEL RH	CRACKED	620.76	620.76
1	FRONT BUMPER BRACKET	NOT NECESSARY	738.76	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	949.84	-
1	FRONT STEERING PUMP	NOT NECESSARY	11,085.92	-
1	FRONT MUDFLAT	NOT NECESSARY	101.20	-
			29,174.96	13,214.22
	<b><u>LABOUR</u></b>			
	TO WIRING SERVICE.		100.00	30.00
	TO REPLACE & REPAIR LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRONT STEP PLATE RH.		1,500.00	1,100.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	700.00
			2,600.00	1,830.00
	<b>GRAND TOTAL</b>		<b>31,774.96</b>	<b>15,044.22</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>12,000.00</b>

Report Ref No. CS/MSG18008650/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.