



Your Ref : S8M00FCY

Date: 05<sup>th</sup> Dec 2018

Our Ref : CS/ASM18008659/Krbe2

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGT 8014J  
ACCIDENT ON 24/04/2018**

Instruction was received to inspect the vehicle Reg. No. SGT 8014J. The inspection was conducted on 11/05/2018 at the premises of M/s Ah Lim Motor Co, No 10 Ang Mo Kio Ind Pk 2A, #01-09 AMK Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SGT 8014J
Make/Model	: Peugeot 207 1.4 2 Tronic Sport
Year of Registration	: 2009
Body Colour	: Red
Chassis Number	: VF3WCKFUC9W073603
Engine Capacity	: 1360 cc

The Vehicle Sustained Damages At The N/S Body And Front Portion. The Undercarriage And Body Structure Affected Due To Collision. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	19,000.00
Less: LTA Reimbursement Value (RV)	(S\$	11,331.00)
Nett Liability	S\$	7,669.00
	=====	

Vehicle Inspected By:



KONG SENG CHEONG  
*Licensed Appraiser*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.