



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with Invoice Name & Address and Owner Name & Vehicle Info columns. Includes details for MR TCMONG MEDICARE PTE.LTD. and vehicle specifications like SLN2582H, KNACC81CVH5062280.

Table with Account No, Terms, Date/Time Printed, CSE, Operator, and WIP No columns. Example: CSM00081, Cash, 30/04/2018/ 09:14, QUD, 247 / DonBong, 27662.

Main table with Description of Goods / Services, Qty, Unit Price, Disc%, and Amount columns. Lists various repair items like 'RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE' and 'PAINT WORK SPRAY FRONT BUMPER FACE' with handwritten notes and amounts.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MR TCMONG MEDICARE PTE.LTD. and vehicle specifications like SLN2582H, 27/04/201, and engine/chassis numbers.

Summary table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include CSM00081, Cash, 30/04/2018/ 09:14, QUD, 247 / DonBong, 27662.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like BRACKET-FR BUMPER SIDE, RH and their respective prices.

Estimate

SURVEYOR NAME: Tanjun 9749544
SURVEYOR SIGNATURE: [Signature]
DATE: 22/5/18
REMARKS: Resurvey before paint
sur@lkkauto.com.
6 days.

LKK Auto Consultants hence notify the Repairer of the following:
Confirm & accepted by survey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Authorized signatory and company stamp

Summary table with columns: Description, Amount. Shows 7% GST on 13141.00 resulting in a Total Payable of 14,060.87.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.