

ASS. REC. BY:

REF: CS/ICS18008679 / Ktb02

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): Janice Goh

of ICS

Date/Time: 11/05/2018 3:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHB 7740X

Insured:

SLX 2724M

at Workshop m/s

Trans Cab

Tel:

of

No. 2 Amk St 63

Policy No:

Claim No:

DMPC1800185H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

06/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

14/05/2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SHB 7740X - X
	SLX 2724M - X

RECEIVED 21 MAY 2018

REF: TCS

ASSIGNMENT

From:

Date: 14/5/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHB 7740X

at Workshop m/s

Trans - Cab

of

No. 2 AMK St 63

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7740X

Vr Regn:

08 / 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

G.C.

1991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading:

433194

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL11A69RTBB 103415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal:

5

mm

R/Bal:

9

mm

L/Bal:

5

mm

L/Bal:

9

mm

D.O.A.

6/5/18

D.O.I.

14/5/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/5 File pass to Carter

" 1/1 En 8/1800 (Red: 16370.66 : 90%)

RECEIVED 21 MAY 2018

Date/Time, File Pass to?



Preli. Report

21/5 Typist



Final Report

Date/Time, File Return to?

Days Of Repair: 2 1/2

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) \$ + ps \$

) Photo:

) Other:

)

TOTAL:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TP
1360450
10

460

Catherine Chong (LKK Auto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Friday, 11 May, 2018 3:13 PM
To: Loong Ghien Yee; assignments@lkkauto.com
Cc: 'Candy Kong'; ECICS Claims
Subject: RE: ARRANGE FOR SURVEY SHB7740X

Without Prejudice

Dear Yee Loong

Thank you for your email.
We will appoint LKK for the TP PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.****

-----Original Message-----

From: Loong Ghien Yee [<mailto:ghienyee.loong@transcab.com.sg>]
Sent: Friday, 11 May, 2018 2:06 PM
To: ECICS Claims
Cc: 'Candy Kong'
Subject: ARRANGE FOR SURVEY SHB7740X

Dear all ,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SLX2724M - 06.05.2018 at 1350Hrs - SHB7740X

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs
Ghien Yee Loong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Friday, 18 May 2018 5:36 PM
To: Denise Tay (LKKAuto); Admin-D (LKKAuto)
Cc: ECICS Claims; assignments; SUR
Subject: RE: ARRANGE FOR SURVEY SHB7740X

Hi Denise

Our ref DMPC1800185H.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.**

-----Original Message-----

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]
Sent: Thursday, 17 May, 2018 4:03 PM
To: Admin-D (LKKAuto); Janice Goh Siew Geok (ECICS, Claims)
Cc: ECICS Claims; assignments; SUR
Subject: RE: ARRANGE FOR SURVEY SHB7740X

Dear Janice,

Can provide claim number in merimen

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Friday, 11 May 2018 3:27 PM
To: 'Janice Goh Siew Geok (ECICS, Claims)' <Janice_Goh@ecics.com.sg>
Cc: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: ARRANGE FOR SURVEY SHB7740X

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2018 13:09
Date Of Accident	06/05/2018 13:50
Exact Location Of Accident	TPE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7740X
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	KANG LENG CHUAN
NRIC No	S7603686A
Date Of Birth	10/02/1976
Occupation	OUTDOOR
Date Of Driving Pass	13/05/1998
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84627316
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 267 YISHUN STREET 22
	#01-198
Postcode	760267
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to Police Report T/20180507/2047

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX2724M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	S8440663E
Contact Number	92337246
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KANG LENG CHUAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB7740X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
ALPAC/ENM No.: _____

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180507/2047

1 of 3

Report No. T/20180507/2047

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/05/2018 13:11	Vide Report No.:	Station Diary No.: 53
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: KANG LENG CHUAN		Address: APT BLK 267 YISHUN STREET 22 #01-198 SINGAPORE 760267	
ID Type / ID No.: NRIC NO / S7603686A		Contact No.: Home/Office: Mobile: 84627316	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 42	Date of Birth: 10/02/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/05/2018 13:50	Type of Location: Filter Lane To Expressway
Location: Along Road 1 Traveling Toward Road 2 TAMPINES EXPRESSWAY UPPER CHANGI ROAD TPE towards Changi Airport. Filter lane from Loyang to TPE (Exit of Upper Changi)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB7740X	TAXI	CHEVROLET		Red	Slightly Damaged	4
SLX2724M	Car	OPEL		White		1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180507/2047

2 of 3

Report No. T/20180507/2047

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Driver			
Name	KANG LENG CHUAN	ID No.	S7603686A
Related Vehicle	SHB7740X (TAXI)	Contact No.	84627316
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	07/05/2018	Date Discharge	07/05/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	HO KOK KOON	ID No.	S8440663E
Related Vehicle	SLX2724M (Car)	Contact No.	92337246
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 06/05/2018, at about 1.50 p.m., I was driving my taxi along TPE towards Changi Airport. I have 4 passengers in my taxi. I was driving my taxi on the extreme left lane (2 lanes). The first lane is having construction. A car (SLX2724M) coming from the filter lane (Loyang to TPE, before Upper Changi Road) had hit onto the side of my taxi when merging to TPE.

Once the accident happened, we stopped along the road shoulder and exchanged our particulars. At that point of time, no injuries were reported by both parties. As my passengers required to proceed to the airport, we left after that.

On 07/05/2018, I woke up and felt that my neck and shoulder area were in pain. As such, I went to the hospital for a check and given 3 days of MC.

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999



T/20180507/2047

3 of 3

Report No. T/20180507/2047

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sr Staff Sgt MOHAMMED SYAZWAN BIN
ABDULLAH

Signature Of Interpreter: Force
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
07/05/2018 13:11

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB7740X
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 May 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1456220K
Chassis No.:	KL1LA69RJB103415
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,201.00
Original Registration Date:	10 Aug 2012
First Registration Date:	10 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$14,201.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2020
PARF Rebate Amount:	\$9,940.00

Intended COE Rebate Details

COE Expiry Date:	09 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$48,892.00
COE Rebate Amount:	\$13,707.00
Total Rebate Amount:	\$23,707.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 May 2018

OK

Trans-cab Auto Services Pte Ltd

AAD1805-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7740X

*Not Authorised
61 Sep 8/8001*

Vehicle No.:

SHB 7740X

Chassis No.:

KL1LA69RJB103415

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

6.5.2018

Third Party Insurer :

ECICS

PART**LIST**

1	1	Front Door LH	\$	<i>R</i>	1,133.00	<i>X</i>
1	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>Not used</i>	1,133.00	<i>—</i>
2	1	Rear door weatherstrip - Inner	\$	<i>Sm</i>	41.40	<i>X</i>
3	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sm</i>	25.90	
4	1	Rear door top hinge	\$	<i>R</i>	35.00	
5	1	Rear door bottom hinge	\$	<i>R</i>	35.00	
6	1	Rear door inner lock	\$	<i>R</i>	425.00	
7	1	Rear door check / arrestor	\$	<i>Sm</i>	65.00	
8	1	Rear door lock striker / latch	\$	<i>R</i>	120.00	
9	1	Rear door outer weatherstrip moulding	\$	<i>Sm</i>	85.00	
10	1	Side Rocker Panel Garnish LH	\$	<i>Sm</i>	236.40	
11	1	Rear Fender LH	\$	<i>R</i>	1,145.00	
12	1	Rear Fender Inner Trim LH	\$	<i>Sm</i>	418.44	<i>X</i>
13	1	Front Side Rocker Panel Garnish LH	\$	<i>Sm</i>	236.40	
14	1	Front Side Rocker Panel Outer LH	\$	<i>R</i>	600.00	
15	1	Front Side Rocker Panel Inner LH	\$	<i>R</i>	519.30	
16	1	Rear Bumper	\$	<i>Sm</i>	1,202.00	

TOTAL	\$	7,455.84
10%	\$	745.58
	\$	6,710.26

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>na</i>	24.00	<i>X</i>
1 Set	Front licence plate with holder	\$	<i>Sm</i>	192.00	<i>X</i>
1 Set	Radiator Grille clip	\$	<i>na</i>	35.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7740X

1 Set	Front Fender Liner clip	\$	na	30.00	X
1	Front Fender RR Bracket LH	\$	na	7.10	X
1	Rear Wheel Rim Hub Cap LH	\$	na	166.30	X
1	Rear Tyre LH	\$	na	180.00	X
1	Rear Tyre Rim RLH	\$	na	126.00	X
1Set	Rear Fender Inner Trim Clip LH	\$	na	30.00	X
1	Front door sticker 'Trans-cab'	\$	na	80.00	6000
1	Rear door sticker "6555-3333"	\$	na	80.00	6000

TOTAL \$ **950.40****TOTAL PARTS** \$ **7,660.66****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	200
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	4000
Putty and spray painting of the affected portion.	\$	4,000.00	6000
Towing Fees.	\$	na	120.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To rust-proofing of the affected areas.	\$	170.00	300

Trans-cab Auto Services Pte Ltd

AAD1805-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7740X

To check steering geometry and computer wheel alignment

\$ *na* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *na* 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 *601*

To transfer of fender fittings, attachment and perform water seepage test.

\$ *na* 170.00 X**TOTAL \$ 10,460.00****Over All Total \$ 18,120.66****Repair Days (Lump Sum)***15 days**2 1/2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18008679/KTBN2

Date: 24/05/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHB7740X	Insured Vehicle No :	SLX2724M
Date of Loss:	06/05/2018	Nature of Claim:	TP
		Claim No:	DMPC1800185H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7740X	Engine No:	Z20S1456220K
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJBB103415
Reg. Date:	10/08/2012 (Man. Year: 2011)	Odometer:	433194 km
Colour:	White/Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,660.66	1,139.70	6,520.96	85.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	1,110.00	9,350.00	89.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,120.66	2,249.70	15,870.96	87.58
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	18,120.66	1,800.00	16,320.66	90.07
+ GST 7.00/7.00% (S\$)	1,268.45	126.00	1,142.45	90.07
Nett Amount (S\$)	19,389.11	1,926.00	17,463.11	90.07

INSPECTION

Date of Assignment: 11/05/2018

Date Inspected: 14/05/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2018)
Parts: 143	CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB7740X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Repair	1,133.00 FL	*- FL
2	1	*REAR DOOR LH (PANEL A-RR DR LH)	Dented/Warped	1,133.00 FL	*1,133.00 FL
3	1	*REAR DOOR WEATHERSTRIP-INNER	Serviceable	41.40 FL	*- FL
4	1	*REAR DOOR WEATHERSTRIP-2ND FRAME	Serviceable	25.90 FL	*- FL
5	1	*REAR DOOR TOP HINGE	Repair	35.00 FL	*- FL
6	1	*REAR DOOR BOTTOM HINGE	Repair	35.00 FL	*- FL
7	1	*REAR DOOR INNER LOCK	Repair	425.00 FL	*- FL
8	1	*REAR DOOR CHECK/ARRESTOR	Serviceable	65.00 FL	*- FL
9	1	*REAR DOOR LOCK STRIKER/LATCH	Repair	120.00 FL	*- FL
10	1	*REAR DOOR OUTER WEATHERSTRIP MOULDING	Serviceable	85.00 FL	*- FL
11	1	*SIDE ROCKER PANEL GARNISH LH	Serviceable	236.40 FL	*- FL
12	1	*REAR FENDER LH	Repair	1,145.00 FL	*- FL
13	1	*REAR FENDER INNER TRIM LH	Serviceable	418.44 FL	*- FL
14	1	*FRONT SIDE ROCKER PANEL GARNISH LH	Serviceable	236.40 FL	*- FL
15	1	*FRONT SIDE ROCKER PANEL OUTER LH	Repair	600.00 FL	*- FL
16	1	*FRONT SIDE ROCKER PANEL INNER LH	Repair	519.30 FL	*- FL
17	1	*REAR BUMPER	Serviceable	1,202.00 FL	*- FL
18	1	*SET FRONT BUMPER FASTENER CLIP	Not Necessary	24.00 FS	*- FS
19	1	*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	192.00 FS	*- FS
20	1	*SET RADIATOR GRILLE CLIP	Not Necessary	35.00 FS	*- FS
21	1	*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*- FS
22	1	*FRONT FENDER RR BRACKET LH	Repair	7.10 FS	*- FS
23	1	*REAR WHEEL RIM HUB CAP LH	Serviceable	166.30 FS	*- FS
24	1	*REAR TYRE LH	Serviceable	180.00 FS	*- FS
25	1	*REAR TYRE RIM RLH	Serviceable	126.00 FS	*- FS
26	1	*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*- FS
27	1	*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
28	1	*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,406.24	1,253.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	745.58	113.30
Total Parts (\$\$)	7,660.66	1,139.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,000.00	600.00
4	TOWING FEES	New	120.00	-
5	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
11	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
12	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (S\$)			10,460.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >