

22/03/2007

ASS. REC. BY:

REF: CS3/MSG 18008715/D24/bcz Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSLG Date/Time: 14/5 @ 10:14am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WC 9413C Insured:

at Workshop m/s Fook Hong Motor Tel: 62443203

of No. 29 Sungai Kadut St 4

Policy No: A28729875MKE Claim No: 557627

Sum Insured: Excess:

Make of Veh: D.O.A.  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' PRI H.O.D. Endorsement:

Date/Time: 14/5 @ 11:08am Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
30/5/18	Assessment
3/7/18	After Repair

\$10,000L

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: WC 4413C Yr Regn: Oct / 2011  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
 Make: ISUZU C.C. 15681  
 Colour: Blue / White A/C: Insured / Std / NI / NA  
 Sp. Reading: 188096 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JALCY452 S13 7000172  
 Gen. Cond: Good / Poor / Poor / Burnt  
 Steering: In Order / Jammed / Leaked / Burnt or  
 Brake: In Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 295/80 R22.5  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WINDFORCE

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>14/5/18</u>

Survey held at Peak 4 Eng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/5/18	No Estimate / GIA

Estimate repair range \$9,000 - \$10,000.

RECEIVED 19 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format: PRO

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

120

50

10

180

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018		14 May 2018 10:14 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD, Co. Reg. No.: 200302202M			
Main Claimant:	TAT HING TRANSPORT PTE LTD, Co. Reg. No.: 201414922Z			
Vehicle Reg. No.:	WC4413C	Date of Loss:	27/04/2018 14:00 - :59 [78 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 557627	Policy/Cover Note No.:	A28729875MKC (Comprehensive) Coverage: 18/05/2017 - 17/05/2018	
Vehicle Reg. No. (Insured):	XD3656H	Policy No. (Claimant):		
		Excess:		
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/05/2018]			
Driver/Custodian (Insured):	YAP CHONG LIN (), NRIC: F7464425L, Tel: +6583011412			
Adj Asg. Remarks:	Liability 100% TP reject SJE - assign LKK Auto Consultants			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

NO 29, Sungei kadut St 4 #08.

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	WC4413C		
Vehicle Type :	B69 - Goods (Open) Concrete Mixer/Cement Mixer		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	ISUZU		
Vehicle Model :	CYH52S		
Chassis No. :	JALCYH52SB7000172		
Propellant :	Diesel		
Engine No. :	6WG1415411		
Engine Capacity :	15681 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	34000 kg		
Unladen Weight :	13420 kg		
Year Of Manufacture :	2011		
Original Registration Date :	25 Oct 2011		
Lifespan Expiry Date :	-		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$32,801.00		
COE Expiry Date :	24 Oct 2021		
Road Tax Expiry Date :	24 Oct 2018		
Inspection Due Date :	24 Oct 2018		
Intended Transfer Date :	19 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable</b>			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>
<b>Message</b>			
This vehicle has a road tax Over Payment of \$412.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4922Z
<b>Vehicle Details</b>	
Vehicle No.:	WC4413C
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	6WG1415411
Chassis No.:	JALCYH52SB7000172
Maximum Power Output:	-
Open Market Value:	\$141,108.00
Original Registration Date:	25 Oct 2011
First Registration Date:	25 Oct 2011
Transfer Count:	1
Actual ARF Paid:	\$7,056.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Oct 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,801.00
COE Rebate Amount:	\$10,704.00
<b>Total Rebate Amount:</b>	<b>\$10,704.00</b>

The information contained herein is correct as at 19 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/04/2018 11:45
Date Of Accident	27/04/2018 14:25
Exact Location Of Accident	UPPER SERANGOON JIA YAI CONSTRUCTION SITE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC4413C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAT HING TRANSPORT PTE LTD
Co Reg No	201414922Z
Email Address	SHARONPHANGSP@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	Office-91055574

### Vehicle Particulars

Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1437471703
Cover Note Number	

### Driver

Name of Driver	MANI SENTHILMURUGAN
Passport No/FIN	G6383463M
Date Of Birth	15/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	06/03/2012
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90569920

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	66 EDGEDALE PLAIN #13-31
Postcode	828732
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SUB-CONTRACTOR EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS UNLOADING CEMENT AT THE CONSTRUCTION SITE. VEHICLE B, XD3656H COMING DOWN A SLOPE TRIED TO TURN TO THE RIGHT SIDE OF MY VEHICLE, ACCIDENTALLY HIT ONTO THE FRONT RIGHT PORTION OF MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD3656H
Vehicle Make/Model/Colour	MITSUBISHI FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YAP CHONG LIN
NRIC/Passport Number	F7464425L
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 28/4/18 1100hrs





Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/4/18 1200hrs



Reporting Centre Personnel's Signature

Name: Cassandra

NRIC/FIN No.: G3229391W



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was unloading cement ~~from my vehicle~~ at the construction site. Vehicle B, XD3656H coming down a slope tried to turn to the right side of my vehicle, accidentally hit onto the front right portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:   
Date & Time: 

Driver's Signature:   
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature:   
Name: Cassandra  
NRIC/FIN No.: 632293914/ 

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018		14 May 2018 10:14 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD, Co. Reg. No.: 200302202M								
Main Claimant:	TAT HING TRANSPORT PTE LTD, Co. Reg. No.: 201414922Z								
Vehicle Reg. No.:	WC4413C	Date of Loss:	27/04/2018 14:00 - :59 [78 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 557627	Policy/Cover Note No.:	A28729875MKC (Comprehensive) Coverage: 18/05/2017 - 17/05/2018						
Vehicle Reg. No. (Insured):	XD3656H	Policy No. (Claimant):							
		Excess:							
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 15/05/2018]								
Driver/Custodian (Insured):	YAP CHONG LIN (), NRIC: F7464425L, Tel: +6583011412								
Adj Asg. Remarks:	Liability 100% TP reject SJE - assign LKK Auto Consultants								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*WC4413C (557627)

[XD3656H]

TP

TAT HING TRANSPORT PTE LTD

Apr 27 2018 2:00PM

[SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD]

Fook Heng Motor Service
















[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)					
1	09/05/18 15:11	<b>Accident Statement</b> <small>From: SC - Reg. No: XD3656H, Claimant: SINGLAND HEAVY MACHINERY &amp; CONSTRUCTION PTE LTD</small>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
1	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 10:47	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/05/18 10:47	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/05/18 15:11	<b>WC4413C e-file report</b> From: SC - Reg. No: XD3656H, Claimant: SINGLAND HEAVY MACHINERY & CONSTRUCTION PTE LTD	 Load PDF	
2	09/05/18 15:13	<b>TP PRI Request</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008715/DZ4BE2

Date: 20/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28729875MKC

Claimant Vehicle  
No : WC4413C

Insured Vehicle No : XD3656H

Date of Loss: 27/04/2018

Nature of Claim: TP

Claim No: 557627

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WC4413C

Make &amp; Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1415411

Reg. Date: 25/10/2011 (Man. Year: 2011)

Chassis No: JALCYH52SB7000172

Colour: White/Blue

Odometer: 188096 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5

Front Left Side: Windforce 6 mm

Rear Left Side: Windforce 6 mm

Front Right Side: Windforce 6 mm

Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 14/05/2018

Date Inspected: 14/05/2018 Inspected At:

Fook Heng Motor Service (HQ)  
29 SUNGAI KADUT STREET 4  
SINGAPORE 729054

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$10,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 20 Jul 2018)

**Parts:** N/A ISUZU CYH52S 15.7 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for WC4413C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >