

Sundari

CC3/III 1800 8779

Rijaz/Y

Surveyor:

Rahul

DOI:

ASSIGNMENT

20/3/2018

Date / Time:

15/5/18

Registered in Merimen:

15/5/18

Pre-assign / CCU / FTE

SHC 3183A



Insured Vehicle No.:

UTPL

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.: 18/3/2018

Is driver the owner?

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

Soh Ery Teck

Driver Tel No.:

(V/L: YES/NO)

Claim No.:

MCT18030596

Policy No.:

M10M0075

Make / Model:

A. Sonata

Place of Accident:

Middle Rd x Victoria St

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability:

%

Final ? Yes / No

SHB80906



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/6

20/6

SHB80906 - 01/06/2018 16:23:20 / 12/6/18 ; 009-10/12/18
 - 009/10/12/2018 / 14 ; 009: 07/02/18
 SHC3183A - 06/3/18/18 02:21:08 / 02/03/18 ; 009: 23/11/18

15/5 Parking Surveyor's Assignment sheet.

11-7-18 FOR MANDATE

RECEIVED 20 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed/ Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

GST

\$5

749.82

Loss of Rental (LOR):

\$5

329.82

(3

days) 109.94

01 REVERSED

Loss of Use (LOU):

\$5

120

(S

40 x 3

days)

Loss of Income (LOI):

\$5

120

(S

40 x 3

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

-

Medical:

\$5

-

Disbursement:

\$5

-

Legal Cost

\$5

-

Total:

\$5

1,198.82

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

1,198.82

Name 1:

PREMIER AUTOMOTIVE SERVICES (PRLM)

Payee 2: (Strike if N.A.)

\$5

X

Name 2:

X

Payee 3: (Strike if N.A.)

\$5

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 18/5/18

Greyhound *Form*

REF:

III

9779/21ja3

(1)

ASSIGNMENT

From:

Date:

20/3/18

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To inspect Vehicle No:

SHB 8090G

at Workshop m/s

Premier Automotive

of

23 changi south Ave 2 #01-02

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS *wp*

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 8090G

Yr Regn:

2016 SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I 30

cc 1582

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

146 273

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TMA 2814VH 5121496

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt ☐

Steering: ☒ Normal ☐ Jammed / Leaked / Burnt or

Brake: ☒ Normal ☐ Jammed / Leaked / Burnt or

Modi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

18/03/18

D.O.I.

20/03/18

Survey held at

PREMIER

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5 \$700

R (\$1,920.02 / 739)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 ☐ S + RS ☐ SI

2) Photos

3) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18008779/R1ja3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 15-05-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3183A	Veh. Inspected	SHB 8090G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/03/2018	Inspection Date	20/03/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

19-Mar-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8090 G

1 pc	Emblem Hyundai	\$	29.40	per ✓	
1 pc	Front bumper	\$	811.11	R	
1 pc	Front bumper sponge	\$	218.03	X ✓	
1 pc	Bonnet grille	\$	566.46	BB ✓	
2 pcs	Front bumper n/s & o/s side bracket @\$32.51	\$	65.02	X ✓	
		\$	1,690.02	595.86	
		Less 20%	\$	338.00	20%
		\$	1,352.02	476.68	
S/NETT					
1 set	Front bumper clips	\$	48.00	per ✓	
1 pc	Front no. plate	\$	50.00	35 CRA ✓	
	Sundry	\$	50.00	10	
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the support panel, etc	\$	650.00	150	
	To putty and spray painting on the front bumper	\$	350.00	180	
	To apply rustproofing on the repaired and replaced panels	\$	120.00	X	
	Total	\$	2,620.02		

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

476.68
423.00
899.68
20%
719.74
43-700
2 days
Rame
Hp 90010068
2 days
H/S
20/03/18 P1550
Rey after repair

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8090G
Previous Vehicle No.: -
Effective Date of Ownership: 28 Sep 2016
Original Regn Date: 28 Sep 2016
Registration Date: 28 Sep 2016
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ121496
Engine No.: D4FBGZ105479
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,131.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Sep 2024
Minimum PARF Benefit: \$7,610.00
No. of Transfers: 0
IU Label No.: 1050681048
COE No.: 2016092801004222R
COE Expiry Date: 27 Sep 2024
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00
PQP Paid: \$42,672.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No

Gary Shi

From: Gary Shi
Sent: Tuesday, 17 July, 2018 1:15 PM
To: 'Joy Irene (LKKAUTO)'; Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: RE: LOD / Accident involving SHB8090G & SHC3183A on 18.03.18 (III Case)
Attachments: SHB8090G - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHB8090G, our client agreed to direct settle the above claims at \$1198.82

We enclosed hereby Discharge voucher & ATA for your kind attention, original copies will pass to Mr Calvin

Kindly let us have your settlement sum of S\$1198.82 in our favour – Premier Automotive Services Pte Ltd within 14 days from the date hereof.


Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, 11 July, 2018 5:30 PM
To: Gary Shi; Asher Sng (LKKAUTO); Vic (LKKAUTO)
Cc: AccReport
Subject: RE: LOD / Accident involving SHB8090G & SHC3183A on 18.03.18 (III Case)

WITHOUT PREJUDICE

Dear Gary,

Attached DV and ATA for your necessary action.

Thank you.

Print Received Message

This mail is associated with :

***SHB8090G (MCT18030596)**
[SHC3183A]

TP

PREMIER TAXIS PTE LTD

Mar 18 2018 3:00AM

[COMFORT TRANSPORTATION PTE LTD]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/07/2018 15:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1198.82) - SHB8090G - Claim Handler: Sundari Nagarajan

Approved:1198.82:Request TP to forward us the video of the accident

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: **SHB8090G**

Chassis Number

: TMAD281UVHJ121496

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A

EXCESS (SECTION II) : S\$3,500

INSURE WITH COE : N/A

HIRE PURCHASE COMPANY : N/A

SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive



Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8090G
 Previous Vehicle No.: -
 Effective Date of Ownership: 28 Sep 2016
 Original Regn Date: 28 Sep 2016
 Registration Date: 28 Sep 2016
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: i30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ121496
 Engine No.: D4FBGZ105479
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1495 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,131.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 27 Sep 2024
 Minimum PARF Benefit: \$7,610.00
 No. of Transfers: 0
 IU Label No.: 1050681048
 COE No.: 2016092801004222R
 COE Expiry Date: 27 Sep 2024
 COE Category: A - Car (up to 1500cc & 97kW (130bhp))
 COE Registration Category: A - Car (up to 1500cc & 97kW (130bhp))
 Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00
 PQP Paid: \$42,672.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8090G/GS

WITHOUT PREJUDICE

8th June 2018

(By Email Only)

Attn: The Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Dear Sir/Madam

ACCIDENT INVOLVING SHB8090G & SHC3183A ALONG MIDDLE ROAD / VICTORIA STREET ON 18.03.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHB8090G, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SHC3183A at the material time of the accident with the driver of our client's vehicle, Mr Kuan Kar Fai

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SHC3183A, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$	749.00 (Incl. GST)
(2) Loss of Rental - 3Days @\$109.94per day	\$	329.82
(3) Loss of Income – 3Days @\$100.00per day	\$	300.00
	\$	<u>1378.82</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHB8090G
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8090G/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd


AUTHORISATION TO ACT

I/We, PREMIER TAXIS PTE LTD ("the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHB 8090G (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHB 8090G that was damaged pursuant to the accident which occurred on 18/03/2018 (date) along MIDDLE ROAD/VICTORIA STREET (location) involving vehicle no/s SHC 3183A ("the accident").

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 17 (day) of July (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18030596
Claimant Ref: SHB8090G/GS

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 749.00 (repair cost), S\$ 449.82 (loss of use/rental), S\$ --- (search fee), vehicle no. SHB 8090G that was damaged pursuant to the accident which occurred on 18.03.2018 (date) at MIDDLE ROAD/VICTORIA STREET (location) involving vehicle no. SHC 3183A (insured vehicle). This is pursuant to the inspection conducted on 20/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 8090G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHB 8090G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,198.82 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 19 day of JULY 2018.

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



MPB

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18030596
Claimant Ref: SHB8090G/GS

We/I, PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 749.00 (repair cost), S\$ 449.82 (loss of use/rental), S\$ --- (search fee), vehicle no. SHB 8090G that was damaged pursuant to the accident which occurred on 18.03.2018 (date) at MIDDLE ROAD/VICTORIA STREET (location) involving vehicle no. SHC 3183A (insured vehicle). This is pursuant to the inspection conducted on 29/08/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PREMIER TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 8090G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SHB 8090G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,198.82 to PREMIER AUTOMOTIVE SERVICES PTE LTD

Dated this 17 day of July 2018

CLAIMANT:

Signature: [Signature]
Name: Gary Shi
NRIC: S8618684
Address: Singaporean
Nationality: Singaporean
Occupation:

WITNESS:

Signature: [Signature]
Name: LKK AUTO CONSULTANTS PTE LTD
NRIC: 199607198R
Address: 51 UBI AVENUE 1 #01-25
Nationality:
Occupation:

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443**TAX INVOICE**DATE 8-Jun-2018
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR HYUNDAI I30 REGN NO: SHB 8090 G			\$ 700.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 700.00
GST @ 7%				\$ 49.00
GRAND TOTAL				\$ 749.00


for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



23 March 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Kuan Kar Fai (Guan Jiahui) of NRIC Number S7507477H was a registered driver of SHB8090G. Kuan Kar Fai (Guan Jiahui) was paying daily rental rate of \$109.94 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to read "Chin Bee Lian".

Chin Bee Lian (Ms)

Assistant Vice President

Taxis Administration

Prepared By: Hasnah

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.premiertaxi.com
Co. Reg. No. 200304975H



REPLACEMENT VEH GIVEN YES / NO


VEH NO. _____

JOB NO. _____

CHECK IN / OUT VOUCHER

DRIVER'S NAME <u>Yap Boon Tiong</u>		E Perlet)	
NRIC <u>S 7504630H</u>		HANDPHONE <u>93288488</u>	
TAXI REGN NO. <u>S H B 8090G</u>		MAKE / MODEL <u>Isuzu (A)</u>	
DATE IN <u>200818</u>	TIME IN <u>11:00</u>	DATE OUT <u>220318</u>	TIME OUT <u>14:57</u>
KILOMETRES IN	FUEL IN	KILOMETRES OUT	FUEL OUT
E 1/4 1/2 3/4 F		E 1/4 1/2 3/4 F	

INDICATE AREA OF DAMAGE HERE:



BODY MARKINGS

- | | |
|---------------------|-------------|
| 1 - Light Dent | 5 - Damaged |
| 2 - Serious Dent | 6 - Chip |
| 3 - Light Scratch | 7 - Crack |
| 4 - Serious Scratch | 8 - Peeling |

TAXI METER DOWNLOADED		DATE / TIME TOWED IN TO WORKSHOP
YES	NO	D D U H H M M
		DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION
		D D M M Y Y H H M M

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

CHECK IN	CHECK OUT
<u>YAP BOON TIONG</u>	<u>KEAN KEE FAI</u>
DRIVER'S NAME	DRIVER'S NAME
<u>[Signature]</u>	<u>[Signature]</u>
DRIVER'S SIGNATURE / DATE / TIME	DRIVER'S SIGNATURE / DATE / TIME
<u>[Signature]</u>	<u>[Signature]</u>
CHECKED IN BY (PREMIER'S AUTHORISED WORKSHOP)	CHECKED OUT BY (PREMIER'S AUTHORISED WORKSHOP)

SERVICE / REPAIRS DONE	DRIVER'S REMARKS
<input type="checkbox"/> SERVICING <input type="checkbox"/> OTHERS: <input type="checkbox"/> T / BELT <input type="checkbox"/> AIRCON SYSTEM <input type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT: <input type="checkbox"/> TURBO D D M M Y Y H H M M <input type="checkbox"/> BRAKE SYSTEM <input type="checkbox"/> CLUTCH SYSTEM <input type="checkbox"/> BULB <input type="checkbox"/> UNDER CARRIAGE <input type="checkbox"/> CPF <input type="checkbox"/> BATTERY	<u>7P/G</u> <u>Hiner - Guan Jia hui - 96975101</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018 Edit Reg		20 Mar 2018 00:00 Edit Adj Rpt	\$5700.00 Edit Estimates	\$5700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHB8090G	Date of Loss:	18/03/2018 03:00 - :59 [17 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18030596	Policy/Cover Note No.:	MCDM0015
Vehicle Reg. No. (Insured):	SHC3183A	Policy No. (Claimant):	5095103893
		Excess:	
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/05/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

































- III_SG (11/07/2018): Alert - Adj Mandate Approved (\$1198.82) - SHB8090G - Claim Handler: Sundari Nag...
- III_SG (24/05/2018): Alert - Adj Mandate Approved (\$50.00) - SHB8090G - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8090G (MCT18030596)
 [SHC3183A]
 TP
 PREMIER TAXIS PTE LTD
 Mar 18 2018 3:00AM
 [COMFORT TRANSPORTATION PTE LTD]
 Premier Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/07/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	11/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	11/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	11/07/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 11:21	TP ESTIMATE - MARKED	 Load PDF	
2	15/05/18 11:21	TP GIA REPORT	 Load PDF	
3	11/07/18 12:41	WORKSHOP INVOICE	 Load PDF	
4	11/07/18 12:41	LOD	 Load PDF	
5	11/07/18 12:41	RENTAL RECEIPT	 Load PDF	
6	23/07/18 10:05	AUTHORISATION TO ACT FORM	 Load PDF	
7	23/07/18 10:05	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/05/18 08:58	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18008779/R1JA3Q2

Date: 23/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MC0M0015
Claimant Vehicle No : SHB8090G **Insured Vehicle No :** SHC3183A
 Date of Loss: 18/03/2018 Nature of Claim: TP Claim No: MCT18030596

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB8090G**
 Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M) Engine No: D4FBGZ105479
 Reg. Date: 28/09/2016 (Man. Year: 2016) Chassis No: TMAD281UVHJ121496
 Colour: Grey Odometer: 146273 km
 Engine Capacity: 1582 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm
 Front Right Side: Maxxis 5 mm Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,500.02	569.69	930.33	62.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	330.00	790.00	70.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,620.02	899.69	1,720.33	65.66
Approved Total (Overridden) (S\$)		700.00		
(S\$)	2,620.02	700.00	1,920.02	73.28
+ GST 7.00/7.00% (S\$)	183.40	49.00	134.40	73.28
Nett Amount (S\$)	2,803.42	749.00	2,054.42	73.28
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$109.94/day) (S\$)		329.82		
Nett Liability (S\$)		1,198.82		

INSPECTION

Date of Assignment: 20/03/2018
 Date Inspected: 20/03/2018 Inspected At: Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jul 2018)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8090G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
2	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Serviceable	218.03 FL	*- FL
4	1		*BONNET GRILLE	Deformed	566.46 FL	*566.46 FL
5	2		*FRONT BUMPER N/S & O/S SIDE BRACKET	Serviceable	65.02 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
7	1		*FRONT NO.PLATE	Cracked	50.00 FS	*35.00 FS
8	1		*SUNDRY	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,838.02	688.86
- List Item Discount on L Items 20.00/20.00% (S\$)	338.00	119.17
Total Parts (S\$)	1,500.02	569.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE SUPPORT PANEL ,ETC	New	650.00	150.00
2	TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER	New	350.00	180.00
3	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,120.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >