

ASS. REC. BY: REF: CS/CTI18008798/0.9d3ⁿ² Special Instruction:

Surveyor: MA ASSIGNMENT (Office)

From (Person): Jowyn Tay of CTI Date/Time: 15/5/18 @ 1:10pm

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 6606R Insured: SGG 1660T

at Workshop in/s: K. Kim Hin Auto Tel: 64527018

of 160 Sin Ming Drive #02-20

Policy No: DMPCSN1622241802 Claim No: SNM18D02416C02

Sum Insured: Excess:

Make of Veh: D.O.A. 12/05/2018 (Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 2:14pm @ 15/5/18 Person Contacted: Shuman Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 6606R-X
03/08/18 @	SGG 1660T - NA/CTI18008757/24 D.O.A.: 12/5/18 U.V.S.M confirmed with Meng Huat final Ag \$4335.25, 5 days. (Red \$1380, 24h)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD-RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SCA6606P Reg: 02/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA HARRIER cc 1986
 Colour: Black A/C Insured / Std / NI / NA
 Sp. Reading: 55222 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ISU 600069354
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or
 Brake: In Order / Jammed / Leaked / Burnt or
 Mod: N/R / S/Rim / STD A/Rim or
 Tyre Size: F: 035/55/218
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR - Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or P28
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. _____ D.O.I. 15/5/2018
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 09 AUG 2018	

Date/Time, File Pass to? : Preli. Report
 1) 03/8 twish : Final Report
 Date/Time, File Return to?

Days Of Repair: 5
 Resurvey No. of Trip: 2

Report Format: NET-TP
 Lump Sum / I.B.I: (\$) 4335.25

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation	
) \$ - PS - SI	
) Photos	
) Others	
TOTAL	220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18008798/M1qd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 15-05-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGG 1660T	Veh. Inspected	SLA 6606R
Policy No.	DMPCSN1622241802	Coverage (\$)	0.00
Claim No.	SNM18D02416C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/05/2018	Inspection Date	15/05/2018
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018 Sendback Est	15 May 2018 11:20 \$5,715.25	15 May 2018 13:10 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEE YONG SENG, ID: 0		
Main Claimant:	LIM YEOW KENG@BERNIE LIM, ID: S0079777D		
Vehicle Reg. No.:	SLA6606R	Date of Loss:	12/05/2018 19:00 - :59 [26 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02416C02	Policy/Cover Note No.:	DMPCSN1622241802 Coverage: 03/05/2018 - 02/05/2019
Vehicle Reg. No. (Insured):	SGG1660T	Policy No. (Claimant):	B28889545QMY
		Excess:	\$50.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/05/2018]		
Driver/Custodian (Insured):	NIL (/ Male), NRIC: 0		
Adj Asg. Remarks:	EST \$5715.25, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

(170)

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'ed	Status
Main	15 May 2018 11:04		15 May 2018 11:20 S\$5,715.25			Pending for Approval

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NIL, ID: 0		
Main Claimant:	LIM YEOW KENG@BERNIE LIM, ID: S0079777D		
Vehicle Reg. No.:	SLA6606R	Date of Loss:	12/05/2018 19:00 - :59 [26 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 03/05/2018 - 02/05/2019
Vehicle Reg. No. (Insured):	SGG1660T	Policy No. (Claimant):	B28889545QMY
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Driver/Custodian (Insured):	NIL (/ Male), NRIC: 0		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

Shiau Chan (LKKAuto)

From: _____
Sent: Friday, 3 August 2018 11:45 AM
To: 'survey@kkimhin.com.sg'
Cc: SUR
Subject: RE: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)

Dear Meng Huat,

WITHOUT PREJUDICE

Confirm final fig \$4,335.25 and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>
Sent: Wednesday, 4 July 2018 12:30 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)

Hi Ms Shiau Chan,

Enclosed you attention.

Before paint photo.

P/P=\$4,335.25

5 working day.

Please confirm.

Thank you.

Regard

Meng Huat

K.Kim Hin Auto Pte Ltd

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: 22 June 2018 Friday 5:27 PM
To: 'Survey KKH' <survey@kkimhin.com.sg>
Subject: RE: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)

Dear Meng Huat,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: survey@kkimhin.com.sg
Sent: Wednesday, 4 July 2018 12:30 PM
To: Shiau Chan (LKKAuto)
Subject: RE: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)
Attachments: P5163132.jpg; P5163115.jpg; P5163116.jpg; P5163117.jpg; P5163120.jpg; P5163123.jpg; P5163126.jpg; P5163127.jpg; P5163130.jpg

Hi Ms Shiau Chan,

Enclosed you attention.
Before paint photo.
P/P=\$4,335.25
5 working day.
Please confirm.
Thank you.

Regard
Meng Huat
K.Kim Hin Auto Pte Ltd

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: 22 June 2018 Friday 5:27 PM
To: 'Survey KKH' <survey@kkimhin.com.sg>
Subject: RE: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)

Dear Meng Huat,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 June 2018 1:25 PM
To: 'Survey KKH' <survey@kkimhin.com.sg>
Subject: FINALISE OF VEHICLE SLA 6606R (DOA: 12/05/2018)

Dear Meng Huat,

Kindly provide us the before paint photographs and final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9777D
Vehicle Details	
Vehicle No.:	SLA6606R
Vehicle to be Exported:	No
Intended De-registration Date:	14 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB706548
Chassis No.:	ZSU600069354
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,168.00
Original Registration Date:	29 Feb 2016
First Registration Date:	29 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$27,836.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2026
PARF Rebate Amount:	\$20,877.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,970.00
COE Rebate Amount:	\$36,597.00
Total Rebate Amount:	\$57,474.00

The information contained herein is correct as at 14 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 11:02
Date Of Accident	12/05/2018 19:10
Exact Location Of Accident	STADIUM CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA6606R
Insured/Policyholder	
Name Of Registered Owner	LIM YEOW KENG@BERNIE LIM
NRIC No	S0079777D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90936606
Alternative Phone No	OFFICE-90936606

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 PREMIUM (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28889545QMY
Cover Note Number	

Driver

Name of Driver	LIM YEOW KENG@BERNIE LIM
NRIC No	S0079777D
Date Of Birth	13/01/1953
Occupation	INDOOR
Date Of Driving Pass	24/05/1973
Driving Experience	44 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90936606
Fax Number	
Contact Number	OFFICE-90936606
EMail Address	NOEMAIL

Address	12 TAMARIND RD
Postcode	806022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KHOO CHWEE NGOH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGG1660T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLH4173Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

[Handwritten Signature]

Policyholder's Signature
Date & Time:

Company chop (if applicable)

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:


14/5/18 @ 10:50 AM

[Handwritten Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS WAITING TO MAKE A RIGHT TURN WHEN VEHICLE B HIT MY CAR REAR PORTION. WHEN I ALIGHTED, I REALISED IT IS A CHAIN COLLISION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:
Company Chop (if applicable)


Driver's Signature
(If driver is not the policyholder)
Date & Time:

14/5/18@
10:50 PM


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
Tel: 6452 7018 (5 Lines) Fax: 6458 3895
Email: service@kkimhin.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
NIL

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/05/2018
Vehicle Reg. No.:	SLA6606R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM YEOW KENG@BERNIE LIM	Driver (Insured):	NIL
Make/Model:	TOYOTA HARRIER, 2.0 PREMIUM (A)	Vehicle Reg. Date:	29/02/2016
Vehicle Colour:	BLACK		
Engine No:	3ZRB706548	Chassis No:	ZSU600069354
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY AND ADVISE LIABILITY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,975.25
Miscellaneous Items	0.00
Labour	1,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,715.25
+ GST 7.00% (\$\$)	400.07
Nett Amount (\$\$)	6,115.32

This claim is handled by: **WONG SHU MAN**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 May 2018)
Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA6606R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER-TOP <i>distorted</i>	0.00	0.00	— *1,415.00 F
2	1		*REAR BUMPER-BOTTOM <i>Distorted</i>	0.00	0.00	— *455.00 F
3	2		*REAR BUMPER SIDE RETAINER (LH/RH) <i>Nuc</i>	0.00	0.00	— *170.00 F
4	2		*REAR BUMPER REFLECTOR (LH/RH) <i>src</i>	0.00	0.00	X *130.00 F
5	10		*REAR BUMPER CLIPS <i>Nuc</i>	0.00	0.00	— *55.00 F
6	1		*REAR BUMPER SPONGE <i>torn</i>	0.00	0.00	— *125.00 F
7	1		*TAILGATE HARRIER EMBLEM <i>Nuc</i>	0.00	0.00	— *110.00 F
8	1		*TAILGATE WEATHERSTRIP <i>Nuc</i>	0.00	0.00	— *442.00 F
9	1		*REAR END PANEL <i>Distorted</i>	0.00	0.00	— *795.00 F
10	1		*REAR END PANEL TOP GARNISH <i>src</i>	0.00	0.00	X *445.00 F
11	1		*O/S TAILLAMP ASSY <i>NH</i>	0.00	0.00	X *865.00 F
12	1		*REVERSE SENSOR <i>Dem</i>	0	0.00	— *220.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	5,227.00
- Add. Disc. on L,N Items 25.00% (S\$)	1,251.75
Total Parts (S\$)	3,975.25

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	600 -650.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	80 120.00
3	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.	New	80. 120.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	700 -850.00
Gross Labour Cost (\$\$)			1,740.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA Aukhan
PH Rep.
Before print PWD
HCC Auto MA

15/5/18
3 wdays


8/6/18

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118008798/DQD3N2

Date: 03/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1622241802
Claimant Vehicle No :	SLA6606R	Insured Vehicle No :	SGG1660T
Date of Loss:	12/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02416C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA6606R	Engine No:	3ZRB706548
Make & Model:	TOYOTA HARRIER, 2.0 Premium (A)	Chassis No:	ZSU600069354
Reg. Date:	29/02/2016 (Man. Year: 2015)	Odometer:	55222 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,975.25	2,875.25	1,100.00	27.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	1,460.00	280.00	16.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,715.25	4,335.25	1,380.00	24.15
+ GST 7.00/7.00% (S\$)	400.07	303.47	96.60	24.15
Nett Amount (S\$)	6,115.32	4,638.72	1,476.60	24.15

INSPECTION

Date of Assignment:	15/05/2018	Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	15/05/2018	Inspected At:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Aug 2018)

Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA6606R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-TOP	Distorted	1,415.00 F	*1,415.00 F
2	1		*REAR BUMPER-BOTTOM	Dented	455.00 F	*455.00 F
3	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Necessary	170.00 F	*170.00 F
4	2		*REAR BUMPER REFLECTOR (LH/RH)	Serviceable	130.00 F	*- F
5	10		*REAR BUMPER CLIPS	Necessary	55.00 F	*55.00 F
6	1		*REAR BUMPER SPONGE	Torn	125.00 F	*125.00 F
7	1		*TAILGATE HARRIER EMBLEM	Necessary	110.00 F	*110.00 F
8	1		*TAILGATE WEATHERSTRIP	Necessary	442.00 F	*442.00 F
9	1		*REAR END PANEL	Dented	795.00 F	*795.00 F
10	1		*REAR END PANEL TOP GARNISH	Serviceable	445.00 F	*- F
11	1		*O/S TAILLAMP ASSY	Not Necessary	865.00 F	*- F
12	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,227.00	3,767.00
- Add. Disc. on L,N Items 25.00/25.00% (\$\$)	1,251.75	891.75
Total Parts (\$\$)	3,975.25	2,875.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	650.00	600.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	80.00
3	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.	New	120.00	80.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	850.00	700.00
Gross Labour Cost (S\$)			1,740.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >