

Jas Tan.

CS3/Am1800 8802, UA3sr

45396

Surveyor:

Majerus

DOI:

ASSIGNMENT

Date / Time:

16/5/18

Registered in Merimen:

Pre-assign / CCU / FTE

* PPI only
SLN 9443E* 16/5/18 - LKK
Survey before AAA
give assignment

Insured Vehicle No.:

SLN 9443E

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

10/5/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLN 3915K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kegulus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLN 3915K x; SLN 9443E - x

* 14/5/18: Please scan whole file.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 22 MAY 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

16/5/18
Majerus

PPI \$100

08/11/13 Wef
ASS. REC. BY: Marcus

REF:

AXA/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TS / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL2391516

at Workshop m/s Pepasus

of _____

Insured: SLN 94436

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 686.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

22006

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL2391516 Yr Regn: 217

Type: C M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make: mazda 3 C.O. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 108035 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6BN22A8H0143338

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 10/5/18 D.O.I. 15/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 50704

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :

not followed
2/5 9
2 dy.
15/5/18
take photo of damage

Quotation No : QO18/05-1125	Quotation Date : 11/05/2018	Terms : 30 DAYS
Vehicle No : SLL3915K	Chassis No : JM6BN22A8H0143338	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
marks : TP INSURER: AXA, INSURED'S VEHICLE NO: SLN9443E, DATE OF ACCIDENT: 10.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>20/2e</i>	1	1,075.0000	1,075.00 ✓
2	N/S REAR BUMPER REFLECTOR <i>11</i>	1	51.0000	51.00 X
3	REAR BUMPER CLIPS <i>1ec</i>	10	5.0000	50.00 ✓
4	REAR BUMPER REINFORCEMENT <i>20</i>	1	538.0000	538.00 ✓
5	REAR BUMPER SIDE RETAINERS <i>11</i>	2	92.0000	184.00 X
6	REAR BUMPER SIDE HOLDERS <i>11</i>	2	74.0000	148.00 X
7	REAR BUMPER SIDE HOLDER RIVETS <i>11</i>	4	6.0000	24.00 X
8	REAR BUMPER TOW COVER	1	17.0000	17.00 X
9	REAR BUMPER SCREW SPACER <i>11</i>	2	10.0000	20.00 X
10	REAR BUMPER CENTRE BRACKET <i>11</i>	8	12.5000	100.00 X
11	LESS 20% ITEM (1-10)	1	-441.4000	-441.40
12	REAR BUMPER PARKING SENSOR <i>shorted</i>	1 <i>set</i>	280.0000	280.00 <i>200</i>
13	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 <i>50</i>
14	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	120.0000	120.00 <i>60</i>
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00 <i>20</i>
16	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	550.0000	550.00 <i>300</i>
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	650.0000	650.00 <i>500</i>

Sub Total 3,545.60
GST(7.00%) 248.19
Total (SGD) 3,793.79

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

- UKF report is to be notified
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and

Approved by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/05/2018 12:26
Date Of Accident	10/05/2018 19:05
Exact Location Of Accident	KEPPEL ROAD TOWARDS ANSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3915K
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68014188

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	KANG TECK GUAN
NRIC No	S7011031H
Date Of Birth	29/03/1970
Occupation	OUTDOOR
Date Of Driving Pass	30/03/2005
Driving Experience	13 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98765432
Fax Number	
Contact Number	
Email Address	BENLOVE70@YAHOO.COM.SG

Address	BLOCK 148 SILAT AVENUE #08-14
Postcode	160148
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 10.05.2018 at about 1905 hours, I was driving my vehicle (A: SLL3915K) along Keppel Road towards Anson direction. The traffic was heavy, vehicle ahead of me was slowed down and stationary, so I followed suit. Suddenly, I felt an impact from the rear and realized that vehicle (B: SLN9443E) hit onto the rear portion of my vehicle. Vehicle A: 1 male and 3 female passengers onboard Vehicle B: no passenger onboard

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN9443E
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	PIER MASSIMO MARRAS
NRIC/Passport Number	
Contact Number	82874916
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KANG TECK GUAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLL3915K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 11-05-2018 @ 0920hrs


Reporting Centre Personnel's Signature
Name: Sen Lou
NRIC/FIN No.: S88598968

SKETCH PLAN

A: SLL 3915K

B: SLN 9443E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11.05.2018 @ 0920hrs

Reporting Centre Personnel's Signature
Name: Sam Low
NRIC/FIN No.: S8854896B

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLL3915K
Vehicle to be Exported:	No
Intended De-registration Date:	15 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520430787
Chassis No.:	JM6BN22A8H0143338
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,004.00
Original Registration Date:	23 Feb 2017
First Registration Date:	23 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$11,004.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2027
PARF Rebate Amount:	\$8,253.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$42,451.00
Total Rebate Amount:	\$50,704.00

The information contained herein is correct as at 15 May 2018

OK

7/20/18: 70 scan

Page 1 of 3

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2013 Audi A3 1.4A Sportback At \$11K Depre Only!







1 Owner Sporty Grey! Fully
Agent Premium Automobile
Servicing Records Since Day1
AutoPrestige Gallery StarAd


[Browse by Category](#)
[« Back \(1 2 \) Next »](#)
[Sort b](#)

22 vehicles

Mazda 3

[Advance](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	Mazda 3		Any	Any	2017	Any	
	Mazda 3 1.5A		\$76,800	\$7,960 /yr	26-May-2017	1,496 cc	7
<p>\$10K Down Payment. Most Popular Mazda Sedan For Your Family And Daily Usage. Fuel Consumption At 15Km/Litre. Ver Non Smoker. Fuel Saving Yet Powerful Drive.</p> <p>SmartCars Boutique Pte Ltd</p> <p>Posted: 14-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda</p>							
	Mazda 3 1.5A		\$69,000	\$7,200 /yr	10-Mar-2017	1,496 cc	8
<p>Cheapest In The Market! Down Payment Start As Low As \$2800 Onwards. Welcome Old Car 1 To 1 Exchange Without C Like New Car. Under 3 Years Eurokars Warranty</p> <p>Posted: 13-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda</p>							
	Mazda 3 1.5A		\$71,800	\$7,410 /yr	24-May-2017	1,496 cc	8
<p>Cheapest In The Market! \$0 Down Payment, Only Need To Pay Advance Installment, And Insurance! Meticulously Maint Agent Warranty, Low Depreciation \$7k Only! Accident Free, ...</p> <p>Heritage Auto Enterprise Pte Ltd</p> <p>Posted: 13-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda</p>							
	Mazda 3 1.5A		\$75,800	\$7,620 /yr	31-Aug-2017	1,496 cc	
<p>One Owner, Low Mileage Done, Agent Warranty. View To Appreciate Showroom Condition. Call Now, Don't Miss.</p> <p>Cycle & Carriage.Fulco Motor Dealer</p> <p>Posted: 12-May-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda</p>							

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)


[Compare](#)

Service Request Details

Claim

S8M00GW4

Reference

None 

Loss Date

May 10, 2018

Request Date

May 16, 2018

Due Date

May 23, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SLL3915K

Make

TPVD MAZDA

16/05/2018 @ 9.40am
Alvinah in
maruz

Service Address

...

Primary Contact/Insured

ACE DRIVE PTE LTD

50 UBI AVENUE 3, #01-01/02 FRONTIER, 408866, Singapore
98166672

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: JAS TAN

Ref: CS3/ASM18008802/Ua3s2

Date: 26-05-2018



Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLN 9443E	Veh. Inspected	SLL 3915K
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00GW4	Excess (\$)	0.00
Assign From		Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0143338	Colour	GREY
Odometer	108035 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	WEST LAKE	8 mm
L/H Front Tyre	205/60R16	WEST LAKE	8 mm
R/H Rear Tyre	205/60R16	WEST LAKE	8 mm
L/H Rear Tyre	205/60R16	WEST LAKE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	10/05/2018	Inspect Date / Time	15/05/2018 (09:51 AM)
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM18008802/Ua3s2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.