

ASS. REC. BY:

REF: CS3/MSG18008809/N240302

Special Instructions:

Surveyor:  
Mehmen

Naz

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

15/5/2018 @ 3:14 pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ4 2535G

Insured:

SKP 2662L

at Workshop in/s

Alpha Car Services

Tel:

6509 8258

of

Kaki Bukit Ave 6 Blkc # 01-59

Policy No:

80438269 QMY

Claim No:

558290

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/05/2018

CA / REV / REP. / REV 24 HRS

1wp

16/5/18 @ 04 1pm

H.O.D. Endorsement:

Date/Time:

3:35pm @ 15/5/18

Person Contacted:

Cai Ling

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SJ4 2535G - X

SKP 2662L - X.

7/5/18

Dismantled

DATE: NA2

REF: MSIG

### ASSIGNMENT

From: Date: 16/5/2018

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 2535G  
at Workshop m/s Alpha Car Services  
of Kaki Bukit Ave 6 Blkc # 01-59

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before 1pm  
cai ling @ 6509 8258

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS /wp)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJU 2535G Yr Regn: NOV / 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO C30

C.C. 1999

Colour: GREY

A/C: ☒ Insured / Std / NI / NA

Sp. Reading: 101,039

T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

C/No: YVIMK43BA2175704

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 225/45 R17

R: 11

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/05/18 D.O.I. 16/05/18

Survey held at Alpha Car Services

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\* Repair Estimate : S\$ 3500 - 4500

\* 3 days

RECEIVED 16 MAY 2018

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2).

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ - RS - \$

Photos

Other

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

120

50

10

180

# CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.1k.AC (SJU2535G)  
Your Ref: SKP2662L

15 May 2018

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

Attn: Motor Claims Department

BY FAX: 6225 7402 ONLY

**URGENT**

MAIN OFFICE  
133 NEW BRIDGE ROAD  
#23-03/04/05  
CHINATOWN POINT  
SINGAPORE 059413  
TEL: 6438 1323  
FAX: 6438 2313

BRANCH OFFICE  
1 JALAN BERSEH  
#03-12 NEW WORLD CENTRE  
SINGAPORE 209037

PLEASE SEND ALL  
CORRESPONDENCES TO  
THE MAIN OFFICE

WE DO NOT ACCEPT  
SERVICE BY FAX

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
CLAIMANT: CHAN WENG SUNG JOHN  
TRAFFIC ACCIDENT ON 12 MAY 2018 AT 18:00 HRS ALONG ESSEX ROAD INVOLVING  
VEHICLES NO. SJU2535G & SKP2662L

We are instructed by Chan Weng Sung John to notify you of a road accident on 12 May 2018 at about 18:00 hrs along Essex Road involving our client's vehicle registration number SJU2535G and vehicle registration number SKP2662L driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Alpha Car Services Pte. Ltd.  
Address: Blk C, #01-59  
Kaki Bukit Avenue 6 @ KB  
Singapore 417883  
Contact: Cai Ling (6509 8258) / Ah Yap (9807 3304) /  
Ah Hwa (9136 8884)

Please liaise with the above workshop directly.

Yours faithfully

Amerjeet Singh

Email: [corene@crossbordersllc.com](mailto:corene@crossbordersllc.com) /  
[huiting@crossbordersllc.com](mailto:huiting@crossbordersllc.com)

encs

**PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION  
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE  
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

**CrossBORDERS LLC**

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K  
GST REGISTRATION NUMBER 201305284K






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18008809/Nz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-05-2018	
		Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SKP 2662L	Veh. Inspected	SJU 2535G
Policy No.	80438269QMY	Coverage (\$)	0.00
Claim No.	558290	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	15/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	12/05/2018	Inspection Date	
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 14/05/2018 17:25  
 Date Of Accident 12/05/2018 18:00  
 Exact Location Of Accident ESSEX ROAD  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SJU2535G  
**Insured/Policyholder**  
 Name Of Registered Owner CHAN WENG SUNG, JOHN  
 NRIC No S8011757D  
 Email Address JOHNCHANWS@GMAIL.COM  
 Mobile Phone No (LOCAL) +65-96929533  
 Alternative Phone No OFFICE-96929533

### Vehicle Particulars

Manufacturer VOLVO  
 Model C30  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number P27255983DMA  
 Cover Note Number

### Driver

Name of Driver CHAN WENG SUNG, JOHN  
 NRIC No S8011757D  
 Date Of Birth 23/04/1980  
 Occupation INDOOR  
 Date Of Driving Pass 25/08/2000  
 Driving Experience 17 YEARS AND 8 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-96929533  
 Fax Number  
 Contact Number OFFICE-96929533  
 Email Address JOHNCHANWS@GMAIL.COM

Address	68B THOMSON ROAD
Postcode	307587
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP2662L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LISSA TOH
NRIC/Passport Number	S7635847H
Contact Number	90388081
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018		15 May 2018 15:14 <a href="#">Edit Adj Rpt</a>	<b>\$50.00</b> <a href="#">Edit Estimates</a>	<b>\$50.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TOH EE-WEN LISSA, ID: S7635847H								
Main Claimant:	CHAN WENG SUNG JOHN, ID: S8011757D								
Vehicle Reg. No.:	SJU2535G	Date of Loss:	12/05/2018 18:00 - :59 [101 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 558290	Policy/Cover Note No.:	80438269QMY (Comprehensive) Coverage: 27/07/2017 - 26/07/2018						
Vehicle Reg. No. (Insured):	SKP2662L	Policy No. (Claimant):							
		Excess:	\$5600.00						
Repairer:	Alpha Car Services Pte Ltd (HQ) BLK C KAKI BUKIT AVE 6 #01-59 AUTOBAY@KB, 417883 Kaki Bukit - Tel: 82265945								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 16/05/2018]								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD OI NOT REPORTED CONTACT: CAI LING (6509 8258)/ AH YAP (9807 3304)/ AH HWA (9136 8884)								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJU2535G (558290)  
[SKP2662L]  
TP  
CHAN WENG SUNG JOHN  
May 12 2018 6:00PM  
[TOH EE-WEN LISSA]  
Alpha Car Services Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/18 18:32	<b>Accident Statement</b> <small>From: SC - Reg. No: SKP2662L, Claimant: TOH EE-WEN LISSA</small>	 Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/18 17:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/18 11:22	PRI - CROSSBORDERS LLC	 Load PDF	
2	15/05/18 11:27	SURVEY DISAGREE ON SJE - ASSIGN AIS	 Load PDF	
3	15/05/18 18:32	SJU2535G E-FILE REPORT <small>From: SC - Reg. No: SKP2663L, Claimant: TCH EE-WEN LISA</small>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> ^ v </div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008809/NZ4D3E2

Date: 21/05/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80438269QMY

Claimant Vehicle  
No : SJU2535G

Insured Vehicle No : SKP2662L

Date of Loss: 12/05/2018

Nature of Claim: TP

Claim No: 558290

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJU2535G

Make &amp; Model: VOLVO C30, 2.0 (A)

Reg. Date: 25/11/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B4204S3171992

Chassis No: YV1MK434BA2175704

Odometer: 101039 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 16/05/2018 Inspected At:

Alpha Car Services Pte Ltd (HQ)  
BLK C KAKI BUKIT AVE 6 #01-59  
AUTOBAY@KB  
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2018)
<b>Parts:</b>	M1-COUPE	VOLVO C30 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU2535G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >