

ASS. REC. BY:

REF:

REF: CS3/MSG18008812/R/240307

Special Instruction

Surveyor :

Menyusun

ASSIGNMENT (Office)

From (Person):

of

MS/G

Date/time:

15/05/18 @ 3:17pm

Estimated Cost:

Bill to:

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SGE 7086 Y

Insured:

YP 4961 U

at Workshop m/s

Monggo Motions

Tel:

9765 5556

of

No. 14 pandan loop Pandan light, Ind. Park (Blk K)

Policy No:

28870711 MKC

- Claim No:

558153

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/05/2018

CA / REV / REP. / REV 24 HRS

(wp)

after 3.30pm. © 16/5/2018

H.O.D. Endorsement

Date/Time: _____

3.23pm @ 5/5/18

Person Contacted:

James

Vehicle:

IN-OUT

[illegible]

Signature: Rafael
(call before going)

REF: MSIG

8812P

CE XPIRY: 2026/mar

ASSIGNMENT

From:

Date:

16/5/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To/Inspect Vehicle No:

SGE 7086 Y

at Workshop m/s

Monggo Motions

of

No. 14 pandan loop penden light Blk K

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

after 3.30pm

Make of Veh:

james : 9765 5556

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGE 7086 Y

Yr Regn:

2026 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN sunny 1.6EXM c.c. 1597

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

166829

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNICFAN1620098238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HIFLY

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

07/05/18

D.O.I.

16/05/18

Survey held at

Monggo Motion

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 7500 - 8500

* 5 days

17/5/18 Submit PRS Report

RECEIVED 17 MAY 2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RC, \$ SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2018		15 May 2018 15:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Magma Pte Ltd, Co. Reg. No.: 199004825E		
Main Claimant:	NG BENG CHOO, ID: S0208812F		
Vehicle Reg. No.:	SGE7086Y	Date of Loss:	07/05/2018 00:00 - :59 [145 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558153	Policy/Cover Note No.:	28870711MKC (Comprehensive) Coverage: 28/12/2017 - 27/12/2018
Vehicle Reg. No. (Insured):	YP4961U	Policy No. (Claimant):	
		Excess:	
Repairer:	Monggo Motions (HQ) No.14 Pandan Loop Pandan Light, Industrial Park (Blk K), 128232 Holland - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2018]		
Adj Asg. Remarks:	SJE - Disagree Please appoint LKK and contact James @ 9765 5556 / 6773 1020 Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18008812/R1z4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-05-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YP 4961U	Veh. Inspected	SGE 7086Y
Policy No.	28870711MKC	Coverage (\$)	0.00
Claim No.	558153	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/05/2018	Inspection Date
Survey held at	NO.14 PANDAN LOOP IND.PARK BLOK K	
Repairer	MONGGO-MOTIONS	

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Copy.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/05/2018 15:08
Date Of Accident	07/05/2018 20:25
Exact Location Of Accident	BLK 412 PANDAN GARDENS OPEN CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE7086Y
Insured/Policyholder	
Name Of Registered Owner	NG BENG CHOO
NRIC No	S0208812F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90039795
Alternative Phone No	OFFICE-90039795

Vehicle Particulars	
Manufacturer	NISSAN
Model	SUNNY-1.5 EX (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC18S0011187
Cover Note Number	

Driver	
Name of Driver	NG BENG CHOO
NRIC No	S0208812F
Date Of Birth	18/09/1954
Occupation	INDOOR
Date Of Driving Pass	17/05/1976
Driving Experience	41 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90039795
Fax Number	
Contact Number	OFFICE-90039795
Email Address	NOEMAIL

BLK 412 PANDAN GARDENS #15-107

Address
Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachments

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP4961U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ALAM MAHBUB

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

BLK 412 RANDAN GARDENS OPEN CAR PARK



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at Rk 412 Pardan Gardens
open car park on 7/may 2018

My vehicle was packed at the car park on 7 May 18.

At 2025 hrs a vehicle No Zorrry YP4961 U

white turning YP4961U collided on to the

left rear of my vehicle causing car damages

I did not make an accident report on 7 May or 8 May

because YP4461 u wanted to mutual settle after his

return from voting in Malaysia election. Upon his return

he said he preferred to file insurance accident report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

50208812 K

NG BENG CHOO

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)




Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2018		15 May 2018 15:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Magma Pte Ltd , Co. Reg. No.: 199004825E								
Main Claimant:	NG BENG CHOO , ID: S0208812F								
Vehicle Reg. No.:	SGE7086Y	Date of Loss:	07/05/2018 00:00 - :59 [145 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 558153	Policy/Cover Note No.:	28870711MKC (Comprehensive) Coverage: 28/12/2017 - 27/12/2018						
Vehicle Reg. No. (Insured):	YP4961U	Policy No. (Claimant):							
		Excess:							
Repairer:	Monggo Motions (HQ) No.14 Pandan Loop Pandan Light, Industrial Park (Blk K), 128232 Holland - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 16/05/2018]								
Adj Asg. Remarks:	SJE - Disagree Please appoint LKK and contact James @ 9765 5556 / 6773 1020 Liability (Non- reporting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGE7086Y (558153)**
[YP4961U]

TP
NG BENG CHOO
May 7 2018 12:00AM
[Magma Pte Ltd]
Monggo Motions

Upload Documents			Upload Photos		Compose New Letter		View <div>View in Browser</div>	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
2	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
3	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
4	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
5	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
6	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
7	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
8	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
9	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
10	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
11	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
12	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
13	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
14	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
15	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
16	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
17	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
18	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
19	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
20	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
21	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
22	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
23	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
24	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
25	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
26	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
27	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
28	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
29	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
30	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
31	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
32	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
33	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
34	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
35	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		
36	17/05/18 10:43	General View			Load JPG	<input checked="" type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008812/R1Z4D3E2

Date: 21/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28870711MKC

Claimant Vehicle No : SGE7086Y

Insured Vehicle No : YP4961U

Date of Loss: 07/05/2018

Nature of Claim: TP

Claim No: 558153

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGE7086Y

Make & Model: NISSAN SUNNY, 1.5 EX (A)

Engine No: QG16402048

Reg. Date: 23/03/2006 (Man. Year: 2006)

Chassis No: JN1CFAN16Z0098238

Colour: Gold

Odometer: 166829 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Rear Tyre Size: 195/55 R16

Front Left Side: HIFLY 5 mm

Rear Left Side: HIFLY 5 mm

Front Right Side: HIFLY 5 mm

Rear Right Side: HIFLY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 16/05/2018 Inspected At:

Monggo Motions (HQ)
No.14 Pandan Loop Pandan Light,
Industrial Park (Blk K)
Singapore 128232

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500.00 -\$8,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 May 2018)
Parts: 143 NISSAN SUNNY 1.5 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGE7086Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >