

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG18008820/R1210342

Instruction:

Survivor:

Mehmen

Raru

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

15/5/18 3:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 2293D

Insured:

SLB 7903 X

at Workshop m/s

Kok Wang Car Grooming

Tel:

9183 9633

of

No. 1 Soon Lee St. # 08-40

Policy No:

MSD/VPCP/17-001233

Claim No:

MSC/V/18-000669

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/05/2018

CA / REV / REP. / REV 24 HRS

16/05/18

H.O.D. Endorsement:

Date/Time:

4:10pm 05/5/18

Person Contacted:

Mr. Kok

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

SLZ 2293D - V

SLB 7903 X - CS3/MSG117019073/SLB02

DOA: 31/10/17

Signature: *[Signature]*

REF: MS19

05216

ASSIGNMENT

From: Date: 16/05/18

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 2293D

at Workshop m/s Kok Wang Car Grooming
of No. 1, Soon Lee Street # 06-10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLZ 2293D

Yr Regn: 2018 / APR

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle HVB 1.5A c.c. 1496

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

003023

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GP 71208204

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

07/05/18

D.O.I.

16/05/18

Survey held at

Kok Wang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 10,000 - 11,000

* 4 days

17/5/18 Submit PRS Report

RECEIVED 16 MAY 2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018		15 May 2018 15:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: M201189993		
Main Claimant:	Lay Auto Leasing Pte Ltd, Co. Reg. No.: 201310521C		
Vehicle Reg. No.:	SLZ2293D	Date of Loss:	07/05/2018 17:00 - :59 [11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VPCP/17-001233 Coverage: 01/06/2017 - 31/05/2018
Vehicle Reg. No. (Insured):	SLB7903X	Policy No. (Claimant):	
		Excess:	
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2018]		
Adj Asg. Remarks:	TP Disagree on SJE - to appoint LKK Contact Person / No : Mr Liang / 91839633 Liability not clear - OI non Reporting		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18008820/R1z4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-05-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLB 7903X	Veh. Inspected	SLZ 2293D
Policy No.	MSD/VPCP/17-001233	Coverage (\$)	0.00
Claim No.	MSC/V/18-000669	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	15/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/05/2018	Inspection Date	
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2018 14:31
Date Of Accident	07/05/2018 17:45
Exact Location Of Accident	MOULMEIN ROAD JUNCTION TURNING INTO CTE (AMK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ2293D
Insured/Policyholder	
Name Of Registered Owner	LAY AUTO LEASING PTE LTD
Co Reg No	201310521C
Email Address	JOEL@LAYAUTO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-93874666
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE HYBRID
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5070522212-03
Cover Note Number	
Driver	
Name of Driver	ISKANDAR ZULKARNAIN BIN NAIM
NRIC No	S13498051
Date Of Birth	31/07/1959
Occupation	OUTDOOR
Date Of Driving Pass	05/10/1982
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82239861
Fax Number	
Contact Number	
Email Address	JOEL@LAYAUTO.COM

Address	APT BLK 171 WOODLANDS STREET 11 #03-41
Postcode	730171
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB7903X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EDDIE GOH
NRIC/Passport Number	
Contact Number	96649004
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I signalled right and turned right to the highway on from the second right lane, suddenly SLB79032 came from the left and bang against the rear left of my vehicle. SLB79032 was turning right for an only going straight lane. SLB79032 was at the wrong way.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018		15 May 2018 15:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: M201189993								
Main Claimant:	Lay Auto Leasing Pte Ltd , Co. Reg. No.: 201310521C								
Vehicle Reg. No.:	SLZ2293D	Date of Loss:	07/05/2018 17:00 - :59 [11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000669	Policy/Cover Note No.:	MSD/VPCP/17-001233 Coverage: 01/06/2017 - 31/05/2018						
Vehicle Reg. No. (Insured):	SLB7903X	Policy No. (Claimant):							
		Excess:							
Repairer:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre, 627603 Pioneer - Tel: 91839633								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 16/05/2018]								
Adj Asg. Remarks:	TP Disagree on SJE - to appoint LKK Contact Person / No : Mr Liang / 91839633 Liability not clear - OI non Reporting								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ2293D (MSC/V/18-000669)

[SLB7903X]






































TP




Lay Auto Leasing Pte Ltd

May 7 2018 5:00PM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Kok Wang Car Grooming - Pioneer

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/05/18 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/18 10:36	PRI Notice + TP Accdt Report	 Load PDF	
2	15/05/18 15:18	TP disagree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008820/R1Z4D3E2

Date: 21/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/PCP/17-001233
Claimant Vehicle No :	SLZ2293D	Insured Vehicle No :	SLB7903X
Date of Loss:	07/05/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000669

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2293D	Engine No:	LEB6550036
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71208204
Reg. Date:	26/04/2018 (Man. Year: 2018)	Odometer:	3063 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/05/2018	
Date Inspected:	16/05/2018 Inspected At:	Kok Wang Car Grooming - Pioneer (HQ) No. 1 Soon Lee Street, #06-40 Pioneer Centre Singapore 627603
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$11,000.00

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 21 May 2018)
Parts:	N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ2293D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.
Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >