

Surveyor: MBT

DOI: 14/5/18

Date / Time: 11/5/18

Registered in Merimen: 15/5/18

Pre-assign / CCU / FTE

SKD 2329m



Insured Vehicle No. : _____

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :SS _____ D.O.A : 11/5/18

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHA 3891 A



INSRS: _____
WSP: CHANN
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 14/5/18 Sent By: [Signature]

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with _____ Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____

Repair Cost: S\$ _____

Loss of Rental (LOR): S\$ _____ (_____ days)

Loss of Use (LOU): S\$ _____ (\$ x _____ days)

Loss of Income (LOI): S\$ _____ (\$ x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$ _____

Medical: S\$ _____

Disbursement: S\$ _____ (e.g. Tow/ Independent)

Legal Cost S\$ _____

1) Claim status: Normal/Reject/Private Settle

2) Report Format: _____

3) Survey fee: _____

Total: S\$ _____ **Global Sum S\$:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____

Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____

Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

Surveyor

REF: FWD

AP30/e

ASSIGNMENT

ROE Aug 2022

From: _____ Date: 14/05/2018

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 3891A

at Workshop m/s: Chunni m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="radio"/>	N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA 3891A Yr Regn: 2014 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai I40 c.c 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 252929 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU430012

C/No: KMHLB41UMEU056177

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

D.O.A. 11/05/2018 D.O.I. 14/05/2018

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body & N/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>FWD SKD 2329M</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

_____ S + RS. _____ SI

Photos _____

Others _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

TOTAL _____