

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC DUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	10	1			REAR FENDER INNER SHIELD LHS			Serviceable	0		25		0	Reviewing	
	11	1			REAR FENDER AIR VENT			Serviceable	0		25		0	Reviewing	
	12	1			SIDE MIRROR LHS			Broken	1130		25		847.5	Reviewing	
	13	1			SIDE MIRROR COVER LHS			Necessary	82		25		61.5	Reviewing	
	14	1			SIDE MIRROR LAMP LHS			Necessary	130		25		97.5	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO REMOVE & REPLACED DAMAGED BODY PARTS. REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS.	1200	0	0	Reviewing		
	2		RUST PROOFING.	100	0	0	Reviewing		
	3		TO CHECK & REPAIR WIRING SYSTEM.	60	0	0	Reviewing		
	4		REMOVE & REFIT FUEL TANK.	60	0	0	Reviewing		
	5		REMOVE REAR WINDSCREEN.	50	0	0	Reviewing		
	6		TO REMOVE & REPLACED LHF DOOR & LHR DOOR. TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR.	60	0	0	Reviewing		
	7		TO REMOVE & REPLACED DOOR WINDSCREEN.	50	0	0	Reviewing		
	8		R&R SPORT RIM & TRANSFER TYRE TO THE NEW RIM.	50	0	0	Reviewing		
	9		REMOVE REAR CHAIR.	50	0	0	Reviewing		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Issue Date		mm/dd/yyyy
Market Value	0		License Expiration Date		mm/dd/yyyy
			Address	Singapore	
			Address type	Personal Correspondence	v
			Gender	Unknown	v
			Marital status	Unknown	v
			Identification #	51289907E	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	9/11/18 4:16 PM	5950	5950	Open	Share	Clone
KUMAR Shalendra	5/14/18 9:37 AM	7409	7409	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
GRAB STATEMENT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 25, 2018
LKK Re-Inspection Photo 1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 16, 2018
Immediate Advice and Mandata.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 16, 2018
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 21, 2018
Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 21, 2018
TP ESTIMATE + SUPPLEMENTARY.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	May 21, 2018
TP GIA REPORT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	May 21, 2018
EMAIL FROM WORKSHOP SLK633Z TP GIA.msg	Forms / Claim Documents	Others	KUMAR Shalendra	May 14, 2018
Motor Cl.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	ANG Richard	May 14, 2018
Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	ANG Richard	May 14, 2018