

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0731/2018
DATE : 12-APR-2018

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

S(068811)

TEL : 63387288

FAX : 68804838/ 3382522

MS LINA EXT: 824

OWNER'S NAME : CHUA ANN LING (CAI ANLING)
ADDRESS : BLK 662A JURONG WEST STREET 64
#10-336
S(641662)
TELEPHONE NO : 9632 7997

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100481585
VEHICLE NO : SLF7897J
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A995782
CHASSIS NO : JF1SJGK85GG076657
MILEAGE : 1 KM
DATE IN : 12/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 12/04/2018

Print Date : 12/04/2018

Print Time : 18:31:57

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF7897J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION: AYE TWD MCE TIME: 0705HRS DATE: 03/04/2018		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, REAR PANEL, REAR TAIGATE AND FLOOR PAN	2800.00	? To confirm
4	ZZ/003	RESPRAY REAR BUMPER, REAR PANEL, REAR TAIGATE AND FLOOR PAN	2100.00	1680/-
5	ZZ/004	DISMENTLE/REFIX UNDERCARRIAGE REAR TO FACILITATE REPAIR	300.00	?
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	120/-
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50/-
8	ZZ/007	TRANSFER TAIGATE MECHANISM	nn 150.00	X
9	ZZ/008	WHEEL ALIGNMENT	200.00	?
10	ZZ/009	TO REMOVE/REFIX FUEL TANK	200.00	7
11	ZZ/011	TO CONDUCT REAR PROTECTANT COATING	500.00	250/-
12	ZZ/012	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	sn 300.00	X
13	ZZ/013	SUNDRIES	100.00	30/-
14	ZZ/10	TO CONDUCT REAR LIGHTING TEST	50.00	30/-
TOTAL LABOUR CHARGES			6950.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF7897J

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	FLOOR PAN R R CP	52129SG0019P	<i>N</i> 432.00	<i>?</i>		
2	SKIRT COMPL R END PANEL	52401SG0109P	288.00	<i>?</i>		
3	BUMPER FACE R	57704SG012	<i>CM</i> 540.00	<i>✓</i>		
4	BRKT CORNER R RH	57707SG060	<i>SN</i> 18.00	<i>X</i>		
5	BRKT CORNER R LH	57707SG070	<i>SN</i> 18.00	<i>X</i>		
6	BRKT SD R RH	57707SG080	<i>N</i> 14.40	<i>X</i>		
7	BRKT SD R LH	57707SG090	<i>N</i> 14.40	<i>X</i>		
8	BEAM COMPL R EU	(SUPP) 57711SG0219P	288.00	<i>?</i>		
9	PANEL CPL R/G	60809SG0509P	<i>N</i> 1072.80	<i>X</i>		
10	REFLEC AY RH	84281SC000	<i>SN</i> 20.40	<i>X</i>		
11	REFLEX AY LH	84281SC010	<i>SN</i> 20.40	<i>X</i>		
12	GARNISH AY RG, B	91111SG000	144.00	<i>?</i>		
13	PROTR R GARNISH	91713SG000	21.60	<i>?</i>		
14	PROTECTOR LWR SD	91713SG010	10.80	<i>?</i>		
15	ORNAMENT R	93033SG001	<i>N</i> 79.20	<i>✓</i>		
16	LETTER MK R XT	(SUPP) 93079SG010	<i>N</i> 64.80	<i>✓</i>		
17	LETTER MK R SUB	(SUPP) 93079SG030	<i>N</i> 64.80	<i>✓</i>		
18	TRIM PNL AY SKIRTR	94026SG000VH	36.00	<i>?</i>		
19	CARGO STEP PANEL S/S	E7710SG000	<i>B1</i> 460.00	<i>✓</i>		
SUB TOTAL			3607.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			721.52	0.00	0.00	0.00
GRAND TOTAL			2886.08	0.00	0.00	0.00
OVERALL TOTAL			2886.08			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLF7897J

TOTAL LABOUR CHARGES	6950.00
TOTAL SPARE PARTS CHARGES	2886.08
GRAND TOTAL	9836.08 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Withheld
Resurvey B4 paint
5-6 days
Henrich

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: