

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.05.2018

Time: 11:38:17

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305159788
REGN NO : SHA5120D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 19.04.2012
DATE/TIME IN : 14.05.2018 09:55
ACCIDENT DATE : 11.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0094-G SNTVC MIRROR ASSY-RH

1 L 260.40 20.00 208.32

X Repair

Front RH Fender X Repair

SUB-TOTAL : 208.32

JOB NATURE

0000 L PANEL BEATING

~~240.00~~ 100

0001 23-502 SPRAYPAINT ON AFFECTED AREA

~~400.00~~ 250

SUB-TOTAL : 640.00

TOTAL : 848.32

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Ka hi (LKK)
14/5/18 1120 hrs.
2 Rep.
45
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: