


Surveyor:

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : 0871 001

Claim No. : _____

Name of Insured : _____

Policy No. :

Insured Tel No. : HP: ,

Make / Model :

Excess Sec II :SS D.O.A: 12/5/18

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability :	%	Final ? Yes / No
1. General Liability		
2. Professional Liability		
3. Directors and Officers Liability		
4. Employment Practices Liability		
5. Cyber Liability		
6. Umbrella Liability		
7. Other		

SHC 32738



INSRS:
WSP: *WSP byang*
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

[illegible]

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ALG
LKK

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508989 24 Serangoon Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 6 Defu Avenue 1 Singapore 539537
321 Ubi Road Singapore 368666

Date/Time: 14.05.2018 09:08

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305159695

STOMER

COMFORT TRANSPORTATION PTE LTD
VMS 7010045
STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755

(R) (O)
(P)

COUNT CARD NO.

REGN NO:

SHC3273Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN 12.05.2018 19:55

YR OF MANU

03.01.2014

TARGET DATE

CHASSIS CODE

KMHLB41UMDU043468

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.05.2018
NATURE: 3P 12.05.18

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC3273Z
LIMTS

Vehicle No.: SHC3273Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard