

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

17/5

WSP

SHC32732 - (13/18/14/15/16/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/32/33/34/35/36/37/38/39/40/41/42/43/44/45/46/47/48/49/50/51/52/53/54/55/56/57/58/59/60/61/62/63/64/65/66/67/68/69/70/71/72/73/74/75/76/77/78/79/80/81/82/83/84/85/86/87/88/89/90/91/92/93/94/95/96/97/98/99/100/101/102/103/104/105/106/107/108/109/110/111/112/113/114/115/116/117/118/119/120/121/122/123/124/125/126/127/128/129/130/131/132/133/134/135/136/137/138/139/140/141/142/143/144/145/146/147/148/149/150/151/152/153/154/155/156/157/158/159/160/161/162/163/164/165/166/167/168/169/170/171/172/173/174/175/176/177/178/179/180/181/182/183/184/185/186/187/188/189/190/191/192/193/194/195/196/197/198/199/200/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220/221/222/223/224/225/226/227/228/229/230/231/232/233/234/235/236/237/238/239/240/241/242/243/244/245/246/247/248/249/250/251/252/253/254/255/256/257/258/259/260/261/262/263/264/265/266/267/268/269/270/271/272/273/274/275/276/277/278/279/280/281/282/283/284/285/286/287/288/289/290/291/292/293/294/295/296/297/298/299/300/301/302/303/304/305/306/307/308/309/310/311/312/313/314/315/316/317/318/319/320/321/322/323/324/325/326/327/328/329/330/331/332/333/334/335/336/337/338/339/340/341/342/343/344/345/346/347/348/349/350/351/352/353/354/355/356/357/358/359/360/361/362/363/364/365/366/367/368/369/370/371/372/373/374/375/376/377/378/379/380/381/382/383/384/385/386/387/388/389/390/391/392/393/394/395/396/397/398/399/400/401/402/403/404/405/406/407/408/409/410/411/412/413/414/415/416/417/418/419/420/421/422/423/424/425/426/427/428/429/430/431/432/433/434/435/436/437/438/439/440/441/442/443/444/445/446/447/448/449/450/451/452/453/454/455/456/457/458/459/460/461/462/463/464/465/466/467/468/469/470/471/472/473/474/475/476/477/478/479/480/481/482/483/484/485/486/487/488/489/490/491/492/493/494/495/496/497/498/499/500/501/502/503/504/505/506/507/508/509/510/511/512/513/514/515/516/517/518/519/520/521/522/523/524/525/526/527/528/529/530/531/532/533/534/535/536/537/538/539/540/541/542/543/544/545/546/547/548/549/550/551/552/553/554/555/556/557/558/559/560/561/562/563/564/565/566/567/568/569/570/571/572/573/574/575/576/577/578/579/580/581/582/583/584/585/586/587/588/589/590/591/592/593/594/595/596/597/598/599/600/601/602/603/604/605/606/607/608/609/610/611/612/613/614/615/616/617/618/619/620/621/622/623/624/625/626/627/628/629/630/631/632/633/634/635/636/637/638/639/640/641/642/643/644/645/646/647/648/649/650/651/652/653/654/655/656/657/658/659/660/661/662/663/664/665/666/667/668/669/670/671/672/673/674/675/676/677/678/679/680/681/682/683/684/685/686/687/688/689/690/691/692/693/694/695/696/697/698/699/700/701/702/703/704/705/706/707/708/709/710/711/712/713/714/715/716/717/718/719/720/721/722/723/724/725/726/727/728/729/730/731/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000/1001/1002/1003/1004/1005/1006/1007/1008/1009/1010/1011/1012/1013/1014/1015/1016/1017/1018/1019/1020/1021/1022/1023/1024/1025/1026/1027/1028/1029/1030/1031/1032/1033/1034/1035/1036/1037/1038/1039/1040/1041/1042/1043/1044/1045/1046/1047/1048/1049/1050/1051/1052/1053/1054/1055/1056/1057/1058/1059/1060/1061/1062/1063/1064/1065/1066/1067/1068/1069/1070/1071/1072/1073/1074/1075/1076/1077/1078/1079/1080/1081/1082/1083/1084/1085/1086/1087/1088/1089/1090/1091/1092/1093/1094/1095/1096/1097/1098/1099/1100/1101/1102/1103/1104/1105/1106/1107/1108/1109/1110/1111/1112/1113/1114/1115/1116/1117/1118/1119/1120/1121/1122/1123/1124/1125/1126/1127/1128/1129/1130/1131/1132/1133/1134/1135/1136/1137/1138/1139/1140/1141/1142/1143/1144/1145/1146/1147/1148/1149/1150/1151/1152/1153/1154/1155/1156/1157/1158/1159/1160/1161/1162/1163/1164/1165/1166/1167/1168/1169/1170/1171/1172/1173/1174/1175/1176/1177/1178/1179/1180/1181/1182/1183/1184/1185/1186/1187/1188/1189/1190/1191/1192/1193/1194/1195/1196/1197/1198/1199/1200/1201/1202/1203/1204/1205/1206/1207/1208/1209/1210/1211/1212/1213/1214/1215/1216/1217/1218/1219/1220/1221/1222/1223/1224/1225/1226/1227/1228/1229/1230/1231/1232/1233/1234/1235/1236/1237/1238/1239/1240/1241/1242/1243/1244/1245/1246/1247/1248/1249/1250/1251/1252/1253/1254/1255/1256/1257/1258/1259/1260/1261/1262/1263/1264/1265/1266/1267/1268/1269/1270/1271/1272/1273/1274/1275/1276/1277/1278/1279/1280/1281/1282/1283/1284/1285/1286/1287/1288/1289/1290/1291/1292/1293/1294/1295/1296/1297/1298/1299/1300/1301/1302/1303/1304/1305/1306/1307/1308/1309/1310/1311/1312/1313/1314/1315/1316/1317/1318/1319/1320/1321/1322/1323/1324/1325/1326/1327/1328/1329/1330/1331/1332/1333/1334/1335/1336/1337/1338/1339/1340/1341/1342/1343/1344/1345/1346/1347/1348/1349/1350/1351/1352/1353/1354/1355/1356/1357/1358/1359/1360/1361/1362/1363/1364/1365/1366/1367/1368/1369/1370/1371/1372/1373/1374/1375/1376/1377/1378/1379/1380/1381/1382/1383/1384/1385/1386/1387/1388/1389/1390/1391/1392/1393/1394/1395/1396/1397/1398/1399/1400/1401/1402/1403/1404/1405/1406/1407/1408/1409/1410/1411/1412/1413/1414/1415/1416/1417/1418/1419/1420/1421/1422/1423/1424/1425/1426/1427/1428/1429/1430/1431/1432/1433/1434/1435/1436/1437/1438/1439/1440/1441/1442/1443/1444/1445/1446/1447/1448/1449/1450/1451/1452/1453/1454/1455/1456/1457/1458/1459/1460/1461/1462/1463/1464/1465/1466/1467/1468/1469/1470/1471/1472/1473/1474/1475/1476/1477/1478/1479/1480/1481/1482/1483/1484/1485/1486/1487/1488/1489/1490/1491/1492/1493/1494/1495/1496/1497/1498/1499/1500/1501/1502/1503/1504/1505/1506/1507/1508/1509/1510/1511/1512/1513/1514/1515/1516/1517/1518/1519/1520/1521/1522/1523/1524/1525/1526/1527/1528/1529/1530/1531/1532/1533/1534/1535/1536/1537/1538/1539/1540/1541/1542/1543/1544/1545/1546/1547/1548/1549/1550/1551/1552/1553/1554/1555/1556/1557/1558/1559/1560/1561/1562/1563/1564/1565/1566/1567/1568/1569/1570/1571/1572/1573/1574/1575/1576/1577/1578/1579/1580/1581/1582/1583/1584/1585/1586/1587/1588/1589/1590/1591/1592/1593/1594/1595/1596/1597/1598/1599/1600/1601/1602/1603/1604/1605/1606/1607/1608/1609/1610/1611/1612/1613/1614/1615/1616/1617/1618/1619/1620/1621/1622/1623/1624/1625/1626/1627/1628/1629/1630/1631/1632/1633/1634/1635/1636/1637/1638/1639/1640/1641/1642/1643/1644/1645/1646/1647/1648/1649/1650/1651/1652/1653/1654/1655/1656/1657/1658/1659/1660/1661/1662/1663/1664/1665/1666/1667/1668/1669/1670/1671/1672/1673/1674/1675/1676/1677/1678/1679/1680/1681/1682/1683/1684/1685/1686/1687/1688/1689/1690/1691/1692/1693/1694/1695/1696/1697/1698/1699/1700/1701/1702/1703/1704/1705/1706/1707/1708/1709/1710/1711/1712/1713/1714/1715/1716/1717/1718/1719/1720/1721/1722/1723/1724/1725/1726/1727/1728/1729/1730/1731/1732/1733/1734/1735/1736/1737/1738/1739/1740/1741/1742/1743/1744/1745/1746/1747/1748/1749/1750/1751/1752/1753/1754/1755/1756/1757/1758/1759/1760/1761/1762/1763/1764/1765/1766/1767/1768/1769/1770/1771/1772/1773/1774/1775/1776/1777/1778/1779/1780/1781/1782/1783/1784/1785/1786/1787/1788/1789/1790/1791/1792/1793/1794/1795/1796/1797/1798/1799/1800/1801/1802/1803/1804/1805/1806/1807/1808/1809/1810/1811/1812/1813/1814/1815/1816/1817/1818/1819/1820/1821/1822/1823/1824/1825/1826/1827/1828/1829/1830/1831/1832/1833/1834/1835/1836/1837/1838/1839/1840/1841/1842/1843/1844/1845/1846/1847/1848/1849/1850/1851/1852/1853/1854/1855/1856/1857/1858/1859/1860/1861/1862/1863/1864/1865/1866/1867/1868/1869/1870/1871/1872/1873/1874/1875/1876/1877/1878/1879/1880/1881/1882/1883/1884/1885/1886/1887/1888/1889/1890/1891/1892/1893/1894/1895/1896/1897/1898/1899/1900/1901/1902/1903/1904/1905/1906/1907/1908/1909/1910/1911/1912/1913/1914/1915/1916/1917/1918/1919/1920/1921/1922/1923/1924/1925/1926/1927/1928/1929/1930/1931/1932/1933/1934/1935/1936/1937/1938/1939/1940/1941/1942/1943/1944/1945/1946/1947/1948/1949/1950/1951/1952/1953/1954/1955/1956/1957/1958/1959/1960/1961/1962/1963/1964/1965/1966/1967/1968/1969/1970/1971/1972/1973/1974/1975/1976/1977/1978/1979/1980/1981/1982/1983/1984/1985/1986/1987/1988/1989/1990/1991/1992/1993/1994/1995/1996/1997/1998/1999/2000/2001/2002/2003/2004/2005/2006/2007/2008/2009/2010/2011/2012/2013/2014/2015/2016/2017/2018/2019/2020/2021/2022/2023/2024/2025/2026/2027/2028/2029/2030/2031/2032/2033/2034/2035/2036/2037/2038/2039/2040/2041/2042/2043/2044/2045/2046/2047/2048/2049/2050/2051/2052/2053/2054/2055/2056/2057/2058/2059/2060/2061/2062/2063/2064/2065/2066/2067/2068/2069/2070/2071/2072/2073/2074/2075/2076/2077/2078/2079/2080/2081/2082/2083/2084/2085/2086/2087/2088/2089/2090/2091/2092/2093/2094/2095/2096/2097/2098/2099/2100/2101/2102/2103/2104/2105/2106/2107/2108/2109/2110/2111/2112/2113/2114/2115/2116/2117/2118/2119/2120/2121/2122/2123/2124/2125/2126/2127/2128/2129/2130/2131/2132/2133/2134/2135/2136/2137/2138/2139/2140/2141/2142/2143/2144/2145/2146/2147/2148/2149/2150/2151/2152/2153/2154/2155/2156/2157/2158/2159/2160/2161/2162/2163/2164/2165/2166/2167/2168/2169/2170/2171/2172/2173/2174/2175/2176/2177/2178/2179/2180/2181/2182/2183/2184/2185/2186/2187/2188/2189/2190/2191/2192/2193/2194/2195/2196/2197/2198/2199/2200/2201/2202/2203/2204/2205/2206/2207/2208/2209/2210/2211/2212/2213/2214/2215/2216/2217/2218/2219/2220/2221/2222/2223/2224/2225/2226/2227/2228/2229/2230/2231/2232/2233/2234/2235/2236/2237/2238/2239/2240/2241/2242/2243/2244/2245/2246/2247/2248/2249/2250/2251/2252/2253/2254/2255/2256/2257/2258/2259/2260/2261/2262/2263/2264/2265/2266/2267/2268/2269/2270/2271/2272/2273/2274/2275/2276/2277/2278/2279/2280/2281/2282/2283/2284/2285/2286/2287/2288/2289/2290/2291/2292/2293/2294/2295/2296/2297/2298/2299/2300/2301/2302/2303/2304/2305/2306/2307/2308/2309/2310/2311/2312/2313/2314/2315/2316/2317/2318/2319/2320/2321/2322/2323/2324/2325/2326/2327/2328/2329/2330/2331/2332/23



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/LCR18008864/K1wa3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 15-05-2018	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLK 662P	Veh. Inspected	SHC 3273Z
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	15/05/2018
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	12/05/2018	Inspection Date	14/05/2018
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ALG
LKK

ComfortDelGro Engineering Pte Ltd

205 Bras Basah Road, Singapore 179701
 Mailing: + 65 6385 6267 Facsimile: + 65 6383 9788
 Workshops:
 28 Loyang Drive Singapore 505085 24 Simulo Loop Singapore 728156
 382 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way, Singapore 728791
 45 Pandan Road Singapore 526196 6 Delta Avenue 3, Singapore 529527
 721 Ponggol Road Singapore 605009

Date/Time: 14.05.2018 09:08 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO:305159695

STOMER		REGN NO. SHC3273Z	MILEAGE
COMFORT TRANSPORTATION PTE LTD		MAKE HYUNDAI	FUEL
7010045		MODEL I-40	E.....1/2.....F
STOMER NO. 383 SIN MING DRIVE		YR OF MANU 03.01.2014	DATE/TIME IN 12.05.2018 19:55
DRESS Singapore SINGAPORE 575717		CHASSIS CODE RMHLE41UMDU043468	TARGET DATE
65508755			COMPLETION DATE/TIME:
(R) (Q)			
(P)			
ICOUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 12.05.2018
 NATURE: 3P 12.05.18

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC3273Z LIMITS

Vehicle No.: SHC3273Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305159695
Date : 16/05/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN ANG


Fax :


Vehicle Reg No. : SHC3273Z Date of Accident : 12-May-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: AIG ASIA --- SLK 662P
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges
 - Total for Part-By-Part Repair Cost
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,400.00
Final Lumpsum Repair cost \$1,400.00
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 17/5/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	*****			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 3273Z

MAKE

MODEL : HYUNDAI i40

Arg Asia - 4sum • TS
 DATE 14/5/2018 10:52

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Bracket (LH)			\$ 24.60
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH)			\$ 169.80
	Front Fender Retainer			\$ 9.20
	Frt Wheel Hub Cap, LH			\$ 150.70
	SUB TOTAL			\$ 1,558.00
	LESS 20%			\$ 311.60
	DISCOUNTED TOTAL			\$ 1,246.40
	Labour Charge			300
	Panel Beating			\$ 500.00
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X 2
	TOTAL LABOUR			\$ 1,090.00
	ESTIMATE TOTAL			\$ 2,336.40

Kalvin
 14/5/18 11:00h
 2 days
 4/5
 After Repair p/c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be authorised and is subject to approval from insurance Company

Acknowledged:
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE*

VEHICLE NO : SHC 3273Z

MAKE

MODEL : HYUNDAI i40

Aig Asia - Usun
DATE 14/5/2018 10:52

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) ?			\$ 169.80
	Front Fender Retainer ?			\$ 9.20
	Frt Wheel Hub Cap, LH ✓			\$ 150.70
	SUB TOTAL			\$ 1,558.00
	LESS 20%			\$ 311.60
	DISCOUNTED TOTAL			\$ 1,246.40
	Labour Charge			300
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00 360
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,090.00
	ESTIMATE TOTAL			\$ 2,336.40
<p> <i>Kalvin</i> <i>14/5/18 11:00h</i> <i>2 days</i> <i>Ys</i> <i>After Repair pld</i> </p> <div data-bbox="805 1538 1321 1960" data-label="Text"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary claims must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Our Ref : T 0518 / SHC3273Z /CL(st)
Your Ref:
Date : 30-May-18

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Buliding
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC3273Z YOUR INSURED SLK 662P
AND OTHER ON 12.05.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHC3273Z** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SLK 662P** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,498.00
2	3.5 days Loss of Rental @ \$ 117.28 per day	\$ 410.48
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
Sub Total :		\$ 1,915.97

HIRER'S CLAIM

7	3.5 days Loss of Income @ \$ 80.00 per days	\$ 280.00
Total Claims :		\$ 2,195.97

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
b) LTA search slip/s of : SLK 662P
c) GIA / Police report/s of : SHC3273Z
d) Letter of authority from owner / hirer / operator
(X) Photograph/s of Accident Scene () Certificate of Insurance
() Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
CDGE Taxi Claims Dept
59 Loyang Drive 4th Floor
Singapore 508969
Mainline +65 6383 6280
Facsimile +65 6280 9755
www.cdge.com.sg

Company Registration No: 109506240W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

A member of

COMFORTDELGRO



Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Friday, 18 May, 2018 12:24 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: ACCIDENT INVOLVING SLK 662P AND SHC 3273Z ON 12/05/2018

Our Ref: CC3/LCR18008864/K1wa3

18 May 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 662P AND SHC 3273Z ON 12/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****I 40 SHC3273Z , SLK662P
NORTH BRIDGE RD TWDS SOUTH BRIDGE RD****ON 12-May-18 16:25****I / We****BOOI KIM SWEE****(Hirer) NRIC No.: S1795869J****and/or****(Relief) NRIC No.:****Taxi Number:****SHC3273Z**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date**13-May-2018****Name of Hirer****BOOI KIM SWEE****Hirer NRIC****S1795869J****Signature :****Address****401 SERANGOON AVENUE 1 #13-11
550401****Contact No.****97928366**

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$ 2,000.00 (Global Sum) for vehicle no. SHC 3273Z that was damaged pursuant to the accident which occurred on 12/05/2018 (date) along BUGIS JUNCTION (location) involving vehicle no/s SLK 662P.

This is pursuant to the inspection conducted on 14/05/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHC 3273Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 3273Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of 05 JUN 2018 (month) 20 (year)

Awk

Signed by appointed surveyor


CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:-
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

GST REG. NO. M2-8921817-3

TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SKENTON WAY, CHARTIS BUILD
SINGAPORE 079120

CONTACT NO: 64193000 3225094

VEHICLE NO

SHC3273Z

MAKE

HYUNDAI

MODEL

I-40

DATE OF REG

03.01.2014

CHASSIS CODE

KMHLB41UMDU043468

INV. NO/DATE

91372985 17.05.2018

JOB NO.

305159695

ODOMETER READING

JOB TYPE

Description : 3P 12.05.18

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	1,400.00
Add GST @ 7.00 %	98.00
Total Invoice amount	1,498.00

Issued by : KATHKINETAN 17.05.2018 11:59:33
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE BORROWED AND TESTED AT OWNERS' RISK.
CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT I.E. AFTER 30 DAYS FROM THE INVOICE FOR THE PERIOD OF DEFAULT.
PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT18050296

Date: 17 May 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	12/05/2018 @ 16:25 hrs
ALONG	BRIDGE RD TWDS SOUTH BRIDGE RDNORTH
INVOLVING	SLK662P

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3273Z** (the "Taxi"). The Taxi was hired to **BOOI KIM SWEE IC NO S1795869J** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Long

MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING					MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO			5	1	8	3	8		FROM	TO
39	0600	2100	8/5/18	Gunny	5	1	8	3	8	5	0545	2130
23	0830	1820	9/5/18	Gunny	5	1	8	5	5	2	0530	2015
3	0830	1550	10/5/18	Gunny	5	1	8	8	7	9	0600	2000
17	0630	1800	11/5/18	Gunny	5	1	9	2	6	1	0545	2145
			12/5/18	Gunny	5	1	9	6	3	2	0800	2000
11	0630	2000	12/5	Accident							1955	1300
5	0630	2020	15/5	repair								
20	0630	2120										
5	0800	1700										
7	0800	1400										
77	0600	2030										

SHC 32737

LY

JA

Cut

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLK662P	12 May 2018 / 16:25:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)

suc32732

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018 Edit Reg		14 May 2018 00:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K	
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	SHC3273Z	Date of Loss: 12/05/2018 16:00 - :59 [52 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1280159388SG	Policy/Cover Note No.: 0999994765
Vehicle Reg. No. (Insured):	SLK662P	Policy No. (Claimant): MCOM0015
		Excess:
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]	
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 24/05/2018]	


ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC3273Z (1280159388SG)**
[SLK662P]
TP
COMFORT TRANSPORTATION PTE LTD
May 12 2018 4:00PM
[LCRF PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit
Photos/Images			3 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
2	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
3	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
4	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
5	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
6	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
7	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
8	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
9	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
10	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
11	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
12	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
13	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
14	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
15	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
16	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
17	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
18	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
19	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
20	16/05/18 08:11	General View	1	Load JPG <input checked="" type="checkbox"/>
21	16/05/18 08:38	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
22	16/05/18 08:38	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
23	16/05/18 08:38	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	16/05/18 08:10	TP ESTIMATE - MARKED	1	Load PDF
2	16/05/18 08:10	TP GIA REPORT	1	Load PDF
3	18/05/18 12:24	Email letter to OI ACCIDENT INVOLVING SLK 662P AND SHC 3273Z ON 12.05.2018	1	Load PDF
4	11/06/18 08:45	WORKSHOP INVOICE	1	Load PDF
5	11/06/18 08:45	AUTHORISATION TO ACT FORM	1	Load PDF
6	11/06/18 08:45	Release Voucher	1	Load PDF
7	11/06/18 08:45	RENTAL RECEIPT	1	Load PDF
8	11/06/18 08:45	LTA SEARCH	1	Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail Print	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/18 12:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

TEAM _____

Vehicle No:	SLK662P (Insd veh)	Model:	HYUNDAI I40 1.7 D CRDI (A)
	SHC3273Z (TP veh)		
Date of Accident:	12/05/2018		

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	: \$	2,000.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

11 Jun
2018
Date

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_doclt... 11/6/2018

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18008864/K1WA3Q2

Date: 11/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994765
Claimant Vehicle No : SHC3273Z **Insured Vehicle No :** SLK662P
 Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: 1280159388SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3273Z**
 Make & Model: HYUNDAI I40, 1.7 D CRDi (A) Engine No: D4FDDU377403
 Reg. Date: 03/01/2014 (Man. Year: 2013) Chassis No: KMHLB41UMDU043468
 Colour: Blue Odometer: 519632 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,246.40	1,065.60	180.80	14.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	680.00	410.00	37.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,336.40	1,745.60	590.80	25.29
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,336.40	1,400.00	936.40	40.08
+ GST 7.00/7.00% (S\$)	163.55	98.00	65.55	40.08
Nett Amount (S\$)	2,499.95	1,498.00	1,001.95	40.08
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$117.28/day) (S\$)		351.84		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,007.33		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment: 14/05/2018

Date Inspected: 14/05/2018 Inspected At: ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	562.30 FL	*562.30 FL
2	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	22.40 FL	*- FL
3	1		*FROMT BUMPER BRACKET (LH)	Serviceable	24.60 FL	*- FL
4	1		*FRONT FENDER (LH)	Dented	619.00 FL	*619.00 FL
5	1		*FRONT FENDER SHIELD (LH)	Serviceable	169.80 FL	*- FL
6	1		*FRONT FENDER RETAINER	Serviceable	9.20 FL	*- FL
7	1		*FRT WHEEL HUB CAP ,LH	Grazed	150.70 FL	*150.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,558.00	1,332.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	311.60	266.40
Total Parts (\$\$)	1,246.40	1,065.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	560.00	300.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	TUFF KOTE	New	50.00	20.00
4	FRT WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,090.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >