

ASS. REC. BY:

REF:

01FC1180032862/NC

Special Instruction:

SUBJECT:

ASSIGNMENT (Office)

From (Person):

Karen Pan

of

FBI

Date/Time:

7/5/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB6366A

Insured:

at Workshop m/s:

Tel:

of

Policy No:

Claim No:

018003281MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/4/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SHB6366A-X

From: Bryan Ang (LKKAuto)
Sent: Monday, 7 May 2018 9:46 AM
To: Naz (LKKAuto)
Cc: Karen Tan; assignments
Subject: FW: URGENT! SHB6366A - Fire on 25/04/18 - MSFCI REF: D18003281MFSH

Dear Karen

Acknowledge your request as per below email. My colleague Naz will carry out the investigations and he will revert in due course.

Dear Naz

Please follow up.

Best Regards,
Bryan Ang
LKK Auto Consultants Pte Ltd
phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan [<mailto:karentan@msfirstcapital.com.sg>]
Sent: Monday, 7 May 2018 9:40 AM
To: SUR <sur@lkkauto.com>
Subject: URGENT! SHB6366A - Fire on 25/04/18 - MSFCI REF: D18003281MFSH

Dear Sirs/Madam,
The above taxi caught fire on 25/04/2018.

Kindly assist to investigate into the matter.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Jumani @ 6214 8315 if you need any other information.

A copy of our driver's report is attached.

Best Regards,

Karen Tan
Motor Claims Dept.
MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3582 | Fax
No. : 6507 3849 | Company Regn. No. 195000106C
A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIAs Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/04/2018 14:29
 Date Of Accident 25/04/2018 08:55
 Exact Location Of Accident BOUNDARY ROAD
 Country/State of Loss SINGAPORE

- Jurong West:
 - Sent at 8 plus:

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB6366A

- Hoang Ave 8, for job

Insured/Policyholder

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No 12 days scheme
 Alternative Phone No 360 per day
 OFFICE-65508768

- Directly in front of him
 - After tm right to
 Yee.
 - Stop @ bus stop

Vehicle Particulars

Manufacturer HYUNDAI
 Model I40

- left right, left alarm
 - took extinguisher

Exact Purpose for which vehicle was being used at time of accident - no problem - check engine oil, coolant

Are you claiming under your own insurance policy for repair to your vehicle? NO

- could open bonnet
 - the came out from
 sides.

If No, Please state action to be taken REPORTING ONLY

Vehicle Category TAXI

- go near 4 spray

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number

- press by called SCDF
 - 15 min SCDF came
 - police came by SCDF
 - police took 2 put out
 fire but no avail

Driver

Name of Driver DHANABALAN S/O A GOPALKRISHNAN
 NRIC No S8945259J
 Date Of Birth 08/11/1969
 Occupation OUTDOOR
 Date Of Driving Pass 12/12/2016
 Driving Experience 1 YEAR AND 4 MONTHS
 Gender MALE
 Mobile Number
 Fax Number
 Contact Number
 Email Address NOEMAIL

- 30 min 2 put out the
 - didn't see how they put
 - extinguisher not working properly
 - out fire
 - a guy from comfort investigation
 - 1 hour was there
 - police asked gas
 - SCDF problem must
 - made police report to a guy
 - comfort called 4 tow truck
 - the plus tow truck

Address	426 02-334 JURONG WEST AVENUE 1
Postcode	640426
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PASIR RIS NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	FIRE
Vehicle Category	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report -
G/20180425/2043

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PT
CO. REG. NO. 1997019218

Policyholder's Signature
Date & Time:

G. Shahid 25/4/18
Driver's Signature
(If driver is not the policyholder)
Date & Time:

R. R. Moorthy
CSO 25/4/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

G:\BAC\Sketch\Bland\Bland_V0



**SINGAPORE
POLICE FORCE**



G/20180425/2043

1 of 2

POLICE REPORT (NP299)

Report No. G/20180425/2043

Police Station Of Origin
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Date/Time Report Made 25/04/2018 12:11	Vide Report No. F/20180425/0086	Station Diary No. 39
Name Of Informant DHANABALAN S/O A GOPALKRISHNAN	Address 1 LORONG 23 GEYLANG SINGAPORE 388352	
ID Type / ID No. NRIC NO / S6945259J	Contact No. Home/Office	Mobile 86228841
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Taxi driver	Sex Male	Age 48
	Date of Birth 08/11/1969	Race Indian
Institution/School Name	Language English	
Date/Time Of Incident 25/04/2018 08:55	Location Of Incident BOUNDARY ROAD SINGAPORE Near to Traffic junction along Boundary Road off Yio Chu Kang Rd	


Brief details.

On 25/04/2018 at about 8.55am, I was driving my vehicle, SHB6366A, along Boundary Rd approaching the traffic junction off Yio Chu Kang Rd when I saw thick smoke emerging out from my front bonnet. As such, I decided to turn right at the junction onto Yio Chu Kang Rd to look for an appropriate spot to stop my vehicle.

I then stopped my vehicle at the bus stop in front of Blk 214, Serangoon Ave 4. Immediately, I went to my vehicle's boot to retrieve the fire extinguisher and proceeded to the front of my vehicle to try to put out the

Signature Of Officer Recording The Report: G / Staff Sgt ANG ZHILONG, JEFFERY	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/04/2018 12:11
Officer In-Charge Of Case: F Division IO Koh Yeow Sin Contact No.: 62180000	Classification Of Case:

Authentication Stamp



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO REG. NO 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



ance needs, buy online at

Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0030 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEH: S66550290 / GST Reg. No.: M400037735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : W-17 61256 4-18 Vehicle Registration No: SMS 6366 A
Name (as shown in NRIC) : Dharmabalan NRIC/FIN/Passport No : _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 25/4/18 Time of Accident : 08:30
Place of Accident : Roundway rd
Insurance Company: First Capital Insurance Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Video captured by car camera

Policyholder / Driver's Signature
Date: 25/4/18

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHB6366A
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	D4FDEU475221
Chassis No.:	KMHLB41UMDU042111
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,490.00
Original Registration Date:	31 Oct 2013
First Registration Date:	31 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$10,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2021
PARF Rebate Amount:	\$8,242.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$26,932.00
Total Rebate Amount:	\$35,174.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Apr 2018

OK

Report ID : EPTSD003
DATE : 25.04.2018
TIME : 15:29:23

Orifont Transportation PL
Vehicle M/V for Fleet Safety Division
AS AT 31.03.2018

DESA ID : CPTSD003
PAGE : 1

Co. Code : CPTA
Licence Pl. No : B08E366A
Old Asset No :
Veh. Model : Hyundai i40
Reg. Date : 31.10.2013
Cap. Date : 31.10.2013
Accident Date : 25.04.2018
Veh. Age : 054

Admin. no	SN. NO	Ins. Unit	Per. Mch. Exp	Sal. Dep. Value	Asset Description 1	Cost	Op. Act. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated page Refund
10030557	0	036	277.77	9,995.72	B08E366A H40 31.10.2013 BASIC DUST N AIRBOX	25,000.00	14,168.10	833.20	14,999.10	10,000.60	1.00
10030557	1	036	41.09	1,479.24	B08E366A H40 31.10.2013 DUST DUTY 205X4018430	3,697.46	2,095.48	123.26	2,218.72	1,479.14	0.00
10030557	2	036	68.84	1,768.24	B08E366A H40 31.10.2013 AC 12VDC/418-590-CD057400	10,980.00	2,481.06	146.54	2,627.60	8,352.40	6,524.00
10030557	3	036	681.38	24,525.08	B08E366A H40 31.10.2013 ODE H08	91,324.00	34,750.26	2,044.14	36,794.40	26,529.60	0.00
10030557	4	000	0.00	0.00	B08E366A H40 31.10.2013 ODE H08	0.00	0.00	0.00	0.00	0.00	0.00
10030557	5	036	0.00	0.00	B08E366A H40 31.10.2013 AIR CONDIT/1000	0.00	0.00	0.00	0.00	0.00	0.00
10030557	6	036	0.00	0.00	B08E366A H40 31.10.2013 PRINTER EXCITON THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10030557	7	036	0.00	0.00	B08E366A H40 31.10.2013 TAXIETER DUMITAX FI	0.00	0.00	0.00	0.00	0.00	0.00
10030557	8	036	1.56	56.16	B08E366A H40 31.10.2013 VEH REG FEE	146.00	79.34	4.67	84.01	56.99	0.00
			1,050.84	37,923.04		101,151.86	53,582.22	3,133.91	56,734.13	44,417.73	

COS
Vehicle
681.38
369.26
1,050.64
37,923.04

Vehicle : Minimum 7/4 & COS
Vehicle : Minimum 7/4, With COS
Toolmaster

1,077.77
3,133.91
0.00

15,935.73
56,734.13
0.00

13,880.13
44,417.73
0.00

Team: ARC Repair OD(CLSO)1

JOB CARD Sales Order:

JC NO305145795

CUSTOMER	REGN NO SHB6366A	MILEAGE
VMS COMFORT TRANSPORTATION PTE LTD	MAKE HYUNDAI	FUEL E 1/2 F
CUSTOMER NO 7010045	MODEL I-40	DATE/TIME IN 25.04.2018 08:55
ADDRESS 383 SIN MING DRIVE	YR OF MANU 31.10.2013	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMDU042111	COMPLETION DATE/TIME
TEL (R) 65508755 (O)		
(P)		
SCOUNT CARD NO.		

(BURN)

JOB DESCRIPTION

Accident Date: 25.04.2018

NATURE: OD 25.04.18

S/NO LABOR CODE DESCRIPTION

**CASE HOLD FOR
INVESTIGATION,
KIV REPAIR!!**

- Police report
- estimate
- book value

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No: SHB6366A JU

Vehicle No: SHB6366A

Signature of Service Advisor

Signature/Data

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6366A

DATE 27/4/2018 16:19

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,526.00
	Bonnet Rubber (LH)			\$ 19.80
	Bonnet Rubber (RH)			\$ 19.80
	Bonnet Hinge (LH/RH)	\$	91.30	\$ 182.60
	Bonnet Moulding			\$ 126.25
	Bonnet Lock			\$ 50.90
	Bonnet Absorber	\$	73.90	\$ 147.80
	Bonnet Insulator			\$ 243.00
	Bonnet Seal			\$ 38.30
	Bonnet Insulator Clips			\$ 8.40
	Bonnet Cable			\$ 47.50
	Radiator Grille			\$ 294.35
	Radiator Grille H Emblem			\$ 113.65
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (LH/RH)	\$	40.30	\$ 80.60
	Front Bumper Centre Grille			\$ 178.60
	Front Bumper Centre Grille Top Garnish			\$ 80.00
	Front Bumper Lip			\$ 62.50
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)	\$	24.60	\$ 49.20
	Headlamp Support Top Cover			\$ 398.00
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	Headlamp Halogen Bulb (LH/RH)	\$	14.40	\$ 28.80
	Radiator			\$ 850.20
	Radiator Fan Blade,Cowling,Motor Assy			\$ 792.95
	Radiator Bracket (RH/LH)	\$	6.50	\$ 13.00
	Radiator Hose Upper			\$ 47.40
	Radiator Hose Lower			\$ 47.40
	Radiator Expansion Tank			\$ 48.00
	Radiator Guard	\$	35.00	\$ 70.00
	Horn Unit (LH/RH)	\$	86.75	\$ 173.50
	Horn Wire			\$ 156.50
	Front Fender (LH/RH)	\$	619.00	\$ 1,238.00
	Front Fender Apron Panel (LH/RH)	\$	1,575.50	\$ 3,151.00
	Front Fender Shield (LH/RH)	\$	169.80	\$ 339.60
	Front Fender Mudflap (LH/RH)			\$ 16.20
	Front Fender Retainer			\$ 9.20
	Front Fender Top Garnish			\$ 120.00
	Air Cleaner Assy			\$ 128.40
	Air Cleaner Bottom Assy			\$ 325.00
	Air Filter			\$ 54.85
	Air Cleaner Cover			\$ 34.30
	Air Duct			\$ 206.05

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Flow Sensor			\$ 633.35
	Resonator Tank Hose			\$ 261.95
	Air Cleaner Body			\$ 106.20
	Air Cleaner Bottom Assy			\$ 325.00
	Aircon Blower Motor Unit			\$ 1,115.50
	Aircon Expansion Valve			\$ 219.50
	Aircon Sensor Pressure - Suc/Liq			\$ 244.10
	Aircon Condenser			\$ 1,137.35
	Aircon Receiver			\$ 71.50
	Aircon Suction & Liquid Hose			\$ 658.90
	Aircon Discharge Hose			\$ 233.30
	Aircon Blower Motor			\$ 619.00
	Aircon Compressor			\$ 2,857.55
	Aircon Evaporation Coil & Heater Unit			\$ 2,492.40
	Aircon Control Assy			\$ 983.70
	Battery Tray			\$ 55.45
	Battery Stay			\$ 20.90
	Fuse Box Front			\$ 415.20
	Front Door Mirror Side Garnish			\$ 83.50
	Front Door (LH/RH)	\$	1,403.00	\$ 2,806.00
	Front Door Rubber	\$	290.50	\$ 581.00
	Front Door Glass (LH/RH)	\$	379.55	\$ 759.10
	Front Door Gear / Regulator (LH/RH)	\$	785.50	\$ 1,571.00
	Front Door Hinge Upper (LH/RH)			\$ 53.40
	Front Door Hinge Lower (LH/RH)			\$ 53.40
	Front Door Check (LH/RH)			\$ 110.15
	Front Door Power Motor	\$	530.50	\$ 1,061.00
	Front Door Trim Board (LH/RH)	\$	1,196.90	\$ 2,393.80
	Door Centre Pillar Outer (LH/RH)	\$	1,786.20	\$ 3,572.40
	Door Centre Pillar Inner (LH/RH)	\$	1,890.50	\$ 3,781.00
	Door Pillar Inner Garnish			\$ 31.70
	Frt Safety Belt (Assy) (LH/RH)	\$	572.65	\$ 1,145.30
	Frt Safety Belt Buckle	\$	86.05	\$ 172.10
	Front Windscreen Glass			\$ 1,059.25
	Front Windscreen Moulding			\$ 60.00
	Front Windscreen Pillar Outer(LH/RH)	\$	1,843.10	\$ 3,686.20
	Front Windscreen Enforcement(LH/RH)			\$ 1,163.30
	Front Windscreen Pillar Inner Garnish(LH/RH)			\$ 117.60
	SunVisor			\$ 282.00
	Wiper Blade			\$ 73.60
	Wiper Motor			\$ 576.00
	Wiper Arm			\$ 56.00
	Wiper Panel Top Garnish			\$ 91.20
	Wiper Link			\$ 426.00
	Wiper Container			\$ 61.90
	Wiper Container Motor			\$ 65.90
	Front Wheel Rim (LH/RH)	\$	351.90	\$ 703.80
	Front Wheel Hub Cap (LH/RH)	\$	150.70	\$ 301.40
	Front Wheel Bearing	\$	258.50	\$ 517.00
	Front Shock Absorber (Assy) (LH/RH)	\$	342.20	\$ 684.40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Shock Absorber Mounting (LH/RH)		\$ 75.10	\$ 150.20
	Front Drive Shaft (LH/RH)		\$ 1,069.55	\$ - 2,139.10
	Rack & Pinion Assy			\$ 2,184.00
	STG Tie Rod		\$ 162.00	\$ 324.00
	STG Tie End		\$ 69.50	\$ 139.00
	Stabilizer Bar		\$ 252.30	\$ 504.60
	Stabilizer Bar Bush (LH/RH)		\$ 16.10	\$ 32.20
	Stabilizer Bar Link		\$ 81.70	\$ 163.40
	Stabilizer Bracket		\$ 24.00	\$ 48.00
	Front Suspension Lower Arm (LH/RH)		\$ 715.10	\$ 1,430.20
	Front Chasis Member (LH/RH)		\$ 1,575.85	\$ 3,151.70
	Knuckle Arm (LH/RH)		\$ 582.95	\$ 1,165.90
	Timing Cover Assy			\$ 535.80
	Timing Cover Upper			\$ 485.30
	Timing Cover Lower			\$ 454.20
	Timing Gear			\$ 213.00
	Timing Belt			\$ 244.50
	Timing Tensioner Assy			\$ 260.80
	Fan Belt			\$ 155.00
	Brake Master Pump			\$ 434.90
	Brake Booster Pump			\$ 1,024.20
	Engine Mounting			\$ 481.90
	Oil Sump			\$ 435.60
	Oil Pump			\$ 1,089.85
	Engine Under Cover			\$ 343.10
	Engine Crossmember			\$ 2,236.90
	Engine Lower Cover			\$ 56.30
	Front Cushion Seat (LH)			\$ 3,151.20
	Front Cushion Seat (RH)			\$ 5,992.00
	Engine Mtg (Front)			\$ 235.30
	Engine Mtg (Rear)			\$ 279.60
	Engine Support Bracket Assy			\$ 546.60
	Hand Brake Cable			\$ 336.00
	Hand Brake Handle			\$ 552.00
	Engine Support Bracket Assy			\$ 546.60
	Gearbox			\$ 14,808.00
	Gearbox Mounting			\$ 342.50
	Gearshift Assy Panel			\$ 1,950.80
	Roof Panel			\$ 1,193.90
	Roof Moulding			\$ 138.10
	Roof Upholstery			\$ 2,875.00
	Instrumental Panel			\$ 1,664.40
	Dashboard Complete			\$ 2,688.00
	Dashboard Re-Inforcement Bar			\$ 658.80
	Console Box Assy			\$ 1,920.00
	Console Box Cover			\$ 427.45
	Dashboard Speedo Meter Assy			\$ 2,880.00
	P/Stg Hose & Bracket			\$ 76.45
	Power Steering Pump			\$ 754.20
	Power Steering Tank			\$ 181.70

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Power Steering Pressure Hose Assy			\$ 614.30
	Power Steering Outlet Hose & Bracket			\$ 76.45
	Power Steering Pipe Assy			\$ 76.45
	Power Steering Pulley			\$ 68.15
	Alt / P.Stg V-Belt CRDI			\$ 74.05
	Alternator Assy			\$ 1,124.15
	Fuel Pump Rubber Seal & Hose			\$ 192.00
	Fuel Injector			\$ 1,680.00
	Fuel Filter			\$ 144.00
	Starter Motor Assy			\$ 1,140.00
	Vacuum Pump Relay			\$ 288.00
	Vacuum Pump (1)			\$ 432.00
	Steering Wheel			\$ 864.00
	Steering Column & Shaft Assy			\$ 1,264.55
	Steering Column			\$ 504.00
	Steering Flexible Joint			\$ 552.00
	Steering Wheel Horn Button Assy			\$ 816.00
	ECU Bracket			\$ 81.70
	ECU Unit			\$ 4,203.50
	Oil Cooler - Tube Assy-P/Stg			\$ 267.10
	Inter Cooler			\$ 921.90
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	Hose B To Inter Cooler			\$ 229.70
	Hose C To Inter Cooler Inlet			\$ 113.30
	Pipe To Inter Cooler			\$ 167.05
	Pipe To Inter Cooler Outlet			\$ 244.55
	Controller (PWN)			\$ 517.45
	Oil Cooles Assy-Gearbox			\$ 283.90
	Turbo Charge			\$ 4,034.90
	ABS Sensor	\$	261.50	\$ 523.00
	Wiring-Engine			\$ 3,326.00
	Wiring-Front			\$ 1,960.80
	Wiring-ECM			\$ 3,243.00
	Wiring-FEM			\$ 168.00
	Wiring Battery			\$ 1,191.30
	Actuator - Swirl Control			\$ 835.10
	Junction Box Assy			\$ 1,081.80
	Inhibitor Switch			\$ 104.40
	MTV Set Assy			\$ 2,760.00
	Head Rest LCD Module Set			\$ 850.00
	Engine Assy			\$ 28,560.00
	Auto Gear Oil			\$ 110.40
	Engine Top Cover			\$ 386.00
	Throttle Body Assy			\$ 1,096.60
	Intake Manifold Assy			\$ 1,212.40
	Airbag Complete			\$ 2,948.50
	Airbag Control Module			\$ 1,894.00
	Steering Angle Assy			\$ 1,150.60
	Sensor Assy Impact -Frt Impact			\$ 1,180.50
	Airbag Sensor	\$	580.00	\$ 1,160.00
	Electric Power Steering			\$ 4,880.50

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	SUB TOTAL			\$ 202,893.95	
	LESS 20%			\$ 40,578.79	
	DISCOUNTED TOTAL			\$ 162,315.16	
	Front Number Plate			\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
	Front Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	New Battery			\$ 207.00	Nett
	Front Door Comfort Logo (LH/RH)		\$ 75.00	\$ 150.00	Nett
	Front Door Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Front Windscreen Sealant			\$ 46.00	Nett
	Front ERP Sticker			\$ 26.00	Nett
	Front Tyre (LH/RH)		\$ 216.00	\$ 432.00	Nett
				\$ 1,316.00	
	Labour Charge				
	Panel Beating			\$ 3,000.00	
	Spray Painting Charge			\$ 1,800.00	
	Wiring Charge			\$ 100.00	
	Tuff Kote			\$ 100.00	
	Towing Charge			\$ 50.00	
	Front Chassis Alignment Charge			\$ 400.00	
	Remove/Refix Undercarriage (FRT)			\$ 400.00	
	FRT Wheel Alignment			\$ 120.00	
	Remove/Refix Radiator			\$ 90.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	
	Remove/Refix Engine			\$ 550.00	
	Remove/Refix Dashboard			\$ 450.00	
	Remove/Refix Fuse Box			\$ 180.00	
	Remove/Refix Front Windscreen Glass			\$ 120.00	
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	
	Remove/Refix Power Steering Pump			\$ 120.00	
	Remove/Refix Brake Master & Booster Pump			\$ 120.00	
	Remove/Refix A/C Pump			\$ 100.00	
	Remove/Refix Roof Top Taxi Digital Sign			\$ 250.00	
	Remove/Refix Roof Top Advertisement			\$ 150.00	
	Re-programme Air Bag & Safety Belt System			\$ 550.00	
	TOTAL LABOUR			\$ 8,890.00	
	ESTIMATE TOTAL			\$ 172,521.16	
	<p>NAZ LKR 9/5/18 1615</p> <p>Vehicle caught fire - Unable to repair - recommend to scrap - book value - request for last 3 months servicing records.</p>				
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				