

SKV 332

22/03/2002

ASS. REC. BY:

REF: CS/ASM18008880/71 S703/52

Special Instruction:

Surveyor:

Tan Kah

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of ASM (AXA)

Date/Time: 15/5/2018

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 2593L

Insured:

at Workshop m/s

Sng Ah Tee

Tel: 6268 6183

of Blk 3 Pioneer Rd north #01-18

Policy No:

Claim No: SEM 0047Q

Sum Insured:

Excess: \$1,500.00

Make of Veh:

D.O.A. 14/5/2018

(Client's Record)

CA ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:23am @ 16/5/18

Person Contacted:

joyce

Vehicle IN

☒ OUT

7/5/18

Date/Time	Action/Instruction ( ) Estimate
	Obtain Dt of the driver; Authorisation letter from Insured Indicate driver is a authorised driver and allow driver to claim OD; confirm usage of the vehicle at the time of accident.
	YP 2593 L-X

14/06/18 @ 15:17 p.m revised IA to Kitty Teo via smart claim.  
14/06/18 @ 15:17 p.m requested authorization to Kitty Teo via smart claim.

REF:

AXIA

## ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess:

\$1500

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its  
repair at the time of inspection.


Bal. or Market Value:

\$84K.

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 2593L

Yr Regn:

29/6 May

Type: M.Car / M.Cycle / Bus / Van / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Pajero

CC

7545

Colour:

white

A/C

Insured / Std / NI / NA

Sp Reading:

145938

T/Radio

Insured / Std / NI / NA

Eng No:

C/No:

KM65FM14300.88

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

11R22.5

R:

22 (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Finanzi

Front

R/Bal.

8 6

mm

Rear

R/Bal.

4/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I.

13/6/18 @ 11am

Survey held at

Sug Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/06/18 @ 11:26 p.m. authorization approved by kitty Teo via smart claim.  
25/06/18 @ 16:18 p.m. revert authorized repair to joyu (repairs) via email.

\* Submit prelim report due with pending some spare parts.

RECEIVED 27 AUG 2018

Date/Time, File Pass to?

27/08/18

1)

Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.B. /



Prelim. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation:

1) S + R = \$

2) Photos

3) Other:

TOTAL

Add Fee:



Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Workshop (\$)

250




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CS/ASM18008880/T1s3d3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 16-05-2018		
		Code : ASM		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected		YP 2593L
Policy No.		Coverage (\$)		0.00
Claim No.	S8M00H7Q	Excess (\$)		1,500.00
Assign From	SMARTCLAIM (KITTY TEO)	Assign Date		16/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date		14/05/2018		Inspection Date
Survey held at		SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



## Service Request Details

Claim

S8M00H7Q

Reference

None 

Loss Date

May 14, 2018

Request Date

May 15, 2018

Due Date

May 22, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

YP2593L

Make

MITSUBISHI

## SERVICE ADDRESS

Blk 3 Pioneer Road North, , 628457

## Primary Contact/Insured

HOTEL LAUNDRY PTE LTD  
80 MARINE PARADE ROAD, #21-01 PARKWAY PARADE, 449269, Singapore  
91159333  
IRENE@DIINSURANCEAGENCY.COM.SG

## Claim Handler

TEO Kitty  
6568804602  
kitty.teo@axa.com.sg

Additional Instructions  
EXCESS \$1500

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## TYPE



## SENT

5/15/18 10:15 PM

## FROM

TEO Kitty

## SUBJECT

Re:WP Survey - YP2593L - Veh @ Sng Ah Tee

## BODY

Hi Please also get estimate from workshop. Thank...



## TYPE



## SENT

5/15/18 10:06 PM

## FROM

TEO Kitty



5551

4. The above claim is pending about 2/25/18





## Re:YP 2593L - REQUEST AUTHORIZATION

Type

🔗 Question

Message

Hi Shirley, Please authorise.

Reply

## Shirley Hiew (LKK Auto)

---

**From:** ADMIN SAT <admin@sngahtee.com>  
**Sent:** Wednesday, 27 June 2018 3:03 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** sur@lkkauto.com  
**Subject:** Re: YP 2593L OD (AXA)

Dear Shirley,


We accept the amount .  
Thanks

Best Regards

---

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



**From:** Shirley Hiew (LKK Auto)  
**Sent:** Monday, June 25, 2018 4:17 PM  
**To:** 'ADMIN SAT'  
**Cc:** sur@lkkauto.com  
**Subject:** RE: YP 2593L OD (AXA)

Dear Joyce,

As Spoken, instructed by our client, please proceed at repair cost not exceeding lump sum \$6,500.00 (inclusive supplementary) to repair the insured vehicle  
**YP 2593L (Excess \$ 1,500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 25 June 2018 4:18 PM  
**To:** 'ADMIN SAT'  
**Cc:** sur@lkkauto.com  
**Subject:** RE: YP 2593L OD (AXA)

Dear Joyce,

As Spoken, instructed by our client, please proceed at repair cost not exceeding lump sum \$6,500.00 (inclusive supplementary) to repair the insured vehicle  
**YP 2593L (Excess \$ 1,500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ADMIN SAT [mailto:[admin@sngahtee.com](mailto:admin@sngahtee.com)]  
**Sent:** Friday, 22 June 2018 4:32 PM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Cc:** sur@lkkauto.com  
**Subject:** Re: YP 2593L OD (AXA)

Dear Shirley,

We accept the amount for lump sum \$6,500  
Thanks

---

JOYCE TAN | [admin@sngahtee.com](mailto:admin@sngahtee.com)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Tuesday, June 19, 2018 4:29 PM  
**To:** 'ADMIN SAT'  
**Cc:** [sur@lkkauto.com](mailto:sur@lkkauto.com)  
**Subject:** YP 2593L OD (AXA)

Hi Joyce,

As Spoken, kindly check whether you are able to repair the vehicle at Lump sum \$6,500.00 .

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/06/2018

### Survey Details:

Date of loss	14-May-18
Date of appointment	15-May-18
Date of survey	13-Jun-18
Location of survey	BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YP 2593L
Make and Model	MITSUBISHI FUSO
Date of registration	16/5/2016
Excess	1500
Market Value	\$84,000
Part Rebate	\$35,180
Nett Loss	\$48,820

### Repair details:

Initial Estimate	11605
------------------	-------

### Proposed/Revised repair cost:

Parts	\$5,585
Check items (estimate)	\$1,660
Labour	\$1,650
Total	\$8,895
Lump Sum(if applicable)	\$

Number of days for repair	7 DAYS
---------------------------	--------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

**Remarks:**

PENDING PART PRICES . DAMAGES CONSISTENT,REPAIR  
COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/05/2018 13:49
Date Of Accident	14/05/2018 20:00
Exact Location Of Accident	ALONG GEYLANG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP2593L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HOTEL LAUNDRY PTE. LTD.
Co Reg No	200610139H
Email Address	LINEN@HOTEL181.COM.SG
Mobile Phone No	(LOCAL) +65-93853090
Alternative Phone No	OFFICE-63638181

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FM657MSRDEC-7.5 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1790744
Cover Note Number	

### Driver

Name of Driver	YANG JUN
NRIC No	G2000289T
Date Of Birth	26/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	27/06/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83319914
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	21 TUAS AVENUE 4
Postcode	639371
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 14/05/2018 AT ABOUT 2000 HRS. MY VEHICLE COME OUT FROM LOR 20 GEYLANG TOWARDS GEYLANG RD. MY VEHICLE STATIONARY OUTSIDE OF THE YELLOW BOX. WHEN TRAFFIC LIGHT TURN TO GREEN, SUDDENLY I FEEL AN IMPACT FROM MY RIGHT SIDE. I NOTICED THAT VEHICLE B HIT ONTO MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3902M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0139H

### Vehicle Details

Vehicle No.: YP2593L

Vehicle to be Exported: No

Intended De-registration Date: 31 May 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FUSO FM65FM2RDEB

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 6M60215185

Chassis No.: FM65FMA30088

Maximum Power Output: -

Open Market Value: \$61,068.00

Original Registration Date: 16 May 2016

First Registration Date: 16 May 2016

Transfer Count: 0

Actual ARF Paid: \$3,054.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 15 May 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$44,213.00

COE Rebate Amount: \$35,180.00

**Total Rebate Amount: \$35,180.00**

The information contained herein is correct as at 15 May 2018

OK

Finanza

11R27.5



 **WORK PERMIT**  
Employment of Foreign Manpower Act (Chapter 91A)  
Republic of Singapore

Employer:  
V HOTEL MANAGEMENT PTE. LTD.




Name:  
**YANG JUN**  
Work Permit No:  
**O 74780325** Sector:  
**SERVICE**





K0113005

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **G2000289T**  
Name:  
**YANG JUN**  
Birth Date: **26 Jun 1970**  
Issue Date: **01 Feb 2018**  
Valid Till: **31/01/2023**







**VISIT PASS**  
Immigration Regulations

29-01-2018

Name:  
**YANG JUN**

File:  
**G2000289T**  
Date of Birth: **26-06-1970** Sex: **M**  
Nationality:  
**CHINESE**



Download SGWorkPass App to check status



**MULTIPLE JOURNEY VISA ISSUED**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES**

EFFECTIVE DATE

- |         |  |             |
|---------|--|-------------|
| Class 3 | Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg | 28 Feb 2012 |
| Class 4 | Motor vehicles which are constructed to carry load or passengers and the unladen weight $>$ 2500kg   | 27 Jun 2012 |
|         | Motor vehicles which are not constructed to carry load or passengers and the unladen weight $\leq$ 7250kg  |             |

NP 428A



# HOTEL LAUNDRY PTE LTD

80 Marine Parade Road #21-01 Parkway Parade  
Singapore 449269 Tel: (65) 63461959 Fax: (65) 63461970  
ROC: 200610139H

RE : Letter of Authorise

Dear Sir / Madam ,

I hereby confirmed that we have authorise Driver Yang Jun ( Fin : G2000289T ) to drive our  
Company Truck of YP 2593L.

Thanks.

Yours faithfully,



Laundry Operations Manager

Daniel Sim

9385 3090





redefining / Insurance

**LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR**

1. I, [Name] [NRIC] HOTEL LAUNDRY PTE LTD, the owner/ authorized driver of vehicle [Registration No.] YP2593L ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. \* To be applicable where person authorizing is the authorized driver.  
I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:



Signature of policyholder/ authorized driver\* and company stamp (where applicable)

Date:



Name and signature of workshop personnel including workshop stamp

Date:

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

# 孫亞弟汽車燒焊私人有限公司 - SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

AXA Ref: S8M00H7Q

Date : 30/5/2018

ATTN: THE MOTOR CLAIMS DEPT

AXA INSURANCE PTE LTD

78 SHENTON WAY #B1-01

AXA TOWER SINGAPORE 068811

## ESTIMATE COST OF REPAIR

Vehicle Reg No.	YP2593L	Model / Year	MIT.FUSO FM65
Date of Accident	14-May-18	Policy No.	CN827400
Type of Claim	Own Damage	Prepared By	JOYCE
Chassis	FM65FM2RDEB		

S/NO	Description	Qty	Unit Price	Amount
1	FRT BUMPER	1	\$ 1,300.00	\$ 1,300.00 <i>bt</i>
3	FRT HEADLAMP (RH)	1	\$ 700.00	\$ 700.00 <i>?</i>
4	FRT HEADLAMP BRACKET(RH)	1	\$ 160.00	\$ 160.00 <i>?</i>
5	FRT FOGLAMP(RH)	1	\$ 800.00	\$ 800.00 <i>?</i>
6	FRT CORNER PANEL (RH)	1	\$ 850.00	\$ 850.00 <i>Rx</i>
7	FRT STEP GARNISH (RH)(TOP)	1	\$ 250.00	\$ 500.00 <i>One</i>
8	FRT WHEEL ARCH(RH) GARNISH	1	\$ 750.00	\$ 1,500.00 <i>One</i>
9	FRT DOOR (RH)	1	\$ 3,200.00	\$ 3,200.00 <i>bt</i>
10	FRT DOOR SIGNAL LAMP(RH)	1	\$ 75.00	\$ 75.00 <i>One</i>
11	FRT HEADLAMP PANEL(RH)	1	\$ -	\$ - <i>nn</i>
12	FRT DOOR RR PANEL(RH)	1	\$ -	\$ - <i>nn</i>
13	FRT DOOR "BLUE TEC" STICKER(RH)	1	\$ 10.00	\$ 10.00 <i>NE</i>
				\$ 9,245.00 <i>9109.5</i>
14	TO CHECK WIRING	1	\$ 30.00	\$ 30.00 <i>✓</i>
15	TO REMOVE & REFIX FRT DOOR RR PANEL (RH)GLAS	1	\$ 80.00	\$ 80.00 <i>60</i>
16	TO REMOVE & REFIX FRT DOOR GLASS(RH)	1	\$ 200.00	\$ 200.00 <i>60</i>
17	TO KNOCK FRT DOOR PILLAR(RH), FRT WHEEL ARCH	1	\$ 100.00	\$ 100.00 <i>700</i>
	FRT WHEEL ARCH PANEL, WELD,	1	\$ 950.00	\$ 950.00
	REMOVE & FIX ON ABOVE PARTS			\$ -
18	TO PUTTY & RESPRAY PAINTING ON AFFECTED ARE	1	\$ 1,000.00	\$ 1,000.00 <i>800</i>
	<b>TOTAL</b>			<b>\$ 11,605.00</b> <i>11355</i>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- This is a computer printout, no signature is required.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\*Get Driving License of Driver,  
Authorisation letter from Insured indicate driver is an authorise driver and allow to claim op. Confirm usage of the vehicle at the time of accident.

13/6/18 @ 11:00am  
Not Authorise, Revert  
Ex: \$1500  
+ sure@lkkauto.com  
7 days.  
Resurvey after repair  
Lumpsum.