

2/03/2002

ASS. REC. BY:

REF: CS/FCI18008881 / N cd367

Special Instruction:

Surveyor:  
CWS

MA

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

15/5/18 @ 5.56pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 3487 X

Insured:

SHD 4366C

at Workshop m/s

Autoworx House

Tel:

64528211

of

176 Sin Ming Drive # 02-01

97368619 Mr Chew

Policy No:

Claim No:

D18003861 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/05/2018

CA / REV / REP. / REV 24 HRS 'wp)

Yuki

Dillon

H.O.D. Endorsement:

Date/Time:

9:02am @ 16/5/18

Person Contacted:

~~Yuki~~Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 3487 X-X
	SHD 4366C-NS/INC16024649/H1g6m2 DOA: 21/12/16
23/10.32am	Confirmed LE \$1950f with Yuki. (Red. 1363.08, 41%)

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

\$63K.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

3

days

Res.: \_\_\_\_\_

Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val: \_\_\_\_\_

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: SLO3487X Yr Regn: 07 / 2016Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: TOYOTA Aqua.

C.C.

1496Colour: white

A/C

Insured / Std / NI / NA

Sp. Reading: 76467

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NHPI6-2515224Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or YOKO

Front

Rear

R/Bal: \_\_\_\_\_

mm

R/Bal: \_\_\_\_\_

mm

L/Bal: \_\_\_\_\_

mm

L/Bal: \_\_\_\_\_

mm

D.O.A. \_\_\_\_\_

D.O.I. 17/5/2019

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: \$63K, LTA: \$44,373.00, NV: \$18627.00

*[Signature]*  
 23/1/2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TPLump Sum / I.B.I: (\$ 1950/-)

130

50

50

16

246



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18008881/M1rd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-05-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4366C	Veh. Inspected	SLD 3487X
Policy No.		Coverage (\$)	0.00
Claim No.	D18003861MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	16/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/05/2018	Inspection Date
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	15-05-2018	<b>Our Ref No.</b> D18003861MFSH
<b>Accident Date</b>	10-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD4366C	<b>Third Party Vehicle.</b> SLD3487X
<b>Survey Location</b>	C/O 176 SIN MING DRIVE #02-01	
<b>Contact Person.</b>	NA	
<b>Contact No.</b>	64528211/ 64528211	<b>Fax No.</b> 64517420
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	AUTOWORX HOUSE	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240333)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18003861MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & AUTOWORX
<b>Workshop Name</b>	AUTOWORX HOUSE (Contact Person : NA)	<b>Survey Location &amp; Contact Details</b>	C/O 176 SIN MING DRIVE #02-01 <b>Mobile:</b> 64528211 , <b>Phone:</b> 64528211 , <b>Fax:</b> 64517420 <b>EmailId:</b> ADMIN@SUPREME.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHD4366C	<b>TP Vehicle No</b>	SLD3487X
<b>PRI Recieved Date</b>	15-05-2018 07:29:26 PM	<b>Surveyor Appointed Date</b>	15-05-2018 05:55:35 PM	<b>Surveyor Accept Date</b>	16-05-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	16-05-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▼	<b>Model</b>	Please Select Model ▼	<b>Year</b>	Select Year ▼
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Celine Fong (LKKAUTO)

---

**From:** admin@supreme.sg  
**Sent:** Wednesday, 23 January 2019 10:32 AM  
**To:** Celine Fong (LKKAUTO)  
**Subject:** RE: SLD 3487 X TP 1STCAP . LKK

Hi Celine,

We accept the offer.  
Thank you.

Best regards,  
Yuki Ho  
Supreme Auto Service Pte Ltd  
No.176 Sin Ming Drive  
#02-01 Singapore 575721  
Tel: 64528211  
Fax: 64517423

-----Original Message-----

From: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>  
Sent: Wednesday, 23 January 2019 9:13 AM  
To: admin@supreme.sg  
Subject: RE: SLD 3487 X TP 1STCAP . LKK

Dear Yuki,

WITHOUT PREJUDICE

Our surveyor has further reviewed, we recommend Lump Sum \$1,950/- @ 3 working days

Please check and confirm.

Best Regards,  
Celine Fong  
LKK Auto Consultants Pte Ltd  
phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: admin@supreme.sg <admin@supreme.sg>  
Sent: Friday, 18 January 2019 2:47 PM  
To: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>  
Subject: RE: SLD 3487 X TP 1STCAP . LKK

Hello Celine,

As spoken, kindly enquire from the surveyor if the damaged door regulator and regulator motor can be stated.

&gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

4838B

## Vehicle Details

Vehicle No.:

SLD3487X

Vehicle to be Exported:

No

Intended Deregistration Date:

20 Nov 2018

Vehicle Make:

TOYOTA

Vehicle Model:

AQUA URBAN 1.5X A

Primary Colour:

White

Manufacturing Year:

2016

Engine No.:

1NZ1851262

Chassis No.:

NHP102515224

Maximum Power Output:

73.0 kW (97 bhp)

Open Market Value:

\$24,439.00

Original Registration Date:

14 Jun 2016

First Registration Date:

14 Jun 2016

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

## Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Jun 2026

PARF Rebate Amount:

\$3,750.00

## Intended COE Rebate Details

COE Expiry Date:

13 Jun 2026

COE Category:

A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$53,694.00

COE Rebate Amount:

\$40,623.00

Total Rebate Amount:

\$44,373.00

The information contained herein is correct as at 20 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/05/2018 01:16
Date Of Accident	10/05/2018 11:50
Exact Location Of Accident	5 FIGARO STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD3487X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TURTLE ON WHEELS
Co Reg No	53334838B
Email Address	KOH.ZHANMING.EDMUND@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81331406
Alternative Phone No	OFFICE-81331406

### Vehicle Particulars

Manufacturer	TOYOTA
Model	AQUA-1.5 E 1.5 SA (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5081218685-01
Cover Note Number	

### Driver

Name of Driver	KOH ZHANMING EDMUND
NRIC No	S8915668H
Date Of Birth	26/04/1989
Occupation	INDOOR
Date Of Driving Pass	24/04/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81331406
Fax Number	
Contact Number	
EMail Address	KOH.ZHANMING.EDMUND@GMAIL.COM

Address	BLK 682B EDGEDALE PLAINS #17-733
Postcode	822682
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	EMAIL TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4366C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



turtle on wheels


Policyholder's Signature  
Date & Time: 10/01/2018  
2125

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 10/01/2018  
2125

Reporting Centre Personnel's Signature  
Name: HAFIZ S. A. H.  
NRIC/FIN No.: S72055332

5B FIGARO STREET

A - SLD348TX  
B - SHD4366C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT NO T/20180510/2153



I/We declare the foregoing particulars are true in every respect.

## turtle on wheels

Policyholder's Signature

Date & Time: 10/25/2011  
2:25

Driver's Signature \_\_\_\_\_

Date & Time: 10/03/2011  
2125

Reporting Centre Personnel's Signature

Name: *HATID SHAH*  
NRIC/FIN No.: *SG22193018*



# SINGAPORE POLICE FORCE



T/20180510/2153

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

1 of 3

Report No. T/20180510/2153

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/05/2018 19:04	Vide Report No.:	Station Diary No.: 50
--	------------------	--------------------------

### Informant's Particulars

Name of Informant: KOH ZHANMING, EDMUND			Address: APT BLK 682B EDGEDALE PLAINS #17-733 SINGAPORE 822682		
ID Type / ID No.: NRIC NO / S8915668H			Contact No.: Home/Office: Mobile: 81331406		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 26/04/1989	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: EDUCATOR			Driving Licence Information: Class: 3 Date of Expiry:		

### General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/05/2018 11:50	Type of Location: Straight Road
Location: Along Road 1 FIGARO STREET				
5 Figaro Street, parked at slanted lot in front of Lian Beng Huat.				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD4366C	Car				No Damage	0
SLD3487X	Car				Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20180510/2153

2 of 3

Police Station Of Origin:

Punggol N.P.C

21A Tebing Lane SINGAPORE 828837

Tel No: 1800-6049999

Report No. T/20180510/2153

**CONTINUATION OF REPORT**

**Brief Details.**

On the 10/05/2018 at around 0830hrs, I parked my vehicle (SLD3487X, Toyota Aqua X-urban, white in color car) along 5B Figaro Street at one of the slanted parking lots (fifth lot along the 5B Figaro street parking lots). After I parked my vehicle, I then went off to work. At that point of time, my vehicle was intact.


I then came back at around 1500hrs to go for lunch. However, I have not realized the dent on the rear right door and I drove the car out for lunch. I then came back to the same parking lot and park my vehicle at around 1545hrs and I went up to the office. I then came back at around 1600hrs.

When I came back, I then realized that there was a dent on my rear right door. I then retrieve the in-car camera footage and at around 1150hrs, I saw in the footage that a taxi (SHD4366C, Comfort, blue in color taxi) reversing into a lot beside my vehicle. While reversing, his vehicle then hit onto the rear right door of my vehicle. Afterwards, he did not stop and instead, he drove off. All these are captured inside my in-car camera. A jerk of my car and a sound of metal being hit can be heard in the footage.

I wish to state that this is the first time such thing happens to me. I still have the In-car camera footage inside my phone and SD card. The owner of the shop "Lian Beng Huat" saw the entire incident.



SINGAPORE  
POLICE FORCE



T/20180510/2153

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

3 of 3

Report No. T/20180510/2153

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 GOH JUN JIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt TAN JEOK LENG

Contact No.: 65476144

Signature Of Informant:

Date/Time:

10/05/2018 19:04

Classification Of Case:

Authentication Stamp

NP168

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

### TURTLE ON WHEELS

c/o 46 Lenton Plain  
Singapore 786548

Date: 15/5/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE: TOYOTA AQUA / SLD 3487 X</b>	
1 pc	rear door — B4C 1235.80	1,093.90
1 pc	rear door hinge upper X NN	159.30
1 pc	rear door hinge lower X NN	150.90
1 pc	rear door regulator gear X 265.40	308.60
1 pc	rear door regulator motor X 365.50	360.90
1 pc	rear door weatherstrip X NEC 298.95	273.50
1 pc	rear door frame sticker X EC 79.90	67.10
1 pc	side rocker panel trim X NN	389.90
	sub total	2,804.10
	Less 25%	701.03
	sub total	2,103.08
	To remove replace the parts mentioned above, panel beat and realign the necessary affected areas.	250 400.00
	To check wiring system.	30.00
	To apply putty & spray painting on affected areas.	550 600.00
	To apply rust proofing on affected areas.	20 120.00
	To transfer rear door accessories.	✓ 60.00
	<b>Total</b>	<b>3,313.08</b>

17/5/2018 Not Authorized  
Rfs Dany  
After painting  
hole Auto  
3071498

21/9/2018




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008881/Ncd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-01-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 4366C	Veh. Inspected	SLD 3487X
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D18003861MFSH	Excess (\$)	0.00
	Assign From	KAREN TAN	Assign Date	15/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA AQUA	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	NHP102515224	Colour	WHITE
	Odometer	70467	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	YOKOHAMA	8 mm
	L/H Front Tyre	195/55 R15	YOKOHAMA	8 mm
	R/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm
	L/H Rear Tyre	195/55 R15	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	Accident Date	10/05/2018	Inspection Date	17/05/2018
	Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 3487X**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR DOOR	BUCKLED	1,093.90	1,093.90
1	REAR DOOR HINGE UPPER	NOT NECESSARY	159.30	-
1	REAR DOOR HINGE LOWER	NOT NECESSARY	150.90	-
1	REAR DOOR REGULATOR GEAR	DISTORTED	308.60	265.40
1	REAR DOOR REGULATOR MOTOR	JAMMED	360.90	360.90
1	REAR DOOR WEATHERSTRIP	NECESSARY	273.50	273.50
1	REAR DOOR FRAME STICKER	NECESSARY	67.10	67.10
1	SIDE ROCKER PANEL TRIM	NOT NECESSARY	389.90	-
	LESS 25% DISCOUNT		-701.03	-515.20
			2,103.07	1,545.60
	<b><u>LABOUR</u></b>			
	TO REMOVE REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS.		400.00	250.00
	TO CHECK WIRING SYSTEM.		30.00	30.00
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		600.00	550.00
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		120.00	20.00
	TO TRANSFER REAR DOOR ACCESSORIES.		60.00	60.00
			1,210.00	910.00
	<b>GRAND TOTAL</b>		<b>3,313.07</b>	<b>2,455.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,950.00</b>

Report Ref No. CS/FCI18008881/Ncd3e2

MARKET VALUE: \$63,000.00(EST)-LTA REIMBURSEMENT VALUE: \$44,373.00=NETT VALUE: \$18,627.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.