

ASS. REC. BY:

REF:

Tml / CC3 / TML18008889 / Ktbn2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Trans Ceb

of

Insured:

GV 62340

Policy No.

MT000931

Claims No.

M1802442

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9281E

Yr Regn:

12, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c

1991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

385036

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KLILA69RTBB 067004

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

NII / S/Rim / STD A/Rim or

Tyre Size:

F:

Wettable

195/65R15

R:

Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

11/5/18

D.O.I.

15/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S in body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/5

Kle pass to Carhome

6/1/82 821001 (Red: 18833.90, 89%)

SHD 9281E - CC3 / IRS / 17022717 / Keng

GV 62340

x

DLA: 261117

RECEIVED 22 MAY 2018

Date/Time, File Pass to?

12/5 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

—

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

250

Transportation:

10

S - RS - SI

Photos

Others

TOTAL

260

Report Format:

Lump Sum / I.B.I. (\$

TP 2100/-

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 17 May 2018 3:58 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 24/4/2018, SHD 9281E (TP VEHICLE), GV 6234D (OI VEHICLE)
Attachments: SHD 9281E EST.pdf; SHD 9281E GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9281E M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/05/2018 16:11
Date Of Accident	11/05/2018 11:30
Exact Location Of Accident	LOWER DELTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9281E
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	EFFENDI MUSTAFA
NRIC No	S2621827F
Date Of Birth	05/10/1961
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1979
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91783319
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 638 BEDOK RESERVOIR ROAD #06-43
Postcode	410638
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TJIANG TJE U - 085266815919 GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NPP
Police Station Address	ROAD: 461 TAMPINES ST 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180511/2073

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV6234D
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	GOODS VEHICLE
Name of Driver	HAMEED SULTAN BIN KADASAR
NRIC/Passport Number	S0613095Z
Contact Number	85017205
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	EFFENDI MUSTAFA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD9281E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180511/2073

1 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20180511/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/05/2018 14:48		Vide Report No.:		Station Diary No.: 19	
Informant's Particulars					
Name of Informant: EFFENDI MUSTAFA			Address: APT BLK 638 BEDOK RESERVOIR ROAD #06-43 SINGAPORE 410638		
ID Type / ID No.: NRIC NO / S2621827F			Contact No.: Home/Office: Mobile: 91783319		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 05/10/1961	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident					
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 11/05/2018 11:30	Type of Location: Straight Road	
Location: Along Road 1 LOWER DELTA ROAD					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No	

Details of Vehicle Involved					
Vehicle No.	Type	Model	Color	Condition	No. of Passenger
GV6234D	Van				0
SHD9281E	Car			Slightly Damaged	3

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



POLICE FORCE

T/20180511/2073

2 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20180511/2073

CONTINUATION OF REPORT

Driver			
Name	HAMEED SULTAN BIN KADASAR MARIKAN		ID No. S0613095Z
Related Vehicle	GV6234D (Van)		Contact No. 85017205
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	EFFENDI MUSTAFA		ID No. S2621827F
Related Vehicle	SHD9281E (Car)		Contact No. 91783319
Hospital/Clinic	W Y TEH FAMILY CLINIC AND SURGERY		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	11/05/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	TJIANG TJE U.		ID No. NIL
Related Vehicle	SHD9281E (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/5/2018 at about 1130 hrs, I was driving along Lower Delta Road with 3 passengers on board. I was driving normally. While driving, suddenly I heard a loud bang sound coming the left passenger door. I then stopped the car. I discovered that van (GV6234D) front portion collided with my left passenger door. I am unsure what the driver is doing. Due to the accident, the left passenger door was damaged. Nobody was conveyed to the hospital. No traffic police came. We the exchanged particulars and took photo and left.

Shortly after, I felt discomfort and seek medical treatment and was given 3 days of MC.



**SINGAPORE
POLICE FORCE**



T/20180511/2073

3 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20180511/2073

CONTINUATION OF REPORT



POLICE FORCE

T/20180511/2073

4 of 4

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20180511/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Staff Sgt WONG JIANYONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
11/05/2018 14:48

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No.: 65476430

Classification Of Case:

Authentication Stamp
NP168

SINGAPORE
POLICE FORCE

SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9281E
Vehicle to be Exported: Yes
Intended De-registration Date: 11 May 2018
Vehicle Make: CHEVROLET
Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour: Red
Manufacturing Year: 2011
Engine No.: Z20S1446987K
Chassis No.: KL1LA69RJBB067004
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$13,811.00
Original Registration Date: 16 Dec 2011
First Registration Date: 16 Dec 2011
Transfer Count: 0
Actual ARF Paid: \$13,811.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Dec 2019
PARF Rebate Amount: \$8,977.00

Intended COE Rebate Details

COE Expiry Date: 15 Dec 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 8
QP Paid: \$39,041.00
COE Rebate Amount: \$7,779.00
Total Rebate Amount: \$16,756.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 May 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9281E

AAD1805-109

Not Authorised
61 Sep @ 2100

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 9281E

KL1LA69RJB067004

CHEVROLET

EPICA 2.0

11.5.2018

*TOLIO***PART****LIST**

1	1	Front Fender LH	\$	<i>R</i> 837.60 <i>X</i>
2	1	Front Fender Liner LH	\$	<i>SL</i> 47.00 <i>X</i>
3	1	Fender Insulation LH	\$	<i>SL</i> 39.00 <i>X</i>
4	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i> 1,437.00 <i>X</i>
5	1	Front Door LH	\$	<i>R</i> 1,133.00 ✓
6	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>SL</i> 60.00
7	1	Front Door Outer Moulding	\$	<i>SL</i> 220.00
8	1	Front Door Outer Handle	\$	<i>SL</i> 125.00
9	1	Front Door Handle Support	\$	<i>SL</i> 3.00
10	1	Front Door outer handle inner seal	\$	<i>SL</i> 89.15
11	1	Front Door outer key lock	\$	<i>SL</i> 25.00
12	1	Front Door Hinge Upper	\$	<i>R</i> 65.00
13	1	Front Door Hinge Lower	\$	<i>R</i> 65.00
14	1	Front Door inner lock	\$	<i>R</i> 586.00 } <i>X</i>
15	1	Front Door Inner Lock Latch LH	\$	<i>SL</i> 206.00
16	1	Front Door Check / Arrestor	\$	<i>SL</i> 67.50
17	1	Front Door Weatherstrip LH	\$	<i>SL</i> 138.79
18	1	Front Door glass channel weatherstrip	\$	<i>SL</i> 160.00
19	1	Front Door inner trim board	\$	<i>SL</i> 455.69
20	1	Front Door window glass	\$	<i>SL</i> 456.12
21	1	Front Door Power Window Motor (Master) LH	\$	<i>SL</i> 284.97
22	1	Front Door power window motor switch	\$	<i>SL</i> 145.00
23	1	Front Door Window Regulator Gear LH	\$	<i>R</i> 84.58
24	1	Front Door Outer Pillar Panel LH	\$	<i>R</i> 715.00
25	1	Front Door Pillar Inner Panel LH	\$	<i>R</i> 850.00
26	1	Front Door Center Pillar Panel LH	\$	<i>R</i> 698.15
27	1	Front Side View Mirror Assy LH	\$	<i>nd / SL</i> 1,191.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1805-109

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9281E

28	1	Rear Door RH (Panel A-RR DR LH)	\$	<i>11</i>	1,133.00	X
----	---	---------------------------------	----	-----------	----------	---

TOTAL	\$	11,317.55
10%	\$	1,131.76
	\$	10,185.80

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>22</i>	24.00	X
1 Set	Front licence plate with holder	\$	<i>92</i>	192.00	X
1 Set	Radiator Grille clip	\$	<i>22</i>	35.00	X
1 Set	Front Fender Liner clip	\$	<i>22</i>	30.00	X
1	Front Fender RR Bracket RH	\$	<i>22</i>	7.10	X

TOTAL	\$	288.10
--------------	-----------	---------------

TOTAL PARTS	\$	10,473.90
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
---	----	--------	------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>201</i>
---	----	----------	------------

Putty and spray painting of the affected portion.	\$	4,000.00	<i>251</i>
---	----	----------	------------

Towing Fees.	\$	<i>22</i>	120.00	X
--------------	----	-----------	--------	---

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>22</i>	380.00	X
---	----	-----------	--------	---

To check steering geometry and computer wheel alignment	\$	<i>22</i>	220.00	X
---	----	-----------	--------	---

To transfer of tire, rim and on wheel balancing.	\$	<i>22</i>	170.00	X
--	----	-----------	--------	---

Trans-cab Auto Services Pte Ltd

AAD1805-109

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9281E

To rust-proofing of the affected areas.	\$	170.00	30/
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60/
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	X

TOTAL \$ 10,460.00**Over All Total \$ 20,933.90****Repair Days (Lump Sum)**~~15 days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18008889/KTBN2
Date: 25/05/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT000931
Claimant: SHD9281E Insured Vehicle No: GV6234D
Vehicle No: SHD9281E Nature of Claim: TP Claim No: M1802442
Date of Loss: 11/05/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9281E Engine No: Z20S1446987K
Make & Model: CHEVROLET EPICA, 2.0 (A) Chassis No: KL1LA69RJBB067004
Reg. Date: 16/12/2011 (Man. Year: 2011) Odometer: 385036 km
Colour: White/Red
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 7 mm Rear Left Side: Giti 8 mm
Front Right Side: West Lake 7 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,473.89	2,091.60	8,382.29	80.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	560.00	9,900.00	94.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,933.89	2,651.60	18,282.29	87.33
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	20,933.89	2,100.00	18,833.89	89.97
+ GST 7.00/7.00% (S\$)	1,465.37	147.00	1,318.37	89.97
Nett Amount (S\$)	22,399.26	2,247.00	20,152.26	89.97

INSPECTION

Date of Assignment: 18/05/2018

Date Inspected: 15/05/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

Adjuster Report

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2018)
Parts:	143	CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9281E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	837.60 FL	*- FL
2	1		*FRONT FENDER LINER LH	Serviceable	47.00 FL	*- FL
3	1		*FENDER INSULATION LH	Serviceable	39.00 FL	*- FL
4	1		*FRONT FENDER INNER WHEEL HOUSE PANEL LH	Repair	1,437.00 FL	*- FL
5	1		*FRONT DOOR LH	Bent	1,133.00 FL	*1,133.00 FL
6	1		*FRONT DOOR GLASS GUIDE RH CHROME MOULDING	Serviceable	60.00 FL	*- FL
7	1		*FRONT DOOR OUTER MOULDING	Serviceable	220.00 FL	*- FL
8	1		*FRONT DOOR OUTER HANDLE	Serviceable	125.00 FL	*- FL
9	1		*FRONT DOOR HANDLE SUPPORT	Serviceable	3.00 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE INNER SEAL	Serviceable	89.15 FL	*- FL
11	1		*FRONT DOOR OUTER KEY LOCK	Serviceable	25.00 FL	*- FL
12	1		*FRONT DOOR HINGE UPPER	Repair	65.00 FL	*- FL
13	1		*FRONT DOOR HINGE LOWER	Repair	65.00 FL	*- FL
14	1		*FRONT DOOR INNER LOCK	Repair	586.00 FL	*- FL
15	1		*FRONT DOOR INNER LOCK LATCH LH	Serviceable	206.00 FL	*- FL
16	1		*FRONT DOOR CHECK/ARRESTOR	Serviceable	67.50 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	138.79 FL	*- FL
18	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP	Serviceable	160.00 FL	*- FL
19	1		*FRONT DOOR WINDOW GLASS	Serviceable	456.12 FL	*- FL
20	1		*FRONT DOOR POWER WINDOW MOTOR (MASTER) LH	Serviceable	284.97 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW MOTOR SWITCH	Serviceable	145.00 FL	*- FL
22	1		*FRONT DOOR WINDOW REGULATOR GEAR LH	Repair	84.58 FL	*- FL
23	1		*FRONT DOOR OUTER PILLAR PANEL LH	Repair	715.00 FL	*- FL
24	1		*FRONT DOOR PILLAR INNER PANEL LH	Repair	850.00 FL	*- FL
25	1		*FRONT DOOR CENTER PILLAR PANEL LH	Repair	698.15 FL	*- FL
26	1		*FRONT SIDE VIEW MIRROR ASSY LH	Dented/Cut	1,191.00 FL	*1,191.00 FL
27	1		*REAR DOOR RH (PANEL A-RR DR LH)	Repair	1,133.00 FL	*- FL
28	1		*SET FRONT BUMPER FASTENER CLIP	Not Necessary	24.00 FS	*- FS
29	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	192.00 FS	*- FS
30	1		*SET RADIATOR GRILLE CLIP	Not Necessary	35.00 FS	*- FS
31	1		*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*- FS
32	1		*FRONT FENDER RR BRACKET RH	Not Necessary	7.10 FS	*- FS
33	1		*FRONT DOOR INNER TRIM BOARD	Serviceable	455.69 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 11,605.65 2,324.00

- List Item Discount on L Items 10.00/10.00% (S\$) 1,131.76 232.40

Total Parts (S\$) 10,473.89 2,091.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	-------------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,000.00	250.00
4	TOWING FEES	New	120.00	-
5	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
11	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
12	TO TRANSFER OF FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (S\$)			10,460.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >