

ASS. REC. BY:

REF: CS/SMD18008899/Dvd3^{p2}

Special Instruction:

Surveyor: Bryan ASSIGNMENT (Office)From (Person): Grace Teo of SMO Date/Time: 16/5/18 @ 1.59pm

Es. insatd Cost: _____ Bill to: _____

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: RD 6149G Insured: SKK 9299Hat Workshop m/s Soon Hock Motor Tel: 6483 6016of B1K10, AMK Ind. Park 2A #01-05/06Policy No: _____ Claim No: CMTD1802047 / GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/05/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS' wp' H.O.D. Endorsement: _____

Date/Time: 2.12pm @ 16/5/18 Person Contacted: Chris Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	RD 6149G - NA/INC18006391/h4 D.O.A: 6/4/18
	SKK 9299H-X
21/5/18	Email preli. revised to Grace Teo


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Transport Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / FR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **RD6149G** Yr Regn: _____
 Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer of: _____
 Make: **BYD**
 Colour: **White/Green** A/C: Insured / Std / NI / NA
 Sp/Reading: **152712** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **LC0CE4DB8G1071054**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / ☒ R/Rim / STD A/Rim or
 Tyre Size: F: **225/65 R17**
 R: **— " —**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Pirelli**
 Front: _____ Rear: _____
 R/Bal: **S** mm R/Bal: **S** mm
 L/Bal: **S** mm L/Bal: **S** mm
 D.O.A: **13/05/2018** D.O.I: **18/05/2018**
 Survey held at **Soon Hock AMK**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or:
Front
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____

04/06/18 **Sompo SKK 9299H**
pinjam 1/5 74001- with 4 days 3 yr (Red 3102.01, 3018)

RECEIVED 04 JUN 2018

Date/Time: File Pass to:

☐: Prel. Report

To:

☐: Final Report

Date/Time: File Return to:

4/6- typist

Report Format:

Lump Sum / L.B.I: 15

TP
74001Days Of Repair: **4**Resurvey No. of Trip: **2**

Add Fee:

☐ Site Insp: \$
☐ Interview: \$
☐ Test: \$
☐ Workshop: \$

Survey Fee:

Transportation:

1) 5.00

2) 1.00

3) 1.00

4) 1.00

5) 1.00

350

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 21 May 2018 2:12 PM
To: 'Teo, Grace'
Cc: 'Gnoh, Pau Loong'; 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD1802047/GPL - SUV(LKK)/ SKK9299H / RD6149G ON 13.05.2018
Attachments: RD 6149G PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle RD 6149G
Date of survey: 18/5/2018
Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 16 May 2018 2:13 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1802047/GPL - SUV(LKK)/ SKK9299H / RD6149G ON 13.05.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 16 May 2018 1:59 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Soon Hock Motor Pte Ltd <soonthockmotor@yahoo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1802047/GPL - SUV(LKK)/ SKK9299H / RD6149G ON 13.05.2018

Our Reference: CMTD1802047/GPL

Dear LKK AUTO/KENNETH,



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1802047/GPL
Our ref: CS/SMO18008899/Dvd3

Date: 21/5/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. RD 6149G


We thank you for your instruction on 16/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/5/2018 at the premises of M/s SOON HOCK MOTOR TTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,502.01
Revised Estimate Amount	: S\$9,260.20
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang

Motor Surveyor / Investigator

Please make arrangement to conduct the survey for RD6149G.

Please be informed that Gnoh Pau Loong the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Soon Hock Motor Pte Ltd [<mailto:soonhockmotor@yahoo.com.sg>]

Sent: Wednesday, May 16, 2018 1:18 PM

To: Teo, Grace

Subject: Re: CMTD1802047/GPL - PRI/ SKK9299H / RD6149G ON 13.05.2018

Hi,

we will like to appoint Mr Kenneth Kong from LKK Auto consultants for the survey. Tks.

Regards

Chris

On Wednesday, 16 May 2018, 11:44:47 AM SGT, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802047/GPL

Your Reference: RD6149G

Without Prejudice

EMAIL ONLY

Date: 16th May 2018

Attention:

M/S SOON HOCK MOTOR PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SKK9299H & RD6149G ON 13.05.2018

We refer to your Notice of Accident dated 16/05/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 16 May 2018 1:59 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Soon Hock Motor Pte Ltd; Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1802047/GPL - SUV(LKK)/ SKK9299H / RD6149G ON 13.05.2018
Attachments: SHM.pdf

Our Reference: CMTD1802047/GPL

Dear LKK AUTO/KENNETH,

Please make arrangement to conduct the survey for RD6149G.

Please be informed that Gnoh Pau Loong the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Soon Hock Motor Pte Ltd [mailto:soonhockmotor@yahoo.com.sg]
Sent: Wednesday, May 16, 2018 1:18 PM
To: Teo, Grace
Subject: Re: CMTD1802047/GPL - PRI/ SKK9299H / RD6149G ON 13.05.2018

Hi,

we will like to appoint Mr Kenneth Kong from LKK Auto consultants for the survey. Tks.

Regards
Chris

On Wednesday, 16 May 2018, 11:44:47 AM SGT, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802047/GPL
Your Reference: RD6149G

Without Prejudice
EMAIL ONLY

Date: 16th May 2018

Attention:
M/S SOON HOCK MOTOR PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SKK9299H & RD6149G ON 13.05.2018

We refer to your Notice of Accident dated 16/05/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



SOON HOCK MOTOR PTE LTD

soonhockmotor@yahoo.com.sg

Your Ref : SKK 9299 H
Our Ref : M5013/18

Date : 16/05/2018

VIA FAX : 6221 3147

The Motor Claims Department
Sompo Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention : Officer-In-Charge

Dear Sir/Mdm

**ACCIDENT INVOLVING RD 6149 G & SKK 9299 H & SJK 4454 X
ALONG CARPARK OF BLK 129 PENDING RD ON 13/05/2018.**

We refer to the above cited accident.

Investigation reveals that you are the insurer of SKK 9299 H at the material time.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved at AMK Autopoint.

We enclose the following document :-

- 1) GIA Report & Police Report
- 2) Quotation for vehicle RD 6149 G
- 3) LTA Search

Please note that our client reserves the right to reject the contents/findings of the survey report as they deem fit.

Regards
Claims Department

(No signature is required as this is a computer generated letter.)

Sompo Insurance Singapore Pte Ltd	
Claims Department	
16 MAY 2018	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 21:00
Date Of Accident	13/05/2018 08:00
Exact Location Of Accident	OPEN CPARK 129 PENDING RD (BKT PANJANG CC)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	RD6149G
Insured/Policyholder	
Name Of Registered Owner	HDT SINGAPORE TAXI PTE. LTD.
Co Reg No	201609494H
Email Address	JAYDENLI@HDT.COM.SG
Mobile Phone No	(LOCAL) +65-93360097
Alternative Phone No	OFFICE-93360097
Vehicle Particulars	
Manufacturer	BYD
Model	OTHERS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5085730780-01
Cover Note Number	
Driver	
Name of Driver	JOE WONG HENG WAH
NRIC No	S1150660G
Date Of Birth	14/11/1956
Occupation	OUTDOOR
Date Of Driving Pass	02/07/1982
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93360097
Fax Number	(LOCAL) +65-93360097
Contact Number	
EMail Address	JAYDENLI@HDT.COM.SG

Address 350 CLEMENTI AVE 2
#08-23

Postcode 120350

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : FEMALE / CHINESE / 30S / NAME UNKNOWN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CLEMENTI NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8729999 - FAX NO: 67748639

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: EMAIL TO MOTOR

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKK9299H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SOON CHOON SENG

NRIC/Passport Number S1774639A

Contact Number 93696113

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJK4454X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name JOE WONG HENG WAH
Approximate Age
Injuries Sustain WHIPLASH
Injured person in which vehicle? RD6149G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan



A - RDG 476
B - SKK 9299H
C - SKK 4454X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 17th May 2018 Sunday afternoon, I was driving my taxi RDG 476 as an employee of HDT Singapore with a lady Chinese passenger to the carpark of Bk 129 Pending Rd.

While entering the carpark over the hump on a one-way street, I saw a pedestrian crossing from left to right just before my entry into the said carpark. After the entry over the hump, I saw the street in front of me was clear while there were cars parked on both sides of the parking lots.

As I moved further at a very low speed, suddenly, a car came out from the second lot (1053) from the right side and I applied brake immediately but it was too late to stop after crossing the hump and as a result, I hit the car rode out from the parking lot 1053 causing damages to both cars (SKK 9299H and SKK 4454X, which was unattended).

No one was injured. No car videos available.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time: 17/5/2018
1600hrs



Reporting Centre Personnel's Signature
Name: Arizon De Souza
NIC/IN No: S823471TH

IMPORTANT NOTICE

1. Please REPORT IMMEDIATELY the details of the accident to your insurance company.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as TRUE and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and so copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 14/05/2018
1600hrs



Reporting Centre Personnel's Signature
Name: Arian
NRIC/VIN No.: S823471714

Police Report



**SINGAPORE
POLICE FORCE**



T/20180515/2003

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3
Report No. T/20180515/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/05/2018 00:51		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: JOE WONG HENG WAH			Address: APT BLK 350 CLEMENTI AVENUE 2 #08-23 SINGAPORE 120350		
ID Type / ID No.: NRIC NO / S1150860G			Contact No.: Home/Office: Mobile: 93360097		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 14/11/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/05/2018 08:00	Type of Location: Car Park
Location: Along Road 1 PENDING ROAD In the Carpark of Blk 129 Pending Road				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
RD6149G	Car				Slightly Damaged	1
SJK4454X	Car					0
SKK9299H	Car					0

Police Report



**SINGAPORE
POLICE FORCE**



T/20180515/2003

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180515/2003

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Drive			
Name	JOE WONG HENG WAH	ID No.	S1150660G
Related Vehicle	RD6149G (Car)	Contact No.	93360597
Hospital/Clinic	EJ FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/05/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Drive			
Name	SOON CHON SENG	ID No.	S1774639A
Related Vehicle	SKK9299H (Car)	Contact No.	93696113
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 13th of May 2018 at around 1800hrs, I was driving my taxi bearing RD6149G with one female passenger in the carpark of Blk 129 Pending Road. While I was entering the carpark, I stopped for a moment as there was a pedestrian crossing on the hump and I moved when the one way street was clear.

As I moved slightly after the hump, a car bearing the registration plate SKK9299H moved out from his parking lot(1053) from my right, and I bumped into his vehicle, causing it to bump into another parked vehicle bearing the registration plate SJK4454X.

I suffered whiplash from the accident due to the impact and received three days of MC. I managed to exchange particulars with the driver. My car suffered a dent in the front bumper. I wish to state that there are in car camera's in my said taxi.

I am lodging a report for record and insurance purposes.

Police Report



SINGAPORE
POLICE FORCE



T/20180515/2003

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129658
Tel No: 1800-8729999

3 of 3

Report No. T/20180515/2003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D/
NABIL FIKRI BIN ADNAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/05/2018 00:51

Officer In Charge Of Case:

TP / AEIT /
SI DZUL HAIRIE BIN RAMLI
Contact No.: 65476220

Classification Of Case:

Authentication Stamp
NP168



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 5 Raffles Quay #18-00 Singapore 048580
 Tel: (65) 6224 0010 Fax: (65) 6224 0039
 Operating Hours: Monday to Friday, 09:00 to 17:00
 UEN: S60500200 / GST Reg. No. M406017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MNI18062900 Vehicle Registration No: RD5149G
 Name (as shown on NRIC): JOE WONG HENG WAH NRIC/FIN/Passport No: S1150660G
 (* Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: 350 CLEMENTI AVE 2 #08-23 Singapore (120350)
 Contact (Tel): _____ Mobile No: 93360097
 Email Address: JAYDENLI@HDT.COM.SG
 Date of Accident: 13/05/2018 Time of Accident: 08:50
 Place of Accident: OPEN CPARK 129 PENDING RD (BKT PANJANG CC)
 Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments.

I wish to make the following amendment to my above attached GIA report in regards to my injury
suffered due to the accident. I have attached the police report.



Policyholder / Driver's Signature
 Date: _____

[Signature]
 Reporting Centre Personnel's Signature
 Name: [Name]
 NRIC/FIN No: [No]
 Date: [Date]

QUOTATION FOR VEHICLE RD 6149 G

PARTS			
1	1	FRONT BUMPER <i>distorted</i>	\$ 1,262.64 ✓
2	1	FRONT BUMPER LAMP (RH) <i>no CRACK mounting</i>	\$ 687.60 ✓
3	1	FRONT BUMPER SIDE GRILLE (RH) <i>3/4 CRACK</i>	\$ 48.36 ✓
4	2	FRONT BUMPER SIDE BRACKET (RH/LH) <i>SLV</i>	\$ 57.12 X
5	1	FRONT BUMPER SIDE REFLECTOR (RH) <i>SLV</i>	\$ 19.25 X
6	1	FRONT BUMPER CENTRE GRILLE <i>CRACK</i>	\$ 214.32 ✓
7	1	FRONT BUMPER REINFORCEMENT <i>2 1/2</i>	\$ 631.32 ✓
8	2	FRONT BUMPER SENSOR <i>Dem</i>	\$ 210.62 421.24 ✓
9	1	FRONT GRILLE WITH LOGO <i>CRACK</i>	\$ 1,531.80 ✓
10	2	FRONT HEADLAMP (RH/LH) <i>2 CRACK</i>	\$ 2,776.80 ✓
11	1	FRONT BONNET <i>1/2</i>	\$ 1,631.21 ✓
12	1	FRONT FENDER (RH) <i>repu</i>	\$ 742.80 X
		SUB TOTAL	\$ 8,994.67
		LESS 10%	\$ 809.52
		DISCOUNTED SUB TOTAL	\$ 10,024.46
			\$ 1,002.45
			\$ 9,022.01

S/NETT			
1	1	FRONT NUMBER PLATE <i>1/2</i>	\$ 40.00 25/-
2	1	FRONT NUMBER PLATE SCREW <i>1/2</i>	\$ 30.00 ✓
3	1	FRONT FENDER ADVERTISEMENT LOGO (RH) <i>NF</i>	\$ 100.00 X
		SUB TOTAL	\$ 170.00

LABOUR			
1		PANEL BEATING	\$ 600.00 500/-
2		SPRAYPAINTING CHARGES	\$ 600.00 540/-
3		WIRING CHARGES	\$ 30.00 ✓
4		REMOVE/REFIX FRONT PARKING SENSOR	\$ 80.00 40/-
		SUB TOTAL	\$ 1,310.00

GRAND TOTAL

\$ 10,502.01

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE.
THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS
REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF
REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE
NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE
SUBJECT TO CHANGE WITHOUT NOTICE.

9260.20

4157400/-



SOON HOCK MOTOR PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06, AMK Autopoint
Singapore 568047
6483 6016 (3 Lines) Fax: 6483 6014
Co. Reg. No. 199604559H

18/5/2018 21:00pm

HSA Andrew

Hsnn 4 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18008899/Dvd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 06-06-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 9299H	Veh. Inspected	RD 6149G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802047/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model	BYD	c.c	0
Engine No.	HIDDEN	Year of Reg.	-
Chassis No.	LC0CE4DB8G1071054	Colour	WHITE / GREEN
Odometer	152712	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	PIRELLI	5 mm
L/H Front Tyre	225/65 R17	PIRELLI	5 mm
R/H Rear Tyre	225/65 R17	PIRELLI	5 mm
L/H Rear Tyre	225/65 R17	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/05/2018	Inspection Date	18/05/2018
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. RD 6149G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	1,262.64	1,262.64
1	FRONT BUMPER LAMP (RH)	MOUNTING CRACKED	687.60	687.60
1	FRONT BUMPER SIDE GRILLE (RH)	CRACKED	48.36	48.36
2	FRONT BUMPER SIDE BRACKET (RH/LH)	SERVICEABLE	57.12	-
1	FRONT BUMPER SIDE REFLECTOR (RH)	SERVICEABLE	19.25	-
1	FRONT BUMPER CENTRE GRILLE	CRACKED	214.32	214.32
1	FRONT BUMPER REINFORCEMENT	BENT	631.32	631.32
4	FRONT BUMPER SENSOR	DAMAGED (2 PCS ONLY)	421.24	210.62
1	FRONT GRILLE WITH LOGO	CRACKED	1,531.80	1,531.80
2	FRONT HEADLAMP (RH/LH)	CRACKED	2,776.80	2,776.80
1	FRONT BONNET	BENT	1,631.21	1,631.21
1	FRONT FENDER (RH)	TO REPAIR SEE LABOUR	742.80	-
	LESS 10% DISCOUNT		-1,002.45	-899.47
			9,022.01	8,095.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	40.00	25.00
1	FRONT NUMBER PLATE SCREW (SN)	NECESSARY	30.00	30.00
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NOT FITTED	100.00	-
			170.00	55.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER (RH).		600.00	500.00
	SPRAYPAINTING CHARGES.		600.00	540.00
	WIRING CHARGES.		30.00	30.00
	REMOVE/REFIX FRONT PARKING SENSOR.		80.00	40.00
	-		-	-
	-		-	-
	-		-	-
			1,310.00	1,110.00
GRAND TOTAL			10,502.01	9,260.20

Report Ref No. CS/SMO18008899/Dvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,400.00
---	--	--	----------

Report Ref No. CS/SMO18008899/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.