

INSURANCE OWNERS

Surveyor:

MTH

DOI:

ASSIGNMENT

5/6/18

Date / Time:

5/6/2018

Registered in Merimen:

16/05/2018

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKX 9496L

Name of Insured:

POH WONG SOON

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.: 15/5/18

Is driver the owner?

(YES (NO))

Nature of Accident:

If NO, Driver Name / Age:

HUANG PUNSHAN

Driver Tel No.:

92983892

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

PMPV 2016 - 0000316-01

BMW 520

PIE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SKC 25386



INSRS:

WSP:

Tel:

Liability:

RMKS:

du



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/6
Bm

SKX 25386 X; SKX 9496L X

19.6.18

Final Rep Liability clear

6.7.18

FILE POSS TYPIST TO PREPARE REPORT.

- LPE received the ORI LOD. NO amendment done.

RECEIVED 8 JUL 2018

RECEIVED 26 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

6/6

Sent By:

Bm

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost:

P/P \$53,813.48

(3 days)

Reduction:

37 %

Email

Call

FINAL SETTLEMENT

Date/Time: 18.7.18

Confirm with: FINANCE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 21

If NO or B 28, Ass. Lia :

Repair Cost:

W/LAS

\$54,144.62

D/O REAR ENDS TP.

Loss of Rental (LOR): W/LAS

\$5 321.00

(3 days) x +100

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

\$5 -

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

Total:

\$5 4,465.62

Global Sum \$5:

FINAL PAYMENT

Date/Time: 18.7.18

Confirm with: FINANCE

Email

Call

Payee 1:

\$5 4,465.62

Name 1:

CYCLE & CARBAGE INDUSTRIES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$500

COPY SENT
26/7/18

REF: FWD

ASSIGNMENT

From:

Date:

5/6/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKC 25389

at Workshop m/s

Cycle & Carriage Ind.
188 Pender Loop

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh.

Kenslyn
10 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

-

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKC 25389

Yr Regn:

2011, Aug

Type: ☒ M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C180

c.c 1597

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

83364

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 204 04 5217 578470

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

↓

mm

D.O.A.

D.O.I.

5/6/18 01030

Survey held at

8C Pender Loop

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P: 3,873.48 (RED: 3,243.48 37%)

Date/Time File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 ___ \$ + RS ___ \$

2 Photos

3 Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD18008908/T1ea3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 16-05-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 9496L	Veh. Inspected	SKC 2538G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/05/2018	Inspection Date	05/06/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKC2538G

Mr Lim Thiam Wee, Thomas

Blk 8 Boon Keng Road
#39-150
Singapore 330008

Mobile: 94555651

Vehicle & Document Information

WIP No **23664**
Reg No/Reg Date **SKC2538G / 03/08/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2040452A578470**
Engine No **27191031346023**
Make/Model **MB/C 180K (BlueEFFICIENCY) S**
Colour/Trim **026 650 Calcit Whit/ 042 221 Leather BI**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	15/05/2018/ 17:48	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				960
A BPILAB				1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				800
RESpray REAR BUMPER				960.00
A BPILAB			0.10	✓ 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				✓ 120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M REAR BUMPER	1.00	1361.96	00.00	de 1361.96
M CTR/ REAR BUMPER CHROME MOULDING	1.00	186.40	00.00	re 186.40
M LH/ REAR BUMPER CHROME MOULDING	1.00	132.56	00.00	re 132.56
M RH/ REAR BUMPER CHROME MOULDING	1.00	132.56	00.00	re 132.56
M LH/ REAR BUMPER SIDE STABILITY	1.00	36.21	00.00	3 36.21
M RH/ REAR BUMPER SIDE STABILITY	1.00	36.21	00.00	36.21
M COVER, REAR-END FLOOR	1.00	45.62	00.00	MIN x 2? 45.62
M CTR/ REAR BUMPER REINFORCEMENT	1.00	135.13	00.00	? 135.13
M REAR CROSS MEMBER	1.00	670.31	00.00	? 670.31

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Confirmed & accepted by
Date:

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Tan Jiah 97495749
wp
5/6/18 2130
3 days
Surv@lkkauto.com
Review before part

Nett **6,116.96**
7% GST on **6116.96** **428.19**
Total Payable 6,545.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKX9496L	Accident Date	: 15/05/2018
TP Vehicle No	: SKC2538G	Assignment Date	: 16/05/2018
Make	: MERCEDES-BENZ C180	Est. Duration of Repair	: 3 days
Date of Inspection	: 05/06/2018		
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,116.96
Revised Amount	:S\$	3,873.48
Check Items (Estimated)	:S\$	923.48
Total	:S\$	4,796.96

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 19 June 2018 9:05 AM
To: 'kerlyn.ong@cyclecarriage.com.sg'
Cc: Admin A
Subject: RE: Accident involving motor vehicle nos. SKC2538G & SKX9496Lalong SLIP RD OF SERANGOON RD, Accident date: 15/05/2018

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Kerlyn Ong Kai Li [mailto:kerlyn.ong@cyclecarriage.com.sg]

Sent: Thursday, 31 May, 2018 9:32 AM

To: Motor Claims SG - SG Common

Subject: RE: Accident involving motor vehicle nos. SKC2538G & SKX9496Lalong SLIP RD OF SERANGOON RD, Accident date: 15/05/2018

Dear Officer,

Please arrange to survey on 05/06/2018 10am.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: motorclaims.sg@fwd.com [<mailto:motorclaims.sg@fwd.com>]
Sent: Friday, 25 May, 2018 10:33 AM
To: Kerlyn Ong Kai Li
Subject: RE: Accident involving motor vehicle nos. SKC2538G & SKX9496Lalong
SLIP RD OF SERANGOON RD, Accident date: 15/05/2018

WITHOUT PREJUDICE

Dear Kerlyn,

We refer to your email of 25 May 2018.

Liability is clear for this accident.

Thank you.

THIS EMAIL SHALL NOT BE CONSTRUED AS AN ADMISSION OF LIABILITY ON THE PARTS
OF WHOMSOEVER IS CONCERNED.

Kind Regards
Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li [<mailto:kerlyn.ong@cyclecarriage.com.sg>]
Sent: Friday, 25 May, 2018 10:05 AM
To: Motor Claims SG - SG Common
Subject: RE: Accident involving motor vehicle nos. SKC2538G & SKX9496Lalong
SLIP RD OF SERANGOON RD, Accident date: 15/05/2018

Dear Officer,

Any update on the liability?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li
Sent: Tuesday, 15 May, 2018 6:01 PM
To: 'motorclaims.sg@fwd.com'
Subject: Accident involving motor vehicle nos. SKC2538G & SKX9496L along SLIP
RD OF SERANGOON RD, Accident date: 15/05/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SKC2538G), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SKX9496L) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at kerlyn.ong@cyclecarriage.com.sg.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and

- destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage
- Industries Pte Ltd and/or any of its related corporations.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	16 May 2018 17:05	Cim Veh Model Changed	(204375) MERCEDES-BENZ C180 1.6 Kompressor (A).	[A] HOW MEI KWAN
2	16 May 2018 17:05	Cim Created	Reg No: SKC2538G, Acct Date: 2018/05/15. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Cycle & Carriage Industries Pte Ltd (Pandan Loop)	[A] HOW MEI KWAN
3	16 May 2018 17:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):: RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : VICOM Ltd.	[A] HOW MEI KWAN
4	16 May 2018 17:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/25	[A] HOW MEI KWAN
5	16 May 2018 17:05	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
6	16 May 2018 17:05	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
7	17 May 2018 15:50	Cim Registration Modified	Pol No:->PNPV2016-00000316-01.	[I] Josey Loh
8	06 Jun 2018 16:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/25	[A] HOW MEI KWAN
9	09 Jul 2018 15:30	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
10	09 Jul 2018 15:30	Cim Dtl Modified	JPJ Reg. Date: -> 2011/08/03.	[A] JOANNE LEE KHANG MIN
11	09 Jul 2018 15:30	Cim Details Notified		[A] JOANNE LEE KHANG MIN
12	10 Jul 2018 10:16	Adj Mandate Request	Cur.Req:4465.62:LIABILITY: 100% B:27 OLD REAR ENDED TP QUANTUM: (a) COR w/G ST: \$4,144.62 + (b) LOR w/GST: \$321.00 (3days x \$100) Total: a+b = \$4,465.62 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1825831	06/06/2018 16:17	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKC2538G	SKX9496L	10.70

Print Received Message

This mail is associated with :

***SKC2538G (1201800006070)**
[SKX9496L]

TP

LIM THIAM WEE THOMAS

May 15 2018 1:00PM

[POH LEONG SOON]

Cycle & Carriage Industries Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 10/07/2018 16:29 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4465.62) - SKC2538G - Claim Handler: Josey Loh

Approved:4465.62.

24-HOUR AIG AUTO HOTLINE: +65 6338 6200**IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.****What can the 24-hour AIG Auto Emergency Hotline provide for you?**

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident) related
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (85) 6418-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 6 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Mercedes Benz Authorised Body Care and Repair Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Daimler Fleet Management Singapore Pte Ltd
Activation Hotline: 82821711

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.98), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.98).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8026741Z**

Name **LIM THIAM WEE, THOMAS**

Birth Date: **02 Sep 1980**

Issue Date: **04 Apr 2015**

002412956G

SG 50

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8026741Z**

Name **LIM THIAM WEE, THOMAS**

林添伟

Race **CHINESE**

Date of birth **02-09-1980** Sex **M**

Country of birth **SINGAPORE**

S8026741Z

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

EFFECTIVE DATE **18 Feb 2002**

FOR C&C USE ONLY



NRIC No: **S8026741Z**



Date of issue **04-09-2010**



Licence No: **S8026741Z**

NP 438A

APT BLK 8 BOON KENG RD #39-150
SINGAPORE 330008

NRIC No: **S8026741Z**

Date: **27/04/2011**

No: **0768841**

Our ref: SKC2538G
Your ref: _____

1201800006070

Date: - 2 JUL 2018

Direct Settlement

To: FWD Singapore Pte Ltd

Singapore _____

RECEIVED
05 JUL 2018

Attn: Motor Claims Department

FWD Singapore Pte Ltd

Re: Accident Involving Motor Vehicle Nos. SKC2538G & SKX9496L
At/Along SLIP RD OF SERANGOON RD On 15/05/2018 @ 13:55

I am the owner of vehicle no. SKC2538G that was involved in an accident with your insured vehicle no. SKX9496L of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -

1. Cost of Repairs	\$ 4144.62
2. Loss of Use / Rental (3 days @ \$ 107 per day)	\$ 321.00
3. LTA/GIA Search Fee	\$ _____
4. GIA Report Fee	\$ _____
5. Others	\$ _____
Total:	\$ 4465.62

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of CYCLE & CARRIAGE INDUSTRIES PTE LTD at Telephone No: 67714420 (Ms Kerlyn Ong) / 67714304 (Ms Amanda Ang).

I hereby give full authority to CYCLE & CARRIAGE INDUSTRIES PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully


Name & Signature

Address: C/o. 188 Pandan Loop Singapore 128378
Cc: Ms Kerlyn Ong/ Ms Amanda Ang
E-mail: kerlyn.ong@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg
Fax No. 67795383

LETTER OF AUTHORIZATION

To: FWD Singapore Pte Ltd

Singapore _____

Attn.: Motor Claims Department

Dear Sir / Mdm,


MOTOR ACCIDENT INVOLVING SKC2538G **(OWNER'S VEHICLE**
NO.) AND SKX9496L **(3RD PARTY'S VEHICLE NO.) ON** 15/05/2018
(DATE) AT 13:55 **(TIME)** AT/ALONG
SLIP RD OF SERANGOON RD **(ROAD)**

I am the registered owner of SKC2538G (Vehicle No.).

I hereby authorise CYCLE & CARRIAGE INDUSTRIES PTE LIMITED and its agents or any person(s) authorised by Cycle & Carriage Industries Pte Limited to do all or any of the following:-

- Submit, resolve and make any claims which I may have against the 3rd party insurers; and/or
- Execute and sign discharge voucher, indemnity forms and all necessary documents in connection with and arising from the above claim.

All payment towards settlement of my claim should be made in favour of CYCLE & CARRIAGE INDUSTRIES PTE LIMITED.



Registered Owner's Signature
(Company stamp & authorized signature if it is a company-registered vehicle)
Name : LIM THIAM WEE THOMAS
NRIC No. : S8026741Z
Date : _____

RELEASE

Claim Reference:	1201800006070
Surveyor's Reference:	CC4/FWD18008908/T1ea3
TP Reference:	SKC2538G

We, **CYCLE & CARRIAGE INDUSTRIES PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SKC 2538G** ("Vehicle") to accept the sum of **\$4,465.62**, being the amount claimed for **\$4,144.62** (repair costs), **\$321.00** (loss of rental/ ~~use~~), **\$ -** (loss of income), **\$ -** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **15/05/2018** (date of accident) at / along **SLIP RD OF SERANGOON RD** (location) involving vehicle no/s. **SKC 2538G** and **SKX 9496L**.


This is pursuant to the inspection conducted on **05/06/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SKX 9496L** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

CLAIMANT

 Dated this 24 day of 07 2018
AMANDA ANG
OFFICER - ADMIN
BODY CARE & REPAIR CENTER
DID: 6771 4304
FAX: 6779 5383
EMAIL: amanda.ang@cyclecarriage.com.sg

[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



MTH

[FWD's appointed surveyor with Co. Stamp]


For and on behalf of FWD Singapore Pte. Ltd.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address		Owner Name & Vehicle Info	
FWD Singapore Pte Ltd		Cust No/Name	/Mr Lim Thiam Wee, Thomas
Motor Claims Department		Reg No/Reg Date	SKC25386 / 03/08/2011
6 Temasek Boulevard		Date In/Mileage	05/06/2018/ 83364
#18-01 Suntec Tower Four		Chassis No	WDD2040452A578470
Singapore 038986		Engine No	27191031346023
Contact No 68208888		Make/Model	MB/C 180K (BlueEFFICIENCY) S
		Colour/Trim	026 650 Calcit Whit/ 042 221 Leather B1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No	
WF000076	Credit	14/06/2018/ 16:54	K0	301 / Kerlyn Ong	23664	28143106	
Description of Goods / Services					Qty	Unit Price S\$	Amount S\$
Z REQUEST							
Customer Request							
A BPILAB							960.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							
A BPIRES							600.00
RESPRAY REAR BUMPER							
A BPILAB						0.10	380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							
A BPILAB							120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT							
M BPNSUN							F.O.C.
POLICY NO/ACC DATE : 2100267971-06 // 15/05/2018							
DRIVE IN/TP VEHICLE NO. : 15/05/2018 // SIKX9496L - FWD							
DATE IN/DATE SURVEY: 05/06/2018 1030 // LKK - TAUFIKH							
DIRECT SETTLEMENT : 25/05/2018 // FWD - JOSEY							
X	REAR BUMPER				1.00	1361.96	1361.96
X	CTR/ REAR BUMPER CHROME MOULDING				1.00	186.40	186.40
X	LH/ REAR BUMPER CHROME MOULDING				1.00	132.56	132.56
X	RH/ REAR BUMPER CHROME MOULDING				1.00	132.56	132.56

Parts	1,813.48		Nett	3,873.48
Labour	2,060.00	7% GST on	3873.48	271.14
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	4,144.62
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	0.00		Total Due	4,144.62
Total(w/o GST)	3,873.48			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel 67532536 Fax:67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

LIM THIAM WEE THOMAS

INVOICE : AR1806-0145
DATE : 12/06/2018
TERMS : C.O.D
STAFF ID : ELAINE
AGREEMENT NO. : HA201806-0054

ATTN: ACCOUNTS PAYABLE

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Vehicle Reg No : SLJ9976E
Make / Model : TOYOTA ALTIS 1.6 AUTO
Rental Dates : Rental Billing From 05/06/2018 To 07/06/2018 (incl)
Period : 3 days
Rental Rate : S\$ 107.00 Per Day (Including GST)
Reference No : SKC2538G

300.00

AMOUNT: S\$
THREE HUNDRED TWENTY-ONE DOLLARS ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 300.00
GST 7% : 21.00

TOTAL S\$: 321.00

Please make your cheques payable to : CHAN'S & SONS ENTERPRISE



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

RENTAL AGREEMENT

201806-0054

Hirer's Name Lim Thiam Wee THOMAS		Date of Birth 02.05.1980	Passport/ Nric No. S80267412	Nationality
Address 8 BROWN KERRY RD		Occupation	Driving Licence No.	Date of Expiry
#38-150	Postal Code 330008	Contact No.	Mobile Phone No. 94555651	
Joint Hirer's / Guarantor's Name		Date of Birth	Passport/ Nric No.	Nationality
Address 28A Jalan Lempeng #22-16		Occupation	Driving Licence No.	Date of Expiry
	Postal Code 128808	Contact No.	Mobile Phone No.	

CHECK OUT

Date 5.6.18	Time 10.10 am	Mileage KM	E 1/4 1/2 3/4 F
Date 7.6.18	Time 4pm	Mileage KM	Remarks fw D.

CHECK IN

IMPORTANT NOTES:-

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability - First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension:- One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT		RATE (\$)	TOTAL (\$)
RATE	3	@	100	300.00
DISCOUNT				
GST @ 7%				21.00
TOTAL				321.00
EXTENSION				
new hire				
OKC 25386				
DEPOSIT (refundable) S\$			K	
CHANGED OVER FROM VEH.			DATE	

I/We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.
I/We declare that all information given on this form is true and accurate.

Thom
Hirer's Signature

Joint Hirer's/ Guarantor's Signature

for CHAN'S & SONS ENTERPRISE

VEHICLE NO.

SL999262

MODEL

FROM

RETURN

*Estimate Date. For actual return use CHECK IN

OPERATING HOURS: MONDAY TO FRIDAY 8.30AM TO 5.30PM. SATURDAY 8.30AM TO 12.30PM. CLOSED ON SUNDAY & PUBLIC HOLIDAY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 May 2018 Edit Reg		15 May 2018 00:00 Edit Adj Rpt	S\$3,873.48 Edit Estimates	S\$3,873.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	POH LEONG SOON, ID: S7612844H								
Main Claimant:	LIM THIAM WEE THOMAS, ID: S8026741Z								
Vehicle Reg. No.:	SKC2538G	Date of Loss:	15/05/2018 13:00 - :59 [81 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800006070	Policy/Cover Note No.:	PNPV2016-00000316-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX9496L	Policy No. (Claimant):	2100267971-06						
		Excess:							
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (10/07/2018): Alert - Adj Mandate Approved (S\$4465.62) - SKC2538G - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC2538G (1201800006070)

[SKX9496L]

































TP





LIM THIAM WEE THOMAS

May 15 2018 1:00PM

[POH LEONG SOON]

Cycle & Carriage Industries Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 16:17	Adjuster Immediate Advice	 Load HTML	
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 16:17	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	
2	06/07/18 16:17	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	
3	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
4	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
5	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
6	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
7	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
8	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
9	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
10	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
11	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
12	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
13	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
14	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
15	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
16	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
17	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
18	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
19	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
20	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
21	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
22	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
23	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
24	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
25	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
26	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
27	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
28	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
29	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	
30	06/07/18 16:17	General View	 Load JPG <input checked="" type="checkbox"/>	

Letters / Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	06/07/18 16:17	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/18 17:06	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load PDF	
2	16/05/18 17:06	ACKNOWLEDGEMENT EMAIL TO FWD DD 16.05.2018	 Load PDF	
3	24/05/18 08:42	EMAIL - FWD TO OI DD 17.05.2018	 Load PDF	
4	31/05/18 14:54	ACKNOWLEDGEMENT EMAIL TO FWD DD 31.05.2018	 Load PDF	
5	09/06/18 16:22	TP ESTIMATE-MARKED	 Load PDF	
6	09/07/18 15:39	WORKSHOP INVOICE	 Load PDF	
7	09/07/18 15:39	RENTAL RECEIPT	 Load PDF	
8	09/07/18 15:39	LOD	 Load PDF	
9	27/07/18 09:52	Release Voucher	 Load PDF	
10	27/07/18 09:52	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/05/18 15:51	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX9496L (Insd veh)	Model:	MERCEDES-BENZ C180 1.6
	SKC2538G (TP veh)		KOMPRESSOR (A)
Date of Accident:	15/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,545.15
Final Repair Cost	:	\$	4,144.62
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	321.00 3 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,465.62
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Cycle & Carriage Industries Pte Ltd	:	\$ 4,465.62
2)		:	\$

JOANNE LEE KHANG MIN

27 Jul
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18008908/T1EA3Q2

Date: 27/07/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2016-00000316-01

Claimant Vehicle No: SKC2538G Insured Vehicle No: SKX9496L

Date of Loss: 15/05/2018 Nature of Claim: TP Claim No: 1201800006070

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC2538G**
 Make & Model: MERCEDES-BENZ C180, 1.6 Kompressor (A) Engine No: 27191031346023
 Reg. Date: 03/08/2011 (Man. Year: 2011) Chassis No: WDD2040452A578470
 Colour: White Odometer: 83364 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,736.96	1,813.48	923.48	33.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,060.00	1,320.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,116.96	3,873.48	2,243.48	36.68
+ GST 7.00/7.00% (S\$)	428.19	271.14	157.05	36.68
Nett Amount (S\$)	6,545.15	4,144.62	2,400.53	36.68
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		4,465.62		

INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 05/06/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
 (Pandan Loop)
 188 Pandan Loop
 Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC2538G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,361.96 FS	*1,361.96 FS
2	1		*CTR/ REAR BUMPER CHROME MOULDING	Necessary	186.40 FS	*186.40 FS
3	1		*LH/ REAR BUMPER CHROME MOULDING	Necessary	132.56 FS	*132.56 FS
4	1		*RH/ REAR BUMPER CHROME MOULDING	Necessary	132.56 FS	*132.56 FS
5	1		*LH/REAR BUMPER SIDE STABILITY	Not Necessary	36.21 FS	*- FS
6	1		*RH/REAR BUMPER SIDE STABILITY	Not Necessary	36.21 FS	*- FS
7	1		*COVER,REAR- END FLOOR	Not Necessary	45.62 FS	*- FS
8	1		*CTR/ REAR BUMPER REINFORCEMENT	Not Necessary	135.13 FS	*- FS
9	1		*REAR CROSS MEMBER	Not Necessary	670.31 FS	*- FS
F=Franchise part, S=SpcNett.						
Total Parts (S\$)					2,736.96	1,813.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY REAR BUMPER	New	960.00	600.00
3	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (S\$)			3,380.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >