



Your Ref: AEMD/105/009/2018/032

Date: 23<sup>rd</sup> May 2018

Our Ref: CS1/SPF18008928/K1qbs2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SGT 2672J INSURED VEHICLE: QX 4925C ACCIDENT DATE: 01/03/2018**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGT 2672J from M/s Kim Auto Assessors Pte. Ltd.
- b) Colour damaged vehicle photographs of SGT 2672J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGT 2672J
Make & Model	: Toyota Corolla Altis 1.6 Auto
Year of Registration	: 2007
Chassis Number	: MR053ZEC107142278

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.