

Your Ref: AEMD/105/009/2017/171

Date: 21st May 2018

Our Ref: CS1/SPF18008939/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHA 9799U INSURED VEHICLE: GBB 7948K ACCIDENT DATE: 22/11/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHA 9799U from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHA 9799U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHA 9799U
Make & Model	: Mercedes Benz E220 CDI (E5)
Year of Registration	: 2013
Chassis Number	: WDD2120022A758753
Engine Capacity	: 2143 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.