



Your Ref: AEMD/105/009/2018/005

Date: 21st May 2018

Our Ref: CS1/SPF18008941/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SHC 7948J INSURED VEHICLE: QX 1026S ACCIDENT DATE: 11/01/2018**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 7948J from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHC 7948J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 7948J
Make & Model	: Hyundai I-40
Year of Registration	: 2015
Chassis Number	: KMHLB41UMFU068351
Engine Capacity	: 1685 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.