

CC 6 / AIG1800

8977, Uwa's

IDAC

SE OWNER

ASSIGNMENT

DOI:

12/5/18

Date / Time:

Registered in Merimen:

12/5/18

12/5/18

Pre-assign / CCU / FTE

Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

SLV2801J

LIAW Chong Hai

HP:

D.O.A:

4/3/2018

(YES / NO)

Nature of Accident:

Lee Sabarmudin Am Lee Sabarmudin

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

170093583

N. ANTHAN

Junction Tampines Ave 4

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SLK937C

INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Ol:

After call ltr to Ol:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to Ol:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3/15/18

SLK 937C - X; SLV2801J - X

To submit independent?

Receive O2's video.

16/4/19

Called O2D, Mr Lee confirm accident details. Inform TP claim. agree to settle at left. letter and out

16/4/19

JULIAN

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

Email ☐ Call ☐

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Final Liability:

SS

100 (Agreed / Assessed) BOLA S/N No.:

27.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2193.50

(5 days) X 66.95

Loss of Rental (LOR):

SS

334.75

(\$ x days)

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical

SS

-

(e.g. Tow/ Independent)

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

2535.74

Global Sum SS: 2530.00

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

2530.00

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Pegasus Engineering & Trading Pte Ltd

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

GIA 15/19

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 9317C

at Workshop m/s Pegasus

of _____

Insured: SL 1/2 815

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: C1 Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLK 9317C Yr Regn: 217

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Mazda 3 c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 89287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6 BN 22A 8 H 0137640

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/3/18 D.O.I. 17/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/5/18 4/5 2050 confirmed with home.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

ced. \$2518.80

57%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18008977/Uwa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-05-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLV 2801J	Veh. Inspected	SLK 9317C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/03/2018	Inspection Date	17/05/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

Confirmation with Marcus *Not Allud* *the*

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer : *17-05-2018* *1/5 @ 2050*

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn : *Lkk Marcus*
Tel :
Fax : *17-05-2018 @ 1350hrs*

3 days
the photo after up
17/5/18

Quotation No : QO18/03-1031	Quotation Date : 05/03/2018	Terms : 30 DAYS
Vehicle No : SLK9317C	Chassis No : JM6BN22A8H0137640	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
marks : TP INSURER:AIG, TP VEHICLE NO:SLV2801J, DATE OF ACCIDENT: 04/03/2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>20/22</i>	1	1,075.0000	1,075.00
2	O/S REAR BUMPER REFLECTOR <i>11</i>	1	51.0000	51.00 <i>x</i>
3	O/S REAR BUMPER END SPLASHIELD COVER <i>11</i>	1	80.0000	80.00 <i>x</i>
4	REAR BUMPER CLIPS <i>rec</i>	8	5.0000	40.00
5	REAR BUMPER REINFORCEMENT <i>20</i>	1	538.0000	538.00
6	REAR BUMPER SIDE RETAINER <i>11</i>	2	37.0000	74.00 <i>x</i>
7	REAR BUMPER SIDE HOLDER <i>11</i>	2	46.0000	92.00 <i>x</i>
8	REAR BUMPER SIDE HOLDER RIVETS <i>11</i>	4	6.0000	24.00 <i>x</i>
9	N/S REAR BUMPER TOW COVER <i>11</i>	1	17.0000	17.00 <i>x</i>
10	REAR BUMPER CENTRE BRACKET <i>11</i>	1	10.0000	10.00 <i>x</i>
11	REAR END PANEL <i>rec</i>	1	506.0000	506.00 <i>x</i>
12	REAR END PANEL INNER TRIM <i>11</i>	1	86.0000	86.00 <i>x</i>
13	BOOTLID MAZDA 3 BADGE <i>rec</i>	1	54.0000	54.00
14	BOOTLID SKYACTIV BADGE <i>rec</i>	1	64.0000	64.00
15	BOOTLID CENTRE EMBLEM BADGE <i>rec</i>	1	75.0000	75.00
16	LESS 20% (ITEMS 1-15)	1	-557.2000	-557.20
17	REAR BUMPER PARKING SENSOR <i>shub</i>	1 <i>set</i>	450.0000	<i>200</i> 450.00
18	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	750.0000	<i>450</i> 750.00
19	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	<i>50</i> 120.00
20	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	120.0000	<i>60</i> 120.00
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	750.0000	<i>300</i> 750.00

1846
1476.80
2556.80
2045.44

P-1846
1476.8
2556.8

C/F 0.00
Page 1 of 2

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1031	Quotation Date : 05/03/2018	Terms : 30 DAYS
Vehicle No : SLK9317C	Chassis No : JM6BN22A8H0137640	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER:AIG, TP VEHICLE NO:SLV2801J, DATE OF ACCIDENT: 04/03/2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
22	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	30 50.00
23	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	100.0000	111X 100.00

LKK Auto Consultants hence notify the Rep of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	4,568.80
GST(7.00%)	319.82
Total (SGD)	4,888.62

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 7200G

Vehicle Details

Vehicle No.: SLK9317C
Vehicle to be Exported: Yes
Intended De-registration Date: 05 Mar 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN
1.5L SP.6EAT
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: P520423453
Chassis No.: JM6BN22A8H0137640
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$14,777.00
Original Registration Date: 07 Feb 2017
First Registration Date: 07 Feb 2017
Transfer Count: 0
Actual ARF Paid: \$9,777.00

Intended PARF Rebate Details

ARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Feb 2027
PARF Rebate Amount: \$7,332.00

Intended COE Rebate Details

COE Expiry Date: 06 Feb 2027
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$48,000.00
COE Rebate Amount: \$38,400.00
Total Rebate Amount: \$45,732.00

The information contained herein is correct as at 05 Mar 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLK9317C

Vehicle to be Exported: No

Intended De-registration Date: 17 May 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: P520423453

Chassis No.: JM6BN22A8H0137640

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$14,777.00

Original Registration Date: 07 Feb 2017

First Registration Date: 07 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$9,777.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 06 Feb 2027

PARF Rebate Amount: \$7,332.00

Intended COE Rebate Details

COE Expiry Date: 06 Feb 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$48,000.00

COE Rebate Amount: \$41,866.00

Total Rebate Amount: \$49,198.00

The information contained herein is correct as at 17 May 2018

OK



Tel: 6858 1846 / HP 9628 6508
Fax: 6858 0877

Date 30-08-2018

Dear Sir/Madam,

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

☒ Original Tax-invoice number 1V18/06-1029
☐ police report / police result
☒ Certificate Of Insurance _____
 ☒ Vehicle search result
☐ Letter from Grab
 ☒ Authorisation To Act - Higher owner
☒ Rental Tariff

*Survey under insurance instruction Lkk

a)	Cost of repair (inclusive GST)	\$ 2,193.50
b)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ 7.49
c)	Loss of rental <u>5</u> days @ \$ <u>66.95</u>	\$ 334.75
d)	Loss of earnings / rental fees _____ days @ \$ _____	\$ -
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ 200.00
	Total	\$ 2,735.74

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Ouw

Email: claims@pegasusengr.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18008977/Uwa3

16 April 2019

Liaw Cheng Hai
Blk 635A Senja Road
#30-253
Singapore 671635

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 2801J AND SLK 9317C ON 04/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLK9317C

ACCIDENT INVOLVING SLV2801J

ALONG/AT Junction of Tampines Avenue 4 to Tampines Central ON 04.03.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 201617200G

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 23.07.2018

Signature



Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Pegasus Engineering & Trading Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$2,530.00 (Global Sum) for vehicle no SLK 9317C that was damaged pursuant to the accident which occurred on 04/03/2018 (date) along TAMPINES AVE 4 (location) involving vehicle no/s SLV 2801J.

This is pursuant to the inspection conducted on 17/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD ("the third party claimant") of vehicle no. SLK 9317C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLK 9317C (vehicle no.) as a result of the accident.



We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 06 (day) of May (month) 2019 (year)

cks

Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Vehicle Model : Mazda 3 Sedan 1.5
Vehicle No : SLK9317C
Chassis No : JM6BN22A8H0137640

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : SLV2801J
Date of accident : 04.03.2018

Tax Invoice No : IV18/06-1029
Invoice Date : 20.06.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 2,050.00
Sub Total	\$ 2,050.00
GST (7.00%)	\$ 143.50
Total	\$ 2,193.50

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD


Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee
Grab Rental Pte Ltd

Thank you



Lee Ming Hui Kelvin has successfully logged out.

Your last login date and time was 05 Mar 2018, 17:43:24.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(\$\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SLV2801J	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	05 Mar 2018 / 17:44:11

Enquire Vehicle & Owner Information (Vehicle No. SLV2801J As At 04 Mar 2018 / 15:50:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLK9317C

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S1155601I
Owner Name: LIAW CHENG HAI
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 47
Registered Street Name: HUME AVENUE
Registered Unit No.: # 07 - 12
Registered Building Name: -
Registered Postal Code: 598748

Current Vehicle Details

Vehicle No.: SLV2801J
Make Description/Model: NISSAN / QASHQAI 1.2 DIG-T CVT
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018 Edit Reg		17 May 2018 00:00 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIAM CHENG HAI , ID: S11556011, Tel: +6599999999								
Main Claimant:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLK9317C	Date of Loss:	04/03/2018 00:00 - :59 [12 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1405140811SG	Policy/Cover Note No.:	1700093583 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLV2801J	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, S39216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (22/05/2018): No Policy Found AIG_SG (18/05/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK9317C (1405140811SG)
[SLV2801J]

TP























GRAB RENTALS PTE LTD

Mar 4 2018 12:00AM

[LIAW CHENG HAI]

Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	13/04/19 20:02	OI Video - Accident												1	Load MP4					
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	17/05/18 17:43	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>				
2	17/05/18 17:43	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>				
3	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
4	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
11	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
12	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
15	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
16	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
17	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
18	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
19	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
20	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
21	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
22	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
23	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
24	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
25	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
26	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
27	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
28	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
29	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				
30	17/05/18 17:43	General View												1	Load JPG	<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 11:59	TP ESTIMATE - MARKED	 Load PDF	
2	25/05/18 11:59	TP GIA REPORT	 Load PDF	
3	15/05/19 11:57	WORKSHOP INVOICE	 Load PDF	
4	15/05/19 11:57	AUTHORISATION TO ACT FORM	 Load PDF	
5	15/05/19 11:57	Release Voucher	 Load PDF	
6	15/05/19 11:57	RENTAL RATES	 Load PDF	
7	15/05/19 11:57	LTA SEARCH	 Load PDF	
8	15/05/19 11:57	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/05/18 12:26	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV2801J (Insd veh)	Model:	MAZDA 3 1.5 SEDAN L
	SLK9317C (TP veh)		SP.6EAT (A)
Date of Accident:	04/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	: \$	4,888.62		
Final Repair Cost	: \$	2,530.00		
Loss of Use	: \$	days at \$0.00 per day		
Rental (if any)	: \$	5 days		
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (Global Sum)	: \$	2,530.00		

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	: \$	2,530.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

15 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008977/UWA3Q2

Date: 15/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700093583
Claimant Vehicle No : SLK9317C **Insured Vehicle No :** SLV2801J
Date of Loss: 04/03/2018 **Nature of Claim:** TP **Claim No:** 1405140811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK9317C**
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520423453
 Reg. Date: 07/02/2017 (Man. Year: 2016) Chassis No: JM6BN22A8H0137640
 Colour: Black Odometer: 89287 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
 Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,678.80	1,676.80	1,002.00	37.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	890.00	1,000.00	52.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,568.80	2,566.80	2,002.00	43.82
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	4,568.80	2,050.00	2,518.80	55.13
+ GST 7.00/7.00% (S\$)	319.82	143.50	176.32	55.13
Nett Amount (S\$)	4,888.62	2,193.50	2,695.12	55.13
+ Car Rental (5.0 x S\$66.95/day) (S\$)		334.75		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,535.74		
Global Sum Settlement (S\$)		2,530.00		

INSPECTION

Date of Assignment: 17/05/2018
 Date Inspected: 17/05/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,075.00 FL	*1,075.00 FL
2	1		*O/S REAR BUMPER REFLECTOR	Not Necessary	51.00 FL	*- FL
3	1		*O/S REAR BUMPER END SPLASHIELD COVER	Not Necessary	80.00 FL	*- FL
4	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	538.00 FL	*538.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	74.00 FL	*- FL
7	2		*REAR BUMPER SIDE HOLDER	Not Necessary	92.00 FL	*- FL
8	4		*REAR BUMPER SIDE HOLDER RIVETS	Not Necessary	24.00 FL	*- FL
9	1		*N/S REAR BUMPER TOW COVER	Not Necessary	17.00 FL	*- FL
10	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	10.00 FL	*- FL
11	1		*REAR END PANEL	Repair	506.00 FL	*- FL
12	1		*REAR END PANEL INNER TRM	Not Necessary	86.00 FL	*- FL
13	1		*BOOTLID MAZDA 3 BADGE	Necessary	54.00 FL	*54.00 FL
14	1		*BOOTLID SKYACTIV BADGE	Necessary	64.00 FL	*64.00 FL
15	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	75.00 FL	*75.00 FL
16	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,236.00	2,046.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	557.20	369.20

Total Parts (\$\$)	2,678.80	1,676.80
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	450.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	120.00	60.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	750.00	300.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	30.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (S\$)			1,890.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >