


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : TIB1169Z  
 Ref. No : BUS/01/18/1029  
 Reg. Date : 22/01/2018  
 Vehicle Type : BUS -17M  
 Make : MB0405G 17M (MERCEDES)  
 BENDY  
 Model : MERCEDES 0405G  
 Name of Driver : Gu Zheng Gen  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 18/01/2018 10:15:00 AM  
 Accident Reported Date / Time : 19/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : MSIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC, if any :  
 TIB1169Z - RIGHT REAR PORTION  
 GW6749E (TP) - INSURED WITH MSIG  
 Prepared Date : 22/01/2018 04:49:03 PM



Sebastian.  
 16/5/18.

- Lump Sum Repair  
 - Photo After Paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,650.00	0.00
Total Spray Painting Charges :	1,126.00	0.00
Total Material Charges :	0.00	0.00
Other Charges :	0.00	0.00
<b>TOTAL :</b>	<b>3,776.00</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>3,800.00</b>	<b>0.00</b>
No. of Repair Days :	5.00	<del>0.00</del>
Prepared / Adjusted By :		4 days
Arc / Surveyor Sign Off Date :	16/05/2018 10:17:06 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/05/2018 10:17:06 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	2,650.00	<del>0.00</del> 2,120
Total Labour	2,650.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,126.00	<del>0.00</del> 900
Total Spray Painting & Panel Beating	1,126.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)							0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									