



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD TOYOTA HIACE (GBF3046T)

Date of Loss

16 May 2018

Time of Loss

20.00

Loss Description

GBF263C (INSD) C/W GBF3046T (TP) (COLLIDED INTO PARKED VEHICLE)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

28/06/2018



Days of work completion *

41



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

GBF3046T

Registration State

SINGAPORE

Mileage

43805

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2016

Purchase Date

dd/mm/yyyy



Registration Date *

07/09/2016



Age of Vehicle

1

*

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

WIN AUNG

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... HIACE

ASSESSMENT INFO... HIACE DX 3.0 M

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... KDH2015021452

CATEGORY Date of Birth

FNOL INFORMATI... 30 August 1981

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 36

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... 1KD2597704

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2982

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... NO 25 KAKI BUKIT RD 3, #06-25,
415815, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

F4503422N

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/80R15

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

195R15

Front left side

DUNLOP7mm

Front right side

DUNLOP7mm

Rear left side

JKTYRE7mm

Rear right side

JKTYRE7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18009048/Nz4be2		
8 SHENTON WAY #24-01 AXA TOWER		Date: 08-06-2018		
SINGAPORE 068811				
ATTN : CYNTHIA LOH		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBF 263C	Veh. Inspected	GBF 3046T	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00HLJ	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDH2015021452	Colour	SILVER	
Odometer	43805 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	7 mm	
L/H Front Tyre	195/80 R15	DUNLOP	7 mm	
R/H Rear Tyre	195 R15	JK TYRE	7 mm	
L/H Rear Tyre	195 R15	JK TYRE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	16/05/2018	Inspect Date / Time	23/05/2018 (04:11 PM)	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18009048/Nz4be2

Inspected By

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.