

ASS. REC. BY

REF:

CS/FCI18009054/Dtd30r

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

aws

Eileen Lee

of

FCI

Date/Time:

17/05/18 @ 5:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 3390K

Insured:

SHC 8438H

at Workshop n/s

Lim Tan Motor

Tel:

6452 0893

of

Blk 176 Sin Ming Drive #03-09

Policy No:

Claim No:

D18003869 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/05/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 5:40pm @ 17/5/18

Person Contacted:

Venus

Vehicle: ☒ IN / OUT

| Date/Time | Action/Instruction (✓) Estimate | |
|-----------|---|-------------------|
| | SGU 3390K - CC6 / AxA1102 1571 / Khdc 1 | D.O.A: 15/10/2011 |
| | SHC 8438H - CS/IN 09012196/Yh | D.O.A: 29/5/2019 |
| 23/5 - | 2:21pm revert via email. | |
| | | |
| | | |
| | | |

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

COE April 2022

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

19/12/18 Janar 215 3600/- with 5 days of pay
(red: 2179.7; 37%)

RECEIVED 20 JUN 2018

Report Format: TP
Lump Sum / LBU: 3600h

20

276

MOTOR SURVEY ASSIGNMENT

| | | |
|--------------------|---|-------------------------------|
| Date | 15-05-2018 | Our Ref No. D18003869MFSH |
| Accident Date | 13-05-2018 | Claim Type. Third Party |
| Insured Vehicle | SHC8438H | Third Party Vehicle. SGU3390K |
| Survey Location | BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE | |
| Contact Person. | MANDY LIM | |
| Contact No. | 64520893/ 64520893 | Fax No. 64589127 |
| Survey Type | DIRECT SETTLEMENT: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|-------------------|-----------------------|-------------------------|
| Cc : Workshop | LIM TAN MOTOR PTE LTD | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | EILEEN LEE | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240342)



PRI Documents



Close



PRI Header Details

| | | | | | |
|-------------------|---|-----------------------------------|--|----------------------|---------------|
| Claim No | D18003869MFSH | Policy No | D-18088936MFSH | Claimant S.No & Name | 1 & LIM TAN M |
| Workshop Name | LIM TAN MOTOR PTE LTD (Contact Person : MANDY LIM) | Survey Location & Contact Details | BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUT Mobile: 64520893 , Phone: 64520893 , Fax: 6458912 EmailId: MANDY@LTM.SG | | |
| Our Surveyor | LKK AUTO CONSULTANTS PTE LTD | Instructions To Surveyor | DIRECT SETTLEMENT: | | |
| Insured Name | COMFORT TRANSPORTATION PTE LTD | Insured Vehicle No | SHC8438H | TP Vehicle No | SGU3390K |
| PRI Recieved Date | 16-05-2018 07:15:30 PM | Surveyor Appointed Date | 17-05-2018 05:39:44 PM | Surveyor Accept Date | 17-05-2018 0 |

Survey Report Upload

| | | | | | |
|-----------------------------|----------------------|----------------------|------------|-------------------------|--|
| Surveyor Inspection Date *: | <input type="text"/> | Surveyor Report Date | 17-05-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|----------------------|----------------------|------------|-------------------------|--|

Vehicle Particulars

| | | | | | |
|-----------|---|----------------|--|---------|--|
| Make | <input type="text" value="Please Select Make"/> | Model | <input type="text" value="Please Select Model"/> | Year | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/> | Engine No | <input type="text"/> | Mileage | <input type="text"/> |
| Color | <input type="text"/> | Cubic Capacity | <input type="text"/> | | |

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 23 May 2018 2:21 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003869MFSH/1
Attachments: PRELI ADVISED SGU 3390K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGU 3390K**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 17 May 2018 5:44 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003869MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 17 May 2018 5:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003869MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

ASS. REC. BY:

REF:

AXA

ASSIGNMENT

Veh No: 895 1100C Yr Regn: Jul, 2006

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUBARU IMPREZA SMT c.c. 1597

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading 241381 T/Radio: Insured / Std / NI / NA

Eng/No: E716C824601

C/No: JF14D5KJ364056359

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 50 R16

R: 205 / 50 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

mm R/Bal. 4

mm L/Bal. 4

D.O.A. 27/12/12

Survey held at A-74C

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

From: 27/12/12

Date:

27/12/12

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGJ 1100C

at Workshop m/s A-74C Automotive Pte Ltd
Swee Hong Building 352 Cecil + Road

Insured: SGJ 9723C

Policy No:

Claims No:

Sum Insured:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

Consistent? : Yes or No

IDAC Accident Report:

Consistent? : Yes or No

Lum Sum:

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Person Contacted: 9710 3383 (James)

Date / Time

Action / Instruction

27/12/12

Received G-2, A Paper

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

Prell. Report

Final Report

Survey Fee:

Date:

Basic & Add.

s + RS, SI

Photos

Others

TOTAL

Part Prices Check:

IN

OUT



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003869MFSH

Date: 23/5/2018

Our Ref: CS/FCI18009054/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGU 3390K.

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/05/2018 at the premises of M/s Lim Tan Motor and have the following to report: -

| | |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>5,779.70</u> |
| Revised Estimate Amount | : S\$ <u>4,848.63</u> |
| "Check" Items Amount | : S\$ <u>-</u> |
| Market Value | : S\$ <u> </u> |
| LTA Reimbursement Value | : S\$ <u> </u> |
| Nett Value | : S\$ <u> </u> |

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

Condition (CON)
 (0) Beam (2) Dent (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
 (4) Not Consistent (N)

Vehicle No: GT 82874

| NAC | INC | Item | CON | ACQ |
|------|-----|--------------------------------|-----|-----|
| 1137 | | Rear Number Plate | DD | ✓ |
| 1138 | | Rear Number Plate Base Bracket | BT | ✓ |
| 1139 | | Rear Number Plate Garnish | | |
| 1140 | | Rear Number Plate Lamp | BT | ✓ |
| 1141 | | Rear Bumper | BT | ✓ |
| 1142 | | Rear Bumper Upper | | |
| 1143 | | Rear Bumper Lower | | |
| 1144 | | Rear Bumper Side | | |
| 1145 | | Rear Bumper Tow Cover | | |
| 1146 | | Rear Bumper Clips | | |
| 1147 | | Rear Bumper Bracket | | |
| 1148 | | Rear Bumper Side Retainer | | |
| 1149 | | Rear Bumper Reinforcement | | |
| 1150 | | Rear Bumper Beam | | |
| 1151 | | Rear Bumper Sponge | | |
| 1152 | | Rear Bumper Damper | | |
| 1153 | | Rear Bumper Protector | | |
| 1154 | | Rear Bumper Pad | | |
| 1155 | | Rear Bumper Moulding | | |
| 1156 | | Rear Bumper Reflector | | |
| 1157 | | Rear Bumper Lower Spoiler | | |
| 1158 | | Reverse Sensor | | |
| 1159 | | Rear End Panel | | |
| 1160 | | Rear End Panel Top Garnish | | |
| 1161 | | Rear End Panel Inner Trim | | |
| 1162 | | Boot Compartment Inner Trim | | |
| 1163 | | Rear LH Tailamp | | |
| 1164 | | Rear LH Tailamp Garnish | | |
| 1165 | | Rear LH Tailamp Panel | BR | ✓ |
| 1166 | | Rear RH Tailamp | BR | ✓ |
| 1167 | | Rear RH Tailamp Garnish | | |
| 1168 | | Rear RH Tailamp Panel | | |
| 1169 | | Rear Apron Panel | | |
| 1170 | | Bootlid | | |
| 1171 | | Bootlid Emblem | | |
| 1172 | | Bootlid Handle | | |
| 1173 | | Bootlid Moulding | | |
| 1174 | | Bootlid Reflector | | |
| 1175 | | Bootlid Lamp LH | | |
| 1176 | | Bootlid Lamp RH | | |
| 1177 | | Bootlid Lock | | |
| 1178 | | Bootlid Rubber | | |
| 1179 | | Bootlid Hinge | | |
| 1180 | | Bootlid Spoiler | | |
| 1181 | | Tailgate | | |
| 1182 | | Tailgate Emblem | | |
| 1183 | | Tailgate Outer Handle | | |
| 1184 | | Tailgate Moulding | | |
| 1185 | | Tailgate Garnish | | |
| 1186 | | Tailgate Reflector | | |
| 1187 | | Tailgate Lamp | | |
| 1188 | | Tailgate Protector | | |
| 1189 | | Tailgate Wiper Arm | | |
| 1190 | | Tailgate Wiper Blade | | |
| 1191 | | Tailgate Wiper Nozzle | | |
| 1192 | | Tailgate Wiper Motor | | |
| 1193 | | Tailgate Glass | | |
| 1194 | | Tailgate Glass Rubber | | |
| 1195 | | Tailgate Glass Moulding | | |
| 1196 | | Tailgate Glass Sealant | | |
| 1197 | | Tailgate Lock | | |
| 1198 | | Tailgate Rubber | | |
| 1199 | | Tailgate Hinge | | |
| 1200 | | Tailgate Damper | | |
| 1201 | | Tailgate Inner Board | | |

Rear Portion

No of Items: Assessor:

| NAC | INC | Item | CON | ACQ |
|------|-----|--------------------------------|-----|-----|
| 1202 | | Spare Tyre Board | | |
| 1203 | | Spare Tyre Panel | | |
| 1204 | | Spare Tyre | | |
| 1205 | | Spare Tyre Lock Screw | | |
| 1206 | | Spare Tyre Cover | | |
| 1207 | | Triangle Breakdown Sign | | |
| 1208 | | CD Changer Assy | | |
| 1209 | | Antenna | | |
| 1210 | | Centre Exhaust Pipe Assy | | |
| 1211 | | Centre Exhaust Moulding | | |
| 1212 | | Rear Exhaust Pipe | | |
| 1213 | | Rear Exhaust Chrome Pipe | | |
| 1214 | | Rear Exhaust Mounting | | |
| 1215 | | Rear Exhaust Heat Shield | | |
| 1216 | | Rear LH Chassis Member | | |
| 1217 | | Rear RH Chassis Member | | |
| 1218 | | Rear LH Fender | | |
| 1219 | | Rear LH Fender Protector | | |
| 1220 | | Rear LH Fender Inner Panel | | |
| 1221 | | Rear LH Fender Inner Trim | | |
| 1222 | | Rear LH Fender Inner Garnish | | |
| 1223 | | Rear LH Fender Inner Shield | | |
| 1224 | | Rear LH Mudflap | | |
| 1225 | | Rear LH Wheel Rim | | |
| 1226 | | Rear LH Rim Cover | | |
| 1227 | | Rear LH Tyre | | |
| 1228 | | Rear RH Fender | | |
| 1229 | | Rear RH Fender Protector | | |
| 1230 | | Rear RH Fender Inner Panel | | |
| 1231 | | Rear RH Fender Inner Trim | | |
| 1232 | | Rear RH Fender Inner Garnish | | |
| 1233 | | Rear RH Fender Inner Shield | | |
| 1234 | | Rear RH Mudflap | | |
| 1235 | | Rear RH Wheel Rim | | |
| 1236 | | Rear RH Rim Cover | | |
| 1237 | | Rear RH Tyre | | |
| 1238 | | Rear Fender Extension Panel LH | | |
| 1239 | | Rear Fender Extension Panel RH | | |
| 1240 | | Rear Fender Inner Top Garnish | | |
| 1241 | | Rear Fender 1/4 Glass | | |
| 1242 | | Rear Fender 1/4 Glass Rubber | | |
| 1243 | | Rear Fender 1/4 Glass Sealant | | |
| 1244 | | Rear Windscreen Glass | | |
| 1245 | | Rear Windscreen Rubber | | |
| 1246 | | Rear Windscreen Moulding | | |
| 1247 | | Rear Windscreen Sealant | | |
| 1248 | | Third Brake Light | | |
| 1249 | | Rear Fender Air Grille | | |
| 1250 | | Fuel Lid | | |
| 1251 | | Fuel Neck | | |
| 1252 | | Fuel Tank | | |
| 1253 | | Fuel Tank Bracket | | |
| 1254 | | Fuel Tank Float | | |
| 1136 | | Sticker | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------|
| Date Of Report | 14/05/2018 15:13 |
| Date Of Accident | 13/05/2018 01:45 |
| Exact Location Of Accident | CTE TOWARDS BRADDELL |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|---------------------------|
| Vehicle Registration Number | SGU3390K |
| Insured/Policyholder | |
| Name Of Registered Owner | FAMILY CAR RENTAL PTE LTD |
| Co Reg No | 200703924M |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-64515120 |

Vehicle Particulars

| | |
|--|---------------|
| Manufacturer | TOYOTA |
| Model | VIOS-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE & REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | 5089453597-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------------------|
| Name of Driver | MUHAMMAD FIRDAUS BIN ABDUL LAJIS |
| NRIC No | S8623015A |
| Date Of Birth | 19/08/1986 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 13/06/2013 |
| Driving Experience | 4 YEARS AND 11 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-86784066 |
| Fax Number | |
| Contact Number | |
| Email Address | FYEZ86@LIVE.COM |

| | |
|---|----------------------------------|
| Address | BLK 302B ANCHORVALE LINK #02-188 |
| Postcode | 542302 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - PRIVATE HIRE DRIVER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| Insurance Company of Driver's Own Vehicle | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----------------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : FARAH GENDER: : FEMALE |

Details of Police Action

| | |
|---|--|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | SENGKANG NPC |
| Police Station Address | ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: - FAX NO: |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

ON 13/05/2018 AT ABOUT 0145 HRS, AS I WAS WORKING AS GRAB DRIVER, I WAS DRIVING MY VEHICLE SGU3390K AND WAS TRAVELLING ALONG CTE TOWARDS BRADDELL INTENDING TO HEAD TOWARDS TOA PAYOH. I HAD A FEMALE PASSENGER SEATED ON THE REAR BACK SEAT. I WAS ON THE 2ND LANE AND DRIVING STRAIGHT. SUDDENLY, THERE WAS A TAXI SHC8438H SUDDENLY COLLIDED ONTO THE LEFT BONNET ('SHOULD BE BOOT') OF MY VEHICLE. MY VEHICLE CAME TO A STOP AND THE NEXT MOMENT, I SAW THE TAXI ALREADY AT THE ROAD SHOULDER. AS SUCH, I WENT OVER TO STOP AT THE ROAD SHOULDER AND ALIGHTED FROM MY VEHICLE AND WANTED TO ASK THE TAXI DRIVER WHAT HAD HAPPENED. HOWEVER, THE TAXI DRIVER JUST ASKED ME TO CLAIM INSURANCE. THE PARTICULARS OF THE TAXI DRIVER AS FOLLOWS: SIM KIAN WEE, S7604075C, 93836001. MY FEMALE PASSENGER INFORMED ME THAT SHE IS NOT INJURED. I DOES NOT HAVE ANY IN CAR CAMERA. NO GOVERNMENT PROPERTY DAMAGED. I WAS GIVEN 5 DAYS OUTPATIENT SICK LEAVE FROM 13/05/2018 TO 17/05/2018.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

Details of Witness 1

| | |
|---------------|----------|
| Name | FARAH |
| Phone Number | 98062713 |
| Email Address | |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------|
| Vehicle Registration Number | SHC8438H |
| Vehicle Make/Model/Colour | BLUE CAB |
| Details Of Properties | FRONT LEFT |
| Vehicle Category | TAXI |
| Name of Driver | SIM JIAN WEE |
| NRIC/Passport Number | S7604075C |
| Contact Number | 93836001 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF INJURED PERSON 1

| | |
|---|----------------------------------|
| Name | MUHAMMAD DIRDAUS BIN ABDUL LAJIS |
| Approximate Age | 32 |
| Injuries Sustain | PAIN, MUSCLE, SWELLING |
| Injured person in which vehicle? | SGU3390K |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | BLK 302B ANCHORVALE LINK #02-188 |
| Postcode | 542302 |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 14 MAY 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 14 MAY 2018

Reporting Centre Personnel's Signature
Name: LIM LI CHUAN
NRIC/FIN No.: S7032011 H

SKETCH PLAN

13. 05. 2018

@ 0145 hrs

A - SGU 3390 K

B - SHC 8438 H



CTE Towards Braddell



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer police report No. T/20180513/2094.

Enclosed some scene's photos.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Family Car Insurance
Signature

Policyholder's Signature

Date & Time: 14 MAY 2018

Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time: 14 MAY 2018

Signature

Reporting Centre Personnel's Signature

Name: Lim H Chao

NRIC/FIN No.: S7032011 H



SINGAPORE POLICE FORCE



T/20180513/2094

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 3

Report No. T/20180513/2094

REPORT OF A TRAFFIC ACCIDENT

| | | | | | |
|---|------------|------------------------------|--|--------------------------|----------------------------|
| Date/Time Report Made: 13/05/2018 19:34 | | Vide Report No.: | | Station Diary No.: 88 | |
| Informant's Particulars | | | | | |
| Name of Informant: MUHAMMAD FIRDAUS BIN ABDUL LAJIS | | | Address: APT BLK 302B ANCHORVALE LINK #02-188 SINGAPORE 542302 | | |
| ID Type / ID No.: NRIC NO / S8623015A | | | Contact No.: Home/Office: Mobile: 87424658 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 31 | Date of Birth: 19/08/1986 | Type of Informant: Driver | | |
| Race: Malay | | | Language: English | | Institution / School Name: |
| Occupation: Grab Driver | | | Driving Licence Information: Class: Date of Expiry: | | |

| | | | | |
|--|------------|------------------------------------|--|---------------------------------|
| General Information of the Accident | | | | |
| Type of Accident: | Non-Injury | Drink Drive: No | Date/Time of Accident: 13/05/2018 01:45 | Type of Location: Expressway |
| Location: Along Road 1 CENTRAL EXPRESSWAY Along CTE toward Braddell | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | Traffic Volume: Light | |
| Type of Collision: Between Moving Vehicles - Head To Side | | | Anyone conveyed by ambulance: No | |

| | | | | | | |
|------------------------------------|------|------|-------|-------|-----------|-----------------|
| Details of Vehicle Involved | | | | | | |
| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
| SGU3390K | Car | | | | | 0 |
| SHC8438H | Taxi | | | | | 0 |

| | |
|-----------------------------------|--------------------------------|
| Details of Person Involved | |
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE
POLICE FORCE**



T/20180513/2094

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No. T/20180513/2094

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|----------------------------------|--|-----------------------------------|
| Driver | | | |
| Name | MUHAMMAD FIRDAUS BIN ABDUL LAJIS | ID No. | S8623015A |
| Related Vehicle | SGU3390K (Car) | Contact No. | 87424658 |
| Hospital/Clinic | KHOO TECK PUAT HOSPITAL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | 13/05/2018 | Date Discharge | 13/05/2018 |
| No. of Days granted Medical Leave | 05 | Degree of Injury | NIL |

Brief Details.

On 13/05/2018 at about 0145hrs, as I was working as a Grab driver, I was driving my vehicle SGU 3390K and was travelling along CTE towards Braddell intending to head towards Toa Payoh. I had a female passenger seated on the rear back seat.

I was on the 2nd lane and driving straight. Suddenly, there was a taxi SHC 8438H suddenly collided onto the left bonnet of my vehicle. My vehicle came to a stop and the next moment, I saw the taxi already at the road shoulder.

As such, I went over to stop at the road shoulder and alighted from my vehicle and wanted to ask the taxi driver what had happened. However, the taxi driver just asked me to claim insurance.

The particulars of the taxi driver as follows: Sim Kian Wee, S7604075C, 93836001. My female passenger informed me that she is not injured. I does not have any in car camera.

No government property damaged. I was given 5 days outpatient sick leave from 13/05/2018 to 17/05/2018.



**SINGAPORE
POLICE FORCE**



T/20180513/2094

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20180513/2094

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt CHEE SI WEI, FELIX

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / G1A

Staff Sgt TANG SIEW PING

Contact No: 65476430

SN 085

Signature Of Informant:

Date/Time:

13/05/2018 19:34

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force



Enquire Vehicle Information

Vehicle No.

Vehicle No.: SGU3390K

Vehicle Details

Vehicle Type: Private Hire (Chauffeur) Motor Car

Vehicle Attachment 1: No Attachment

Make / Model: TOYOTA / VIOS 1.5E A

Primary Colour: Black

Year of Manufacture: 2006

Maximum Laden Weight: 1480 kg

Unladen Weight: 1020 kg

No. Of Axles: 2

Engine No.: 1NZX520640

Chassis No.: MR053HY4204217940

Engine Capacity: 1497 cc

Maximum Power Output: 80.0 kW (107 bhp)

IU Label No.: 1121116099

Propellant: Petrol

Passenger Capacity: 4

Original Registration Date: 11 May 2007

First Registration Date: 11 May 2007

Open Market Value: \$12,237.00

Additional Registration Fee Rate: 110.00 %

Actual ARF Paid: \$13,461.00

PARF Eligibility: Forfeited

Minimum PARF Benefit: -

COE No.: 2007050101000782R

COE Category: A - Car (1600cc & below)

COE Expiry Date: 30 Apr 2022

Quota Premium (QP): \$14,000.00

PQP Paid: \$25,115.00

OPC Cash Rebate Eligibility: No

QP during COE Bidding Exercise: \$14,000.00

Private Hire Vehicle Decal No.: A045533 (Issued on 03 Jul 2017)

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5089453597-01

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SGU3390K**
 Chassis Number : MR053HY4204217940
2. Name of Policyholder : FAMILY CAR RENTAL PTE LTD
3. Effective Date of Insurance : 11 May 2018
4. Expiry Date of Insurance : 10 May 2019
5. Persons or Classes of Persons entitled to drive#
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

| | |
|--------------------------------------|---|
| EXCESS (SECTION 1) | : S\$2,000 |
| EXCESS (SECTION 2) | : S\$1,500 |
| WINDSCREEN EXCESS | : S\$100 |
| ADDITIONAL EXCESS | : N/A |
| UNNAMED DRIVER EXCESS | : PLEASE REFER OVERLEAF |
| REPAIR AT OWNER'S PREFERRED WORKSHOP | : NO |
| INSURE WITH COE | : YES |
| NCD PROTECTION | : NO |
| TRANSPORT ALLOWANCE | : NO |
| EXCESS WAIVER | : NO |
| PRIMARY DRIVER | : N/A |
| NAMED DRIVER (1) | : N/A |
| NAMED DRIVER (2) | : N/A |
| HIRE PURCHASE COMPANY | : WAH SOON HENG VEHICLE TRADING |
| SUM INSURED | : MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS |

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : AUTOSHIELD PTE. LTD. (00000573469)
 Date of Issue : 26 Apr 2018 13:14 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



ESTIMATE TO REPAIR

VEHICLE NO. : SGU 3390 K
 MAKE : TOYOTA
 MODEL : VIOS 1.5 AUTO
 YEAR : 2006
 CHASSIS NO : MR053HY4204217940

SURVEYOR NAME :
 DATE OF SURVEY : 13 MAY 2013
 TIME OF SURVEY : 3-35pm
 DATE : 15-May-18
 DATE OF ACCIDENT : 13-May-18
 THIRD PARTY REF : SHC 8438 H / FIRST CAPITAL

| No. | Parts Description/ Labour | Type | Unit Price | Nett Item Amt | Amount |
|----------------|--|----------------|------------|---------------|-------------------|
| 1 pc | rear bumper <i>broken</i> | | | | \$589.70 |
| 2 ps | rear bumper bracket <i>src</i> | | \$42.50 | | \$85.00 |
| 2 ps | rear bumper retainer <i>n/s broken</i> | <i>b/s src</i> | \$40.40 | | \$80.80 |
| 1 pc | rear end panel <i>Dented</i> | | | | \$286.70 |
| 1 pc | rear end panel garnish <i>src</i> | | | | \$102.70 |
| 1 pc | n/s taillamp <i>broken</i> | | | | \$166.70 |
| 1 pc | n/s rear fender <i>Dented</i> | | | | \$987.50 |
| 1 pc | n/s rear fender air duct garnish <i>deformed</i> | | | | \$157.70 |
| 1 pc | rear boot lid <i>src</i> | | | | \$687.70 |
| 1 pc | rear boot rubber <i>deformed</i> | | | | \$68.70 |
| 1 pc | rear boot lock <i>src</i> | | | | \$70.40 |
| 1 pc | rear boot CENTRE emblem <i>huc</i> | | | | \$65.70 |
| 1 pc | rear boot 1.5 emblem <i>huc</i> | | | | \$77.11 |
| 1 pc | rear boot VVTI emblem <i>huc</i> | | | | \$55.20 |
| 1 pc | rear windscreen moulding <i>huc</i> | | | | \$98.00 |
| | | | | 3438.74 | |
| | | | | 2579.05 | |
| | Less 25% | | | | \$4,079.61 |
| | | | | | \$1,019.91 |
| | | | | | \$3,059.70 |
| 1 set | rear bumper reverse sensor <i>Dcm</i> | S.Nett | | | \$200.00 |
| 1 tube | rear windscreen sealant <i>huc</i> | S.Nett | | | \$40.00 |
| | To putty & spray paint. | | | | \$1,200.00 |
| | To remove & refix rear windscreen glass. | | | | \$120.00 |
| | To remove & refix fuel tank. | | | | \$80.00 |
| | To anti-rust. | | | | \$80.00 |
| | Labour charges. <i>18/05 2013 e 15000</i> | | | | \$1,000.00 |
| TG-ML/- | Total | | | | \$5,779.70 |
| | | | | | 4539.05 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

is subject to final approval from insurance company

This document is not to be used as evidence

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176, Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co Reg No. 199307277D

GST Reg No. M2-0019086-0

This document is not to be used as evidence, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

1/53600/-

Date: _____
 Signature: _____
 Acknowledged by Repairer: _____

is subject to final approval from Insurance Company
 • Supplemental item(s) must be resurveyed and
 • No illegal modification(s) is allowed
 • Third party survey is on a "Without Prejudice" basis
 • Parts prices are subject to confirmation
 • To display damaged parts) during resurvey
 • To resurvey before/after spray painting
 the Repairer of the following:

LKK Auto Consultants hence notify




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------------|-----------------------------|---|
| FIRST CAPITAL INSURANCE LTD | | | Ref : CS/FCI18009054/Dtd3e2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | | Date : 27-06-2018 |  |
| | | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHC 8438H | Veh. Inspected | SGU 3390K | |
| Policy No. | D-18088936MFSH | Coverage (\$) | 0.00 | |
| Claim No. | D18003869MFSH | Excess (\$) | 0.00 | |
| Assign From | EILEEN LEE | Assign Date | 17/05/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA VIOS | c.c | 1497 | |
| Engine No. | HIDDEN | Year of Reg. | 2007 | |
| Chassis No. | MR053HY4204217940 | Colour | BLACK | |
| Odometer | 261515 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 185/65 R14 | LING LONG | 5 mm | |
| L/H Front Tyre | 185/65 R14 | LING LONG | 5 mm | |
| R/H Rear Tyre | 185/65 R14 | LING LONG | 5 mm | |
| L/H Rear Tyre | 185/65 R14 | LING LONG | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 13/05/2018 | Inspection Date | 18/05/2018 | |
| Survey held at | LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721 | | | |
| 5a. Remarks | | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 3390K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|------------------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | BROKEN | 589.70 | 589.70 |
| 2 | REAR BUMPER BRACKET @\$42.50 | SERVICEABLE | 85.00 | - |
| 2 | REAR BUMPER RETAINER @\$40.40 | N/S BROKEN / O/S SERVICEABLE | 80.80 | 40.40 |
| 1 | REAR END PANEL | DENTED | 786.70 | 595.85 |
| 1 | REAR END PANEL GARNISH | SERVICEABLE | 102.70 | - |
| 1 | N/S TAILLAMP | BROKEN | 166.70 | 166.70 |
| 1 | N/S REAR FENDER | DENTED | 987.50 | 765.58 |
| 1 | N/S REAR FENDER AIR DUCT GARNISH | DEFORMED | 157.70 | 157.70 |
| 1 | REAR BOOT LID | BENT | 687.70 | 687.70 |
| 1 | REAR BOOT RUBBER | DEFORMED | 68.70 | 68.70 |
| 1 | REAR BOOT LOCK | BENT | 70.40 | 70.40 |
| 1 | REAR BOOT CENTRE EMBLEM | NECESSARY | 65.70 | 65.70 |
| 1 | REAR BOOT 1.5 EMBLEM | NECESSARY | 77.11 | 77.11 |
| 1 | REAR BOOT VVTI EMBLEM | NECESSARY | 55.20 | 55.20 |
| 1 | REAR WINDSCREEN MOULDING | NECESSARY | 98.00 | 98.00 |
| | LESS 25% DISCOUNT | | -1,019.90 | -859.69 |
| | | | 3,059.71 | 2,579.05 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET REAR BUMPER REVERSE SENSOR (SN) | DAMAGED | 200.00 | 200.00 |
| 1 | TUBE REAR WINDSCREEN SEALANT (SN) | NECESSARY | 40.00 | 40.00 |
| | | | 240.00 | 240.00 |
| <u>LABOUR</u> | | | | |
| | TO PUTTY & SPRAY PAINT. | | 1,200.00 | 800.00 |
| | TO REMOVE & REFIX REAR WINDSCREEN GLASS. | | 120.00 | 80.00 |
| | TO REMOVE & REFIX FUEL TANK. | NOT NECESSARY | 80.00 | - |
| | TO ANTI-RUST. | | 80.00 | 40.00 |
| | LABOUR CHARGES. | | 1,000.00 | 800.00 |
| | | | 2,480.00 | 1,720.00 |
| GRAND TOTAL | | | 5,779.71 | 4,539.05 |

Report Ref No. CS/FCI18009054/Dtd3e2



| | | | |
|---|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,600.00 |
|---|--|--|----------|

Report Ref No. CS/FCI18009054/Dtd3e2

MARKET VALUE: \$25,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,700.00=NETT VALUE: \$5,300.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

