

20/03/2002

ASS. REC. BY:

REF: cs 1A1G18009065/G 1362

General Instruction:

Surveyor:

GR

ASSIGNMENT (Office)

From (Person):

Lim Shen Yang

of

AIG

Date/Time: 18/05/2018 @ 12:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 4952L

Insured:

GR 9510H

at Workshop m/s

New Union Company

Tel:

of

BIK 9004, Tampines Street 93 # 01-106

Policy No:

Claim No:

8799096875 SG

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

14/03/2018

21/05/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (wp)

Date/Time: 1:55pm @ 18/5/18

Person Contacted:

Linda

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBC 4952L - X
	GR 9510H - NA/INC14008893/CD2

DOA: 13/5/14

che.

NCE

11/1

ADDITIONAL

From: Date: 21052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBC 4952L

at Workshop m/s: New Union

of Blk 9004 Tampines St 93 #01-106

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$7000

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

3

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

FBC 4952L

Vt Regn:

31 May 2018

Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB 400

399

Colour:

Red

A/O:

Insured / Std / NI / NA

Sp Reading:

T/Ratio: Insured / Std / NI / NA

Eng No:

C/No:

NC391031755

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

120/60 R17

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

D.O.I.

21-05-18

Survey held at

W/S

CPM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ant.

The U/C / Chassis frame / Body Structure affected due to collision

05/7

Finalized \$2000 with Boss

used to pay, 4/2/18

RECEIVED 11 JUL 2018

5/1/2018

Date/Time: File Pass No:

☐

Prel. Report

11/7 11/7

☐

Final Report

Date/Time: File Return No:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1. S-P: %

1. Blank:

1. Other:

1. Other:

Add Fee:

☐

Site Insp: (\$

☐

Interview: (\$

☐

Techn. Insp: (\$

☐

Workshop: (\$

Report Format:

mer-9p

Lump Sum: 1. P: (\$

3000

250

20

270


- Pre repair inspection request - FBC4952L VS GR9510H (OI) DOA: 14/03/2018

From: Lim, Sheng Yang

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Chan, Yoke Shi, Supramaniam, Darshene

Sent: 18/5/2018 12:40:06 PM

Attachments:  SKMRT_C354e18051611140.pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: mail@cheonghoh.sg

To: ShengYang.Lim@aig.com

Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Imran.Ishak@aig.com, yokeshi.chan@aig.com, Darshene.Supramaniam@aig.com

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GR9510H AND FBC4952L ON 14/03/2018

Date: Fri, 18 May 2018 03:47:20 +0000

Dear Sheng Yang,

Our email yesterday stated very clear that we nominate Xing Gao Qiang as the SJE to conduct the pre-repair survey.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 18 May 2018, at 9:03 AM, Lim, Sheng Yang <ShengYang.Lim@aig.com> wrote:

Dear Catherine,

Please confirm that you are nominating Xing Guo Qiang of LKK Auto Consultants Pte Ltd named in the list of surveyors as the Single Joint Expert to conduct the pre-repair survey.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Thursday, May 17, 2018 5:23 PM

To: Lim, Sheng Yang

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GR9510H AND FBC4952L ON 14/03/2018

Importance: High

Dear Sirs,

We refer to the above matter and to your email of 16 May 2018.

Our client hereby nominate Xing Gao Qiang of LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, New Union Company, Blk 9004 Tampines Street 93 #01-106 Singapore 528838 to conduct the survey of FBC 4952 L.

Contact Person : Mr B T Yeo
Telephone : 6784 9488

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 17 May 2018, at 11:01 AM, Lim, Sheng Yang <ShengYang.Lim@aig.com> wrote:

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

From: Lim, Sheng Yang

Sent: Wednesday, May 16, 2018 11:26 AM

To: Cheonghoh Law

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GR9510H AND FBC4952L ON 14/03/2018

Without Prejudice

Your Reference : LCH.Ig/TNU-80431.18
Our Reference : GR9510H

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motorsurveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

From: Cheonghoh Law [<mailto:mail@mail@cheonghoh.sg>]

Sent: Wednesday, May 16, 2018 11:20 AM

To: Supramaniam, Darshene

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi
Subject: Re: PRS for FBC 4952 L involving vehicle GR 9510 H on 14 March 2018 along Open Carpark of Blk 466 - 477 of Pasir Ris Drive 6 (Oref: LCH.lg/TNU-80431.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: c364@cheonghoh.sg
Subject: Message from KMBT_C364e
Date: 16 May 2018 at 11:15:02 AM SGT
To: mail@cheonghoh.sg
Reply-To: c364@cheonghoh.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

<SKMBT_C364e18051611140.pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8126E

Vehicle Details

Vehicle No.:	FBC4952L
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400SF2J
Primary Colour:	Blue
Manufacturing Year:	2002
Engine No.:	NC23E2031768
Chassis No.:	NC391031755
Maximum Power Output:	-
Open Market Value:	\$8,050.00
Original Registration Date:	31 May 2002
First Registration Date:	31 May 2002
Transfer Count:	13
Actual ARF Paid:	\$1,208.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Apr 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,757.00
COE Rebate Amount:	\$789.00
Total Rebate Amount:	\$789.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/7764/\)](#)[+ ADD TO SHORTLIST](#)[© SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB400-SUPER-4-SPEC-2/7764/\)](#)

Honda CB400 Super 4 Spec 2

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Spec 2 (/listing/usedbike/model/honda-cb400-super-4-spec-2/)
Engine Capacity	399cc
Classification	2A
Registration Date	06/06/2002
COE Expiry Date	31/03/2021 (2 years 10 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

Price: ^{SGD}\$8700

DETAILS

Honda CB400 Spec 2 for sale. Come with 3.5k nea rebate upon scrap. Bike come with yoshimura exhaust, ohlins suspension. Viewing at Soon Hin Motors Pte Ltd. Address: Yishun Industrial Park A Block 1018 S768760. Tel 67524893. We accept Trade in and many other brands new and used models available for sale. Installment plans available. No early settlement penalty.

**SPOT SIGNS
OF PHISHING**

**FIND OUT
MORE >**



SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2018 15:38
Date Of Accident	14/03/2018 18:20
Exact Location Of Accident	PASIR RIS DRIVE 6 BLK477 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC4952L
Insured/Policyholder	
Name Of Registered Owner	AHMAD TAUFIK BIN ABDUL HALIM
NRIC No	S9138126E
Email Address	TAUPHAT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98959822
Alternative Phone No	OTHERS-98959822

Vehicle Particulars

Manufacturer	HONDA
Model	CB400-399CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5097761035
Cover Note Number	

Driver

Name of Driver	AHMAD TAUFIK BIN ABDUL HALIM
NRIC No	S9138126E
Date Of Birth	21/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	12/01/2018
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98959822
Fax Number	
Contact Number	OTHERS-98959822
Email Address	TAUPHAT@GMAIL.COM

Address	BLK477 PASIR RIS DRIVE 6 #02-510
Postcode	510477
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	YES
If Yes, against whom?	GR9510H

Circumstances of Accident

AS PER POLICE REPORT ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GR9510H
Vehicle Make/Model/Colour	DAIHATSU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ATW 15/5/16
Policyholder's Signature
Date & Time:

ATM
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

late report for insurance claim is because due to waiting of
FP (Traffic Police) investigation to be completed. ~~and~~


As per Police Report No: T/20180314/2170 attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

A.T.W 15/5/18
Policyholder's Signature
Date & Time:

A.T.W
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180314/2170

1 of 3

Report No. T/20180314/2170

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/03/2018 21:39	Vide Report No.: G/20180314/0169	Station Diary No.: 67
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: AHMAD TAUFIK BIN ABDUL HALIM		Address: APT BLK 477 PASIR RIS DRIVE 6 #02-510 SINGAPORE 510477	
ID Type / ID No.: NRIC NO / S9138126E		Contact No.: Home/Office: Mobile: 98959822	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 26	Date of Birth: 21/10/1991	Type of Informant: Vehicle Owner
Race: Malay		Language: English	Institution / School Name:
Occupation: Student		Driving Licence Information: Class: 2B,2A Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/03/2018 18:20	Type of Location: Car Park
Location: Along Road 1 PASIR RIS DRIVE 6				
OPEN SPACE CARPARK OF BLK 466-477				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBC4952L	Motorcycle	HONDA	CB400SF2J	Red		0
GR9510H	Van	DAIHATSU	S200RV-SMLK	Silver		0

Details of Person Involved	
Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20180314/2170

2 of 3

Report No. T/20180314/2170

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Vehicle Owner		ID No.		S9138126E
Name	AHMAD TAUFIK BIN ABDUL HALIM		Contact No.	98959822
Related Vehicle	FBC4952L (Motorcycle)		Class of Driving Licence & Expiry Date	Class: 2B, 2A Date of Expiry: NIL
Hospital/Clinic	NIL		Date Discharge	NIL
Date Treatment	NIL	No. of Days granted Medical Leave	NIL	Degree of Injury
				NIL

Brief Details.

On 14/03/2018 at about 1820hrs, my mother informed me that she had heard a loud sound. She then proceeded to the window and noticed that my parked motorbike had fallen onto the bikes beside it. She also noticed a van in front of my motorbike and spotted a member of public shouting at the van driver, asking him to stop. Moreover, the van driver drove off without stopping.

I wish to state that my mom had not witnessed the accident. I am lodging this report for insurance claim purposes as there are some damages to my motorbike.



SINGAPORE
POLICE FORCE



T/20180314/2170

3 of 3

Report No. T/20180314/2170

Police Station Of Origin:
Pasir Ris N.P.
1 Pasir Ris Eye 4 #01-01 SINGAPORE
519457
Tel No: 1800852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 1 S NANDHINI DEVI

Signature Of Interpreter:
Not applicable

Signature Of Informant:

Date/Time:
14/03/2018 21:39

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt ESTHER CHONG
Contact No.: 65476368



SINGAPORE
POLICE FORCE

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6269
www.police.gov.sg

Our Ref : TP/IP/16957/2018
Date : 10 April, 2018

AHMAD TAUFIK BIN ABDUL HALIM
APT 477 PASIR RIS DRIVE 6
#02-510
SINGAPORE 510477

Dear Sir/Madam

**ACCIDENT INVOLVING FBC4952L/FBD8864B/FS2073E/GR9510H ON 14.03.2018 AT 1836 HRS,
ALONG PASIR RIS DRIVE 6 (CARPARK OF BLK 477)**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of GR9510H has committed an offence of Careless Driving under Rule 29 Road Traffic Rules, Failing to stop after accident under Section 84(1) Road Traffic Act, Chapter 276, Failing to lodge report within 24 hours after an accident under Section 84(2) Road Traffic Act, Chapter 276. Action has been initiated against the driver for the said offence.

3. If you have any queries, please contact the Investigation Officer, Jamie Ng at telephone number 6547 6397.

Yours faithfully

SHAHUL HAMEED
FOR HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

New Union Company

Pg
1

GST Reg No: M90370043N

9004 Tampines Street 93 #01-106
Singapore 528838P: 67849488
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern

Address:

Phone:

Fax:

Email:

Quotation No. #21_05_2018_1

Quote Date:

Quotation For: Bike Repair - FBC4952L

Item #	Description	Qty	Unit Price	Discount	Price
1	Crash Bar Assy <i>Cut</i>	1	\$ 150.00		\$ 150.00
2	Spray Paint	1	750.00		\$ 750.00
3	Meter Assy <i>Cut</i>	1	1,300.00		\$ 1,300.00
4	Headlamp Assy <i>Cut</i>	1	380.00		\$ 380.00
5	Handle Bar <i>BT</i>	1	120.00		\$ 120.00
6	Fork Press	1	140.00		\$ 140.00
7	Steering Corn Bearing <i>MC</i>	1	150.00		\$ 150.00
9	Signal Lamp Front, LHS <i>RH BR</i>	1	70.00		\$ 70.00
10	Exhaust En-can <i>Cut</i>	1	350.00		\$ 350.00
11	Box <i>Cut</i>	1	150.00		\$ 150.00
12	Rack for Box <i>NN</i>	1	135.00		\$ 135.00
13	Mirror <i>Cut</i>	1	80.00		\$ 80.00
14	Balancer <i>Cut</i>	2	38.00		\$ 76.00
15	Rim Press	1	250.00		\$ 250.00
16	Front Wheel Bearing <i>NN</i>	2	30.00		\$ 60.00
17	Front Wheel Shaft	1	65.00		\$ 65.00
18	Front Brake disc <i>BT</i>	1	350.00		\$ 350.00
19	Fork Seal Assy <i>MC</i>	1	150.00		\$ 150.00
20	Head Lamp Stay Bracket <i>BT</i>	1	165.00		\$ 165.00
21	Footrest Pinion, RHS <i>BT</i>	1	45.00		\$ 45.00
22	Fork oil <i>MC</i>	1	15.00		\$ 15.00
23	Labour Charge	1	250.00		\$ 250.00
Sub-Total					\$ 5,201.00
Tax Rate					7.00%
GST					364.07
Other					
Grand Total					5,565.07

Customer Signature

LKK Make all checks payable to New Union Company.
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

One Q:ap
82880282

2556
10%: 2660.4
labour: 560
2220.4
20%: 2550

3386
10%: 3047.4
610
3772.4
20%: 3000

21/5/18. L/S
After repair photos 3 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018 Edit Reg		18 May 2018 00:00 Edit Adj Rpt	S\$3,822.40 Edit Estimates	S\$3,822.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	ANNLY SERVICE & TRADING, Co. Reg. No.: 52986125M		
Main Claimant:	AHMAD TAUFIKH BIN ABDUL HALIM, ID: S9138126E		
Vehicle Reg. No.:	FBC4952L	Date of Loss:	14/03/2018 18:00 - :59 [189 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8799096825SG	Policy/Cover Note No.:	2100030352 (Comprehensive)
Vehicle Reg. No. (Insured):	GR9510H	Policy No. (Claimant):	
		Excess:	
Repairer:	New Union Company (HQ) BLK 9004 TAMPINES STREET 93 #01-106, 528838 Tampines - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wul, Shawn-KJ] Shawnkaijye.Wul@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (03/07/2018): Request To Upload TP GIA Report





































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)


































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC4952L (87990968255G)
[GR9510H]

TP
AHMAD TAUFIKH BIN ABDUL HALIM
Mar 14 2018 6:00PM
[ANNLY SERVIVE & TRADING]
New Union Company

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/07/18 09:23	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/07/18 09:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/07/18 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 10:43	Singapore Accident Statement and Police Report	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/07/18 13:28	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18009065/GQD3E2
Date: 17/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100030352
 Claimant Vehicle No: FBC4952L Insured Vehicle No: GR9510H
 Date of Loss: 14/03/2018 Nature of Claim: TP Claim No: 8799096825SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC4952L Engine No: NC23E2031768
 Make & Model: HONDA CB400, 399cc Chassis No: NC391031755
 Reg. Date: 31/05/2002 (Man. Year: 2002) Odometer: 0 km
 Colour: Red
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60 R17 Rear Tyre Size: 120/60 R17
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,061.00	3,212.40	848.60	20.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	610.00	530.00	46.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,201.00	3,822.40	1,378.60	26.51
+ GST 7.00/7.00% (S\$)	364.07	267.57	96.50	26.51
Nett Amount (S\$)	5,565.07	4,089.97	1,475.10	26.51

INSPECTION

Date of Assignment: 18/05/2018
 Date Inspected: 21/05/2018 Inspected At:

New Union Company (HQ)
 BLK 9004 TAMPINES STREET 93 #01-106
 Singapore 528838

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CRASH BAR ASSY	Cut	150.00 FS	*150.00 FS
2	1		*METER ASSY	Cut	1,300.00 F	*1,300.00 FL
3	1		*HEADLAMP ASSY	Cut	380.00 F	*380.00 FL
4	1		*HANDLE BAR	Bent	120.00 F	*120.00 FL
5	1		*STEERING CORN BEARING	Necessary	150.00 F	*150.00 FL
6	1		*SIGNAL LAMP FRONT, RH	Broken	70.00 F	*70.00 FL
7	1		*EXHAUST EN-CAN	Cut	350.00 F	*350.00 FL
8	1		*BOX	Cut	150.00 F	*150.00 FL
9	1		*RACK FOR BOX	Not Necessary	135.00 F	*- FL
10	1		*MIRROR	Cut	80.00 F	*80.00 FL
11	2		*BALANCER	Cut	76.00 F	*76.00 FL
12	1		*RIM PRESS	Not Necessary	250.00 F	*- FL
13	2		*FRONT WHEEL BEARING	Not Necessary	60.00 F	*- FL
14	1		*FRONT WHEEL SHAFT	Not Necessary	65.00 F	*- FL
15	1		*FRONT BRAKE DISC	Bent	350.00 F	*350.00 FL
16	1		*FORK SEAL ASSY	Necessary	150.00 F	*150.00 FL
17	1		*HEAD LAMP STAY BRACKET	Bent	165.00 F	*165.00 FL
18	1		*FOOTREST PINION, RHS	Bent	45.00 F	*45.00 FL
19	1		*FORK OIL	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,061.00	3,551.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	338.60
Total Parts (\$\$)	4,061.00	3,212.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT	New	750.00	350.00
2	FORK PRESS	New	140.00	60.00
3	LABOUR CHARGE	New	250.00	200.00
Gross Labour Cost (S\$)			1,140.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >