

ASS. REC. BY:

REF:

CS/CTI18009066/R/qd3er

Special Instruction:

Surveyor:

Rasu

From (Person):

Irene Tay

of

ETI

Date/Time:

18/5/2018 @ 9:14am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SJX3326X

Insured:

SLP 1806J

at Workshop m/s:

Alls Well Motor

Tel:

6679 1146

of

25 Defu Lane 9

Policy No:

DMHCSN1739411700

Claim No:

SNM18D02426C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13/05/2018

CA / REV / REP. / REV 24 HRS

wp

21/05/18 @ 1pm owner waiting

H.O.D. Endorsement:

Date/Time:

9:50 am @ 18/5/18

Person Contacted:

chai yee

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SJX3326X - NA/CTI18008750/13

DOA: 13/05/18

SLP1806J - NA/CTI18008750/13

DOA: 13/05/2018

07/6/18 @ 5:31pm From Analysis final fig @ 2603.15, 4 days.
(feet @ 1031.75, 28%)

James

REF:

25412

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 57X 3326X
 at Workshop m/s: ALLWELL MOTOR
 of 25, Fern Lane 9
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

1pr

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 57X 3326X Yr Regn: 2010 / Jan
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA VELL FIRE 2-4 C.C. 2362
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 466697 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ANH208110389
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/45ZR18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wearance

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. <u>13/05/18</u>		D.O.I. <u>21/05/18</u>	

Survey held at Atsura
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 08 NOV 2018

James
8/11/2018

Date/Time, File Pass to?

11/08/18 James

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

OVER TP

Lump Sum / I.B.I. (\$) 2603.15

220

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18009066/R1qd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 18-05-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 1806J	Veh. Inspected	SJX 3326X	
Policy No.	DMHCSN1739411700	Coverage (\$)	0.00	
Claim No.	SNM18D02426C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/05/2018	Inspection Date		
Survey held at	ALLSWELL MOTOR TRADERS 100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 May 2018		18 May 2018 09:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SGRENTACAR PTE LTD, Co. Reg. No.: 201329402W		
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD		
Vehicle Reg. No.:	SJX3326X	Date of Loss:	13/05/2018 10:00 - :59
Claim Type:	TP / SNM18D02426C02	Policy/Cover Note No.:	DMHCSN1739411700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP1806J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: account5 leasing <account5@allswellmotor.com.sg>
Sent: Wednesday, 16 May, 2018 6:02 PM
To: Lucas Lee
Subject: Fwd: PRS FOR SJX3326X (CTI REF: SNM18D02426C02)

----- Forwarded message -----

From: **account5 leasing** <account5@allswellmotor.com.sg>
Date: Wed, May 16, 2018 at 6:01 PM
Subject: Re: PRS FOR SJX3326X (CTI REF: SNM18D02426C02)
To: ben OOI <ben@allswellmotor.com.sg>

Hi Lucas Lee,

Please get XING QUO QIANG from LKK to perform the SJE. Do survey the vehicle soonest..

Company Name : Allswell Motor Traders

Address : 25 Defu Lane 9 (S) 539266

Thanks

On Wed, May 16, 2018 at 1:37 PM, account5 leasing <account5@allswellmotor.com.sg> wrote:

----- Forwarded message -----

From: **Lucas Lee** <lucas.lee@sg.cntaiping.com>
Date: Wed, May 16, 2018 at 1:17 PM
Subject: PRS FOR SJX3326X (CTI REF: SNM18D02426C02)
To: account5 leasing <account5@allswellmotor.com.sg>

Without Prejudice

Dear Sirs

Kindly provide your company name & address for the next reply thanks.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG

SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential: its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: account5 leasing [mailto:account5@allswellmotor.com.sg]
Sent: Tuesday, 15 May, 2018 6:13 PM
To: Claims Dept of CTI; ben OOI; Edmund Ng; Mark Mark
Subject: SJX3326X Accident 13.05.2018 - 3rd party claim against CTI insured SLP1806J

Dear China Taiping (motor claims department)

(Without Prejudice)

We are the owner of the vehicle **SJX3326X** and your insured vehicle **SLP1806J** came in contact with our vehicle at the material time.

Before we proceed to repair our damaged vehicle, please us know within 2 working days till **17.05.2018** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you, we will proceed repair without any more reference to you.

Please expedite...

Thank You

Chai Yee

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Rasul (LKKAUTO)

From: OOI, Ben <ben@allswellmotor.com.sg>
Sent: Wednesday, 7 November, 2018 5:31 PM
To: Rasul (LKKAUTO)
Cc: account5 leasing
Subject: Re: Photos Old Parts Of Vehicle SJX3326X
Attachments: image001.jpg

Thank you, Rasul.

We agreed and confirmed the \$2,603.15/ 04 days p/p

Thanks again

Truly
OOI, Ben

Allswell Motor Traders
25, Defu Lane 9
Singapore 539266
Office: +65 6679 1146
Mobile: +65 9147 8545
Email: ben@allswellmotor.com.sg

On Wed, Nov 7, 2018 at 5:28 PM Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Ben,

As spoken, finalise amount is at \$ 2,603.15 / 4 days part by part

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)
Sent: Wednesday, 7 November, 2018 1:40 PM
To: OOI, Ben
Cc: account5 leasing
Subject: RE: Photos Old Parts Of Vehicle SJX3326X

Hi Ben,

Finalised amount is \$ 2,100.00 / 4 days lump sum

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: OOI, Ben [<mailto:ben@allswellmotor.com.sg>]
Sent: Monday, 5 November, 2018 6:56 PM
To: Rasul (LKKAuto)
Cc: account5 leasing
Subject: Fwd: Photos Old Parts Of Vehicle SJX3326X

Hi Rasul,

Attached are the pictures for your perusal.

Please finalise estimate..

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: ben@allswellmotor.com.sg

----- Forwarded message -----

From: **OOI, Ben** <ben@allswellmotor.com.sg>

Date: Mon, Nov 5, 2018 at 6:48 PM

Subject: Re: Photos Old Parts Of Vehicle SJX3326X

To: account5 leasing <account5@allswellmotor.com.sg>

Cc: <rasul@lkkauto.com>

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: ben@allswellmotor.com.sg

On Tue, Sep 4, 2018 at 2:51 PM account5 leasing <account5@allswellmotor.com.sg> wrote:

Hi, Mr Rasul

Please refer below attached file as photos old parts of vehicle SJX3326X.

Thank you.

Regard,

Yuna

Allswell Motor Traders

25, Defu Lane 9 Singapore 539266

Office: +65 6679 1146

Email: account5@allswellmotor.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/05/2018 09:27
Date Of Accident	13/05/2018 11:05
Exact Location Of Accident	ADMIRALTY ROAD WEST JUNCTION WOODLAND AVENUE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJX3326X
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VELLFIRE-2.4 Z PLATINUM SELECTION II (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5085700497-01
Cover Note Number	
Driver	
Name of Driver	JAILANI BIN HAMID
NRIC No	S1604600J
Date Of Birth	29/12/1963
Occupation	OUTDOOR
Date Of Driving Pass	27/08/1985
Driving Experience	32 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84384445
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 657 WOODLANDS RING ROAD #05-334
Postcode	730657
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MALAY PASSENGER GENDER: : FEMALE
Passenger 2	NAME: : MALAY PASSENGER GENDER: : FEMALE
Passenger 3	NAME: : MALAY PASSENGER GENDER: : FEMALE
Passenger 4	NAME: : MALAY PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT 11.05, I WAS DRIVING TOWARDS ADMIRALTY ROAD WEST TOWARDS JUNCTION OF SEMBAWANG DRIVE IN THE FAVOUR OF MY GREEN TRAFFIC LIGHT. ALL A SUDDENLY A HONDA CIVIC CAR TURNING RIGHT INTO MY LANE AND I HIT THE LEFT SIDE OF THE CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	NAZ
Phone Number	91226455
Email Address	

Details of Witness 2

Name	SABRINA
Phone Number	87137783
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP1806J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/HN No.:

Sketch Plan #2

SKETCH PLAN



A = SJX 3326X

B = SUP 1806J


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 11:45. I was driving towards Adairth Road west towards junction of Sembang Road. In the lane of my green traffic light. All a sudden a Honda Civic car turning right into my lane and I hit the left side of the car.

DECLARATION

(We declare the foregoing particulars are true in every respect.)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/HN No.:

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against Containing Insured sup 18065)

Estimate repair

Vehicle No. : SJX3326X Submitted by : Ben
 Make & Model : Toyota Vellfire 2.4 COE expiry : 31-05-2020
 Chassis No. : _____ Engine No. : _____
 Date of survey : _____

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Front bumper DE	01	\$1,195.1		2208.20
02	LH headlamp centre panel CR	01	\$697.0	\$187.4	258
03	Front chrome grille CR	01	\$291.6	\$697.0	
04	Front bumper lower grille DE	01	\$128.7		1686.15
Special net					
01	Clips @ \$11.00 each AM	02	\$22.0		57
02	License plate C/W license casing AM	01	\$30.0	35	
Labour description					
01	Dismantle / Assembly of front bumper / centre chrome	01	\$160.0	350	
02	Panel beating of LH fender chassis panel	01	\$360.0		890
03	Spray painting of all affected parts.	01	\$660.0	500	
04	Make good all minor / scuff elements.	01	\$40		
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Signature: Survey on 21/5/18
Rasul (LKK)

- arrange for before paint survey
 take photo old part to Rasul
 3634.40 Rasul@lkkauto.com.

402690

1656.15
 57.00
 890.00
 2603.15
 4 days
 PTP
 21/05/18 @ 1305 hrs

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 May 2018		18 May 2018 09:14 Edit Adj Rpt	S\$2,603.15 Edit Estimates	S\$2,603.15 View Rpt		Pending for Survey Report Cancel Case


















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SGRENTACAR PTE LTD , Co. Reg. No.: 201329402W								
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD								
Vehicle Reg. No.:	SJX3326X	Date of Loss:	13/05/2018 10:00 - :59 [95 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02426C02	Policy/Cover Note No.:	DMHCSN1739411700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLP1806J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/05/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJX3326X (SNM18D02426C02)**
[SLP1806J]

TP
ALLSWELL LEASING & LIMOUSINE PTE LTD
May 13 2018 10:00AM
[SGRENTACAR PTE LTD]
Allswell Motor Traders

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	14/05/18 19:37	Accident Statement	1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
11	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
12	14/05/18 19:33	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
13	14/05/18 19:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
14	14/05/18 19:35	Driving License [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
15	14/05/18 19:35	Identification Card [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/11/18 14:28	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	08/11/18 14:28	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	08/11/18 14:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	08/11/18 14:28	General View	1	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
14	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/11/18 14:28	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	08/11/18 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/05/18 09:13	PRS	 Load PDF	
2	18/05/18 09:13	OT GIA REPORT	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	14/05/18 19:34	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	14/05/18 19:34	Individual Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	14/05/18 19:37	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	14/05/18 19:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	14/05/18 19:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	14/05/18 19:35	Driving License	 Load JPG	<input checked="" type="checkbox"/>
15	14/05/18 19:35	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	14/05/18 19:34	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	14/05/18 19:34	Individual Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18009066/R1QD3E2

Date: 09/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1739411700

Claimant Vehicle
No : SJX3326XInsured Vehicle
No : SLP1806J

Date of Loss: 13/05/2018

Nature of Claim: TP

Claim
No: SNM18D02426C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX3326X	Engine No:	2AZC840599
Make & Model:	TOYOTA VELLFIRE, 2.4 Z Platinum Selection II (A)	Chassis No:	ANH208110389
Reg. Date:	01/06/2010 (Man. Year: 2010)	Odometer:	460697 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45ZR18	Rear Tyre Size:	245/45ZR18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,819.80	1,713.15	1,106.65	39.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,220.00	890.00	330.00	27.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,039.80	2,603.15	1,436.65	35.56
+ GST 7.00/7.00% (S\$)	282.79	182.22	100.57	35.56
Nett Amount (S\$)	4,322.59	2,785.37	1,537.22	35.56

INSPECTION

Date of Assignment: 18/05/2018

Date Inspected: 21/05/2018

Inspected At:

Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2018)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z Platinum Selection II (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX3326X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,195.10 F	*1,195.10 FL
2	1		*LH HEADLAMP CENTRE PANEL	Cracked	697.00 F	*187.40 FL
3	1		*FRONT CHROME GRILLE	Cracked	697.00 F	*697.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Deformed	128.70 F	*128.70 FL
5	2		*CLIPS	Necessary	22.00 FS	*22.00 FS
6	1		*LICENSE PLATE C/W LICENSE CASING	Bent	80.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	2,819.80	2,265.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	552.05
Total Parts (S\$)	2,819.80	1,713.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING OF LH FENDER CHASSIS PANEL }	New	360.00	350.00
2	DISMANTLE/ASSEMBLY OF FRONT BUMPER/CENTRE CHROME }	New	160.00	-
3	SPRAY PAINTNG OF ALL AFFECTED PARTS	New	660.00	500.00
4	MAKE GOOD ALL WIRING/SENSOR ELEMENTS	New	40.00	40.00
Gross Labour Cost (S\$)			1,220.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >