

REF: ALG

91N / Ana3



ASSIGNMENT

From: Date: 22052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKC 1485L

at Workshop m/s

Premium

of

55 Ubi Rd 1

Insured.

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10-30cm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKC4485L Yr Regn: 2011 August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5

c.c 1984.

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

49753.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZ28R9CA014933.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/65R19.

R: 235/65R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

22/05/18

Survey held at

Premium.

Des. of Damages: Frt (Rear) O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG.

Date/Time. File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS. \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)