

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18009148/R1ps3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Date: 08-07-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJJ 2788B	Veh. Inspected	SJG 7116Z	
	Policy No.	GA283386	Coverage (\$)	0.00	
	Claim No.	S8M00HN3	Excess (\$)	0.00	
	Assign From		Assign Date	18/05/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS E A	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MR053HY9305072256	Colour	BLACK	
	Odometer	226949	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
	L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
	R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
	L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/05/2018	Inspection Date	18/05/2018	
	Survey held at	8 Kaki Bukit Ave 4 #08-46			
	Repairer	SK AUTOMOBILE PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			