



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2016 PORSCHE MACAN PDK CYP E5 SR PORXXX (SKZ47Z)

Date of Loss

15 May 2018

Time of Loss

20.00

Loss Description

SKZ47Z (INSD) GRAZED WALL

Comment

Workshop Details

Total Rebate Amount

112323

Nett Loss Amount

\$132,677.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

09/08/2018



Days of work completion *

80



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKZ47Z

Registration State

SINGAPORE

Mileage

26835

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2016

ASSESSMENT INFO...

2016

Purchase Date

dd/mm/yyyy



Registration Date *

22/07/2016



Age of Vehicle

1

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LIM SIEW NGOH

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... PORSCHE MACAN PDK CYP E5 SR

ASSESSMENT INFO... PORSCHE

CATEGORY Model

POLICY INFORMAT... PORXXX

ASSESSMENT INFO... MACAN PDK CYP E5 SR

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WP1ZZZ95ZHLB00931

CATEGORY Date of Birth

FNOL INFORMATI... 2 January 1968

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 50

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... WP1ZZZ95ZHLB00931

CATEGORY Engine No

POLICY INFORMAT... 019192

ASSESSMENT INFO... 019192

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1984

CATEGORY Sum Insured

POLICY INFORMAT... 252000

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 245000

FNOL INFORMATI... 22

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...

50 MARINE PARADE ROAD, #08-13,
449307, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S6800026B

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

24/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/60R18

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

255/55R18

Front left side

HANKOOK7mm

Front right side

HANKOOK7mm

Rear left side

HANKOOK7mm

Rear right side

HANKOOK7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			REAR DOOR (LH)			Dented	1833.1		20		1466.48	Reviewir
☐		2	1			REAR DOOR INSULATION			Necessary	8.7		20		6.96	Reviewir
☐		3	1			REAR DOOR SEAL OUTER			Necessary	219.9		20		175.92	Reviewir
☐		4	6			REAR DOOR CLIP			Necessary	0.8		20		3.84	Reviewir
☐		5	2			REAR DOOR SEAL STICKER			Necessary	0.8		20		1.28	Reviewir
☐		6	2			REAR DOOR LOCK SCREW			Serviceable	0	0	0	0	0	Deny
☐		7	1			CAVITY PRESERVATION			Serviceable	0	0	0	0	0	Deny
☐		8	2			DAMPING			Serviceable	0	0	0	0	0	Deny
☐		9	1			REAR DOOR SEAL			Necessary	168.6		20		134.88	Reviewir
☐		10	1			REAR DOOR SEAL LOWER			Necessary	128.2		20		102.56	Reviewir
☐		11	1			REAR DOOR ARRESTER			Necessary	89.6		20		71.68	Reviewir
☐		12	2			DOOR ARRESTER SCREW			Necessary	1.7		20		2.72	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		13	4			DOOR ARRESTER HEAD BOLT			Necessary	1.5		20		4.8	Reviewir
☐		14	1			DOOR HANDLE LH			Cracked	429.6		20		343.68	Reviewir
☐		15	1			DOOR HANDLE CAP			Cracked	9.5		20		7.6	Reviewir
☐		16	1			DOOR HANDLE GASKET BIG			Necessary	6.3		20		5.04	Reviewir
☐		17	1			DOOR HANDLE GASKET SMALL			Necessary	5.8		20		4.64	Reviewir
☐		18	1			DOOR HANDLE INNER SUPPORTING BOW			Cracked	73.3		20		58.64	Reviewir
☐		19	1			REAR DOOR TRIM GARNISH			Necessary	514.3		20		411.44	Reviewir
☐		20	1			REAR DOOR STONE GUARD LH			Necessary	82.9		20		66.32	Reviewir
☐		21	1			REAR DOOR TRIM GARNISH TAPE			Necessary	99.1		20		79.28	Reviewir
☐		22	1			REAR DOOR MOULDING MATT BLACK			Necessary	140.7		20		112.56	Reviewir
☐		23	1			REAR BUMPER			Cut	844.3		20		675.44	Reviewir
☐		24	1			REAR BUMPER INSULATION LH			Necessary	32.8		20		26.24	Reviewir
☐		25	1			REAR BUMPER INSULATION RH			Necessary	32.8		20		26.24	Reviewir

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			REAR FENDER LH			Dented	3028.9		20		2423.12	Reviewir
		27	1			REAR FENDER INNER PROTECTIVE FILM			Necessary	63.2		20		50.56	Reviewir
		28	1			REAR BUMPER INNER SHIELD			Damaged	242.3		20		193.84	Reviewir

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
		1		TO REPLACE LH REAR FENDER, LH REAR DOOR, REAR BUMPER & TO REPAIR LH REAR DOOR INNER PANEL AFFECTED BY THE ACCIDENT	10920	0	0	Reviewing		
		2		TO RESPRAY LH REAR FENDER, LH REAR DOOR, LH FENDER INNER PANEL, LH ROCKER PANEL & REAR BUMPER	4600	0	0	Reviewing		
		3		TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	200	0	0	Reviewing		
		4		TO CARRY-OUT BODY CAVITY PRESERVATION	200	0	0	Reviewing		
		5		TO REMOVE & REFIT CARPET, SEATS & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	1560	0	0	Reviewing		
		6		TO TRANSFER THE DOOR MECHANISM	780	0	0	Reviewing		
		7		TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	250	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
		8		TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	600	0	0	Reviewing		
		9		TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 14 DAYS	Reviewing			
☐		2	EXPANDER NUT (2PCS) (DISC 20%)	Reviewing	2.4	NECESSARY (SUPPLEMENTARY)	
☐		3	CLINCH PIN (6PCS) (DISC 20%)	Reviewing	37.44	NECESSARY (SUPPLEMENTARY)	
☐		4	SUNDRIES	Reviewing	50	NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$23,655.60

Claim Amount

\$23,655.60

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$19,110.00	\$19,110.00
Miscellaneous	\$89.84	\$89.84
Excess	-\$2,000.00	-\$2,000.00
Spare Parts	\$6,455.76	\$6,455.76

Submit for Review