

NATIONAL Assessment Centre Services. [wef 1 Jan 05] MNA118066116

Date In: 21/5/18-16:29	Job description	Date & Time Completed	Done by
Ref No: NA/INC18009177/C24	SAS e-filing		
Veh No: 6BE88344	E-mail (within 3hrs, AIC 2hrs)		
D.O.A : 29/4/18-16:30	i-Motor Claim Form	MT10995251-001	21/5/18 17:18
OD : TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: Curb	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (	Date:	Time: ()
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-
() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.
() Total Loss Case : to e-mail Insurer URGENTLY.
Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury : _____

Date/Time	Actions

NA1803280	Invoice Preparation Checklist	Amt (\$) In Bill	Amt (\$) Add Bill
Claimant's Particulars:-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments:-	For claiming against INC Only (wef 10 Jan 2005)		
Pat. 1:	6) TR: Re-inspection \$75		
Pat. 2 / 3:	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	Q11*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idac Mobile 30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 16:29
Date Of Accident	29/04/2018 16:30
Exact Location Of Accident	OLD CHOA CHU KANG RD OPP NEA CHOA CHU KANG CREMATO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8834H
Insured/Policyholder	
Name Of Registered Owner	CSP MAINTENANCE PTE LTD
Co Reg No	199400236K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97648814
Alternative Phone No	OFFICE-97648814

Vehicle Particulars

Manufacturer	TOYOTA
Model	TOYOTA DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088922128-01
Cover Note Number	

Driver

Name of Driver	A K GUNASEKARAN
NRIC No	S1650530G
Date Of Birth	23/03/1964
Occupation	OUTDOOR
Date Of Driving Pass	04/12/2007
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82352735
Fax Number	
Contact Number	OFFICE-82352735
Email Address	NOEMAIL

Address	BLK 162 YISHUN STREET 11 #08-268
Postcode	760162
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180507/2048.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CURB
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	A K GUNASEKARAN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	GBE8834H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

P/s refer to the police report: T/20180507/2048

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT STATEMENT

ACCIDENT DATE: (29/04/2018) (DD/MM/YYYY), TIME: (16:30) (HH:MM)

LOCATION: Chua Chu Kang

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: G8E 8834H
b) INSURANCE COMPANY: NTUC
c) POLICY NUMBER: 5088922128-01
d) POLICY TYPE: (COMPREHENSIVE) / THIRD PARTY / THIRD PARTY FIRE & THEFT
e) MAKE & MODEL: TOYOTA / DYNG 1.50
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY) / MOTORCYCLE / OTHERS
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL) / MOTORCYCLE
h) PURPOSE OF USING AT ACCIDENT TIME: working time
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: CSP maintenance pte ltd (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 97648814
c) ADDRESS: _____

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: A.K. Gunasekaran (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: S165053016 CONTACT: 82352735
c) ADDRESS: Blk 162 Yishun St 11 # 08-268 (760162)

*d) DATE OF BIRTH: (23/03/1964) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: _____

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING) / OTHERS _____

b) ROAD SURFACE: (DRY / WET) / OTHERS _____

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: 1Cerb MODEL: _____
b) DRIVER'S NAME: _____
c) NRIC/FIN/PASSPORT: _____ CONTACT: _____

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
e) DRIVER'S NAME: _____
f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

Email =

fax =



SINGAPORE POLICE FORCE



T/20180507/2048

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20180507/2048

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/05/2018 13:13		Vide Report No.:		Station Diary No.: 66	
Informant's Particulars					
Name of Informant: A K GUNASEKARAN			Address: APT BLK 162 YISHUN STREET 11 #08-268 SINGAPORE 760162		
ID Type / ID No.: NRIC NO / S1650530G			Contact No.: Home/Office: Mobile: 82352735		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 23/03/1964	Type of Informant: Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 29/04/2018 16:30	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 OLD CHOA CHU KANG ROAD				
Along Old Choa Chu Kang Road opposite NEA Choa Chu Kang Crematorium towards				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE8834H	Van	TOYOTA	Dyna	Silver	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20180507/2048

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20180507/2048

CONTINUATION OF REPORT

Driver			
Name	A K GUNASEKARAN	ID No.	S1650530G
Related Vehicle	GBE8834H (Van)	Contact No.	82352735
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/04/2018	Date Discharge	03/05/2018
No. of Days granted Medical Leave	13	Degree of Injury	Serious

Brief Details.

On 29/04/2018 at about 1630hrs, I was driving my company vehicle GBE8834H (silver Toyota Dyna) alone along Old Choa Chu Kang Road opposite NEA Choa Chu Kang Crematorium towards Jalan Bahar. It was drizzling slightly at that point of time. It was a bend with single lane road each on both directions with no road divider; thereafter there was a big lorry which was travelling on the opposite lane which was coming onto my lane, so I avoided by swerving to my vehicle to the left and it mounted onto the kerb side of the road. The said big lorry then drove off. My company vehicle did not make any contact with any other vehicle or any government properties.

Subsequently, I became unconscious and was conveyed to Ng Teng Fong Hospital by the ambulance and I was warded from 29/04/2018 to 03/05/2018. I was given 13 days of hospitalization leave dated from 29/04/2018 to 11/05/2018.



**SINGAPORE
POLICE FORCE**



T/20180507/2048

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20180507/2048

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt LAU JIXIANG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NOR FAIZAL BIN YAHYA

Contact No.: 65476202 / 65470000

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

07/05/2018 13:13

Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1650530G



Name

A K GUNASEKARAN

Race

INDIAN

Date of birth

23-03-1964

Country/Place of birth

SINGAPORE

Sex

M

5723154



NRIC No. S1650530G



Date of issue

16-03-2017

Address

APT BLK 162 YISHUN STREET 11
#08-268
SINGAPORE 760162

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number

S1650530G

Name

A K GUNASEKARAN

Birth Date: 23 Mar 1964

Issue Date: 21 Nov 2016




002631105E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 04 Dec 2007

NP 428A



Licence No: S1650530G

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	29/04/2018 16:30						
Vehicle No. (For Motor)	GBE8834H								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5088922128-01	CSP MAINTENANCE PTE LTD	199400236K	GCV	Comprehensive	GBE8834H	GBE8834H	18/04/2018	17/04/2019
Continue									

 Policy Information

Policy No.	5088922128-01	Policyholder Name	CSP MAINTENANCE PTE LTD	Policyholder NRIC	199400236K
Address	1 BUKIT BATOK CRESCENT #08-24 WCEGA PLAZA SINGAPORE 658064				
Product Name	COMMERCIAL VEHICLE INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	16/03/2018	Effective Date	18/04/2018 00:00	Expiry Date	17/04/2019 23:59
Excess Type		All Claim Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess		OS Premium	1306.21		
Outside Singapore OD Excess		Outside Singapore TP Excess		Young/Inexperience Driver Excess	
Agent	TIMES INS BROKERS (MOTOR B	Agent Tel.	62528888	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	1 BUKIT BATOK CRESCENT	Address 2	#08-24 WCEGA PLAZA	Address 3	SINGAPORE 658064
Address 4		Address Type	Singapore address	Post Code	658064
Unit No.		Related Policy Number	5100352695		

 Insured Object: GBE8834H

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

The premium on this policy has not been collected.

Exit

Accident MT/0995251

Policy No.	5088922128-01	Vehicle No.	GBE8834H	GST Registration No.	
Policyholder Name	CSP MAINTENANCE PTE LTD			Policyholder NRIC	199400236K
Product Code	COMMERCIAL VEHICLE INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	97648814	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	
KPK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	15	Private Hire	No

Accident Details

Report Date	21/05/2018 17:14	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	29/04/2018	Time of Accident (hh:mm)	16:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	OLD CHOA CHU KANG RD OPP NEA CHOA CHU KANG CREMATO				

Benefits

Excess

Own Damage Excess	500.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	No
Modification History			

Policyholder Mailing Address

Address 1	1 SUKIT BATOK CRESCENT	Address 2	#08-24 WCEGA PLAZA	Address 3	SINGAPORE 658064
Address 4		Address Type	Singapore address	Post Code	658064
Unit No.		Related Policy Number	S100352695		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	A K GUNASEKARAN	Driver NRIC	S1650530G	Driver DOB	23/03/1954
Register Date of Driver License	04/12/2007	Driver Age	54	Driving Experience	10
Contact No.(Mobile)	82352735	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 162	Address 2	YISHUN STREET 11	Address 3	SINGAPORE 760162
Address 4		Address Type	Singapore address	Post Code	760162
Unit No.	08-268				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 New

Claim Type *	DO-MD	Insured Name	CSP MAINTENANCE PTE LTD	Insured NRIC	199400236K
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	65700139
Email Address		OI Vehicle Number	GBE8834H	TP Vehicle Number	CURB
Claim Description	GBE8834H / CURB ON 29 Apr 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered	21/05/2018 17:18	Claim Close Date		Date Received	21/05/2018 00:00
Report Taken By	Jackson				
☒ Print AK letter					

Save Submit

Attachment

Accident No.	MT/0995251	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	21/05/2018 17:20

Path *	Category *	Confidential	Urgency *	Description *

☐ Send Message Upload

Attachment List

Attachment	uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:20	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:20	SAS	Normal	SAS 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:19	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 21 May 2018 17:18	Photos	Normal	Photos 2018-5-21		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
		Display in New Window	Scan and uploading	

ASSIGNMENT (IDAC)By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn. Property () b) Road Work Object ()
- (Eg: signboard, barrier, tree etc) c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
- when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal informationRemarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: GBE 8834 H Yr Regn: 18 Apr 2016

Type: M.Car / M.Cycle / Bus / Van (Loro) / Taxi / Prime Mover / MPV

/ Truck / Trailer or _____

Make & Model: Toyota Dyna 150 C.C. 2982

Colour: Silver Transmission Type: Auto / Manual

Eng/No: _____ Sp. Reading: no key 22/5

C/No: JTFAT35Y20K206217

Gen. Cond: Good / Fair / Poor / Burnt or _____

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195 R15

R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>4</u> mm		R/Bal. <u>4/4</u> mm	
L/Bal. <u>4</u> mm		L/Bal. <u>4/4</u> mm	

Parallel Import: Yes / No

Repair Type: LS / I.B.I

No of Repair Days: 15

D.O.I. 22/5/2018

Towed-In: Yes / No

Towing Required: Yes / No

Vehicle in Idac: Yes / No

Time: 8.50 am

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

VAN / LORRY (Fr)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Fit Number Plate	BT		
1002	991887	Fit Number Plate Base	BT		
1004	991300	Fit Bumper	BT		
2001	991477	Fit Bumper Upper			
2002	991387	Fit Bumper Lower			
2003	991449	Fit Bumper Side Cover			
2004	991443	Fit Bumper Side			
1006	991325	Fit Bumper Bracket	BT		2
1008	991433	Fit Bumper Reinforcement	DD		
2005	991466	Fit Bumper Signal Lamp			
1017	995100	Fit LH Bumper Fog Lamp Cover			
1018	991355	Fit RH Bumper Fog Lamp Cover			
1019	995079	Fit LH Bumper Fog Lamp			
1020	995080	Fit RH Bumper Fog Lamp			
1021	991793	Fit Grille	CR		
1022	991328	Fit Grille Emblem	BR		
2006	990247	Fit Grille Sticker			
1023	991799	Fit Grille Chrome Moulding			
2007	991891	Fit Panel	DD		
2008	991874	Fit Lower Panel	DD		
2009	991328	Fit Panel Emblem	NEC		
2010	990247	Fit Panel Sticker			
2011	991893	Fit Panel Garnish	DIS		
1024	991222	Fit Apron Panel			
2012	991527	Fit Corner Panel	DIS		2
2013	991532	Fit Corner Panel Signal Lamp Garnish	DIS		
2014	995245	Fit Signal Lamp LH			
2015	995246	Fit Signal Lamp RH			
1029	995153	Fit LH Headlamp Assy			
1030	991821	Fit RH Headlamp Assy	BR		
1031	995088	Fit LH Side Lamp			
1032	995089	Fit RH Side Lamp			
2016	992149	Fit Wiper Panel	BT		
2017	995043	Fit Wiper Nozzle			
1120	992140	Fit Wiper Arm			
1121	992142	Fit Wiper Blade			
2018	992145	Fit Wiper Link			
2019	992148	Fit Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Fit Windscreen	BR		
1115	992097	Fit Windscreen Rubber			
1117	992098	Fit Windscreen Sealant			
2020	992114	Fit Windscreen Outer Pillar	DD		
2021	992113	Fit Windscreen Inner Pillar	DD		
1118	991019	ERP Bracket	NEC		
1119	991020	ERP Unit			
2022	991958	Fit Side Mirror (Big)			
2023	991959	Fit Side Mirror (Small)			
2024	991962	Fit Side Mirror (Round)			
2025	995015	Fit Wing Mirror Stay			
1025	992013	Fit Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser	BT		
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler	BT		
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct	AS		
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No: GBE 8834 H

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Fit Cabin Assy			
2028	991501	Fit Cabin Mounting			
2029	991502	Fit Cabin Rear Panel	RH		
1092	991520	Fit LH Chassis Member	DD		
1093	991520	Fit RH Chassis Member	BT		
1094	990728	Fit Vertical Cross Member			
1095	991863	Fit Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag	BT		
1128	994485	Steering Wheel Airbag Sensor	NEC		
1131	990029	Airbag Control Unit			
1133	991922	Fit RH Seat Belt Assy			
1135	995182	Fit LH Seat Belt Assy			
1124	990753	Dashboard Assy	BR		
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Fit LH Fender			
1097	995072	Fit LH Fender Inner Panel			
1100	991740	Fit LH Fender Inner Shield			
1101	995179	Fit LH Mudflap			
2035	994966	Fit LH Wheel Guard			
1102	995170	Fit LH Wheel Rim			
1104	995065	Fit LH Tyre			
1105	995071	Fit RH Fender			
1106	991739	Fit RH Fender Inner Panel	BT		
1109	991740	Fit RH Fender Inner Shield	DIS		
1110	991884	Fit RH Mudflap	DIS		
2036	994966	Fit RH Wheel Guard	DD		
1111	992087	Fit RH Wheel Rim	DIS		
1113	995065	Fit RH Tyre			
1255	995326	Fit LH Door	SCR		
1256	995140	Fit LH Door Protector			
1257	995104	Fit LH Door Hinge			
1258	995142	Fit LH Door Wing Mirror			
1262	995103	Fit LH Door Glass			
1263	991595	Fit LH Door Glass Regulator			
1264	991596	Fit LH Door Glass Regulator Motor			
1265	991662	Fit LH Door Rubber			
1266	991636	Fit LH Door Outer Handle			
1272	991617	Fit LH Door Inner Trim Board			
1316	995327	Fit RH Door	BT		
1317	991654	Fit RH Door Protector			
1318	991601	Fit RH Door Hinge	BT		
1319	991685	Fit RH Door Wing Mirror	BR		
1323	991584	Fit RH Door Glass	BR		
1324	991595	Fit RH Door Glass Regulator	BT		
1325	991596	Fit RH Door Glass Regulator Motor			
1326	991662	Fit RH Door Rubber	BT		
1327	991636	Fit RH Door Outer Handle	BT		
1333	991617	Fit RH Door Inner Trim Board	BT		
2037	991644	Fit Door Fit Pillar	RH		
2038	991657	Fit Door Rear Pillar	RH		
2039	992072	Fit Wheel Arch Panel			
2040	992069	Fit Wheel Arch Panel Garnish			
2041	991996	Fit Step Panel			
2042	994498	Fit Step Panel Top Garnish			
2043	994495	Fit Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sucker	NEC		
		Instrument Cluster	CR		
		Roof Panel	DD		
		Fit RH Dr R Pillar Emblem	NEC		
		Fit RH Dr Lock	BT		
		Lock Sticker	BT		

Conditioning (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

VAN / LORRY (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (3) Check (✓)
(4) Not Consistent (NC)

Aug 2003

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Vehicle No: GBE 8834H

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate RH	DD	✓	
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge	DD	✓	6
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap	DIS	✓	
1235	993934	Rear RH Wheel Rim	DD	✓	
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			50%
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket	BT	✓	
1136	990247	Sticker			
		Rear Canopy	DD	✓	
		Rear Cabin Railing	DD	✓	
		Rear RH Mud Guard	DIS	✓	

No of Items: _____ Assessor: _____

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			
		Steering Coupling			
		Coupling			

No of Items: _____ Assessor: _____

Original copy

Claim Handling

Task Transfer Exit

Accident MT/0995251

IDS SALS

Policy No.	S08922128-01	Vehicle No.	GB8834H	GST Registration No.	M201190363
Policyholder Name	CSP MAINTENANCE PTE LTD			Policyholder NRIC	199400236K
Product Code	COMMERCIAL VEHICLE INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	97648814	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	FL
KPIK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	15	Private Hire	No

Accident Details

Report Date	21/05/2018 17:14	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	29/04/2018	Time of Accident hh:mm	16:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	OLD CHOA CHU KANG RD OPP NEA CHOA CHU KANG CREMATO				

Benefits

Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

GST Registered Information

GST Registered	Yes	GST Registration Date	01/04/1994
GST Registration No.	M201190363	GST Status Verified	Yes
Modification History	22/05/2018 10:48:25 Carol Wan changed GST Registered from No to Yes 22/05/2018 10:48:25 Carol Wan changed GST Registration No. from null to M201190363 22/05/2018 10:48:25 Carol Wan changed GST Registration Date from null to 01/04/1994		

Policyholder Mailing Address

Address 1	1 SUKIT BATOK CRESCENT	Address 2	#08-24 WCEGA PLAZA	Address 3	SINGAPORE 658064
Address 4		Address Type	Singapore address	Post Code	658064
Unit No.		Related Policy Number	S100352695		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	A K GUNASEKARAN	Driver NRIC	S1650530G	Driver DOB	23/03/1964
Register Date of Driver License	04/12/2007	Driver Age	54	Driving Experience	10
Contact No.(Mobile)	82352735	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 162	Address 2	YISHUN STREET 11	Address 3	SINGAPORE 760162
Address 4		Address Type	Singapore address	Post Code	760162
Unit No.	08-268				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimee Bin Mantau

IDS SALS

Claim Type	OD-MD	Insured Name	CSP MAINTENANCE PTE LTD	Insured NRIC	199400236K
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	65700139
Email Address		OI Vehicle Number	GB8834H	TP Vehicle Number	CURB
Claim Description	GB8834H / CURB ON 29 Apr 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	income to assign workshop	GIA report	Received
Date Registered	21/05/2018 17:50	Claim Close Date		Date Received	22/05/2018 18:18
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment

Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	DYNA 150	Engine Capacity	1.70
Date of Registration	18/04/2016	Class No.	JTPAT35Y20K208217		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 RAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrap Value(\$)		Economical Repair Value(\$)	

REMARK: NO OF REPAIR DAY: 15 DAYS. 1X FRT LOWER PANEL-REPLACE. 1X FRT WINDSCREEN-REPLACE. 1X FRT RH WINDSCREEN OUTER PILLAR-REPLACE. 1X AIR CON LIQUID PIPE-UNCONFIRM. 1X AIR DUCT-REPLACE. 1X AIR CLEANER-UNCONFIRM. 1X STEERING WHEEL AIRBAG-REPLACE. 1X STEERING WHEEL AIRBAG SENSOR-REPLACE. 1X FRT RH WHEEL GUARD-REPAIR. 1X FRT LH WHEEL RIM-UNCONFIRM. 1X FRT RH WHEEL RIM-REPLACE. 2X FRT RH DOOR HINGE-REPLACE. 1X FRT RH DOOR WING MIRROR-REPLACE. 1X FRT RH DOOR OUTER HANDLE-REPLACE. 1X FRT RH DOOR INNER TRIM BOARD-REPLACE. 1X FRT RH DOOR PRT PILLAR-REPAIR. 1X FRT RH DOOR REAR PILLAR-REPLACE. 1X FRT STEP PANEL-UNCONFIRM. 1X FRT STEP PANEL TOP GARNISH-UNCONFIRM. 1X FRT STEP PANEL INNER GARNISH-UNCONFIRM. 1X STICKER-REPLACE. 1X INSTRUMENT CLUSTER-REPLACE. 1X FRT RH OR PILLAR EMBLEM-REPLACE. 1X FRT RH DOOR LOCK-REPLACE. 1X FRT RH DR LOCK STICKER-REPLACE. 1X REAR RH SIDE GATE-REPLACE. 1X REAR RH MUDGUARD-REPLACE. 1X REAR CANOPY-REPAIR. 6X REAR SIDE GATE HINGE-REPLACE. 1X CTR EXHAUST PIPE-REPLACE. 1X FRT RH TIE

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	16000101	BUMPER (FRONT)	1	Replace	X
ABSORBER						
ACCELERATOR	3	16001301	BUMPER BRACKET (FRONT LEFT)	1	Replace	X
ACTUATOR	4	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace	X
ADVERTISEMENT STICKER						
AIR BAG	5	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR BLOWER						
AIR BOX	6	27100101	GRILLE (FRONT)	1	Replace	X
AIR CHAMBER BOX						
AIR CLEANER	7	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR COMPRESSOR	8	33000101	PANEL (FRONT)	1	Replace	X
AIR CON	9	33000301	PANEL EMBLEM (FRONT)	1	Replace	X
AIR CON (VAN)	10	33000401	PANEL GARNISH (FRONT)	1	Replace	X
AIR COOLER						
AIR DISTRIBUTOR	11	21300101	CORNER PANEL (FRONT LEFT)	1	Replace	X
AIR FILTER	12	21300102	CORNER PANEL (FRONT RIGHT)	1	Replace	X
AIR FLOW						
AIR GRILLE	13	21300202	CORNER PANEL GARNISH (FRONT RIGHT)	1	Replace	X
AIR HORN						
AIR INTAKE	14	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
AIR RESONATOR BOX	15	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR THROTTLE BODY AND SENSOR	16	454008	WIPER PANEL	1	Repair	X
ALARM						
ALTERNATOR	17	45400301	WIPER BLADE (FRONT LEFT)	1	Unconfirm	X
ALUMINIUM PANEL - SIDE						
AMPLIFIER	18	45101901	WINDSCREEN RUBBER (FRONT LEFT)	1	Unconfirm	X
ANTENNA	19	45100902	WINDSCREEN INNER PILLAR (FRONT RIGHT)	1	Replace	X
ANTI ROLL						
APRON	20	245001	ERP BRACKET	1	Replace	X
ARCH	21	112023	AIR CON CONDENSER	1	Replace	X
ARM REST						
ASH TRAY	22	112360	AIR CON FAN	1	Unconfirm	X
AUTO CLUTCH	23	344001	RADIATOR	1	Unconfirm	X
AUTO COOLER PIPE	24	344005	RADIATOR COWLING	1	Unconfirm	X
AUTO CRUISE MOTOR						
AUTO TRANSMISSION	25	344008	RADIATOR FAN	1	Unconfirm	X
AXLE						
BACK REST (MC)	26	323001	OIL COOLER	1	Replace	X
BACK SEAT	27	24301902	ENGINE MOUNTING (CENTRE)	1	Unconfirm	X
BALANCER						
BATTERY	28	161010	CABIN MOUNTING	1	Unconfirm	X
BEADING (MC)	29	161011	CABIN PANEL	1	Replace	X
BELT COVER (MC)						
BELT TENSIONER	30	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Repair	X
BODY	31	112053	AIR CON EVAPORATOR	1	Unconfirm	X
BODY (MC)	32	112003	AIR CON BLOWER	1	Unconfirm	X
BOLT CAP (MC)						
BOLT HEAD COVER (MC)	33	15701602	BRAKE MASTER PUMP (FRONT RIGHT)	1	Unconfirm	X
BONNET						
BOOT	34	15700501	BRAKE BOOSTER PUMP (FRONT)	1	Unconfirm	X
BOX (MC)	35	106007	AIR BAG CONTROL UNIT	1	Unconfirm	X
BOX BRACKET (MC)						
BOX CARRIER (MC)	36	22600102	DASHBOARD (TOP)	1	Replace	X
BOX DOOR	37	356009	ROOF PANEL	1	Repair	X
BOX STICKER (MC)						
BRACE PANEL	38	31900102	MUDFLAP (FRONT RIGHT)	1	Replace	X
BRAKE	39	41600101	TYRE (FRONT LEFT)	1	Unconfirm	X
BRAKE - ABS	40	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
BRAKE (MC)						
BUMPER	41	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
CABIN						
CAMBER	42	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	X
CAMSHAFT	43	23300201	DOOR (FRONT LEFT)	1	Replace	X
CAR AUDIO SYSTEM	44	23300202	DOOR (FRONT RIGHT)	1	Replace	X
CAR JACK						
CARBURATOR	45	23302002	DOOR GLASS (FRONT RIGHT)	1	Replace	X
CARGO						
CARRIAGE	46	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	1	Replace	X
CARRIER MOUNTING	47	23302502	DOOR GLASS REGULATOR MOTOR (FRONT RIGHT)	1	Unconfirm	X
CASTOR	48	23306102	DOOR RUBBER (FRONT RIGHT)	1	Replace	X
CATALYTIC CONVERTOR						
CD CHANGER	49	390001	SPARE TYRE	1	Unconfirm	X
CD PLAYER						
CD UNIT (MC)	50	247017	EXHAUST PIPE	1	Unconfirm	X
CENTRE BOTTOM	51	247013	EXHAUST MOUNTING	1	Unconfirm	X
CENTRE BRACKET						
CENTRE CONSOLE	52	31900104	MUDFLAP (REAR RIGHT)	1	Replace	X
CENTRE COWLING (MC)	53	448014	WHEEL RIM	1	Replace	X
CENTRE CROSS MEMBER	54	43600104	TYRE (REAR RIGHT)	1	Unconfirm	X
CENTRE EXHAUST						
CENTRE FARING (MC)	55	264008	FUEL TANK	1	Unconfirm	X
CENTRE FOOTREST COVER (MC)	56	264009	FUEL TANK BRACKET	1	Replace	X
CENTRE GARNISH						
CENTRE GLASS FRAME	57	161015	CABIN RAILING	1	Replace	X
CENTRE GRILLE						
CENTRE JAW (MC)	58	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm	X
CENTRE LOWER MEMBER	59	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	X
CENTRE OUTER PILLAR						
CENTRE RH LAMP	60	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	X

61	30500101	LOWER ARM (FRONT LEFT)	1	unconfirm	X
62	401028	STEERING RACK & PINION	1	unconfirm	X
63	401021	STEERING CROSS MEMBER	1	Replace	X
64	407001	SUB FRAME	1	unconfirm	X
65	12800101	ANTI ROLL BAR (FRONT)	1	unconfirm	X
66	243030	ENGINE OIL SLUMP	1	unconfirm	X
67	36600102	SHOCK ABSORBER (FRONT RIGHT)	1	Replace	X
68	36600602	SHOCK ABSORBER MOUNTING (FRONT RIGHT)	1	unconfirm	X
69	30000102	KNUCKLE ARM (FRONT RIGHT)	1	Replace	X
70	30000202	KNUCKLE ARM BEARING (FRONT RIGHT)	1	Replace	X
71	30500102	LOWER ARM (FRONT RIGHT)	1	Replace	X

LKK Paya Ubi

From: Zuraimee Bin Mantau <zuraimee.mantau@income.com.sg>
Sent: Thursday, 24 May 2018 3:50 PM
To: Hock Wah
Cc: LKK Paya Ubi
Subject: Vehicle GBE8834H, OD Claim No: MT/0995251-001, DOA; 29/04/2018
Attachments: Capture.2.PNG; Capture.PNG; Capture.3.PNG

Dear Hock Wah Motor

Excess \$600 applies.

Vehicle is currently at NAC Paya Ubi.

Please arrange to tow the vehicle and update Mr Lim at 97648814 on the repair status.

Strictly no further supplementary is allowed. A **survey before repair** is required.

Please forward the invoice and DV within 7 working days to us once repairs has been done and survey conducted. Update the 'Repair Status' when repairs are done.

XX

Our Ref: MT/CA/OD/051/0995251-001/ZBM

24 May 2018

HOCK WAH MOTOR (BEDOK)

BLK 3011 #01-2008

BEDOK INDUSTRIAL PARK E

BEDOK INDUSTRIAL PARK E

SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/0995251-001

REPAIR OF VEHICLE NUMBER: GBE8834H

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 24 May 2018

Make: TOYOTA

Model: DYNA 150

Estimated Repair Days: 0

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimee Bin Mantau at 64307891 or email us at

motor@income.com.sg.

Thank you

Zuraimee Bin Mantau
Senior Executive, Motor Insurance
T +65 6430 7891
www.income.com.sg





NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: GBE 8834 14 Date In: 25/05/18 Time In: 9.00am with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: HOCK HWA

Collection Date: 25/05/18 Time: 9.00 am with Keys: Yes No

Tow Truck No: VM 7317B Tow Man: Lim Kah Hoony NRIC: F8305085M

Signature: [Signature] Hp: 9039 4179

For office use

Attended by: ROSLINDA

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____