

22/03/2002

ASS. REC. BY:

REF: CS/EQ218009178/Uuber

Special Instruction:

Surveyor:

Manus.

ASSIGNMENT (Office)

From (Person):

Francis Ng

of

EQ2

Date/Time:

18052018 323pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 179P

Insured:

SLJ 44082

at Workshop m/s

Autobury Pte Ltd

Tel:

8618 8611

of

Blk 1 Kaki Bukit Ave 6 #02-11

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

18052018 502pm

Person Contacted:

Victor

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 44082 - NA / EQ218009178 / 24

OA 18052018

SKN 179P - X

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKN1799at Workshop m/s Autobey pte ltd

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 22k.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5/1/2020

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN1799Yr Regn: 1 / 100Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Porsche 911 GT3c.c. 3600Colour: orange

A/C: Insured / Std / NI / NA

Sp. Reading: 193871

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP0ZZZ99Z45690480Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/40 R18R: 295/30 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 15/5/18D.O.A. 21/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S H.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
2/6/18	confirm LTA 300 / Rep 12k. 1yrs. 3mth
	d/s \$ 8100 with victor (Red 13, 663-26, 6390)

RECEIVED 8 JUN 2018

Date/Time, File Pass to?

☐ : Prel. Report1) ☐ : Final Report

Date/Time, File Return to?

2) 7/6 - typistDays Of Repair: 5Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 300

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

300Report Format: TPLump Sum / I.B.I: (\$ 8100p)

Nivitha (LKK Auto)

From: Francis Ng <francis.ng@eqinsurance.com.sg>
Sent: Friday, 18 May 2018 3:23 PM
To: assignments
Subject: FW: Pre-Repair Survey /Inspection; Your Ref: CL/180524/T/VAC; EQ Ref: SLJ4408L/TO BE ADVISED; Accident on 15-05-2018 involving SLJ4408L & SKN179P
Attachments: SLJ4408L15.05.2018.PDF; 18052018083557-0001.pdf

Dear Sirs,

Please conduct PRS as requested by the lawyer below.

The lawyer has specifically requested either Adrian Ling or Marcus Chua to conduct the PRS.

Please arrange accordingly.

Regards,
Francis Ng
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Catherine Lim LLC [mailto:info@catherinelimllc.com]
Sent: Friday, May 18, 2018 3:11 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Subject: Re: Pre-Repair Survey /Inspection; Your Ref: CL/180524/T/VAC; EQ Ref: SLJ4408L/TO BE ADVISED; Accident on 15-05-2018 involving SLJ4408L & SKN179P

Dear Sir

Our client chose as per below for pre repair survey:

LKK Auto Consultants Pte Ltd - either Adrian Ling or Marcus Chua.

Tks/rgds
wendy
Catherine Lim LLC
20 Havelock Road #03-01
Central Square

Singapore 059765
Tel: 6438 5500
Fax: 6438 0111
email: info@catherinelimllc.com

From: Francis Ng
Sent: Friday, May 18, 2018 8:37 AM
To: Catherine Lim LLC
Subject: Pre-Repair Survey /Inspection; Your Ref: CL/180524/T/VAC; EQ Ref: SLJ4408L/TO BE ADVISED; Accident on 15-05-2018 involving SLJ4408L & SKN179P

To: CATHERINE LIM LLC

Dear Sirs,

Without Prejudice

We refer to your letter dated 17.05.2018.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors.

If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us.

Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Hui Lian
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662

Contact Person: Kelvin	Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Francis Ng
 Executive | Claims

EQ Insurance Company Limited
 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L.LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K
GST Registration No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation with
limited liability

Your Ref: SLJ 4408L
Our Ref: CL/180524/T/VAC

17 May 2018

M/s EQ Insurance Company Ltd
22 Gemmil Lane
Singapore 069257
Attn: Motor Claims Department

RECEIVED
17 MAY 2018
EQ INSURANCE CO. LTD.

via fax: 6223 4190 & By Hand

Roset Limousine Services Pte Ltd
53 Ubi Avenue 1 #03-47
Paya Ubi Industrial Park
Singapore 408934

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING SKN 179P / SLJ 4408L ON 15.05.2018 ALONG PIE TOWARDS JURONG
(AFTER PAYA LEBAR)**

We are instructed by JAMES STUART MACTAGGART to notify you of a road traffic accident involving our client's vehicle No. SKN 179P and vehicle No. SLJ 4408L driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Company: Autobay Pte Ltd
1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Contact: 86188611

Yours faithfully

Enc
cc: M/s VAC

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9563E
Vehicle Details	
Vehicle No.:	SKN179P
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	PORSCHE
Vehicle Model:	911 GT3
Primary Colour:	Red
Manufacturing Year:	1999
Engine No.:	63Y00986
Chassis No.:	WPOZZZ99ZYS690480
Maximum Power Output:	-
Open Market Value:	\$127,606.00
Original Registration Date:	06 Jan 2000
First Registration Date:	06 Jan 2000
Transfer Count:	9
Actual ARF Paid:	\$178,649.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$18,484.00
COE Rebate Amount:	\$3,001.00
Total Rebate Amount:	\$3,001.00

The information contained herein is correct as at 21 May 2018

OK

cee

CONSUMER ELECTRONICS EXHIBITION 2018

24-27 MAY

LEVEL 3, 11AM-9PM

LEVEL 4, 12PM-9PM

SURE WIN INSTANT LUCKY SPIN

\$300,000

WORTH OF PRIZES & VOUCHERS

Click to find out more!

SUNTE

X

Porsche 911

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Prem Roy Motoring » Porsche 911 C2 Cabriolet Tip (COE till 03/2020)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

CL LEASING

YOUR PREFERRED CAR LEASING OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Porsche 911 C2 Cabriolet Tip (COE till 03/2020)

Overview Financial Accessories Similar Research Photos Map

CONSIGNMENT

RENTCARLEASE PTE LTD in affiliation with

Prem Roy Motoring Pte Ltd

DRIVE YOUR DREAM

COMPLETE CAR TRADE SOLUTIONS

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$80,800	
Depreciation	\$43,370 /yr	?
Reg Date	24-Feb-2001 (1yr 10mths 10days COE left)	
Manufactured	2001	?
Mileage	83,000 km (4.8k /yr)	
Transmission	Auto	
Engine Cap	3,387 cc	
Road Tax	\$4,488 /yr	?
Features	3.6L Tiptronic Flat, 6 Cyclinders With 355Bhp At 6600Rpm, Max 400NM, 4600Rpm, 0 To 100km/h At 4.9 Seconds. Fully Automatic Soft Top Roof.	
Accessories	Paddle Shift Gear, Ceramic Brakes, Bluetooth Connectivity.	
Description	This Lifestyle Drive Promise A Whole Lots Of Fun And Practicality. Engine, Smooth Transmissions, Sound Undercarriage. Immaculate Condition! Car That Has Been Lovingly Cared For. Very Low Mileage Done. Original Condition. Consignment Unit! Call Now For Viewing Appointment!	
COE	\$20,926	?
OMV	\$109,407	?
ARF	\$153,170	?
Dereg Value	\$3,899 as of today (change)	?
No. of Owners	More than 6	?
Type of Veh	Sports Car	
Category	COE Car, Consignment Car, Low Mileage Car	
Availability	Available	CONSIGNMENT

Add to Shortlist Add to Compare Add a Note

Posted on: 31-Mar-2018 | Last Updated on: 08-May-2018
Tags: Porsche 911, 2001 Porsche 911, Porsche, 911, Used Porsche

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Seller Information

Company

Prem Roy Motoring

» dealer's pricelist

» 186 vehs sold | 203 vehs available

Address

9 Tagore Lane #02-03

Search cars nearby this location

MR PORTER

Compare

Upfront Payment » more Financial info

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/05/2018 21:24
Date Of Accident	15/05/2018 16:25
Exact Location Of Accident	PIE TOWARDS JURONG (AFTER PAYA LEBAR)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN179P
Insured/Policyholder	
Name Of Registered Owner	JAMES STUART MACTAGGART
NRIC No	S6869563E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91715589
Alternative Phone No	OFFICE-91715589

Vehicle Particulars

Manufacturer	PORSCHE
Model	911-GT3
Exact Purpose for which vehicle was being used at time of accident	ON MY WAY HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	17-MH001204-R01
Cover Note Number	

Driver

Name of Driver	JAMES STUART MACTAGGART
NRIC No	S6869563E
Date Of Birth	22/12/1968
Occupation	INDOOR
Date Of Driving Pass	18/06/2013
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91715589
Fax Number	
Contact Number	OFFICE-91715589
EMail Address	NOEMAIL

Address	6 CAIRNHILL CIRCLE #03-10
Postcode	229813
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	SFF1668P - -
Insurance Company of Driver's Own Vehicle	TOKIO MARINE INSURANCE SINGAPORE LTD - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG. CANNOT UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ4408L
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	FRONT RIGHT PORTION DAMAGED
Vehicle Category	PRIVATE CAR
Name of Driver	TEOH TECK HIN
NRIC/Passport Number	S1467329F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT RIGHT PORTION DAMAGED
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation. *
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 16/05/18

Driver's Signature

(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature


Name:

NRIC/TIN No.:

16/05/18

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO THE ATTACHED REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 16/05/18

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

16/05/18

ACCIDENT REPORT

On 15th May 2018 at about 16:25 o'clock, I was travelling in lane 2 along PIE towards CTE (City). It was raining hard and there was heavy traffic, and so all cars were moving slowly.

Just before KPE/Bendemeer road exit, the vehicles in all lanes (including my lane 2) slowed, and then the vehicles in my lane 2 came to a complete stop. I stopped my vehicle (Regn No: SKN179P), maintaining a safe distance from the vehicle in front of me (registration no: SJN6805M).

As I was not far from the PIE exit on to CTE, I wished to move to lane 3. The vehicles in lane 3 and 4 started to move, and so I used my light indicator to show I wanted to move to lane 3. I observed that it was clear and safe for me to filter left into lane 3, and there was a large opening after the lorry (NCK Transport Services) cleared the path.

At that time of my filtering, I noticed that another vehicle (Regn No: SLJ4408L) which was 3 vehicles behind me and in lane 2, quickly filtered left into lane 3 and then started to cross over to lane 4. It appeared that he was going to pass me on the left in lane 4. However, just as I moved forward slowly in to lane 3, the front right portion of vehicle SLJ4408L suddenly hit the left portion of my slow moving vehicle (SKN179P). When the accident occurred, the driver of SLJ4408L (Mr Teoh Teck Hin, NRIC No: S1467328F) was driving partly in lane 3 and lane 4, and it looks like he was more in lane 4 than lane 3. After the accident, we moved our vehicles to the expressway hard shoulder, so as not to block traffic.

In my more than 30 years of driving, this is the first accident I have been involved in, and ipso facto, my first accident in Singapore. I therefore called the police to inform them of the accident but was advised that there was no need to make a police report as no one was injured and there was not damage to government property.

I requested the NRIC and telephone number of the driver and although he reluctantly provided his NRIC, he refused to provide contact details or a phone number.

I have video recordings from my in-vehicle cameras (both front and rear cameras) showing the accident, including the positions of both my car and that of vehicle SLJ4408L.

Identification Card

REPUBLIC OF SINGAPORE DRIVING LICENCE


James Stuart Mactaggart

56869563E

James Stuart Mactaggart

Issued: 22 Dec 1968
Valid till: 20 Jun 2016

56869563E



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. 56869563E


James Stuart Mactaggart

James Stuart Mactaggart

56869563E

Issued: 22 Dec 1968
Valid till: 20 Jun 2016

56869563E



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

	EFFECTIVE DATE
Class 2 Motor cars with unladen weight ≤ 2000 kg with ≤ 2 axles and/or 1000 kg or less motor vehicle with unladen weight ≤ 2000 kg	15 Jun 2013

Location No: 50959521E

MP 429A

BRITISH
Czech of India
10-22-2015
6 CARMALL CIRCLE 403-10
SINGAPORE 229813
MOBILE NO: 98689503E
DATE: 20/04/2018

Accident Photo



AUTOBAY PTE LTD

1 Kaki Bukit Ave 6, #02-11 AutoBay @ Kaki Bukit, Singapore 417883
Tel/Fax : 6636 5355

not Allowed
take
1/5 @ 8100/2
5 day
21/5/18
take photo after rep

Vehicle number: SKN179P

Vehicle Made & Model: PORSCHE 911 GT3

Qty	List Items	Amount \$
1	Front fender - LH <i>body</i>	1,899.55
1	Front fender inner shield <i>del/torn</i>	481.93
15	Front fender inner shield clips @ 5.60 <i>nu</i>	84.00
1	Front door - LH <i>PP/meyal 3650.30</i>	3,950.60
1	Front door glass outer moulding <i>11</i>	281.95
1	Front door glass regulator assy <i>11</i>	891.50
1	Front door inner trim board <i>11</i>	1,265.50
1	Front door insulation <i>11</i>	180.90
1	Front door w/strip <i>nu</i>	290.60
1	Front door checker <i>11</i>	145.00
2	Front door hinges @ 135 <i>tw</i>	270.00
1	Front shock absorber - LH <i>11</i>	1,150.00
1	Front top control arm <i>11</i>	680.60
1	Front knuckle arm <i>11</i>	1,559.60
1	Front wheel hub bearing <i>11</i>	726.50
1	Front anti roll bar <i>11</i>	645.00
1	Front anto roll bar link <i>11</i>	211.50
Sub-total		14,714.73
Less 10%		1,471.47
Total List		13,243.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damage report(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

<u>Special Nett Items</u>		
1	Front sport wheel <i>20/cw</i>	2,500.00
1	Front tyre <i>su</i>	1,200.00
1 set	Front sill panel skirt <i>cre</i>	1,800.00
Total Special Nett		5,500.00

<u>Labour Charges</u>		
To remove, refix front undercarriage	<i>11</i>	350.00
To re-seal anti-rust		120.00
To check wheel alignment		150.00
To respray painting & etc		1,200.00
Panel beating, cut, weld, remove & replacing above parts		1,200.00
Total Labour		3,020.00

ESTIMATE PARTS & LABOUR GRAND TOTAL \$ **21,763.26**




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18009178/Uvbe2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 13-06-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 4408L	Veh. Inspected	SKN 179P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	FRANCIS NG	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE 911 GT3 (A)	c.c	3600	
Engine No.	HIDDEN	Year of Reg.	2000	
Chassis No.	WPOZZZ99ZYS690480	Colour	ORANGE	
Odometer	193871	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	MICHELIN	6 mm	
L/H Front Tyre	235/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	295/30 R18	MICHELIN	6 mm	
L/H Rear Tyre	295/30 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/05/2018	Inspection Date	21/05/2018	
Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 179P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER - LH	BADLY DENTED	1,899.55	1,899.55
1	FRONT FENDER INNER SHIELD	DEFORMED / TORN	481.93	481.93
15	FRONT FENDER INNER SHIELD CLIPS @\$5.60	NECESSARY	84.00	84.00
1	FRONT DOOR - LH	DENTED / WARPED	3,950.60	3,650.30
1	FRONT DOOR GLASS OUTER MOULDING	NOT NECESSARY	281.95	-
1	FRONT DOOR GLASS REGULATOR ASSY	NOT NECESSARY	891.50	-
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	1,265.50	-
1	FRONT DOOR INSULATION	NOT NECESSARY	180.90	-
1	FRONT DOOR W/STRIP	NECESSARY	290.60	290.60
1	FRONT DOOR CHECKER	NOT NECESSARY	145.00	-
2	FRONT DOOR HINGES @\$135.00	TWISTED	270.00	270.00
1	FRONT SHOCK ABSORBER - LH	NOT NECESSARY	1,150.00	-
1	FRONT TOP CONTROL ARM	NOT NECESSARY	680.60	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	1,559.60	-
1	FRONT WHEEL HUB BEARING	NOT NECESSARY	726.50	-
1	FRONT ANTI ROLL BAR	NOT NECESSARY	645.00	-
1	FRONT ANTO ROLL BAR LINK	NOT NECESSARY	211.50	-
	LESS 10% DISCOUNT		-1,471.47	-667.64
			13,243.26	6,008.74
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT WHEEL (SN)	DENTED / CUT	2,500.00	850.00
1	FRONT TYRE (SN)	SERVICEABLE	1,200.00	-
1	SET FRONT SILL PANEL SKIRT (SN)	CRACKED	1,800.00	1,500.00
			5,500.00	2,350.00
<u>LABOUR</u>				
	TO REMOVE, REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO RE-SEAL ANTI-RUST.		120.00	50.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO RESPRAY PAINTING & ETC.		1,200.00	900.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS.		1,200.00	800.00
			3,020.00	1,830.00
GRAND TOTAL			21,763.26	10,188.74

Report Ref No. CS/EQI18009178/Uvbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,100.00
---	--	--	----------

Report Ref No. CS/EQ18009178/Uvbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.