

ASS. REC. BY:

REF: CS/AGL18009195/Urbnz

Special Instruction:

Surveyor:

MARCUS

ASSIGNMENT (Office)

From (Person):

Julie

of

AGL

Date/Time:

21/05/2018 1pm

Estimated Cost:

Bill to:

OD / FF / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDZ 7088S

Insured:

SKT 154D

at Workshop m/s

Kah Motor

Tel:

6514 5687

of

19 ubi Rd 4

Policy No:

Claim No:

C10001605/AH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/05/2018

CA / REV / REP. / REV 24 HRS WP

21/05/2018 @ 10am

H.O.D. Endorsement:

Date/Time:

21/05/2018 1:05pm

Person Contacted:

Mr. Liew

Vehicle IN OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SDZ 7088S - x
	SKT 154D - x

REF: AGI

ASSIGNMENT

From: \_\_\_\_\_ Date: 23/5/18

Estimated Cost: \_\_\_\_\_

OD  TP  WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDZ 7088S

at Workshop m/s Kah Motor

of 15 Ubi Road #

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) 10 am

Make of Veh: Mir-Hew

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 36k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GA / PR Seen:  Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SDZ 7088S Yr Regn: 6 03

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Odyssey C.C. 2253

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 108694 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRA 68403C 200792

Gen. Cond: Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm

D.O.A. 15/5/18 D.O.I. 23/5/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/7/18 contact final by 32694 5 yrs. @ 1371.50 with Ruben (Ref 500, 279)

RECEIVED 20 JUL 2018

Date/Time. File Pass to?  : Preli. Report

1)  : Final Report

Date/Time. File Return to? \_\_\_\_\_

2) soft - typist

Report Format: TP

Lump Sum / I.B.I: (\$) 1371.50

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

3) Photos

4) Others: \_\_\_\_\_

TOTAL 250

## Veron Chen (LKKAuto)

---

**From:** Jeshurueben Rao Thomas <jeshurueben@honda.com.sg>  
**Sent:** Wednesday, 11 July 2018 11:42 AM  
**To:** Marcus Chua (LKKAuto)  
**Cc:** SUR  
**Subject:** Pre-Invoice Of Vehicle No: SDZ7088S For Finalising  
**Attachments:** 3098\_001.pdf

Dear Marcus,

We enclosed the total final repair costs of...

Vehicle No. SDZ7088S  
Final Repair Costs (include GST) \$1,467.51  
Repair Period\*(Working Day) 2 days  
\*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank You

### Warmest Regards

Jeshurueben Rao Thomas (Rueben)  
Bodyshop Service Advisor  
Kah Motor Body Repair Centre  
15, Ubi Road 4  
Singapore 408610  
Tel : 68465672  
Hp : 90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

**Catherine Chong (LKK Auto)**

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Monday, 21 May, 2018 1:00 PM  
**To:** SUR; assignments  
**Cc:** Albert Hong  
**Subject:** FW: DIRECT SETTLEMENT OF VEHICLE NO: SDZ7088S AGAINST SKT154D. Accident date on 15/5/18 | AGI Claim ref: C10001605/AH  
**Attachments:** 1643\_001.pdf

Hi Team

Sent on behalf of Albert.  
Please accept TPPD survey assignment and survey on a without prejudice basis.

Thank you,

---

**From:** Liew Thye Wui <twliew@honda.com.sg>  
**Sent:** Monday, 21 May, 2018 12:10 PM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Subject:** DIRECT SETTLEMENT OF VEHICLE NO: SDZ7088S AGAINST SKT154D. Accident date on 15/5/18

Dear Officer-in-charge,

Kindly refer to the attachments for third party direct settlement.  
Vehicle is not in our workshop. Please call for the arrangement.  
Meanwhile, kindly get back to me once liability has establish.

*21052018 @ 1.55pm  
Mr. Liew veh not in*

Thank you very much.

Best Regards

TW LIEW  
Kah Motor Co. Sdn. Bhd.  
15 Ubi Road 4  
Singapore 408610  
DID: 6514 5687  
Fax: 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8780F
<b>Vehicle Details</b>	
Vehicle No.:	SDZ7088S
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY2.3 A
Primary Colour:	White
Manufacturing Year:	2003
Engine No.:	F23Z44000727
Chassis No.:	JHMRA68403C200792
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$29,715.00
Original Registration Date:	04 Jun 2003
First Registration Date:	04 Jun 2003
Transfer Count:	0
Actual ARF Paid:	\$38,630.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Jun 2023
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$65,001.00
COE Rebate Amount:	\$32,694.00
<b>Total Rebate Amount:</b>	<b>\$32,694.00</b>

The information contained herein is correct as at 23 May 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/05/2018 15:16
Date Of Accident	15/05/2018 13:20
Exact Location Of Accident	UPPER SERANGOON ROAD & HOUGANG AVE 3 JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDZ7088S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHANWING HON BENJAMIN
NRIC No	S0028780F
Email Address	BENJAMINCHAN89@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98382688
Alternative Phone No	OFFICE-67289178
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	ODYSSEY-2.3 RA6 (A)
Exact Purpose for which vehicle was being used at time of accident	FETCH MY SON HOME FROM HOSPITAL APPOINTMENT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P0094196
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHANWING HON BENJAMIN
NRIC No	S0028780F
Date Of Birth	28/09/1951
Occupation	INDOOR
Date Of Driving Pass	03/04/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98382688
Fax Number	
Contact Number	OFFICE-67289178
EMail Address	BENJAMINCHAN89@GMAIL.COM

Address	BLK 830 SIM AVE #08-898
Postcode	400830
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JOSHUA CHAN CHEE WENG GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHMENT REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT154D
Vehicle Make/Model/Colour	MAZDA / 2 / PURPLE
Details Of Properties	FRONT
Vehicle Category	PRIVATE CAR
Name of Driver	MS TOH CHEIA WEI
NRIC/Passport Number	S7930972I
Contact Number	98780721
Address	BLK 951 HOUGANG AVE 9 #11-504
Postcode	530951
Insurance Company Name	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Vehicle No SDZ 7088S

**SKETCH PLAN**

Annex D

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*WChan*

Policyholder's Signature / Date & Time  
17 May 2018

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Hougang Avenue 3

Upper Serangoon Road

← Honda  
 ← Mazda

Please continue to Annex E

Vehicle No SDZ 7088S

Annex E

**Describe Circumstances of the Accident**

Please refer to attached "Describe Circumstances of the Accident" for details  
Please also refer to attached "Summary of SMS Conversations with Mr Teh Choo, Owner of Mazda 2 SKT 154D, who hit the rear of my car, Honda Odyssey, SDZ 7088S" for details.

**Declaration**

We declare the foregoing particulars are true in every respect.

*W Chan*

Policyholder's Signature / Date & Time

17 May 2018

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Vehicle No SDZ 7088S

Annex E

**Describe Circumstances of the Accident**

On Tuesday, 15 May 2018, I, Chan Wing Hon Benjamin, was driving my car, Honda Odyssey SDZ 7088S, into Hougang Avenue 3 from Upper Serangoon Road. Suddenly I heard a very loud sound at the back of my car as it was hit by another car. My son, Joshua Chan, who was seated at the back of the car shouted that my car had been hit by another car from behind.

I alighted and inspected my car for damages. I discovered dents, cracks and gaps in my bumper on the right side of the car, rear bumper and interior of the car boot. Please refer to photographs for reference.

Ms. Toh Cheia Wei, NRIC No: S7930972i, Block 951, Hougang Avenue 9, #11-504, Singapore 530951 is the driver of the purple-coloured Mazda 2, SKT 154D, that hit the rear my car. At the scene of accident, Ms Toh Cheia Wei admitted her fault and apologised to me. She said to me "Sorry. It is my fault. I should be more careful. You can see my body is shaking."

Ms. Toh wants to settle privately or through her insurance without me paying for the repairs or claiming from my insurance. Please refer to her attached SMS on 15 May at 1.50 pm for reference. After the quotation from Honda Kah Motor was SMSed to her in the evening of 15 May 2018, Ms Toh, in her telephone conversation with me around 10.07 pm, remarked the repairs are expensive and increase in her insurance premium and NCD would not be much compared to quoted price of \$1,103.71. She would call the Ubi Workshop on why need to pay upfront deposit of \$675.71 to Workshop first before it can backorder rear bumper from Japan.

Despite several reminders SMSes from me, she contacted Workshop Supervisor only on Thursday, 17 May, around 11 am. Ms. Toh SMEed at 11.08 am the reason why Workshop requires upfront deposit payment is because my car is old model. It will not be easy to source for the parts. She requested to go to her Mazda accident reporting centre to lodge accident report first. After that, proceed to Honda Ubi where she will pay cash if there is a need as the parts of my car are old and hard to source for. She understands the need for cash deposit. No worries about that she added in her SMS on 17 May 2018, 11.58 am.

I called Mr. Liew Thye Wui who informed that Kah Motor Ubi Workshop is also the authorised accident reporting centre for Honda cars. He informed that I would need to pay a penalty equivalent to 10% loss of No-Claim Bonus Discount (NCD) for late accident reporting of accident due to Ms. Toh's last minute change of decision to claim from her insurance company. Late reporting penalty of 10% loss of NCD amounts to \$200 according to Ms Lei Sing, Winner Insurance Agency. I have been enjoying 50% No-Claim Bonus for many years all along. I SMSed Ms Toh that she has to compensate me for this \$200 penalty from late reporting and loss of no-claim bonus discount. Repair costs would also be 10 to 20% higher than quoted \$1,103.71 according to Workshop Supervisor.

Sketch Plan Pg. 4

At 1.42 pm on Thursday, 17 May, Ms. Toh SMSed that she has decided to let her insurance company take over and assist me in the repairs and other claims professionally due to a large number of details and uncertainty in the situation.

Kindly refer to attached "SUMMARY OF SMS CONVERSATIONS WITH Ms TOH CHEIA WEI, OWNER OF MAZDA 2 SKT 154D, WHO HIT THE REAR OF MY CAR, HONDA ODYSSEY, SDZ 7088S" for more details.

Chan Wing Hon Benjamin

Name

*WCH*

Signature

17 May 2018

Date



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair  
Tel: +65 6841 3838 Website: www.honda.com.sg  
For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: AUTO & GENERAL INSURANCE 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING SINGAPORE 239924	<b>Document No.</b>	: SQT18001993	<b>Page</b>	1
<b>Registration No</b>	: SDZ7088S	<b>Date</b>	: 15. May 2018	<b>Customer No.</b>	: WZA002
<b>Chassis No</b>	: JHMRA68403C200792	<b>Svc Advisor</b>	: LIEW THYE WEI	<b>Engine No</b>	: F23Z44000727
<b>Model</b>	: ODYSSEY 2.3 AUTO	<b>Date   Time</b>	: 15. May 2018 4:42:36 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: CHAN WING HON BENJAMIN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 15/5/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: CHAN WING HON BENJAMIN OWNER INSURER: AXA INSURANCE PTE LTD ACC DATE: 15/5/18 SURVEYED BY: DATE: REF NO: TP INSURER: AUTO & GENERAL INSURANCE (S) PTE. LTD. TP VEH: SKT154D						
04715-S3N-J00ZZ	FACERR BUMPER	1	842.00	25	631.50	44.21	675.71
				<b>Sum Item</b>	<b>631.50</b>	<b>44.21</b>	<b>675.71</b>
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BKBU02R	REMOVE & RENEW RR BUMPER.	1	560.00		560.00	39.20	599.20
BP01R	SPRAY PAINTING ON REAR BUMPER.	1	650.00		650.00	45.50	695.50
				<b>Sum Labor</b>	<b>1240.00</b>	<b>86.80</b>	<b>1,326.80</b>

Survey By	<u>mercy kch</u>	<b>Total Amount</b>	1,871.50	131.01	2,002.51
Date & Time	<u>23/5/18 @ 10am</u>	<b>Total (Inclusive of GST)</b>			<b>2,002.51</b>
Excess					
Status	<u>Take up the repair party.</u>				
Signature	<u>2-Body</u>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 19/5/2018 1:04:26 PM

This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s)

11/7/2018

PAGE 1/1



# (C) SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

ATTN: MARCUS (LKK)

 GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

WD: 2 DAYS

**Customer:** WZA002 / AUTO & GENERAL  
**Chassis No:** JHMRA68403C200792  
**License No:** SDZ7088S  
**Mileage:** 108851  
**Engine No:** F23Z44000727

**Document No:** SVO18029937  
**Printed By:** JESHURUEBEN  
**Order Date:** 4. June 2018  
**Order Time:** 9:15:58 AM  
**Service Advisor:** RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	incl GST
	TP DIRECT SETTLEMENT (J/NO: 70605 ) OWNER: CHAN WING HON BENJAMIN OWNER INSURER: AXA INSURANCE PTE LTD ACC DATE: 15/5/18 SURVEYED BY: MARCUS (LKK) DATE: 23/5/18 @10AM. REF NO: TP INSURER: AUTO & GENERAL INSURANCE (S) PTE. LTD. TP VEH: SKT154D						
04715-S3N-J00ZZ	FACERR BUMPER	1	842.00	25	631.50	44.21	675.71
					<b>SUM PARTS:</b>	<b>631.50</b>	<b>44.21</b>
							<b>675.71</b>
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BKBU02R	EXT-YJ REMOVE & RENEW RR BUMPER.	1	280.00		280.00	19.60	299.60
BP01R	EXT-YBH SPRAY PAINTING ON REAR BUMPER.	1	450.00		450.00	31.50	481.50
					<b>SUM LABOUR:</b>	<b>740.00</b>	<b>51.80</b>
					<b>TOTAL SGD</b>	<b>1,371.50</b>	<b>96.01</b>

**Total Payable (SGD)**
**1,467.51**

GST Amount is calculated from individual line(s)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009195/Uvbn2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 23-07-2018



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 154D	Veh. Inspected	SDZ 7088S
Policy No.		Coverage (\$)	0.00
Claim No.	C10001605/AH	Excess (\$)	0.00
Assign From	JULIE	Assign Date	21/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2253
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	JHMRA68403C200792	Colour	WHITE
Odometer	108694	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	15/05/2018	Inspection Date	23/05/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 7088S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FACERR BUMPER (SN)	DENTED / CRACKED	631.50	631.50
1	SUNDRIES (SN)	NECESSARY	30.00	10.00
			661.50	641.50
	<b><u>LABOUR</u></b>			
	REMOVE & RENEW RR BUMPER.		560.00	280.00
	SPRAY PAINTING ON REAR BUMPER.		650.00	450.00
			1,210.00	730.00
	<b>GRAND TOTAL</b>		<b>1,871.50</b>	<b>1,371.50</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,371.50</b>

Report Ref No. CS/AGI18009195/Uvbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.