

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.05.2018

REPAIR ESTIMATE

Time: 15:14:11

Page: 1

Argenta-CLS)

Lrp - kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305161843
 REGN NO : SHA7236R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.04.2014
 DATE/TIME IN : 18.05.2018 08:55
 ACCIDENT DATE : 17.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0578-G	FRT BUMPER	1	562.30	20.00	449.84	✓
0002	04-01-0103-0654-G	FRT BUMPER GRILLE RH	1	40.30	20.00	32.24	✓
0003	04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	?
0004	04-01-0103-0640-G	FRT BUMPER BRKT RH	1	24.60	20.00	19.68	?
0005	04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40	✓
0006	04-01-0103-0582-G	RADIATOR GRILLE	1	417.00	20.00	333.60	?
0007	04-01-0103-0658-G	FRT WHEEL CAP RH	1	150.70	20.00	120.56	✓
0008	04-01-0103-0573-G	FRT FENDER RH	1	619.00	20.00	495.20	✓

SUB-TOTAL : 2,579.44

JOB NATURE

0000 L	PANEL BEATING	560.00	400
0001 23-502	SPRAYPAINT ON AFFECTED AREA	500.00	400
0002 17-01	CHECK ALL LIGHTING	40.00	20

TS

Ang Hsua

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305161843
REGN NO : SHA7236R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.04.2014
DATE/TIME IN : 18.05.2018 08:55
ACCIDENT DATE : 17.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-00 TUFF COAT ON AFFECTED PARTS.

0004 L WHEEL ALIGNMENT

~~40.00~~ 20~~120.00~~ X

SUB-TOTAL : 1,260.00

TOTAL : 3,839.44

Limpf

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Kelvin 10064
18/5/18 1520 hrs
2 Pgs.
4/5
After Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: