

INS. CASE OWNER:

CC 4 / III 1800 9244 / G pasy

Surveyor:

DOI:

ASSIGNMENT

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJJ 67024



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

x

days)

Loss of Income (LOI):

S\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: ☐ Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

ASSIGNMENT

(-2018)

From: Date: 18/05/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJJ 6702 Y
at Workshop m/s Wei Lee Motor Works
of Blk 9 Sin Ming Ind. Est #01-32

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$33K 12K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJJ 6702 Y Yr Regn: 23 Sep 2008

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tapah AHI's C.C. 1598

Colour: black A/C: Insured / Std / NI / NA

Sp. Reading: 144554 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR0538EE106114377

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 18-05-18

Survey held at: W/S 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIS \$3000 (Rear) \$4171.20 / 58%

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RD \$

) Photos

) Other

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

威利摩 叻 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986
Business Regn No : 269436/00J

Dated : 17/5/2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street, #04/#05/#06-02

IOB Building, Singapore 049711

Attn: Motor claim department-3rd party claim

Claiming against your insured vehicle no: SHA7224A

Accident involving vehicle no : SJJ6702Y / SHA7224A

Date of Accident : 14/05/2018

PL : At Telok Blangah Rd heading Tuas from Kampong Bahru

Dear officer incharge,

Re: Estimate of repair to SJJ6702Y

To supplied:-

Description	Quantity	Amount \$
Rear Bumper / <i>RL</i>	1	482.00
Bumper Foglamp Rh n Lh @ 37.20 <i>X NN</i>	2	74.40
Bumper Retainer Rh n Lh @ 69.80 <i>/ MC</i>	2	139.60
Boot Weatherstrip <i>/ TN</i>	1	184.70
End Panel Top Garnish <i>/ RL</i>	1	202.70
End Panel <i>/ Bue</i>	1	580.60
Rear Bumper Sponge / Enforcement <i>X / CRA</i>	1	123.50
Tailamp Rh n Lh @ 409.90 <i>/ Cut</i>	2	819.80
Tailamp Lower Bracket @ 57.30 <i>X NN</i>	2	114.60
Lid <i>/ BT</i>	1	618.50
Lid Handle <i>X NN</i>	1	232.50
Lid - Toyota Emblem <i>/</i>	1	58.30
Lid - "1.6" Emblem <i>/</i>	1	33.90
Lid - Altis Emblem <i>/</i>	1	46.60
Lid - Corolla Emblem <i>/</i>	1	46.60
Lid Lock <i>/ BT</i>	1	105.60
Lid Reflector Rh n Lh @ 171.60 <i>/ CRA</i>	2	343.20
Bumper Clip <i>/ MC</i>	10	36.00
Rear Boot Carpet <i>/ TN</i>	1	180.20
Rear Bumper Lower Skirt <i>/ CRA</i>	1	728.50

Reverser Sensor */ DM*

220.00

To remove damage parts & attachments

Repair/Reshape dented lid and all dented areas

To renew/ align all parts into position

To spray paint:-

**Please arrange to survey the vehicle as soon as possible

Thank you.

KK Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after spray painting

and part(s) during resurvey

and subject to confirmation

* Third party survey is on a "Without Prejudice" basis

* No legal modification(s) is allowed

* Sample parts must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

5 Days.

Lump Sum Repair

After repair photos.

Guo Qianf - 82880282

18/5/18.

700 900.00

800 900.00

Hsiao Tong (LKKAuto)

From: karen Seah <weileemotorworks@gmail.com>
Sent: Friday, 22 June 2018 11:51 AM
To: Hsiao Tong (LKKAuto)
Subject: Re: Finalize repair amount for Vehicle No: SJJ6702Y *LKK REF: CC4/III18009244/pa3
Attachments: doc02521220180622115153.pdf

Vehicle No: SJJ6702Y

Hi Hsiao
Attached with the necessary document for the above vehicle.
Appreciate if you could acknowledge receipt of this email.

On Fri, Jun 22, 2018 at 11:10 AM, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Hi Karen,

Noted with thanks.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Hi Mei Kwan,

File please.

AUDIT TRAIL				By
No.	On	Audit	Remarks	
20	07 Jul 2018 14:27	Adj Mandate Request	Cur.Req:3307.45:PODS Liability: 100% Quantum:(a)COR: \$3,000.00 + (b)LOU(5days x \$60.00):\$300.00 + (c)LTA/GIA Search fee: \$7.45 = Total: \$3,307.45 Vehicle Model: Toyota Altis (1598cc) For your approval.	[A] CHEW HSIAO TONG
Date From		<input type="button" value="Previous"/> <input type="button" value="Today"/> <input type="button" value="Next"/>	Date To	<input type="button" value="Previous"/> <input type="button" value="Today"/> <input type="button" value="Next"/>
Audit Type				None <input type="button" value="Go"/>

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Ref No	Ref Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1850243	04/07/2018 12:41	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJJ6702Y	SHA7224A	10.70

Print Received Message

This mail is associated with :

***SJJ6702Y (MCT18050321)**
[SHA7224A]

TP

KH LEASING PTE. LTD.

May 13 2018 11:00AM

[-]

Wei Lee Motor Works

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/07/2018 12:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3307.45) - SJJ6702Y - Claim Handler: NATALIE LEE

Approved:3307.45.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 11 July 2018 12:25 PM
To: 'karen Seah'
Cc: Admin A
Subject: RE: Finalize repair amount for Vehicle No: SJJ6702Y *LKK REF: CC4/III18009244/Gpa3
Attachments: DV_SJJ 6702Y.pdf

Without Prejudice

Hi Karen,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,000.00
2. Loss of Use (5days x \$60.00)	\$ 300.00
3. LTA/GIA search fee	\$ 7.45
Total	\$ 3,307.45

If our offer is acceptable by your client, please duly sign the **DV** enclosed and return together with the following document to us(LKK) for our necessary action: -

- Original LOD
- Original Repair Invoice
- Original Authorisation to Act signed by your client, KH Leasing Pte Ltd

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 23 June 2018 7:43 AM
To: 'karen Seah' <weileemotorworks@gmail.com>

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~455 3986~~ 6458 0128
Business Regn No : 269436/00J

22, June 2018

India International Insurance PL

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SHA7224A

Accident involving vehicle no: SJJ6702Y/SHA7224A

ON 14/05/2018 AT Telok Blangah Rd heading Tuas from Kampong Bahru

Dear officer incharge

We are the workshop for the owner of vehicle no: SJJ6702Y

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SJJ6702Y as follow:-

Cost of repair to SJJ6702Y \$ 3,000.00 finalised with your surveyor

Loss of use \$ 400.00 \$80x05d

LTA search fee \$ 7.45

\$ 3,407.45

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.




AUTHORISATION TO ACT

I, KH Leasing Pte Ltd ("the third party claimant") of
261 A UPP Thomson Road (address), owner of
SG 6702 Y (vehicle no.) hereby authorize Wei Lee Motor Works
the (workshop) to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. SG 6702 Y that was damaged pursuant to the accident
which occurred 13/5/2018 (date) at Telok Blangah Rd heading Tuas (location)
involving vehicle no/s. 2HA 7224A This ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 17 (day) of May (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18050321
Claimant Ref: SJJ 6702Y

We/I, Wei Lee Motor Works ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,000.00 (repair cost), S\$ 300.00 (loss of use), S\$ 7.45 (search fee), vehicle no: SJJ 6702Y that was damaged pursuant to the accident which occurred on 13/05/2018 (date) at Telok Blangah Rd Heading Tuas From Kampong Bahru (location) involving vehicle no. SHA 7224A (insured vehicle). This is pursuant to the inspection conducted on 18/05/2018 (date) at "the workshop".

We/I confirm that we/I are/are authorized by the owner KH LEASING PTE. LTD. ("the third party claimant") of vehicle no. SJJ 6702Y to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJJ 6702Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,307.45 to Wei Lee Motor Works

Dated this 11 day of July 2018

CLAIMANT: KH Leasing PL

Signature:

Signed by "the workshop" (workshop)

Name:

WEI LEE MOTOR WORKS

NRIC:

269436100J

Address:

BLOCK 9 SIN MIN GIM ESTATE

#01-32 5575644

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)

Nationality:

Occupation:



威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

India international Insurance Pte Ltd
64 Cecil Street #04/#05/#06-02
IOB Building S 049711

INVOICE NO:12561
DATE:22,June 2018

PARTICULARS	AMOUNT (S\$)
Vehicle No; SJJ6702Y	
Cost of repair for vehicle No: SJJ6702Y	3,000.00
Lump sum repaired as recommended by your appointed surveyor-LKK Auto Consultants.	<u>3,000.00</u> =====



Payments to be made by crossed cheque in favour of WEI LEE MOTOR WORKS

[> Back to OneMotoring](#)

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 17 May 2018 / 11:43:08

Receipt Date/Time : 17 May 2018 / 11:43:08

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180517-000762

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA7224A				
As at 13 May 2018/11:10:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHA7224A Enquiry Fee 20180517114159765488	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180517114226878	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2018 Edit Reg		17 May 2018 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SJJ6702Y	Date of Loss:	13/05/2018 11:00 - :59 [115 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18050321	Policy/Cover Note No.:	MCOM0015 (Third Party Only)
Vehicle Reg. No. (Insured):	SHA7224A	Policy No. (Claimant):	5099812204
		Excess:	
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/05/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (09/07/2018): Alert - Adj Mandate Approved (S\$3307.45) - SJJ6702Y - Claim Handler: NATALIE LEE
- III_SG (07/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SJJ6702Y - Claim Handler: NATALIE LEE

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ6702Y (MCT18050321)
[SHA7224A]
TP
KH LEASING PTE. LTD.
May 13 2018 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Wei Lee Motor Works

Upload Documents			Upload Photos		Compose New Letter		View <div>View in Browser</div>	
Photos/Images							3 per page	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
2	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
3	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
4	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
5	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
6	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
7	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
8	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
9	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
10	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
11	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
12	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
13	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
14	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
15	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
16	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
17	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
18	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
19	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
20	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
21	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
22	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
23	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
24	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
25	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
26	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
27	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
28	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
29	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
30	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
31	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
32	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
33	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
34	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
35	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
36	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			
37	22/06/18 07:47	General View	<div></div>	Load JPG	<div></div>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/06/18 07:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/06/18 07:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/06/18 07:47	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
41	22/06/18 07:47	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 20:42	ACKNOWLEDGEMENT EMAIL TO III DD 17.05.2018	 Load PDF	
2	21/05/18 20:42	TP ESTIMATE + TP GIA REPORT	 Load PDF	
3	26/06/18 14:13	TP ESTIMATE	 Load PDF	
4	04/07/18 12:48	LTA SEARCH	 Load PDF	
5	13/07/18 15:10	AUTHORISATION TO ACT FORM	 Load PDF	
6	13/07/18 15:10	DISCHARGE VOUCHER	 Load PDF	
7	13/07/18 15:10	LOD	 Load PDF	
8	13/07/18 15:13	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 08:36	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009244/GPA3Q2

Date: 13/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SJJ6702Y Insured Vehicle No: SHA7224A
 Date of Loss: 13/05/2018 Nature of Claim: TP Claim No: MCT18050321

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ6702Y
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4784183
 Reg. Date: 23/09/2008 (Man. Year: 2008) Chassis No: MR053ZEE106114377
 Colour: Black Odometer: 144554 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,371.80	3,522.71	1,849.09	34.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,500.00	300.00	16.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,171.80	5,022.71	2,149.09	29.97
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,171.80	3,000.00	4,171.80	58.17
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,307.45		

INSPECTION

Date of Assignment: 17/05/2018
 Date Inspected: 18/05/2018 Inspected At: Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL
 ESTATE #01-32
 Singapore 575644
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ6702Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	482.00 F	*482.00 FL
2	2		*BUMPER FOGLAMP RH N LH	Not Necessary	74.40 F	*- FL
3	2		*BUMPER RETAINER RH N LH	Necessary	139.60 F	*139.60 FL
4	1		*BOOT WEATHERSTRIP	Torn	184.70 F	*95.67 FL
5	1		*END PANEL TOP GARNISH	Deformed	202.70 F	*36.00 FL
6	1		*END PANEL	Buckled	580.60 F	*580.60 FL
7	1		*REAR BUMPER SPONGE /ENFORCEMENT	Cracked	123.50 F	*123.50 FL
8	2		*TAILLAMP RH N LH	Cut	819.80 F	*819.80 FL
9	2		*TAILLAMP LOWER BRACKET	Not Necessary	114.60 F	*- FL
10	1		*LID	Bent	618.50 F	*618.50 FL
11	1		*LID HANDLE	Not Necessary	232.50 F	*- FL
12	1		*LID -TOYOTA EMBLEM	Necessary	58.30 F	*30.75 FL
13	1		*LID -1.6 EMBLEM	Necessary	33.90 F	*33.90 FL
14	1		*LID -ALTIS EMBLEM	Necessary	46.60 F	*25.70 FL
15	1		*LID -COROLLA EMBLEM	Necessary	46.60 F	*24.10 FL
16	1		*LID LOCK	Bent	105.60 F	*105.60 FL
17	2		*LID REFLECTOR RH N LH	Cracked	343.20 F	*343.20 FL
18	10		*BUMPER CLIP	Necessary	36.00 F	*36.00 FL
19	1		*REAR BOOT CARPET	Torn	180.20 F	*180.20 FL
20	1		*REAR BUMPER LOWER SKIRT	Cracked	728.50 F	*728.50 FL
21	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,371.80	4,623.62
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,100.91
Total Parts (\$\$)	5,371.80	3,522.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS & ATTACHMENTS REPAIR /RESHAPE DENTED LID AND ALL DENTED AREAS TO RENEW /ALIGN ALL PARTS INTO POSITION	New	900.00	700.00
2	TO SPRAY PAINT	New	900.00	800.00
Gross Labour Cost (\$\$)			1,800.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >