

威利摩 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
SINGAPORE 575644.
TEL: 456 9830 • FAX: 455 5986
Business Regn No : 269436/00J

Dated : 17/5/2018

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street, #04/#05/#06-02
IOB Building, Singapore 049711

Attn: Motor claim department-3rd party claim
Claiming against your insured vehicle no: SHA7224A
Accident involving vehicle no : SJJ6702Y / SHA7224A
Date of Accident : 14/05/2018
PL : At Telok Blangah Rd heading Tuas from Kampong Bahru

Dear officer incharge,

Re: Estimate of repair to SJJ6702Y

To supplied:-

Description	Quantity	Amount \$
Rear Bumper / <i>RE</i>	1	482.00
Bumper Foglamp Rh n Lh @ 37.20 <i>X NN</i>	2	74.40
Bumper Retainer Rh n Lh @ 69.80 <i>/ NCC</i>	2	139.60
Boot Weatherstrip <i>/ TN</i>	1	184.70
End Panel Top Garnish <i>/ RE</i>	1	202.70
End Panel <i>/ Bue</i>	1	580.60
Rear Bumper Sponge / Enforcement <i>/ CRA</i>	1	123.50
Tailamp Rh n Lh @ 409.90 <i>/ Cut</i>	2	819.80
Tailamp Lower Bracket @ 57.30 <i>X NN</i>	2	114.60
Lid <i>/ BT</i>	1	618.50
Lid Handle <i>X NN</i>	1	232.50
Lid - Toyota Emblem <i>/</i>	1	58.30
Lid - "1.6" Emblem <i>/</i>	1	33.90
Lid - Altis Emblem <i>/</i>	1	46.60
Lid - Corolla Emblem <i>/</i>	1	46.60
Lid Lock <i>/ BT</i>	1	105.60
Lid Reflector Rh n Lh @ 171.60 <i>/ CRA</i>	2	343.20
Bumper Clip <i>/ NCC</i>	10	36.00
Rear Boot Carpet <i>/ TN</i>	1	180.20
Rear Bumper Lower Skirt <i>/ CRA</i>	1	728.50

Reverser Sensor */ PM* 220.00

To remove damage parts & attachments 700 900.00

Repair/Reshape dented lid and all dented areas

To renew/ align all parts into position

To spray paint:- 800 900.00

****Please arrange to survey the vehicle as soon as possible**

Thank you.

KK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• Any damaged part(s) during resurvey
• Any work done subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary items must be resurveyed and
• Is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *[Signature]*
Date: *18/5/18*

After repair photos.
Guo Qian - 82880282
18/5/18